

OWNER: CESSNA FINANCE CORPORATION
ADDRESS: 100 N. BROADWAY
 WICHITA KS 67202
PHONE: 316-660-1321 J BECKSTEIN
FAX: 316 660 1260

OPERATOR: CESSNA FINANCE CORPORATION
ADDRESS: 100 N. BROADWAY
 WICHITA KS 67202
PHONE: 316-660-1321 J BECKSTEIN
FAX: 316 660 1260

ANALYST: HERVE NG
EMAIL: HNG@CAMPSYSTEMS.COM

514-448-1128 (OFFICE)
 514-448-1120 (FAX)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

AIRCRAFT SERIAL/REGNO: 5121/N328AM **MODEL:** CL-601-3A/3R (CIMMS) **MANUFACTURER:** BOMBARDIER INCORPORATED

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	01-OCT-1992	8947.8 A/C HRS	as of 19-JUL-2010	A/C HRS	as of ___/___/___
		4353 AFL	as of 19-JUL-2010	AFL	as of ___/___/___
		6016 APH	as of 19-JUL-2010	APH	as of ___/___/___

APU SERIAL/PART: P-413/3800050-5-1 **MODEL:** GTCP36-100(E) (3A/3R,600/011) **MANUFACTURER:** HONEYWELL

INSTALLED ON 20-AUG-2003		LAST ACTUALS		CURRENT ACTUAL	
4169	APU HRS	6016	APU HRS as of 19-JUL-2010	APU HRS	as of ___/___/___
6082	APUS	7799	APUS as of 19-JUL-2010	APUS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: 350-499/6063T01G04 **MODEL:** CF-34 (CIMMS) **MANUFACTURER:** GENERAL ELECTRIC

INSTALLED ON 29-AUG-2002		LAST ACTUALS		CURRENT ACTUAL	
5852	ENG. HRS	5989.9 A/C HRS	8809.9 ENG. HRS as of 19-JUL-2010	ENG. HRS	as of ___/___/___
3407	ENC		4344 ENC as of 19-JUL-2010	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: 350-498/6063T01G04 **MODEL:** CF-34 (CIMMS) **MANUFACTURER:** GENERAL ELECTRIC

INSTALLED ON 29-AUG-2002		LAST ACTUALS		CURRENT ACTUAL	
5852	ENG. HRS	5989.9 A/C HRS	8774 ENG. HRS as of 19-JUL-2010	ENG. HRS	as of ___/___/___
3407	ENC		4433 ENC as of 19-JUL-2010	ENC	as of ___/___/___

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS								
050012	100 HOUR CHECK PKG 1	MOS HRS/MSC AFL	100			19-JUL-2010 8947.8 4353	9047.8		100
	REF: GENERIC NO REF								
050014	300 HOUR CHECK PKG 2	MOS HRS/MSC AFL	300	+30/-30		09-SEP-2008 8806.5 4265	9106.5		158.7
	REF: GENERIC NO REF								
050016	600 HOUR CHECK PKG 3	MOS HRS/MSC AFL	600	+30/-30	-58.2	20-MAR-2009 8873.5 4304	9415.3		467.5
	REF: GENERIC NO REF								
050018	1200 HOUR CHECK PKG 4	MOS HRS/MSC AFL	1200	+30/-30		17-JUN-2005 8180 3964	9380		432.2
	REF: GENERIC NO REF								
050024	2400 HOUR CHECK PKG 6	MOS HRS/MSC AFL	2400	+30/-30		15-NOV-2003 7003 3486	9403		455.2
	REF: GENERIC NO REF								
050026	4800 HOUR CHECK PKG 10	MOS HRS/MSC AFL	4800	+30/-30	-257	27-MAR-2001 4859 2516	9402		454.2
	REF: GENERIC NO REF								
050042	12 MONTH CHECK PKG 30	MOS HRS/MSC AFL	12	+1m/-1m	-21	19-JUL-2010 8947.8 4353	28-JUN-2011	28-JUL-2011	294 d
	REF: GENERIC NO REF								
050044	24 MONTH CHECK PKG 32	MOS HRS/MSC AFL	24	+1m/-1m	31	28-MAY-2009 8928.6 4336	28-JUN-2011	28-JUL-2011	294 d
	REF: GENERIC NO REF								
050046	36 MONTH CHECK PKG 33	MOS HRS/MSC AFL	36	+1m/-1m	-129	19-JUL-2010 8947.8 4353	12-MAR-2013	11-APR-2013	917 d
	REF: GENERIC NO REF								
050048	48 MONTH CHECK PKG 40	MOS HRS/MSC AFL	48	+1m/-1m	-4	19-MAR-2007 8468 4101	15-MAR-2011	14-APR-2011	189 d
	REF: GENERIC NO REF								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
050050	60 MONTH CHECK PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60 +1m/-1m	-45		05-APR-2006 8305.8 4018	19-FEB-2011	20-APR-2011	165 d
APU Model : GTCP36-100(E) (3A/3R,600/011) Serial # P-413 Part # 3800050-5-1									
050013	APU - 400 HOURS APU PKG 1 REF:	MOS HRS/MSC APUS	400 +30/-30			04-JUN-2008 5745 7579	6145		129

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
CHAPTER 06										
DIMENSIONS AND AREAS										
T06T01	DIMENSIONS AND AREAS									
	REF:	MOS								
		HRS/MSC	O/C							
		AFL								
CHAPTER 11										
PLACARDS AND MARKINGS										
119001	CHECK CONDITION / SECURITY OF REQUIRED PLACARDS									
	REF:	MOS					09-SEP-2008			
		HRS/MSC	300				8806.5	9106.5		158.7
		AFL					4265			
CHAPTER 12										
SERVICING										
12-10-29-301 (s)	CHECK HYDRAULIC SYSTEM (NO. 1, NO. 2 AND NO. 3 SYSTEMS)ACCUMULATOR CHARGE PRESSURES - SERVICE HYDRAULIC OVERSPILL CONTAINERS						PKG			
	PKG 2	MOS					09-SEP-2008			
	REF: AMM 12-10-29-301	HRS/MSC	300				8806.5			
		AFL					4265			
12-10-29-318 (s)	CHECK HYDRAULIC SYSTEM REPLENISHING (NO.1,2 AND 3), VERIFY RESERVOIR FOR FLUID LEVEL.						PKG			OPTIONAL
	PKG 2	MOS					09-SEP-2008			
	REF: AMM 12-10-29-318	HRS/MSC	300				8806.5			
		AFL					4265			
12-10-32-316 (s)	CHECK MAIN GEAR SHOCK STRUT EXTENSION						PKG			
	PKG 2	MOS					09-SEP-2008			
	REF: AMM 12-10-32-316	HRS/MSC	300				8806.5			
		AFL					4265			
12-10-32-317 (s)	CHECK NOSE GEAR SHOCK STRUT EXTENSION						PKG			
	PKG 2	MOS					09-SEP-2008			
	REF: AMM 12-10-32-317	HRS/MSC	300				8806.5			
		AFL					4265			
12-20-00-302 (s)	SERVICING LUBRICATE LANDING GEAR DOORS						PKG			
	PKG 2	MOS					09-SEP-2008			
	REF: AMM 12-20-00-302	HRS/MSC	300				8806.5			
		AFL					4265			
12-20-00-303 (s)	SERVICING LUBRICATE DUAL BRAKE CONTROL VALVE PUSH RODS						PKG			
	PKG 2	MOS					09-SEP-2008			
	REF: AMM 12-20-00-303	HRS/MSC	300				8806.5			
		AFL					4265			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
12-20-00-304 (s)	SERVICING LUBRICATE SERVICING DOORS - LUBRICATE BAGGAGE COMPARTMENT DOOR PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 12-20-00-304									
12-20-00-305 (s)	SERVICING LUBRICATE INBOARD FLAP VANE MECHANISM PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 12-20-00-305									
12-20-00-306 (s)	SERVICING LUBRICATE MAIN TRACKS PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 12-20-00-306									
12-20-00-307 (s)	SERVICING LUBRICATE PYLON TRACKS PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 12-20-00-307									
12-20-00-308 (s)	SERVICING LUBRICATE BUTE DOOR HINGE - LUBRICATE BUTE DOOR ROLLERS PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: AMM 12-20-00-308									
12-20-00-309 (s)	SERVICING LUBRICATE THROTTLE CONTROL INNER ELEMENT AND PRESSURE SEAL PKG 30	MOS HRS/MSC AFL	12				PKG 19-JUL-2010 8947.8 4353			
	REF: AMM 12-20-00-309									
12-20-00-311 (s)	SERVICING LUBRICATE WING-FUSELAGE PICK-UP LINK PKG 4	MOS HRS/MSC AFL	1200				PKG 06-JUN-2005 8180 3964			
	REF: AMM 12-20-00-311									
12-20-00-312 (s)	SERVICING LUBRICATE AIR DRIVEN GENERATOR (ADG) PKG 30	MOS HRS/MSC AFL	12				PKG 19-JUL-2010 8947.8 4353			
	REF: AMM 12-20-00-312									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
12-20-00-313 (s)	SERVICING LUBRICATE FLAP ACTUATOR PKG 30	MOS	12				PKG 19-JUL-2010 8947.8 4353			
	REF: AMM 12-20-00-313	HRS/MSC AFL								
ENGINE NO. 1 Model : CF-34 (CIMMS) Serial # 350-499 Part # 6063T01G04										
12-20-00-314 (s)	NO. 1 ENGINE - LUBRICATE VARIABLE GEOMETRY ACTUATOR (AIRCRAFT 3001-3066 AND 5001-5134) PKG 2	MOS					PKG 09-SEP-2008 8668.5			
	REF: EMM 05-21-00	HRS/MSC ENC	300							
ENGINE NO. 2 Model : CF-34 (CIMMS) Serial # 350-498 Part # 6063T01G04										
12-20-00-314	NO. 2 ENGINE - LUBRICATE VARIABLE GEOMETRY ACTUATOR (AIRCRAFT 3001-3066 AND 5001-5134) PKG 2	MOS					09-SEP-2008 8632.5	(8932.5) 9106.3		158.5
	REF: EMM 05-21-00	HRS/MSC ENC	300							
CHAPTER 20 STANDARD PRACTICES - AIRFRAME										
20-40-00-201 (s)	INSPECTION WIRE CABLES - FLIGHT CONTROLS (EXCEPT FOR STRAIGHT RUNS UNDER CABIN FLOOR AND IN VERTICAL STABILIZER) PKG 3	MOS					PKG 20-MAR-2009 8873.5 4304			
	REF: AMM 20-40-00-201	HRS/MSC AFL	600							
+ 20-40-00-202 (s)	INSPECTION WIRE CABLES - FLIGHT CONTROLS (STRAIGHT RUNS UNDER CABIN FLOOR AND IN VERTICAL STABILIZER) PKG 34	MOS	60				PKG 03-APR-2006 8305.8 4018			
	REF: AMM 20-40-00-202	HRS/MSC AFL								
20-40-00-203	VISUAL CHECK (USING A BORESCOPE) OF FLIGHT CONTROL CABLES LOCATED BELOW TOILET/GALLEY AREAS (WITHOUT REMOVAL) PKG 30	MOS	12				19-JUL-2010 8947.8 4353	19-JUL-2011		315 d
	REF: GENERIC NO REF	HRS/MSC AFL								
CHAPTER 21 AIR CONDITIONING										
21-20-00-201 (s)	VISUAL CHECK DISTRIBUTION - OF ACCESSIBLE AIR CONDITIONING PLUMBING AND DUCTING PKG 3	MOS					PKG 20-MAR-2009 8873.5 4304			
	REF: GENERIC NO REF	HRS/MSC AFL	600							

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 21-20-11-202 (s)	INSPECTION CHECK VALVES (A/C 5001 TO 5134) - (FOOTWARMER/DEMIST MANIFOLD CHECK VALVE ONLY) PKG 6	MOS HRS/MSC AFL	2400				PKG 28-OCT-2003 7003 3486			
	REF: AMM 21-20-11-202									
+ 21-20-11-203	VISUAL CHECK CONDITIONED AIR AND COLD AIR CHECK VALVES FOR INTERNAL CONDITION	MOS HRS/MSC AFL	9600				01-OCT-1992 0 0	9600	9645	652.2
	REF: GENERIC NO REF									
21-27-11-206 (s)	VISUAL CHECK EFIS COOLING SYSTEM PKG 30	MOS HRS/MSC AFL	12				PKG 19-JUL-2010 8947.8 4353			
	REF: GENERIC NO REF									
21-27-16-204 (s)	VISUAL CHECK LIRS COOLING SYSTEM - OF FANS AND CARTRIDGE FILTERS PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 21-27-16-204									
21-27-16-303 (s)	CLEAN LIRS COOLING SYSTEM - CARTRIDGE FILTER PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 21-27-16-303									
+ 21-30-00-207 (s)	OPERATIONAL TEST PRESSURIZATION CONTROL (A/C 5001 TO 5134) - OF EMERGENCY PRESSURIZATION SYSTEM PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: AMM 21-30-00-207									
+ 21-30-00-208 (s)	OPERATIONAL TEST EMERGENCY DEPRESSURIZATION CONTROL SYSTEM PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: AMM 21-30-00-208									
+ 21-30-00-209 (s)	OPERATIONAL CHECK PRESSURIZATION CONTROL - CABIN LOW PRESSURE WARNING SYSTEM PKG 6	MOS HRS/MSC AFL	2400				PKG 15-NOV-2003 7003 3486			
	REF: AMM 21-30-00-209									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 21-30-00-210 (s)	OPERATIONAL TEST OF THE PRESSURIZATION CONTROL- MANUAL PRESSURIZATION CONTROL SYSTEM , OF JET PUMP RIGHT BLEED AIR CHECK VALVE, AND OF THE JET PUMP LEFT BLEED AIR CHECK VALVE. PKG 6 REF: AMM 21-30-00-210	MOS HRS/MSC AFL	2400				13-NOV-2003 7003 3486			
+ 21-30-11-211 (s)	FUNCTIONAL TEST/ VISUAL CHECK OUTFLOW VALVES (USING PRESSURE TEST KIT) PKG 4 REF: AMM 21-30-11-211	MOS HRS/MSC AFL	1200				12-JUN-2005 8180 3964			
21-30-11-301 (s)	REMOVE AND INSTALL NEW FILTER ELEMENT - OUTFLOW VALVES PKG 3 REF: AMM 21-30-11-301	MOS HRS/MSC AFL	600				20-MAR-2009 8873.5 4304			
+ 21-51-31-212 (s)	FUNCTIONAL TEST AIR CONDITIONING OVERHEAT SWITCH - OF OVERHEAT WARNING PKG 10 REF: AMM 21-51-31-212	MOS HRS/MSC AFL	4800				22-FEB-2001 4859 2516			
+ 21-53-11-213 (s)	FUNCTIONAL TEST EMERGENCY RAM AIR SHUTOFF VALVE PKG 3 REF: AMM 21-53-11-213	MOS HRS/MSC AFL	600				20-MAR-2009 8873.5 4304			
21-70-11-302 (s)	CLEAN WATER SEPARATOR - COALESCER BAG PKG 3 REF: AMM 21-70-11	MOS HRS/MSC AFL	600				20-MAR-2009 8873.5 4304			
212011-001	VALVE:NO. 1 2 INCH CHECK VALVE 3202062-1-1 SN-UNKNOWN REF: AMM 212011	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
212011-002	VALVE:NO. 2 2 INCH CHECK VALVE 3202062-1-1 SN-UNKNOWN REF: AMM 212011	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
212014-001	VALVE:NO. 1 BALANCING - 4 INCH VALVE 600-95278-1 SN-UNKNOWN REF: AMM 212014	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
212014-002	VALVE:NO. 2 BALANCING - 4 INCH VALVE 600-95278-1 SN-UNKNOWN REF: AMM 212014	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
212016-001	VALVE:DIVERTER VALVE 228565-1 278A REF: AMM 212016	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
212025-001	CHECK VALVE:L/H BULKHEAD CONDITIONED CHECK VALVE 3202076-1-1 SN-UNKNOWN REF: AMM 21-20-11	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
212025-002	CHECK VALVE:R/H BULKHEAD CONDITIONED CHECK VALVE 123790-1-1 SN-UNKNOWN REF: AMM 21-20-11	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
212026-001	VALVE:NO. 1 FOOT WARMER PRESSURE REGULATING SHUTOFF VALVE 228935 SN-UNKNOWN REF: AMM 212026	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
212026-002	VALVE:NO. 2 FOOT WARMER PRESSURE REGULATING SHUTOFF VALVE 228545-5 515 REF: AMM 212026	MOS HRS/MSC AFL	O/C	TSN:45 TSN:1535 TSN:735			07-JUN-1993 120 68			
212031-001	EXCHANGER:HEAT EXCHANGER 172165-2 287 REF: AMM 212031	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
212036-001	FAN:MOTOR DRIVEN FAN 605385-6-1 41-412 REF: AMM 212036	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
213011-001	VALVE:PRESSURE REGULATING PRIMARY VALVE 103632-2 118-310 REF: AMM 213011	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
213011-002	VALVE:SECONDARY OUTFLOW VALVE 103664-1 90-308 REF:	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
213018-001	VALVE:REGULATING VALVE 131400-2 16-881 REF: AMM 21-30-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			05-APR-2006 8305.8 4018			
213019-001	REGULATOR:AIR PRESSURE REGULATOR 131402-2 0250 REF: AMM 213019	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
213031-001	VALVE:SHUTOFF VALVE 228845 330 REF: AMM 213031	MOS HRS/MSC AFL	O/C				16-AUG-2005 8215.3 3975			
213036-001	INDICATOR:CABIN PRESSURE INDICATOR 600-59117-5 2341 REF: AMM 213036	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
213041-001	CONTROLLER:CABIN PRESSURE CONTROLLER 2117804-5 108-310 REF: AMM 213041	MOS HRS/MSC AFL	O/C				26-MAY-2006 8344.8 4037			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
213042-001	SELECTOR:CABIN PRESSURE SELECTOR 2117598-3 40-299 REF: AMM 21-30-16	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
215022-001	CHECK VALVE:FOOT WARMER/DEMIST MANIFOLD CHECK VALVE 123690-2-1 SN-UNKNOWN REF: AMM 215022	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
215100-001	MOTOR:NO. 1 TORQUE MOTOR 124904-1-1 SN-UNKNOWN REF: AMM 215100	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
215100-002	MOTOR:NO. 2 TORQUE MOTOR 124904-1-1 SN-UNKNOWN REF: AMM 215100	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
215101-001	TURBINE:NO. 1 COOLING TURBINE 586110-9 58-1850C REF: AMM 215101	MOS HRS/MSC AFL	O/C				13-APR-2002 5707 2916			
215101-002	TURBINE:NO. 2 COOLING TURBINE 586110-3 SN-UNKNOWN REF: AMM 215101	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
215105-001	SWITCH:NO. 1 PRESSURE SWITCH 642000-1 535 REF: AMM 215105	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-FEB-2002 5557 2858			
215105-002	SWITCH:NO. 2 PRESSURE SWITCH 642000-1 SN-UNKNOWN REF: AMM 215105	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
215106-001	SWITCH:NO. 1 THERMAL SWITCH 641119-2 SN-UNKNOWN REF: AMM 215106	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
215106-002	SWITCH:NO. 2 THERMAL SWITCH 641119-2 SN-UNKNOWN REF: AMM 215106	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
215107-001	ECU:NO. 1 CONTROL UNIT AIR CONDITIONING ECU 2201600-5 71-675 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
215107-002	ECU:NO. 2 CONTROL UNIT AIR CONDITIONING ECU 2201600-5 71-677 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
215111	VALVE:LEFT FOOTWARMER/DEMIST PRESSURE REGULATING/SHUTOFF VALVE 228545-5 646 REF:	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
215126-001	VALVE:NO. 1 EJECTOR SHUTOFF VALVE 979142-1-1 SN-UNKNOWN REF: AMM 215126	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
215126-002	VALVE:NO. 2 EJECTOR SHUTOFF VALVE 979142-1-1 SN-UNKNOWN REF: AMM 215126	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
215311-001	VALVE:3 INCH SHUTOFF (EMERGENCY RAM AIR) VALVE 398724-1-1 480 REF: AMM 215311	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
216000-001	CONTROL:COCKPIT TEMPERATURE CONTROL 625514-2-1 111C723 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
216000-002	CONTROL:CABIN TEMPERATURE CONTROL 625514-2-1 071C695 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
216001-001	CONTROL:NO. 1 LOW LIMIT TEMPERATURE CONTROL 625520-2 0326-729 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
216001-002	CONTROL:NO. 2 LOW LIMIT TEMPERATURE CONTROL 625520-2 051C676 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
216003-001	INDICATOR:CABIN TEMPERATURE INDICATOR 600-50918-1 92040304 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
216011-001	VALVE:NO. 1 MODULATING/SHUTOFF VALVE 979558-8 743 REF: AMM 216011	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
216011-002	VALVE:NO. 2 MODULATING/SHUTOFF VALVE 979558-8 931 REF: AMM 216011	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-JUN-1995 1266 613			
216021-001	VALVE:NO. 1 PRESSURE REGULATING VALVE 3214066-1 1470 REF: AMM 216021	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
216021-002	VALVE:NO. 2 PRESSURE REGULATING VALVE 3214066-1 1473 REF: AMM 216021	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
216026-001	VALVE:NO. 1 TEMPERATURE LIMITER VALVE 129580-6 1847 REF: AMM 216026	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
216026-002	VALVE:NO. 2 TEMPERATURE LIMITER VALVE 129580-6 1848 REF: AMM 216026	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
216031-001	SENSOR:COCKPIT DUCT TEMPERATURE SENSOR 627962-2 022C6014 REF: AMM 216031	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
216031-002	SENSOR:CABIN DUCT TEMPERATURE SENSOR 627962-2 022C6007 REF: AMM 216031	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
216032-001	SENSOR:COCKPIT FAN SENSOR 625692-2-1 079C-196 REF: AMM 21-60-31	MOS HRS/MSC AFL	O/C	TSN:128			23-JAN-1995 1049 517			
216032-002	SENSOR:CABIN FAN SENSOR 625692-2-1 101C0148 REF: AMM 21-60-31	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
216041	SENSOR:BAGGAGE COMPARTMENT LEFT DUCT TEMPERATURE SENSOR 627962-2 022C6012 REF:	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
216046	SENSOR:BAGGAGE COMPARTMENT RIGHT DUCT TEMPERATURE SENSOR 627962-2 022C6010 REF:	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
219001	LEAK CHECK AIR CONDITION UNIT SYSTEMS REF:	MOS HRS/MSC AFL	300				09-SEP-2008 8806.5 4265	9106.5		158.7
219006	EJECTOR:AIR CONDITION UNIT TUBE EJECTOR 2214802-1 NSN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			08-DEC-1994 1010 502			
219010	OPERATIONAL CHECK FOOT WARMER FAN REF:	MOS HRS/MSC AFL	300				09-SEP-2008 8806.5 4265	9106.5		158.7
219071	EXTRACTOR:LEFT AIR CONDITION UNIT WATER EXTRACTOR 2340666-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				01-OCT-1992 0 0			
219076	EXTRACTOR:RIGHT AIR CONDITION UNIT WATER EXTRACTOR 2340666-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				01-OCT-1992 0 0			
219091	SEPARATOR:LEFT AIR CONDITION UNIT WATER SEPARATOR 85020-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
219096	SEPARATOR:RIGHT AIR CONDITION UNIT WATER SEPARATOR 85020-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
T21T01	FUNCTIONAL TEST OUTFLOW VALVE (USING AIRCRAFT SYSTEM)	MOS								
	REF:	HRS/MSC AFL	O/C							
T21T02	OPERATIONAL TEST AUTOMATIC PRESSURE CONTROL SYSTEM, TEMPERATURE CONTROL SYSTEM	MOS								
	REF:	HRS/MSC AFL	O/C							
CHAPTER 22		AUTO FLIGHT								
220000-001	TRANSMITTER:POSITION TRANSMITTER	MOS						01-OCT-1992		
	600-59191-3	HRS/MSC	O/C	TSN:0				0		
	SN-UNKNOWN	AFL						0		
	REF: GENERIC NO REF									
221000-001	DISPLAY:ADVISORY DISPLAY	MOS						01-OCT-1992		
	7003652-631	HRS/MSC	O/C	TSN:0				0		
	92062002	AFL		TSN:0				0		
	REF: AMM 221000									
221001-001	COMPUTER:NO. 1 FLIGHT GUIDANCE COMPUTER	MOS						28-AUG-1999		
	7003974-726	HRS/MSC	O/C					3812		
	89112068	AFL						1968		
	REF: GENERIC NO REF									
221001-002	COMPUTER:NO. 2 FLIGHT GUIDANCE COMPUTER	MOS						31-AUG-1994		
	7003974-726	HRS/MSC	O/C					808		
	92053288	AFL						401		
	REF: GENERIC NO REF									
221002-001	SERVO:DUPLEX AILERON SERVO	MOS						01-OCT-1992		
	4015373-813	HRS/MSC	O/C	TSN:0				0		
	92042741	AFL						0		
	REF: GENERIC NO REF									
221002-005	SERVO:ELEVATOR AUTOPILOT DUPLEX SERVO	MOS						01-OCT-1992		
	4015373-816	HRS/MSC	O/C	TSN:0				0		
	92052763	AFL						0		
	REF: GENERIC NO REF									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
221003-001	CONTROLLER:MANUAL CONTROLLER 7007990-901 90010358 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			11/27/2000	27-NOV-1999 3984 2069			
221006-001	CONTROLLER:NO.1 GUIDANCE CONTROLLER 7003975-706 89080998 REF: AMM 22-10-00	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			15-JUN-2006 8355 4043			
222000-001	ACTUATOR:NO. 1 YAW DAMPER LINEAR ACTUATOR 601A92602-1 92040584 REF: AMM 222000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
222000-002	ACTUATOR:NO. 2 YAW DAMPER LINEAR ACTUATOR 601A92602-1 92030581 REF: AMM 222000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
22R001	SWITCH:PILOT (TCS) SWITCH 611-4301 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
22R006	SWITCH:COPILOT (TCS) SWITCH 611-4301 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
T22T01	OPERATIONAL TEST AUTOPILOT SYSTEM REF:	MOS HRS/MSC AFL	O/C							
CHAPTER 23 COMMUNICATIONS										
+ 23-13-00-201 (s)	PRESSURE CHECK HF COMMUNICATION SYSTEM - ANTENNA COUPLER UNIT PKG 30 REF: AMM 23-13-00-201	MOS HRS/MSC AFL	12				PKG 19-JUL-2010 8947.8 4353			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
23-60-00-202 (s)	FUNCTIONAL TEST/ VISUAL CHECK PKG 4 REF: AMM 23-60-00-202	STATIC DISCHARGERS MOS HRS/MSC AFL	1200				PKG 08-JUN-2005 8180 3964			
+ 23-71-00-203 (s)	OPERATIONAL TEST PKG 3 REF: AMM 23-71-00-203	FLIGHT COMPARTMENT VOICE RECORDER SYSTEM MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
231100-001	ANTENNA:UPPER VHF ANTENNA S65-8280-10 1095 REF: AMM 231100	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
231100-002	ANTENNA:LOWER VHF ANTENNA S65-8280-10 1577 REF: AMM 231100	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
231101-001	TRANSCEIVER:NO. 1 VHF TRANSCEIVER 822-1113-001 37455 REF: AMM 231101	MOS HRS/MSC AFL	O/C			02/26/2000	26-FEB-1999 3575 1829			
231101-002	TRANSCEIVER:NO. 2 VHF TRANSCEIVER 822-1113-001 37458 REF: AMM 231101	MOS HRS/MSC AFL	O/C			02/26/2000	26-FEB-1999 3575 1829			
231102-001	CONTROL:NO. 1 VHF COMMUNICATIONS CONTROL 822-1120-005 18588 REF: AMM 231102	MOS HRS/MSC AFL	O/C			02/26/2000	26-FEB-1999 3575 1829			
231102-002	CONTROL:NO. 2 VHF COMMUNICATIONS CONTROL 822-1120-005 18589 REF: AMM 231102	MOS HRS/MSC AFL	O/C			02/26/2000	26-FEB-1999 3575 1829			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
231300-001	CONTROL:NO. 1 HF CONTROL 622-8111-005 1211 REF: AMM 231300	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
231300-002	CONTROL:NO. 2 HF CONTROL 622-8111-005 569 REF: AMM 231300	MOS HRS/MSC AFL	O/C				15-JUN-2006 8355 4043			
231301-001	RECEIVER/TRANSMITTER:NO. 1 HF (HF9030) RECEIVER/TRANSMITTER 622-8112-002 815 REF: AMM 231301	MOS HRS/MSC AFL	O/C	TSN:7608			11-SEP-2004 7608 3724			
231301-002	RECEIVER/TRANSMITTER:NO. 2 HF (HF9030) RECEIVER/TRANSMITTER 622-8112-002 425 REF: AMM 231301	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			24-APR-2004 7411 3682			
232100-001	DECODER:SELCAL DECODER NA137-714B 706CSJ0013 REF: AMM 232100	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
233000-001	COUPLER:NO. 1 HF ANTENNA COUPLER 622-8114-002 649 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-SEP-2004 7608 3724			
233000-002	COUPLER:NO. 2 HF ANTENNA COUPLER 685-0350-002 32 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-AUG-1996 2015 1018			
234001	ELECTRONIC UNIT:AUDIO ELECTRONIC UNIT 600-59144-17 409 REF:	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
237100-001	SWITCH:CVR INERTIAL SWITCH 3L0-453-2 SN-UNKNOWN REF: AMM 237100	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
237101-001	RECORDER:COCKPIT VOICE RECORDER 93A100-83 60627 REF: AMM 23-71-00	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			02-SEP-2003 6860 3429			
237104-001A	BEACON:DISCARD CVR UNDERWATER LOCATING BEACON ULB BATTERY (23-71-11-204) REF: GENERIC NO REF	MOS HRS/MSC AFL	DUE				10-SEP-2004 7608.8 3724	30-NOV-2010 M		84 d
237105-001	CONTROLLER:COCKPIT VOICE RECORDER (A151B) CONTROLLER 93A151-20 74305 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
237110-001	MICROPHONE:COCKPIT VOICE RECORDER MICROPHONE 93A055-40 50812 REF: AMM 23-71-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		08/12/2003	12-AUG-2002			
239001	ARTU:MAGNASTAR ARTU 724855-801 MSA0118 REF:	MOS HRS/MSC AFL	N/R	TSR:0 TSR:0 TSR:0			05-OCT-2007			
239005	CONTROL:RAD-TEL CKPT NO1 CONTROL 724866-807WH MX21323 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0		08/28/1998	28-AUG-1996 2015 1018			
239009	CONTROL:RAD-TEL CABIN NO1 CONTROL 724866-805WH MX23387 REF:	MOS HRS/MSC AFL	N/R				29-JAN-2002 5505 2821			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
239021	ANTENNA:RAD-TEL NO.1 ANTENNA 902131-2 0313 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0		08/28/1998	28-AUG-1996 2015 1018			
239027	PHONE:COCKPIT REEL ASSY PHONE 620346-8 N/A REF:	MOS HRS/MSC AFL	N/R				03-NOV-2003 7003			
239106	CONTROL:AUDIO PILOT'S CONTROL B1045-FBCJ-GHK7 9302047 REF:	MOS HRS/MSC AFL	N/R				30-MAY-2000 4332 2241			
239108	CONTROL:AUDIO COPILOT'S CONTROL B1045-FBCJ-GHK7 9302048 REF:	MOS HRS/MSC AFL	N/R				30-MAY-2000 4332 2241			
239111	ADAPTER:COCKPIT AUDIO ADAPTER 444-1281-103 006 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
239113	SPEAKER:COCKPIT AUDIO NO1 SPEAKER 4C5Z8 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
239115	SPEAKER:COCKPIT AUDIO NO2 SPEAKER 4C5Z8 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
239131	MICROPHONE:CKPT AUDIO NO1 MICROPHONE 488T 72984 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			01-APR-1993 19 12			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
239518	RACK:RADIO TELECOMMUNICATION UNIT RACK 724868-802 MST9064 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			09-FEB-2005 7915			
239520	DUPLEXER:AIRFONE DUPLEXER 620317-2 02408 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-FEB-2004			
239550	HANDSET:BACK-UP AIRCELL HANDSET 400-11218-001 1121810018 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0						
239551	ANTENNA:AIRCELL ANTENNA 015-11203-001 581 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0						
239600	TRANSCEIVER:IRIDIUM TRANSCEIVER R400-11050-001 1105010050 REF:	MOS HRS/MSC AFL	O/C	TSN:6 TSN:358 TSN:138			16-MAR-2005 7984 3870			
239610	SWITCH PANEL:NO. 1 L/H HEADPHONE SWITCH PANEL HSP-037C-02-1 080400008 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0						
239611	SWITCH PANEL:NO. 2 L/H HEADPHONE SWITCH PANEL HSP-037C-02-1 080400009 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0						
239612	SWITCH PANEL:NO. 3 L/H HEADPHONE SWITCH PANEL HSP-037C-02-1 080400010 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0						

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
239613	SWITCH PANEL:NO. 4 L/H HEADPHONE SWITCH PANEL HSP-037C-02-1 080400011 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0						
239614	SWITCH PANEL:NO. 1 R/H HEADPHONE SWITCH PANEL HSP-037C-01-1 080400154 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0						
239615	SWITCH PANEL:NO. 2 R/H HEADPHONE SWITCH PANEL HSP-037C-01-1 080400155 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0						
239616	SWITCH PANEL:NO. 3 R/H HEADPHONE (FWD DIVAN) SWITCH PANEL HSP-037C-01-1 080400156 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0						
239617	SWITCH PANEL:NO. 4 R/H HEADPHONE (AFT DIVAN) SWITCH PANEL HSP-037C-01-1 080400325 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0						
23R001	HEADSET:PILOT HEADSET 1265076-18 DAV. CLRK MODEL-H10-40 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
23R006	HEADSET:COPILOT HEADSET 1265076-18 DAV. CLRK SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
23R007	HEADSET:FLIGHT ENGINEER HEADSET 1265076-18-DAVCLRK 810-40 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
23R011	MICROPHONE:PILOT MICROPHONE SHURE BODS. 488T 72977 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
23R012	--:MIC.,CO-PILOT SHURE BROS. 488T 72984 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			01-APR-1993 19 12			
23R016	MICROPHONE:FLT. ENGR. MICROPHONE SHURE BODS. 488T 72923 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
23R021	CONTROLLER:CABIN/LAV CALL CONTROLLER MSM288B 301111B REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
23R023	AMP:OBSVR AUDIO HEADPHONE AMP M1052A 9301134 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
23R026	AMPLIFIER:CABIN/LAV CALL AMPLIFIER M7850-B 9112029 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
23R031	SPEAKER:CABIN/LAV CALL SPEAKER 4C5Z8 NSN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
23R169	OPERATIONAL CHECK HF SYSTEMS REF:	MOS HRS/MSC AFL	3				19-JUL-2010 8947.8 4353	19-OCT-2010		42 d

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
T23T01	BONDING RESISTANCE VALUES	MOS HRS/MSC AFL	O/C							
T23T02	OPERATIONAL TEST HF COMMUNICATION SYSTEM	MOS HRS/MSC AFL	O/C							
CHAPTER 24 ELECTRICAL POWER										
24-00-00-301 (s)	OPERATIONAL TEST BATTERY SYSTEM, CYCLING OF THE THERMAL CIRCUIT BREAKERS	MOS HRS/MSC AFL	12				PKG 19-JUL-2010 8947.8 4353			OPTIONAL
+ 24-20-00-201 (s)	FUNCTIONAL TEST AC GENERATION - COMPLETE GENERATOR SYSTEM	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
24-21-00-203 (s)	PRESSURE CHECK INTEGRATED DRIVE GENERATOR SYSTEM - DIFFERENTIAL	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
+ 24-21-00-301 (s)	REPLENISH INTEGRATED DRIVE GENERATOR OIL SYSTEM	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
+ 24-21-16-204 (s)	INSPECT/INSTALL IDG OIL-IN FILTER ASSEMBLY	MOS HRS/MSC AFL	2400				PKG 29-OCT-2003 7003 3486			
+ 24-21-21-205 (s)	REMOVE/INSPECT/REINSTALL IDG OIL-OUT FILTER ASSEMBLY	MOS HRS/MSC AFL	2400				PKG 30-OCT-2003 7003 3486			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 24-23-00-208	CHECK AIR DRIVEN GENERATOR SYSTEM - OIL LEVEL - OIL LEAKAGE REF: AMM 24-23-00-208	MOS HRS/MSC AFL	6				19-JUL-2010 8947.8 4353	19-JAN-2011		134 d
+ 24-23-00-209	OPERATIONAL TEST AIR DRIVEN GENERATOR SYSTEM - ADG PKG 32 REF: AMM 24-23-00-209	MOS HRS/MSC AFL	24				28-MAY-2009 8928.6 4336	28-MAY-2011		263 d
+ 24-23-46-210 (s)	OPERATIONAL TEST ADG AUTO-DEPLOY CONTROL UNIT PKG 30 REF: AMM 24-23-46-210	MOS HRS/MSC AFL	12				19-JUL-2010 8947.8 4353			
+ 24-31-00-211 (s)	FUNCTIONAL TEST DC STATIC CONVERSION SYSTEM PKG 3 REF: AMM 24-31-00-211	MOS HRS/MSC AFL	600				20-MAR-2009 8873.5 4304			
+ 24-33-00-212	TEST MAIN BATTERY - CAPACITY TEST & ELECTROLYTE CHECK BATTERY SYSTEM (REF. CMM/PSP 608/608A 24-30-99 OR 24-32-05, AS APPLICABLE; CHECK, PERIODIC CHECK) REF: GENERIC NO REF	MOS HRS/MSC AFL	6				19-JUL-2010 8947.8 4353	19-JAN-2011		134 d
+ 24-33-00-213 (s)	FUNCTIONAL TEST BATTERY SYSTEM - MAIN BATTERY CHARGER THERMAL SENSOR PKG 30 REF: AMM 24-33-00-213	MOS HRS/MSC AFL	12				19-JUL-2010 8947.8 4353			
+ 24-33-00-302 (s)	VISUAL CHECK OF BATTERY SYSTEM, PAYING PARTICULAR ATTENTION TO CELLS,CASE AND VENT SYSTEM FOR DEPOSITS, LEAKAGE AND CORROSION PKG 1 REF: GENERIC NO REF	MOS HRS/MSC AFL	100				19-JUL-2010 8947.8 4353			
242100-001	GENERATOR:NO. 1 IDG GENERATOR 720845D 1058 REF: AMM 242100	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
242100-002	GENERATOR:NO. 2 IDG GENERATOR 720845D 1049 REF: AMM 242100	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
242101-001	CONTROL UNIT:NO. 1 GENERATOR CONTROL UNIT 720846C 1025 REF: AMM 242141P201	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
242101-002	CONTROL UNIT:NO. 2 GENERATOR CONTROL UNIT 720846C 1026 REF: AMM 242141P201	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
242101-003	CONTROL UNIT:NO. 3 GENERATOR CONTROL UNIT 720846C 1058 REF: AMM 242221P201	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
242103-001	EXCHANGER:NO. 1 HEAT IDG EXCHANGER 24E26-1 04910520 REF: AMM 242103	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
242103-002	EXCHANGER:NO. 2 HEAT IDG EXCHANGER 24E26-1 04910519 REF: AMM 242103	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
242200-001	ADAPTER:APU GENERATOR ADAPTER 722773C 0301 REF: AMM 242200	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
242301-001	TURBINE ASSY:ADG AIR DRIVEN TURBINE ASSY 728315C 0399 REF: AMM 24-23-00	MOS HRS/MSC AFL	O/C	TSN:24 TSN:15			08-APR-1993 24 15			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
242302-001	UPLOCK ASSEMBLY:AIR DRIVEN GENERATOR UPLOCK ASSEMBLY 721863C 0316 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:808 TSN:401			02-SEP-1994 808 401			
242303-001	CONTROLLER:AIR DRIVEN GEN AUTO DEPLOY CONTROLLER 600-59143-3 343 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
242304-001	HAND PUMP:AIR DRIVEN GENERATOR HAND PUMP 731879C 0425 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
242305-001	JACK:AIR DRIVEN GENERATOR EJECT JACK 728431B 0411 REF: AMM 242305	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
242306-001	ACTUATOR:ELECTRICAL UPLOCK (SQUIB) ACTUATOR 055046B 290 REF: AMM 242306	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-JUL-2010 8947.8 4353			
242306-001A	ACTUATOR:SERVICE LIFE ELECTRICAL UPLOCK (SQUIB) ACTUATOR (42 MOS FROM INSTALLATION) REF: GENERIC NO REF	MOS HRS/MSC AFL	42				19-JUL-2010	19-JAN-2014	SERVICE LIFE LIMIT	1230 d
242306-001B	ACTUATOR:SHELF LIFE ELECTRICAL UPLOCK (SQUIB) ACTUATOR (60 MOS FROM MANUFACTURE) REF: GENERIC NO REF	MOS HRS/MSC AFL	60				19-JUL-2010	19-JUL-2015	LIFE LIMIT	1776 d
242310-001	CONTROL:AIR DRIVEN GENERATOR CONTROL 756654A 0106 REF: AMM 242310	MOS HRS/MSC AFL	O/C				02-SEP-1994 808 401			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
243300-002	BATTERY:MAIN BATTERY 40178-24 / 600-59151-11 115560 REF: AMM 243300	MOS HRS/MSC AFL	O/C				14-MAR-2005 7984 3870			
243303-002	CHARGER:MAIN BATTERY CHARGER 600-59140-11 506 REF: AMM 24-33-00	MOS HRS/MSC AFL	O/C				05-JAN-2000 4034 2096			
243990	CONTACTOR:BATTERY CONTACTOR HA9A048 079 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-FEB-2002 5552 2854			
244100-001	RELAY:MONITOR - EXTERNAL POWER RELAY 600-59142-3 11341 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-FEB-1997 2390 1186			
245101-001	SENSOR:FREQUENCY/VOLTAGE SENSOR VS403.3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
245303-001	UNIT:NO. 1 TRANSFORMER RECTIFIER (TRU) AC UNIT MS17976-2 4772 REF: AMM 245303	MOS HRS/MSC AFL	O/C	TSN:786			26-SEP-1994 858 423			
245303-002	UNIT:NO. 2 TRANSFORMER RECTIFIER (TRU) AC UNIT MS17976-2/28VS100Y-10A 4114 REF: AMM 245303	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			15-FEB-2005 7924 3845			
245303-003	UNIT:NO. 3 TRANSFORMER RECTIFIER (TRU) AC UNIT MS17976-2 4775 REF: AMM 245303	MOS HRS/MSC AFL	O/C	TSN:827			06-OCT-1994 870 429			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
245303-004	UNIT:NO. 4 TRANSFORMER RECTIFIER (TRU) AC UNIT MS17976-2 4777 REF: AMM 245303	MOS HRS/MSC AFL	O/C				19-APR-1995 1180 576			
249456	INDICATOR:DC POWER INDICATOR 600-50915-1 81E0104 REF:	MOS HRS/MSC AFL	N/R	TSO:0 TSO:0 TSO:0			08-APR-1993 24 15			
24R001	RELAY:AC ESS FAIL U/VOLT RELAY V210D090BC SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
24R011	--:FAN ASSY,#1 TRU 035338 AKC880 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			26-SEP-1994 858 423			
24R016	--:FAN ASSY,#2 TRU 2651601 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			17-FEB-1998 2986 1500			
24R021	--:FAN ASSY,ESS #1 TRU 035338 AKD612 REF:	MOS HRS/MSC AFL	N/R				06-OCT-1994 870 429			
24R026	--:FAN ASSY,ESS #2 TRU 2651601 MAB322 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			19-APR-1995 1180 576			
24R051	INVERTER:T.V. 60 HZ INVERTER 4A1000-1HCP W8928383 REF:	MOS HRS/MSC AFL	N/R				12-DEC-2000 4764 2460			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
24R052	--:PRESS. SWT.,T.V. INVERTER A45C-60 1284 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
T24T01	ISOLATE ELECTRICAL POWER/OBSERVE SAFETY PRECAUTIONS - REMOVE/INSTALL EXTERNAL AC AND DC POWER REF:	MOS HRS/MSC AFL	O/C							
T24T02	DEPLOYMENT /STOWAGE ADG (MANUAL) REF:	MOS HRS/MSC AFL	O/C							
T24T03	DRAINAGE AND REPLENISHMENT AND FILLING REF:	MOS HRS/MSC AFL	O/C							
T24T04	FUNCTIONAL TEST GENERATOR SYSTEM REF:	MOS HRS/MSC AFL	O/C							
T24T05	SERVICING INTERGRATED DRIVE GENERATOR - GENERAL, REPLENISHING, DRAINING, FILLING, PRIMING OIL SYSTEM REF:	MOS HRS/MSC AFL	O/C							
APU Model : GTCP36-100(E) (3A/3R,600/011) Serial # P-413 Part # 3800050-5-1										
24-22-00-206	APU - VISUAL CHECK AUXILIARY GENERATOR SYSTEM - OF V-BAND MOUNTING CLAMP REF:	MOS HRS/MSC APUS	2400				29-OCT-2003 4261	6661		645
24-22-00-214 (s)	APU - INSPECT AUXILIARY GENERATOR SYSTEM - APU GENERATOR ADAPTOR DRY CAVITY - DRAIN OIL (P/N 722882B & SUBS) PKG 1 REF:	MOS HRS/MSC APUS	400				04-JUN-2008 5745 7579			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
24-22-16-207	APU - INSPECT APU GENERATOR ADAPTOR FILTER ELEMENT - REMOVE, INSPECT AND INSTALL NEW ELEMENT	MOS HRS/MSC 2400 APUS					28-OCT-2003 4264	6664		648
REF:										
CHAPTER 25 EQUIPMENT/FURNISHINGS										
25-11-00-201 (s)	VISUAL CHECK CREW SEATS/SAFETY HARNESS AND INERTIA REEL.	MOS HRS/MSC 600 AFL					PKG 20-MAR-2009 8873.5 4304			
REF: GENERIC NO REF										
251100-001	SEAT:PILOT SEAT 600-40022-7 280-91	MOS HRS/MSC O/C AFL		TSN:0 TSN:0			01-OCT-1992 0 0			
REF: AMM 251100										
251100-002	SEAT:COPILOT SEAT 600-40022-8 278-91	MOS HRS/MSC O/C AFL		TSN:0			01-OCT-1992 0 0			
REF: AMM 251100										
251300-001	HARNESS:NO. 1 REEL AND CONTROL HARNESS 1S20B25A4X21 SN-UNKNOWN	MOS HRS/MSC O/C AFL		TSN:0			01-OCT-1992 0 0			
REF: GENERIC NO REF										
251300-002	HARNESS:NO. 2 REEL AND CONTROL HARNESS 1S20B25A4X21 SN-UNKNOWN	MOS HRS/MSC O/C AFL		TSN:0			01-OCT-1992 0 0			
REF: GENERIC NO REF										
251326-001	LAP BELT:PILOT LAP BELT 1101020-29 SN-UNKNOWN	MOS HRS/MSC O/C AFL		TSN:0			01-OCT-1992 0 0			
REF: AMM 251326										
251326-002	LAP BELT:COPILOT LAP BELT 1101020-31 SN-UNKNOWN	MOS HRS/MSC O/C AFL		TSN:0			01-OCT-1992 0 0			
REF: AMM 251326										

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
259071	LIFE RAFT:INSPECT NO. 1 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER	MOS	12				19-JUL-2010 8947.8 4353	19-JUL-2011		315 d
	REF:	HRS/MSC AFL								
259076	LIFE RAFT:INSPECT NO. 2 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER	MOS	12				19-JUL-2010 8947.8 4353	19-JUL-2011		315 d
	REF:	HRS/MSC AFL								
259091	LIFE RAFT:REPLACE NO. 1 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER BATTERY	MOS					19-JUL-2010 8947.8 4353	01-MAY-2012 M		602 d
	REF:	HRS/MSC DUE AFL								
259096	LIFE RAFT:REPLACE NO. 2 LIFE RAFT EMERGENCY LOCATOR TRANSMITTER BATTERY	MOS					19-JUL-2010 8947.8 4353	01-MAY-2012 M		602 d
	REF:	HRS/MSC DUE AFL								
259101	TOILET:#1 ELECTRIC TOILET 4620-2	MOS					08-APR-1993 24			
	881	HRS/MSC N/R		TSN:0			15			
	REF:	AFL		TSN:0						
259104	CORROSION CHECK NO. 1 TOILET	MOS					09-SEP-2008 8806.5 4265	9106.5		158.7
	REF:	HRS/MSC 300 AFL								
259105	CHECK CONDITION/SECURITY OF NO. 1 TOILET MOUNT	MOS					09-SEP-2008 8806.5 4265	9106.5		158.7
	REF:	HRS/MSC 300 AFL								
259108	CHECK CONDITION/SECURITY OF VANITY MOUNTING	MOS					09-SEP-2008 8806.5 4265	9106.5		158.7
	REF:	HRS/MSC 300 AFL								

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
259116	CHECK PASSENGER CHAIR / DIVAN / BELT / TRACKS REF:	MOS HRS/MSC AFL	300				09-SEP-2008 8806.5 4265	9106.5		158.7
259201	LOCATOR TRANSMITTER:EMERGENCY LOCATOR TRANSMITTER 453-5000-999 07694 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			10-SEP-2004 7608.8 3724			
259203	406 MHZ EMERGENCY LOCATOR TRANSMITTER REGISTRATION REF:	MOS HRS/MSC AFL	24				04-JUN-2008 8763.5 4242	04-JUN-2010		CUSTOMER CODE OVD
259204	LOCATOR TRANSMITTER:TEST/INSPECT EMERGENCY LOCATOR TRANSMITTER ELT & NAV INTERFACE REF:	MOS HRS/MSC AFL	12				19-JUL-2010 8947.8 4353	19-JUL-2011		315 d
259206	ANTENNA:ELT ANTENNA 110-337 4024369 REF:	MOS HRS/MSC AFL	N/R				10-SEP-2004 7608.8 3724			
259207	INTERFACE UNIT:ELT NAV INTERFACE UNIT 453-6500 03248 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-SEP-2004 7608.8 3724			
259225	LOCATOR TRANSMITTER:REPLACE EMERGENCY LOCATOR TRANSMITTER BATTERY REF:	MOS HRS/MSC AFL	DUE				19-JUL-2010 8947.8 4353	01-FEB-2015 M		1608 d
259230	HANDSET:PHONE HANDSET 725729-815WH MX49910 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-SEP-2004 7608.8 3724			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
259232	AMPLIFER:HEADPHONE DISTRIBUTION AMPLIFER 30300153 070400096 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-SEP-2004 7608.8 3724			
259301	LIFE JACKET:NO. 1 LIFE JACKET D21343-105 561268 REF:	MOS HRS/MSC AFL	O/C	TSN:11			08-APR-1993 24 15			
259303	--:JACKET,#2 LIFE D21343-105 561259 REF:	MOS HRS/MSC AFL	O/C	TSN:11			08-APR-1993 24 15			
259305	--:JACKET,#3 LIFE D21343-105 561261 REF:	MOS HRS/MSC AFL	O/C	TSN:11			08-APR-1993 24 15			
259307	--:JACKET,#4 LIFE D21343-105 561267 REF:	MOS HRS/MSC AFL	O/C	TSN:11			08-APR-1993 24 15			
259309	--:JACKET,#5 LIFE D21343-105 561260 REF:	MOS HRS/MSC AFL	O/C	TSN:11			08-APR-1993 24 15			
259311	--:JACKET,#6 LIFE D21343-105 561257 REF:	MOS HRS/MSC AFL	O/C	TSN:11			08-APR-1993 24 15			
259313	--:JACKET,#7 LIFE D21343-105 561266 REF:	MOS HRS/MSC AFL	O/C	TSN:11			08-APR-1993 24 15			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
259315	--:JACKET,#8 LIFE D21343-105 561264 REF:	MOS HRS/MSC AFL	O/C	TSN:11			08-APR-1993 24 15			
259317	--:JACKET,#9 LIFE D21343-105 561265 REF:	MOS HRS/MSC AFL	O/C	TSN:11			08-APR-1993 24 15			
259319	--:JACKET,#10 LIFE D21343-105 561262 REF:	MOS HRS/MSC AFL	O/C	TSN:11			08-APR-1993 24 15			
259321	--:JACKET,#11 LIFE D21343-105 561263 REF:	MOS HRS/MSC AFL	O/C	TSN:11			08-APR-1993 24 15			
259323	--:JACKET,#12 LIFE D21343-105 561258 REF:	MOS HRS/MSC AFL	O/C	TSN:11			08-APR-1993 24 15			
259333	--:JACKET,PILOT'S LIFE D21344-105 561269 REF:	MOS HRS/MSC AFL	O/C	TSN:11			08-APR-1993 24 15			
259335	--:JACKET,COPILOT'S LIFE D21344-105 561271 REF:	MOS HRS/MSC AFL	O/C	TSN:11			08-APR-1993 24 15			
259337	--:JACKET,#1 OBSERVER'S LIFE D21344-105 L759569 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		08/18/1998	18-AUG-1997 2664 1346			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
259401	LIFE RAFT:NO. 1 LIFE RAFT R0297A119RB TW12005 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-MAR-2001 4859 2516			
259406	LIFE RAFT:NO. 2 LIFE RAFT R0297A119RB TW12008 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-MAR-2001 4859 2516			
259411	LIFE RAFT:CHECK NO. 1 LIFE RAFT REF:	MOS HRS/MSC AFL	12				19-JUL-2010 8947.8 4353	19-JUL-2011		315 d
259416	LIFE RAFT:CHECK NO. 2 LIFE RAFT REF:	MOS HRS/MSC AFL	12				19-JUL-2010 8947.8 4353	19-JUL-2011		315 d
259506	CHECK SECURITY #1 FIRST AID KIT MOUNTTING REF:	MOS HRS/MSC AFL	300				09-SEP-2008 8806.5 4265	9106.5		158.7
259508	SURVIVAL KIT:NO. 1 SURVIVAL KIT 105120-100 7-018 REF:	MOS HRS/MSC AFL	O/C				26-APR-1993 49 24			
259510	SURVIVAL KIT:INSPECT NO. 1 SURVIVAL KIT REF:	MOS HRS/MSC AFL	DUE				06-MAR-2006 8296.17 4013	30-JUN-2011 M		296 d
259625	INTERFACE:AIRSHOW DIGITAL INTERFACE 920050 1658 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			11-FEB-2002 5535 2843			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
259721	CHECK CONDITION / SECURITY OF GALLEY MOUNTINGS	MOS					09-SEP-2008			
	REF:	HRS/MSC	300				8806.5	9106.5		158.7
		AFL					4265			
259733	CHECK CONDITION/SECURITY OF ENTERTAINMENT EQUIPMENT MOUNT	MOS					09-SEP-2008			
	REF:	HRS/MSC	300				8806.5	9106.5		158.7
		AFL					4265			
259736	CHECK CONDITION / SECURITY OF BULKHEAD MOUNTINGS	MOS					09-SEP-2008			
	REF:	HRS/MSC	300				8806.5	9106.5		158.7
		AFL					4265			
259741	CHECK CONDITION / SECURITY OF CABIN TABLE MOUNTING	MOS					09-SEP-2008			
	REF:	HRS/MSC	300				8806.5	9106.5		158.7
		AFL					4265			
259746	CHECK CONDITION / SECURITY OF EMGENCY EXIT LIFE-LINE MOUNTING	MOS					09-SEP-2008			
	REF:	HRS/MSC	300				8806.5	9106.5		158.7
		AFL					4265			
259901	INSPECT CREW LIFE VESTS	MOS	12				19-JUL-2010	19-JUL-2011		315 d
	REF:	HRS/MSC					8947.8			
		AFL					4353			
259906	INSPECT PASSENGER LIFE VESTS	MOS	12				19-JUL-2010	19-JUL-2011		315 d
	REF:	HRS/MSC					8947.8			
		AFL					4353			
259B01	--:CHAIR,#1 L/H CABIN	MOS					01-APR-1993			
	2525014-67C	HRS/MSC	N/R				19			
	921228-4	AFL					12			
	REF:									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
259B02	--:CHAIR,#1 R/H CABIN 2526014-67D 921228-6 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			01-APR-1993 19 12			
259B03	--:CHAIR,#2 L/H CABIN 2524014-67B 921228-3 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			01-APR-1993 19 12			
259B04	--:CHAIR,#2 R/H CABIN 2524014-67A 921228-1 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			01-APR-1993 19 12			
259B05	--:CHAIR,#3 L/H CABIN 2524014-67C 921228-5 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			01-APR-1993 19 12			
259B07	--:CHAIR,#4 L/H CABIN 2524014-67B 921228-2 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			01-APR-1993 19 12			
25R001	SMOKE GOGGLES:CKPT (3 EA) SMOKE GOGGLES MXP210-00 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			08-APR-1993 24 15			
25R006	SMOKE HOODS:CABIN (12 EA) SMOKE HOODS PROVITA SN-UNKNOWN REF:	MOS HRS/MSC AFL	DUE				24-APR-2008 8728 4226			
25R011	--:SMOKE MASK,FULL FACE 900-700-040-34 208 REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
25R016	AXE:CRASH AXE 56D6221 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R018	BOX:STORAGE BOX 444-2612-103 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R051	OVEN:HI TEMPERATURE OVEN 1539-P (T.I.) 93-2-18167 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R056	CONTROL:HI TEMP OVEN CONTROL 500-280-1 (T.I.) 93-2-18168 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R061	CONTAINER:HOT LIQUID CONTAINER 80037-110 (PREPCO) 2962 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0		11/22/1997	22-NOV-1996 2209 1102			
25R066	OVEN:MICROWAVE (G.E.) OVEN JE-48A005 SG979125B REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R071	INVERTER:MICROWAVE OVEN INVERTER SPH-1606B-3 (K.G.S.) 436 REF:	MOS HRS/MSC AFL	N/R			04/18/1996	18-JAN-1996 1637 811			
25R076	COFFEE MAKER:GALLEY COFFEE MAKER F-1300-42 KRUPS REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
25R101	AMPLIFIER:PAGING (BAKER) AMPLIFIER M1060A905-01 9201050 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R106	RECORDER:VIDEO CASSETTE RECORDER SVO-160 (SONY) 811249 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R111	---PRE-AMP,VCR (BAKER) 990-3273-001 9303021 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R116	MONITOR:TV (JVC) MONITOR BMH1300SU 11451510 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			10-OCT-1999 3890 2021			
25R121	RELAY:AIRSHW VIDEO SELECT RELAY 912000 (ASINC) 869 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R131	SPEAKER:LT FS 364 CABIN SPEAKER TSA-1640 (PIONEER) NSN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R136	SPEAKER:RT FS 364 CABIN SPEAKER TSA-1640 (PIONEER) SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R141	SPEAKER:RT FS 424 CABIN SPEAKER TSA-1640 (PIONEER) SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
25R146	SPEAKER:LT FS 450 CABIN SPEAKER TSA-1640 (PIONEER) SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R151	SPEAKER:LT FS 473 CABIN SPEAKER TSA-1640 (PIONEER) SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R156	SPEAKER:RT FS 506 CABIN SPEAKER TSA-1640 (PIONEER) SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R161	SPEAKER:LT FS 530 CABIN SPEAKER TSA-1640 (PIONER) NSN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R166	SPEAKER:RT FS 530 CABIN SPEAKER TSA-1640 (PIONEER) SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R171	SPEAKER:FS 559 LAVATORY SPEAKER 4C5Z8 (QUAM) NSN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R201	--:SEAT BELTS,CABIN CMM-1500-00-03 MFG 1-93 REF:	MOS HRS/MSC AFL	N/R	TSN:3			08-APR-1993 24 15			
25R205	DIVAN:TOSSINGTON DIVAN T480-65 6397 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
25R206	--:SEAT BELTS,DIVAN CMM-1600-00-03 MFG 1-93 REF:	MOS HRS/MSC AFL	N/R	TSN:3			08-APR-1993 24 15			
25R207	--:SHOULDER HARNESS, DIVAN CMM-1601-01-03 MFG 1-93 REF:	MOS HRS/MSC AFL	N/R	TSN:3			08-APR-1993 24 15			
25R210	SEAT:FLT. ENGR. SEAT 444-0005-105 4/5/93 5121 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
25R211	--:SEAT BELTS,FLT ENG SEAT FDC5900-211-625 MFG 1-93 REF:	MOS HRS/MSC AFL	N/R	TSN:3			08-APR-1993 24 15			
25R212	--:SHLDR HARNESS, F/E SEAT FDC7275-24-625 MFG 1-93 REF:	MOS HRS/MSC AFL	N/R	TSN:3			08-APR-1993 24 15			
25R220	RENEW SUBSCRIPTION REF:	MOS HRS/MSC AFL	12				09-SEP-2008 8806.5 4265	09-SEP-2009		OVD
CHAPTER 26 FIRE PROTECTION										
26-10-11-201 (s)	VISUAL CHECK POWER PLANT AND APU FIRE SENSING CABLES - ALL VISIBLE PORTIONS OF THE FIREWIRES PKG 2 REF: GENERIC NO REF	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
+ 26-10-21-203 (s)	FUNCTIONAL TEST MAIN LANDING GEAR BAY OVERHEAT DETECTION SYSTEM PKG 4 REF: AMM 26-10-21-203	MOS HRS/MSC AFL	1200				PKG 07-JUN-2005 8180 3964			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 26-21-00-204 (s)	FUNCTIONAL TEST APU FIRE EXTINGUISHING SYSTEM PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 26-21-00-204									
26-21-21-205 (s)	VISUAL CHECK AUXILIARY POWER UNIT FIREX DISCHARGE LINE PKG 30	MOS HRS/MSC AFL	12				PKG 19-JUL-2010 8947.8 4353			
	REF: GENERIC NO REF									
+ 26-23-00-208 (s)	FUNCTIONAL TEST POWER PLANT FIRE EXTINGUISHING SYSTEM PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 26-23-00-208									
26-23-21-214 (s)	VISUAL CHECK POWER PLANT FIREX DISCHARGE LINES - PAYING PARTICULAR ATTENTION FOR ANY CHAFING WITH THE PRSOV SENSING LINE PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: AMM 26-23-21-214									
26-25-00-211 (s)	CHECK PRESSURE PORTABLE FIRE EXTINGUISHER PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 26-25-00-211									
+ 26-25-00-212 (s)	WEIGHT CHECK PORTABLE FIRE EXTINGUISHER PKG 30	MOS HRS/MSC AFL	12				PKG 19-JUL-2010 8947.8 4353			
	REF: AMM 26-25-00-212									
+ 26-25-00-213	BOTTLE:HYDROSTATIC TEST COCKPIT FIRE EXTINGUISHER-PORTABLE BOTTLE PORTABLE FIRE EXTINGUISHER	MOS HRS/MSC AFL	144				01-SEP-2003	01-SEP-2015		1820 d
	REF: GENERIC NO REF									
261000-001	CONTROL:LEFT ENGINE FIRE DETECTION CONTROL 377-02836 8947-023	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
	REF: GENERIC NO REF									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
261000-002	CONTROL:RIGHT ENGINE FIRE DETECTION CONTROL 377-02836 9004-009 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
261000-003	CONTROL:LH JETPIPE & PYLON FIRE DETECTION CONTROL 377-02836 9116-010 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
261000-004	CONTROL:RH JETPIPE & PYLON FIRE DETECTION CONTROL 377-02836 9116-016 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
261000-005	CONTROL:APU FIRE DETECTION CONTROL 377-02836 8947-018 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
261000-006	CONTROL:MLG WHEEL BIN FIRE DETECTION CONTROL 377-02836 9004-019 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
261001-001	ELEMENT:NO. 1 MAIN LANDING GEAR FIRE SENSING ELEMENT 244-03615 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
261001-002	ELEMENT:NO. 2 MAIN LANDING GEAR FIRE SENSING ELEMENT 244-03615 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
261010-001	ELEMENT:NO. 1 FIRE SENSING PYLON ELEMENT 244-05215 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
261010-002	ELEMENT:NO. 2 FIRE SENSING PYLON ELEMENT 244-05215 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
261011-001	ELEMENT:LEFT INBOARD FIRE SENSING ELEMENT 244-06322 SN-UNKNOWN REF: AMM 261011	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
261011-003	ELEMENT:LEFT OUTBOARD FIRE SENSING ELEMENT 244-06322 SN-UNKNOWN REF: AMM 261011	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
261011-004	ELEMENT:RIGHT OUTBOARD FIRE SENSING ELEMENT 244-06322 SN-UNKNOWN REF: AMM 261011	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
261011-007	ELEMENT:RIGHT INBOARD FIRE SENSING ELEMENT 244-06322 SN-UNKNOWN REF: AMM 261011	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
261012-001	ELEMENT:NO. 1 OVERHEAT DETECTION JET PIPE ELEMENT 244-06322 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
261012-002	ELEMENT:NO. 2 OVERHEAT DETECTION JET PIPE ELEMENT 244-06322 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
261014-001	ELEMENT:FIRE SENSING - APU ELEMENT 244-21086 SN-UNKNOWN REF: AMM 26-10-11	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
262111-001	BOTTLE:APU FIRE EXTINGUISHER BOTTLE 897889 99157EK REF: AMM 262111	MOS HRS/MSC AFL	O/C				03-APR-2006 8305.8 4018			
+ 262111-001A	BOTTLE:HYDROSTATIC TEST APU FIRE EXTINGUISHER BOTTLE (26-21-11-207) REF: SMM 26-21-28	MOS HRS/MSC AFL	60				30-MAR-2006	30-MAR-2011		204 d
+ 262111-001B (s)	BOTTLE:CHECK APU FIRE EXTINGUISHER BOTTLE (26-21-11-206) PKG 30 REF: AMM 26-21-11-206	MOS HRS/MSC AFL	12				PKG 19-JUL-2010 8947.8 4353			
262300-001	CARTRIDGE:LEFT NO.1 FIRE EXTINGUISHING CARTRIDGE 897776-01 00597 REF: AMM 262300	MOS HRS/MSC AFL	120	TSN:57			05-APR-2006 8305.8 4018	05-JUL-2011 M		LIFE LIMIT 301 d
262300-002	CARTRIDGE:LEFT NO.2 FIRE EXTINGUISHING CARTRIDGE 897776-01 00806 REF: AMM 262300	MOS HRS/MSC AFL	120	TSN:57			05-APR-2006 8305.8 4018	05-JUL-2011 M		LIFE LIMIT 301 d
262300-003	CARTRIDGE:RIGHT NO. 1 FIRE EXTINGUISHING CARTRIDGE 897776-01 00797 REF: AMM 262300	MOS HRS/MSC AFL	120	TSN:57			05-APR-2006 8305.8 4018	05-JUL-2011 M		LIFE LIMIT 301 d
262300-004	CARTRIDGE:RIGHT NO. 2 FIRE EXTINGUISHING CARTRIDGE 897776-01 00824 REF: AMM 262300	MOS HRS/MSC AFL	120	TSN:57			05-APR-2006 8305.8 4018	05-JUL-2011 M		LIFE LIMIT 301 d
262300-005	CARTRIDGE:APU FIRE EXTINGUISHING CARTRIDGE 897776-9 00751 REF: AMM 26-21-16	MOS HRS/MSC AFL	120	TSN:57			05-APR-2006 8305.8 4018	05-JUL-2011 M		LIFE LIMIT 301 d

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
262311-001	BOTTLE:NO. 1 ENGINE FIRE EXTINGUISHER BOTTLE 899074 5441EL REF: AMM 262311	MOS HRS/MSC AFL	O/C				03-APR-2006 8305.8 4018			
+ 262311-001A	BOTTLE:HYDROSTATIC TEST NO. 1 ENGINE FIRE EXTINGUISHER BOTTLE (26-23-11-210) REF: SMM 26-20-81	MOS HRS/MSC AFL	60				30-MAR-2006	30-MAR-2011		204 d
+ 262311-001B (s)	BOTTLE:CHECK NO. 1 ENGINE FIRE EXTINGUISHER BOTTLE (26-23-11-209) PKG 30 REF: AMM 26-23-11-209	MOS HRS/MSC AFL	12				PKG 19-JUL-2010 8947.8 4353			
262311-002	BOTTLE:NO. 2 ENGINE FIRE EXTINGUISHER BOTTLE 899074 5445EL REF: AMM 262311	MOS HRS/MSC AFL	O/C				03-APR-2006 8305.8 4018			
+ 262311-002A	BOTTLE:HYDROSTATIC TEST NO. 2 ENGINE FIRE EXTINGUISHER BOTTLE (26-23-11-210) REF: SMM 26-20-81	MOS HRS/MSC AFL	60				30-MAR-2006	30-MAR-2011		204 d
+ 262311-002B (s)	BOTTLE:CHECK NO. 2 ENGINE FIRE EXTINGUISHER BOTTLE (26-23-11-209) PKG 30 REF: AMM 26-23-11-209	MOS HRS/MSC AFL	12				PKG 19-JUL-2010 8947.8 4353			
262500-001	BOTTLE:COCKPIT FIRE EXTINGUISHER-PORTABLE BOTTLE 100-9750N F001882C REF: AMM 262500	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-DEC-2003 7091 3530			
262500-001A	BOTTLE:HYDROSTATIC TEST COCKPIT FIRE EXTINGUISHER-PORTABLE BOTTLE (26-25-00-213) REF: GENERIC NO REF	MOS HRS/MSC AFL	144				01-SEP-2003	01-SEP-2015		1820 d

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
269006	FIRE EXTINGUISHER:NO. 1 CABIN PORTABLE FIRE EXTINGUISHER 352T X133175 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-APR-2006 8305.8 4018			
269014	FIRE EXTINGUISHER:PORTABLE WATER FIRE EXTINGUISHER 892-480 492 REF:	MOS HRS/MSC AFL	O/C				05-APR-2006 8305.8 4018			
269026	FIRE EXTINGUISHER:WEIGHT CHECK NO. 1 CABIN PORTABLE FIRE EXTINGUISHER REF:	MOS HRS/MSC AFL	12				19-JUL-2010 8947.8 4353	19-JUL-2011		315 d
269034	FIRE EXTINGUISHER:WEIGHT CHECK PORTABLE WATER FIRE EXTINGUISHER REF:	MOS HRS/MSC AFL	12				19-JUL-2010 8947.8 4353	19-JUL-2011		315 d MANDATORY
269046	FIRE EXTINGUISHER:HYDROSTATIC TEST NO. 1 CABIN PORTABLE FIRE EXTINGUISHER REF:	MOS HRS/MSC AFL	144				01-MAR-2006	01-MAR-2018		2732 d
269054	FIRE EXTINGUISHER:HYDROSTATIC TEST PORTABLE WATER FIRE EXTINGUISHER REF:	MOS HRS/MSC AFL	60				01-MAR-2006	01-MAR-2011		175 d MANDATORY
269216	DETECTOR:NO. 1 AFT SMOKE BAG DETECTOR 30-231-17 0028W REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
269266	DETECTOR:OPERATIONAL TEST NO. 1 AFT SMOKE BAG DETECTOR REF:	MOS HRS/MSC AFL	6				19-JUL-2010 8947.8 4353	19-JAN-2011		134 d

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
26R002	--:ELMT,OVHT DET STG10 A48WK 35563-2-310 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				18-JAN-2000 4062 2105			
288010	SWITCH:LEFT SCAVENGE EJECTOR SWITCH 601R62292 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C							
T26T01	OPERATIONAL TEST ENGINE AND APU FIRE EXTINGUISHING SYSTEM REF:	MOS HRS/MSC AFL	O/C							
CHAPTER 27 FLIGHT CONTROLS										
27-11-00-201 (s)	VISUAL CHECK AILERON, FLAPS, ACTUATORS AND ATTACHMENTS PKG 2 REF: GENERIC NO REF	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
+ 27-11-00-202 (s)	CHECK AILERON CONTROL - AILERON BACKLASH PKG 3 REF: AMM 27-11-00-202	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
+ 27-11-11-203 (s)	OPERATIONAL TEST TENSION REGULATOR PKG 3 REF: AMM 27-11-11-203	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
+ 27-13-11-204 (s)	OPERATIONAL TEST ANTI-FLOAT MECHANISM PKG 4 REF: AMM 27-13-11-204	MOS HRS/MSC AFL	1200				PKG 09-JUN-2005 8180 3964			
+ 27-13-21-205 (s)	CHECK AILERON FLUTTER DAMPERS - FLUTTER DAMPER SHEAR PINS PKG 3 REF: AMM 27-13-21-205	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 27-15-00-207 (s)	FUNCTIONAL TEST ROLL DISCONNECT MECHANISM PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: AMM 27-15-00-207									
+ 27-17-00-208 (s)	OPERATIONAL TEST AILERON POWER CONTROL UNIT PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 27-17-00-208									
27-17-00-209 (s)	VISUAL CHECK AILERON POWER CONTROL UNIT PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: GENERIC NO REF									
27-21-00-210 (s)	CHECK RUDDER CONTROL - RUDDER BACKLASH - PCU INPUT LOAD LIMITER TRAVEL - VISUAL CHECK PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: AMM 27-21-00-210									
+ 27-21-00-211 (s)	FUNCTIONAL TEST RUDDER CONTROL - RUDDER ANTI-JAM MECHANISM PKG 6	MOS HRS/MSC AFL	2400				PKG 12-NOV-2003 7003 3486			
	REF: AMM 27-21-00-211									
+ 27-25-00-212 (s)	OPERATIONAL TEST RUDDER POWER CONTROL UNITS PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 27-25-00-212									
+ 27-30-00-234 (s)	BENCH CHECK PITCH TRIM SUPPRESSOR UNIT PKG 6	MOS HRS/MSC AFL	2400				PKG 30-OCT-2003 7003 3486			
	REF: See Workcard									
27-31-00-213 (s)	CHECK ELEVATOR CONTROL - ELEVATOR BACKLASH, PCU INPUT JAM TOLERANT MECHANISM TRAVEL, AND VISUAL CHECK PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: AMM 27-31-00-213									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
27-31-00-214	VISUAL CHECK ELEVATOR CONTROL (A/C 5001 TO 5054, PRE SB-601-0304) - OF ELEVATOR CONTROL LEVERS	MOS					08-JUN-2005			
	REF: GENERIC NO REF	HRS/MSC	N/A				8180			
		AFL					3964			
+ 27-31-00-215 (s)	TEST ELEVATOR LOAD LIMITERS						PKG			
	PKG 6	MOS					12-NOV-2003			
	REF: AMM 27-31-00-215	HRS/MSC	2400				7003			
		AFL					3486			
+ 27-35-00-218 (s)	OPERATIONAL TEST PITCH DISCONNECT MECHANISM						PKG			
	PKG 3	MOS					20-MAR-2009			
	REF: AMM 27-35-00-218	HRS/MSC	600				8873.5			
		AFL					4304			
+ 27-37-00-219 (s)	OPERATIONAL TEST ELEVATOR POWER CONTROL UNITS						PKG			
	PKG 2	MOS					09-SEP-2008			
	REF: AMM 27-37-00-219	HRS/MSC	300				8806.5			
		AFL					4265			
+ 27-39-00-101	FUNCTIONAL TEST STALL PROTECTION SYSTEM (SPS) (PRE SB-601-0510) - OF THE FLAP INPUT									
		MOS					02-AUG-2005			
	REF: AMM 27-39-00-101	HRS/MSC	N/A				8215.3			
		AFL					3975			
+ 27-39-00-102	FUNCTIONAL TEST STALL PROTECTION SYSTEM (SPS) (PRE SB-601-0510) - OF THE PHASE ADVANCE AND SIDESLIP COMPENSATION									
		MOS					02-AUG-2005			
	REF: AMM 27-39-00-102	HRS/MSC	N/A				8215.3			
		AFL					3975			
27-39-00-103	FUNCTIONAL TEST STALL PROTECTION SYSTEM (SPS) (POST SB-601-0510) - OF THE FLAP AND SIDESLIP COMPENSATION MONITOR									
		MOS								
	REF: AMM 27-39-00-103	HRS/MSC	4800						12408 M	3460.2
		AFL								
27-39-00-104	FUNCTIONAL TEST OF STICK PUSHER CAPSTAN (SPS) SHAFT									AIRWORTHINESS
		MOS					09-SEP-2008			
	REF: AMM 27-39-00-104	HRS/MSC	1500				8806.5		10306.5	1358.7
		AFL					4265			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 27-39-00-220 (s)	OPERATIONAL TEST STALL PROTECTION SYSTEM PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: AMM 27-39-00-220									
+ 27-39-00-221 (s)	FUNCTIONAL TEST STALL PROTECTION SYSTEM PKG 6	MOS HRS/MSC AFL	2400				PKG 28-OCT-2003 7003 3486			
	REF: AMM 27-39-00-221									
27-40-00-102	OPERATIONAL TEST TRIM SYSTEM ACTUATOR BRAKE (POST SB-A601-0443, PART C AND/OR POST SB601-0555)	MOS HRS/MSC AFL	600		-34		12-AUG-2007 8558 4142	9124		176.2
	REF: AMM 27-40-00-102									
+ 27-40-00-222 (s)	ACTUATOR:CHECK HORIZONTAL STABILIZER TRIM ACTUATOR PITCH TRIM ACTUATOR BACKLASH PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: AMM 27-40-00-222									
27-40-00-237 (s)	LUBRICATE HORIZONTAL STABILIZER PITCH TRIM ACTUATOR PKG 4	MOS HRS/MSC AFL	1200				PKG 01-OCT-1992 0 0			
	REF: GENERIC NO REF									
27-40-16-223 (s)	INSPECT PITCH TRIM ACTUATOR PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: AMM 27-40-16-223									
27-50-16-101	ACTUATOR:RESTORATION LEFT INBOARD (OUTER FLAP) ACTUATOR	MOS HRS/MSC AFL	2000				(EBT)	6356	6356	AIRWORTHINESS 2003
	REF:									
27-50-16-101	ACTUATOR:RESTORATION LEFT OUTBOARD (OUTER FLAP) ACTUATOR	MOS HRS/MSC AFL	2000				(EBT)	6356	6356	AIRWORTHINESS 2003
	REF:									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
27-50-16-101	ACTUATOR:RESTORATION RIGHT INBOARD (OUTER FLAP) ACTUATOR						(EBT)			AIRWORTHINESS
	REF:	MOS HRS/MSC AFL	2000					6356	6356	2003
27-50-16-101	ACTUATOR:RESTORATION RIGHT OUTBOARD (OUTER FLAP) ACTUATOR						(EBT)			AIRWORTHINESS
	REF:	MOS HRS/MSC AFL	2000					6356	6356	2003
+ 27-50-16-224	CHECK FLAP ACTUATOR - OUTBOARD FLAP ACTUATOR BACKLASH									
	REF: AMM 27-50-16-224	MOS HRS/MSC AFL	9600				01-OCT-1992 0 0	9600	9660	5247
+ 27-50-16-235 (s)	DETAILED INSPECTION FLAP ACTUATOR						PKG			
	PKG 3	MOS HRS/MSC AFL	600				20-MAR-2009 8873.5 4304			
REF: AMM 27-50-16-103										
+ 27-50-16-236 (s)	CHECK FLAP ACTUATOR - TORQUE AND SIDE PLAY						PKG			
	PKG 6	MOS HRS/MSC AFL	2400				03-NOV-2003 7003 3486			
REF: AMM 27-50-16-104										
+ 27-50-21-225 (s)	OPERATIONAL TEST POWER DRIVE UNIT (PDU) - OF FLAP PDU MOTOR BRAKE						PKG			
	PKG 3	MOS HRS/MSC AFL	600				20-MAR-2009 8873.5 4304			
REF: AMM 27-50-21-225										
+ 27-50-26-226 (s)	TEST ASYMETRY/OVERSPEED DETECTOR AND BRAKE - BRAKE DRAG TORQUE						PKG			
	PKG 3	MOS HRS/MSC AFL	600				20-MAR-2009 8873.5 4304			
REF: AMM 27-50-26-226										
27-50-41-227 (s)	CHECK FLEXIBLE DRIVE SHAFT - FLEXIBLE DRIVE SHAFT CASING						PKG			
	PKG 3	MOS HRS/MSC AFL	600				20-MAR-2009 8873.5 4304			
REF: AMM 27-50-41-227										

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 27-50-41-301 (s)	CHECK FLEXIBLE DRIVE SHAFT CASING - FLEXIBLE DRIVE SHAFT INNER CORE PKG 6	MOS HRS/MSC 2400 AFL					PKG 29-OCT-2003 7003 3486			
	REF: AMM 27-50-41-301									
27-61-00-229 (s)	VISUAL CHECK OF FLIGHT SPOILER AND GROUND SPOILER ACTUATORS, ATTACHMENTS AND MECHANISMS, PAYING PARTICULAR ATTENTION TO THE FLIGHT SPOILER TRACK ROLLER, CAM AND DETENT ASSEMBLY FOR WEAR AND FREEDOM OF MOVEMENT PKG 3	MOS HRS/MSC 600 AFL					PKG 20-MAR-2009 8873.5 4304			
	REF: GENERIC NO REF									
27-61-00-230 (s)	LUBRICATE FLIGHT SPOILERS FLEXSHAFT AND CONTROLEX CABLE END PKG 2	MOS HRS/MSC 300 AFL					PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 27-61-00-230									
+ 27-65-00-232 (s)	OPERATIONAL TEST FLIGHT SPOILER POWER CONTROL UNITS PKG 3	MOS HRS/MSC 600 AFL					PKG 20-MAR-2009 8873.5 4304			
	REF: AMM 27-65-00-232									
27-69-00-228	CHECK GROUND SPOILER ACTUATORS AND MANIFOLD ASSEMBLY (A/C 5001 TO 5038 PRE SB-601-0224) - MECHANICAL LOCKING MECHANISM PKG 2	MOS HRS/MSC N/A AFL					PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 27-69-00-228									
270000-001	WHEEL:PILOT CONTROL COLUMN WHEEL 600-90101-5	MOS HRS/MSC O/C AFL		TSN:0			01-OCT-1992 0 0			
	REF: GENERIC NO REF									
270000-002	WHEEL:COPILOT CONTROL COLUMN WHEEL 600-90101-6	MOS HRS/MSC O/C AFL		TSN:0			01-OCT-1992 0 0			
	REF: GENERIC NO REF									
270001-001	INDICATOR:CONTROL SURFACE POSITION INDICATOR 600-59133-5	MOS HRS/MSC O/C AFL		TSN:0			01-OCT-1992 0 0			
	REF: AMM 270001									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
270002-001	INDICATOR: SURFACE TRIM INDICATOR 600-59125-17 143 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			27-APR-2007 8539 4126			
270500-001	UNIT: FLIGHT CONTROL MONITOR UNIT 600-59133-5 356 REF: AMM 270500	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
271016	TRANSMITTER: LEFT AILERON POSITION TRANSMITTER 13TX0515A SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
271021	TRANSMITTER: RIGHT AILERON POSITION TRANSMITTER 13TX0515A SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
271111-001	REGULATOR: LEFT TENSION - AILERON REGULATOR 600-91301-11 002-91 REF: AMM 271111	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
271111-002	REGULATOR: RIGHT TENSION - AILERON REGULATOR 600-91301-12 007-91 REF: AMM 271111	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
271116-001	ACTUATOR: RUDDER TRIM (ROLL & YAW) ACTUATOR 600-91100-3 0647 REF: AMM 271116	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
271116-002	ACTUATOR: AILERON TRIM (ROLL & YAW) ACTUATOR 600-91100-3 0599 REF: AMM 271116	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
271700-001	PCU:NO. 1 POWER CONTROL AILERON PCU 600-75100-15 0035CD REF: AMM 271700	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			05-APR-2006 8305.8 4018			
271700-002	PCU:NO. 2 POWER CONTROL AILERON PCU 600-75100-15 593B REF: AMM 271700	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
272041	LIMITER:RUDDER MIDDLE LOAD LIMITER 37380 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
272100-001	TRANSMITTER:RUDDER POSITION TRANSMITTER 13TX0515A SN-UNKNOWN REF: AMM 272100	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
272102-001	LIMITER:NO. 1 LOAD - POWER CONTROL UNITS LIMITER 36990 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
272111-001	LIMITER:YAW DAMPER LOAD LIMITER 36980 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
272112-001	LIMITER:RUDDER LOAD LIMITER 37390 SN-UNKNOWN REF: AMM 27-21-11	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
272112-002	LIMITER:RUDDER LOAD LIMITER 37390 SN-UNKNOWN REF: AMM 27-21-11	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
272500-001	UNIT:NO. 1 POWER CONTROL RUDDER UNIT 600-75101-27 6869 REF: AMM 272500	MOS HRS/MSC AFL	O/C			12/21/2000	21-DEC-1999 4021 2088			
272500-002	UNIT:NO. 2 POWER CONTROL RUDDER UNIT 600-75101-27 6896 REF: AMM 272500	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
272500-003	UNIT:NO. 3 POWER CONTROL RUDDER UNIT 600-75101-27 6925C REF: AMM 272500	MOS HRS/MSC AFL	O/C				27-JUN-1998 3141 1599			
273100-001	LIMITER:NO. 1 LOAD - ELEVATOR CONTROLS LIMITER 36960 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
273100-002	LIMITER:NO. 2 LOAD - ELEVATOR CONTROLS LIMITER 36960 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
273101-001	SIMULATOR:NO. 1 PITCH FEEL SIMULATOR 600-92300-53 203 REF: AMM 273101	MOS HRS/MSC AFL	O/C				02-SEP-1994 808 401			
273101-001A	SIMULATOR:FUNCTIONAL TEST NO. 1 PITCH FEEL SIMULATOR (27-31-11-101) REF: AMM 27-31-11-101	MOS HRS/MSC AFL	1500				09-SEP-2008 8806.5 4265	10306.5		1358.7
273101-002	SIMULATOR:NO. 2 PITCH FEEL SIMULATOR 600-92300-53 P146 REF: AMM 273101	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-SEP-1994 808 401			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
273101-002A	SIMULATOR:FUNCTIONAL TEST NO. 2 PITCH FEEL SIMULATOR (27-31-11-101)									AIRWORTHINESS
		MOS					09-SEP-2008			
		HRS/MSC	1500				8806.5		10306.5	1358.7
	REF: AMM 27-31-11-101	AFL					4265			
273102-001	TRANSMITTER:NO. 1 POSN ELEVATOR TRANSMITTER									
	13TX0515A	MOS					01-OCT-1992			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 273102	AFL					0			
273102-002	TRANSMITTER:NO. 2 POSITION TRANSMITTER									
	13TX0515A	MOS					01-OCT-1992			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: GENERIC NO REF	AFL					0			
273311-001	DAMPER:LOB ELEVATOR DAMPER									
	600-75142-5	MOS					01-OCT-1992			
	HA0178	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 273311	AFL					0			
+ 273311-001A (s)	DAMPER:CHECK LOB ELEVATOR DAMPER (27-33-11-216)						PKG			
	PKG 3	MOS					20-MAR-2009			
		HRS/MSC	600				8873.5			
	REF: GENERIC NO REF	AFL					4304			
+ 273311-001C (s)	DAMPER:TEST LOB ELEVATOR DAMPER - REMOVE, CARRY OUT "TESTING AND FAULT ISOLATION" OF FLUTTER DAMPER AND REINSTALL (27-33-11-217)						PKG			
	PKG 10	MOS					05-MAR-2001			
		HRS/MSC	4800				4859			
	REF: GENERIC NO REF	AFL					2516			
273311-002	DAMPER:LIB ELEVATOR DAMPER									
	600-75142-5	MOS					01-OCT-1992			
	HA0179	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 273311	AFL					0			
+ 273311-002A (s)	DAMPER:CHECK LIB ELEVATOR DAMPER (27-33-11-216)						PKG			
	PKG 3	MOS					20-MAR-2009			
		HRS/MSC	600				8873.5			
	REF: GENERIC NO REF	AFL					4304			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 273311-002C (s)	DAMPER:TEST LIB ELEVATOR DAMPER - REMOVE, CARRY OUT "TESTING AND FAULT ISOLATION" OF FLUTTER DAMPER AND REINSTALL (27-33-11-217)						PKG			
	PKG 10	MOS						05-MAR-2001		
		HRS/MSC	4800					4859		
	REF: GENERIC NO REF	AFL						2516		
273311-003	DAMPER:RIB ELEVATOR DAMPER									
	600-75142-5	MOS						01-OCT-1992		
	HA0180	HRS/MSC	O/C	TSN:0				0		
	REF: AMM 273311	AFL						0		
+ 273311-003A (s)	DAMPER:CHECK RIB ELEVATOR DAMPER (27-33-11-216)						PKG			
	PKG 3	MOS						20-MAR-2009		
		HRS/MSC	600					8873.5		
	REF: GENERIC NO REF	AFL						4304		
+ 273311-003C (s)	DAMPER:TEST RIB ELEVATOR DAMPER - REMOVE, CARRY OUT "TESTING AND FAULT ISOLATION" OF FLUTTER DAMPER AND REINSTALL (27-33-11-217)						PKG			
	PKG 10	MOS						05-MAR-2001		
		HRS/MSC	4800					4859		
	REF: GENERIC NO REF	AFL						2516		
273311-004	DAMPER:ROB ELEVATOR DAMPER									
	600-75142-5	MOS						01-OCT-1992		
	HA0173	HRS/MSC	O/C	TSN:0				0		
	REF: AMM 273311	AFL						0		
+ 273311-004A (s)	DAMPER:CHECK ROB ELEVATOR DAMPER (27-33-11-216)						PKG			
	PKG 3	MOS						20-MAR-2009		
		HRS/MSC	600					8873.5		
	REF: GENERIC NO REF	AFL						4304		
+ 273311-004C (s)	DAMPER:TEST ROB ELEVATOR DAMPER - REMOVE, CARRY OUT "TESTING AND FAULT ISOLATION" OF FLUTTER DAMPER AND REINSTALL (27-33-11-217)						PKG			
	PKG 10	MOS						05-MAR-2001		
		HRS/MSC	4800					4859		
	REF: GENERIC NO REF	AFL						2516		
273312-001	DAMPER:NO. 1 AILERON FLUTTER DAMPER									
	600-75142-5	MOS						01-OCT-1992		
	HA0135	HRS/MSC	O/C	TSN:0				0		
	REF: AMM 273312	AFL						0		

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 273312-001A (s)	DAMPER:CHECK NO. 1 AILERON FLUTTER DAMPER (27-13-21-205) PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: GENERIC NO REF									
+ 273312-001C (s)	DAMPER:TEST NO. 1 AILERON FLUTTER DAMPER - REMOVE, CARRY OUT "TESTING AND FAULT ISOLATION" OF FLUTTER DAMPER AND REINSTALL (27-13-21-206) PKG 10	MOS HRS/MSC AFL	4800				PKG 05-MAR-2001 4859 2516			
	REF: GENERIC NO REF									
273312-002	DAMPER:NO.2 AILERON FLUTTER DAMPER 600-75142-7 HA0149	MOS HRS/MSC AFL	O/C				06-MAY-1999 3649 1876			
	REF: AMM 273312									
+ 273312-002A (s)	DAMPER:CHECK NO.2 AILERON FLUTTER DAMPER (27-13-21-205) PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: GENERIC NO REF									
+ 273312-002C (s)	DAMPER:TEST NO.2 AILERON FLUTTER DAMPER - REMOVE, CARRY OUT "TESTING AND FAULT ISOLATION" OF FLUTTER DAMPERS AND REINSTALL (27-13-21-206) PKG 10	MOS HRS/MSC AFL	4800				PKG 05-MAR-2001 4859 2516			
	REF: GENERIC NO REF									
273700-001	PCU:NO. 1 POWER CONTROL ELEVATOR PCU 600-75102-21 1160	MOS HRS/MSC AFL	O/C		TSN:0		01-OCT-1992 0 0			
	REF: AMM 273700									
273700-002	PCU:NO. 2 POWER CONTROL ELEVATOR PCU 600-75102-21 1149	MOS HRS/MSC AFL	O/C		TSN:0		01-OCT-1992 0 0			
	REF: AMM 273700									
273700-003	PCU:NO. 3 POWER CONTROL ELEVATOR PCU 600-75102-21 1153	MOS HRS/MSC AFL	O/C		TSN:0		01-OCT-1992 0 0			
	REF: AMM 273700									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
273700-004	PCU:NO. 4 POWER CONTROL ELEVATOR PCU 600-75102-21 1184 REF: AMM 273700	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
273903-001	ACTUATOR:STICK PUSHER ACTUATOR 600-59156-15 1278 REF: AMM 273903	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
273904-001	SHAFT:STICK PUSHER CAPSTAN (SPS) SHAFT PN SN-UNKNOWN REF: AMM 273904	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			
273912-001	ACCELEROMETER:NO. 1 LATERAL STALL WARNING SYSTEM ACCELEROMETER 600-59199-9 2960 REF: AMM 273912	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-SEP-2004 7627 3734			
273912-002	ACCELEROMETER:NO. 2 LATERAL STALL WARNING SYSTEM ACCELEROMETER 600-59199-9 2971 REF: AMM 273912	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-SEP-2004 7627 3734			
273913-001	COMPUTER:STALL WARNING COMPUTER 600-59152-29 1039M1-60 REF: AMM 27-39-36	MOS HRS/MSC AFL	O/C				10-SEP-2004 7608.8 3724			
273914-001	TRANSDUCER:LEFT ANGLE OF ATTACK TRANSDUCER 600-59154-3 GST05012 REF: AMM 273914	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-DEC-2004 7791 3791			
+ 273914-001A	TRANSDUCER:FUNCTIONAL TEST LEFT ANGLE OF ATTACK TRANSDUCER VANE LINEARITY (27-39-11-101) REF: AMM 27-39-11-101	MOS HRS/MSC AFL	300				09-SEP-2008 8806.5 4265	9106.5		158.7

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 273914-001B	TRANSDUCER:OVERHAUL LEFT ANGLE OF ATTACK TRANSDUCER VANE, PART NUMBER 600-59154-5 (27-39-11-102)									AIRWORTHINESS
		MOS								
	REF: AMM 27-39-11-102	HRS/MSC -								
		AFL								
273914-002	TRANSDUCER:RIGHT ANGLE OF ATTACK TRANSDUCER									
	600-59154-3	MOS		TSN:0			03-DEC-2004			
	GST05013	HRS/MSC	O/C	TSN:0			7791			
	REF: AMM 273914	AFL		TSN:0			3791			
+ 273914-002A	TRANSDUCER:FUNCTIONAL TEST RIGHT ANGLE OF ATTACK TRANSDUCER VANE LINEARITY (27-39-11-101)									
		MOS					09-SEP-2008			
		HRS/MSC	300				8806.5	9106.5		158.7
	REF: AMM 27-39-11-101	AFL					4265			
+ 273914-002B	TRANSDUCER:OVERHAUL RIGHT ANGLE OF ATTACK TRANSDUCER VANE, PART NUMBER 600-59154-5 (27-39-11-102)									AIRWORTHINESS
		MOS								
	REF: AMM 27-39-11-102	HRS/MSC -								
		AFL								
273915-001	INDICATOR:NO. 1 STALL MARGIN INDICATOR									
	600-59217-1	MOS					27-DEC-2001			
	1319	HRS/MSC	O/C				5429			
	REF: GENERIC NO REF	AFL					2786			
273915-002	INDICATOR:NO. 2 STALL MARGIN INDICATOR									
	563-127	MOS					01-OCT-1992			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: GENERIC NO REF	AFL					0			
273916-001	SHAKER:NO. 1 STICK SHAKER									
	600-59155-1	MOS					01-OCT-1992			
	5479	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 273916	AFL					0			
273916-002	SHAKER:NO. 2 STICK SHAKER									
	600-59155-1	MOS		TSO:0			08-APR-1993			
	823	HRS/MSC	O/C	TSO:0			24			
	REF: AMM 273916	AFL		TSO:0			15			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
273917-001	TRANSDUCER:NO. 1 ALTITUDE TRANSDUCER 7001648-902 92051240 REF: AMM 273917	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
273917-002	TRANSDUCER:NO. 2 ALTITUDE TRANSDUCER 7001648-902 92051244 REF: AMM 273917	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
274002-001	ACTUATOR:HORIZONTAL STABILIZER TRIM ACTUATOR 600-92301-65 131E REF: AMM 274002	MOS HRS/MSC AFL	13200	TSN:3994 TSN:2593		09/16/1998	16-MAR-1998 2992 1506	12198	3250.2	LIFE LIMIT
+ 274002-001A	ACTUATOR:OVERHAUL HORIZONTAL STABILIZER TRIM ACTUATOR (27-40-16-101) REF: GENERIC NO REF	MOS HRS/MSC AFL	6600				05-JUN-2002 5826 2976	12426	3478.2	MANDATORY OVERHAUL
274010-001	UNIT:HORIZONTAL STABILIZER TRIM CONTROL UNIT 601-59116-3 394 REF: AMM 274010	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-JUN-2005 8180 3964			
274021-001	TRANSMITTER:HORIZONTAL STABILIZER POSITION TRANSMITTER ASSEMBLY 600-92443-9 SN-UNKNOWN REF: AMM 274021	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
275000-001	CONTROL:UNIT FLAP CONTROL 600-93000-117 82-564 REF: AMM 27-50-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
275016-001	ACTUATOR:LEFT INBOARD (INNER FLAP) ACTUATOR 600-93000-95 12-1435 REF: AMM 275016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
275016-002	ACTUATOR:RIGHT INBOARD (INNER FLAP) ACTUATOR 600-93000-95 12-1433 REF: AMM 275016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
275016-003	ACTUATOR:LEFT OUTBOARD (INNER FLAP) ACTUATOR 600-93000-93 11-1352 REF: AMM 275016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
275016-004	ACTUATOR:RIGHT OUTBOARD (INNER FLAP) ACTUATOR 600-93000-93 11-1353 REF: AMM 275016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
275016-005	ACTUATOR:LEFT INBOARD (OUTER FLAP) ACTUATOR 600-93000-115 72-1731 REF: AMM 275016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
275016-006	ACTUATOR:RIGHT INBOARD (OUTER FLAP) ACTUATOR 600-93000-116 42-1518 REF: AMM 275016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
275016-007	ACTUATOR:LEFT OUTBOARD (OUTER FLAP) ACTUATOR 600-93000-113 42-1728 REF: AMM 275016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
275016-008	ACTUATOR:RIGHT OUTBOARD (OUTER FLAP) ACTUATOR 600-93000-114 42-1553 REF: AMM 275016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
275020-001	LEVER:FWD TE FLAP SYSTEM CONTROL LEVER 777501-1 SN-UNKNOWN REF: AMM 275020	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
275023-001	UNIT:POWER DRIVE FLAP UNIT 600-93000-71 71-465 REF: AMM 27-50-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
275026-001	UNIT:LH FLAP BRAKE DETECTOR UNIT 600-93000-103 16-570M REF: AMM 275026	MOS HRS/MSC AFL	O/C				10-SEP-2004 7608.8 3724			
275026-002	UNIT:RH FLAP BRAKE DETECTOR UNIT 600-93000-103 71-854M REF: AMM 275026	MOS HRS/MSC AFL	O/C				30-OCT-1997 2832 1418			
275031-001	TRANSMITTER:NO. 1 FLAP POSITION TRANSMITTER 600-93030-1 REL52W REF: AMM 275031	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
275031-002	TRANSMITTER:NO. 2 FLAP POSITION TRANSMITTER 600-93030-5 REL44B REF: AMM 275031	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
275032-001	INDICATOR:FLAP POSITION INDICATOR 600-59179-1 94120364 REF: AMM 27-50-31	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			27-APR-2007 8539 4126			
275041-001	SHAFT:LEFT NO.1 FLEXIBLE DRIVE SHAFT 600-93000-61 1600 REF: AMM 275041	MOS HRS/MSC AFL	O/C				28-FEB-2001 4859 2516			
275041-002	SHAFT:RIGHT NO. 1 FLEXIBLE DRIVE SHAFT 600-93000-61 71-963 REF: AMM 275041	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
275041-003	SHAFT:LEFT NO.2 FLEXIBLE DRIVE SHAFT 600-93000-63 086-1148 REF: AMM 275041	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-APR-1997 2415 1208			
275041-004	SHAFT:RIGHT NO. 2 FLEXIBLE DRIVE SHAFT 600-93000-63 1781 REF: AMM 275041	MOS HRS/MSC AFL	O/C				31-OCT-2003 7003 3486			
275041-005	SHAFT:LEFT NO.3 FLEXIBLE DRIVE SHAFT 600-93000-65 1382 REF: AMM 275041	MOS HRS/MSC AFL	O/C				28-FEB-2001 4859 2516			
275041-006	SHAFT:RIGHT NO. 3 FLEXIBLE DRIVE SHAFT 600-93000-65 71-956 REF: AMM 275041	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
275041-007	SHAFT:LEFT NO.4 FLEXIBLE DRIVE SHAFT 600-93000-67 11-896 REF: AMM 275041	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
275041-008	SHAFT:RIGHT NO. 4 FLEXIBLE DRIVE SHAFT 600-93000-67 90-866 REF: AMM 275041	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
275041-009	SHAFT:LEFT NO.5 FLEXIBLE DRIVE SHAFT 600-93000-69 106-1326 REF: AMM 275041	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-APR-1997 2415 1208			
275041-010	SHAFT:RIGHT NO. 5 FLEXIBLE DRIVE SHAFT 600-93000-69 42-972 REF: AMM 275041	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
276001	LIMITER:LEFT FLIGHT SPOILER LOAD LIMITER 37315 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
276006	LIMITER:RIGHT FLIGHT SPOILER LOAD LIMITER 37315 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
276066	TRANSMITTER:LEFT FLIGHT SPOILER POSITION TRANSMITTER 13TX0515A SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
276101-001	LEVER:SPOILER CONTROL LEVER 600-90606-7 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
276105-001	CONTROL:GROUND SPOILER CONTROL 600-59147-5 306 REF: AMM 276105	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
276500-001	UNIT:NO. 1 POWER CONTROL GROUND SPOILER UNIT 600-75103-15 1142 REF: AMM 276500	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
276500-002	UNIT:NO. 2 POWER CONTROL GROUND SPOILER UNIT 600-75103-15 1143 REF: AMM 276500	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
276500-003	UNIT:NO. 3 POWER CONTROL FLIGHT SPOILER UNIT 600-75103-15 1144 REF: AMM 276500	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
276500-004	UNIT:NO. 4 POWER CONTROL FLIGHT SPOILER UNIT 600-75103-15 1145 REF: AMM 276500	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
276900-001	PCU:NO. 1 GROUND SPOILER ACTUATOR PCU 600-75106-5 590 REF: AMM 276900	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
276900-002	PCU:NO. 2 GROUND SPOILER ACTUATOR PCU 600-75106-5 0594 REF: AMM 276900	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
276901-001	MANIFOLD:GROUND SPOILER SELECT MANIFOLD 600-75124-7 277 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
279001	SWITCH:PROX GRND SPOIL L SWITCH 8-405-04 43958 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			26-OCT-2001 5296 2722			
279006	SWITCH:PROX GRND SPOIL R SWITCH 8-405-04 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
279011	SWITCH:PROX FLT SPOIL L SWITCH 8-405-04 B55075 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			11-NOV-2003 7003 3486			
279016	SWITCH:PROX FLT SPOIL R SWITCH 8-405-04 B55047 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			29-NOV-2004 7787 3789			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
279051	SWITCH:PILOT PITCH TRIM SWITCH 309-4312 NSN REF:	MOS HRS/MSC AFL	N/R				27-APR-2004 7417			
279056	SWITCH:COPILOT PITCH TRIM SWITCH 309-4312 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				01-OCT-1992 0 0			
279061	SWITCH:AILERON TRIM SWITCH 309-4311 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			24-NOV-1993 445 225			
279075	POTENTIOMETER:PITCH TRIM POTENTIOMETER 600-93033-5 6861954 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-APR-2005 8095 3917			
27R001	--:SUPRSSR,P/TRIM TRANS VOLT 600-56156-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
27R007	--:JAM TOL MECH, LH ELV,INBD 600-92404-9 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				02-SEP-1994			
27R009	--:JAM TOL MECH,LH ELV,OUTBD 600-92404-11B SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				02-SEP-1994 808 401			
27R011	--:QUAD, RUDDER-REAR SUBASSY 600-92614-5 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			02-SEP-1994 808 401			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
27R013	--:GRDSPL,LH THRL ATO STO SW 215X39-T SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			02-SEP-1994 808 401			
27R015	LEVER:RUDDER QUADRANT LEVER 600-92615-3 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				02-SEP-1994 808 401			
27R017	ASSY:RUDDER QUADRANT ASSY 600-92600-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				02-SEP-1994 808 401			
27R020	MOTOR:FLAP PDU - LEFT MOTOR 516456-2 83-447 REF:	MOS HRS/MSC AFL	N/R				05-FEB-1996 1690 827			
27R021	MOTOR:FLAP PDU - RIGHT MOTOR 516456-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				01-OCT-1992 0 0			
T27T01	FUNCTIONAL TEST ELEVATOR SYSTEM REF:	MOS HRS/MSC AFL	O/C							
T27T02	FUNCTIONAL TEST TRIM SYSTEM REF:	MOS HRS/MSC AFL	O/C							
T27T03	FUNCTIONAL TEST AILERON RIGGING REF:	MOS HRS/MSC AFL	O/C							

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
T27T04	RIG ELEVATORS AND PCU(S)	MOS								
	REF:	HRS/MSC	O/C							
		AFL								
T27T05	RIG RUDDER AND PCU'S	MOS								
	REF:	HRS/MSC	O/C							
		AFL								
CHAPTER 28 FUEL										
28-10-00-201 (s)	VISUAL CHECK FUEL STORAGE (POST SB-601-0262 OR A/C 5135 AND SUBS) - OF TAIL TANK VENT LINE (EXTERNAL TO TANK)						PKG			
	PKG 3	MOS						20-MAR-2009		
	REF: GENERIC NO REF	HRS/MSC	600					8873.5		
		AFL						4304		
28-10-00-202 (s)	VISUAL CHECK FUEL STORAGE (POST SB-601-0262 OR A/C 5135 AND SUBS) - OF AFT CONE AND LOWER FAIRING, PAYING PARTICULAR ATTENTION FOR FUEL LEAKAGE, DAMAGE TO STROBE LIGHT/POWER SUPPLY/DUMP VALVE WIRING.						PKG			
	PKG 4	MOS						08-JUN-2005		
	REF: GENERIC NO REF	HRS/MSC	1200					8180		
		AFL						3964		
28-10-00-203 (s)	VISUAL CHECK FUEL STORAGE (POST SB-601-0262 OR A/C 5135 AND SUBS) - OF TAIL TANK INTERNAL AND EXTERNAL STRUCTURE AND COMPONENTS, PAYING PARTICULAR ATTENTION FOR CORROSION AND LEAKAGE						PKG			
	PKG 34	MOS	60					05-APR-2006		
	REF: GENERIC NO REF	HRS/MSC						8305.8		
		AFL						4018		
28-10-00-224 (s)	INSPECT FUEL TANK GRAVITY FILLER CAP - REMOVE, INSPECT FOR CONDITION AND RE-INSTALL						PKG			
	PKG 3	MOS						20-MAR-2009		
	REF: GENERIC NO REF	HRS/MSC	600					8873.5		
		AFL						4304		
28-10-11-204 (s)	VISUAL CHECK FUEL TANKS FOR LEAKS						PKG			
	PKG 6	MOS						31-OCT-2003		
	REF: AMM 28-10-11-204	HRS/MSC	2400					7003		
		AFL						3486		
28-10-21-206 (s)	EXTERNAL INSPECTION FORWARD AND AFT AUXILIARY FUEL TANKS						PKG			
	PKG 34	MOS	60					05-APR-2006		
	REF: AMM 28-10-21-206	HRS/MSC						8305.8		
		AFL						4018		

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 28-10-21-207	EXTERNAL INSPECTION FORWARD AND AFT AUXILIARY FUEL TANKS - (USING BORESCOPE)	MOS	120	TSI:0	1		23-FEB-2001 4859 2516	23-MAR-2011	22-MAY-2011	197 d
	REF: AMM 28-10-21-207	HRS/MSC AFL								
+ 28-10-31-205 (s)	PRESSURE TEST FUEL AND VENT LINE SHROUDS - FUSELAGE TANK WALL INTERSPACE AND ASSOCIATED SHROUDS	PKG 34	MOS	60			03-APR-2006 8305.8 4018			
	REF: AMM 28-10-31-205	HRS/MSC AFL								
+ 28-10-31-208 (s)	PRESSURE TEST FUEL AND VENT LINE SHROUDS	PKG 34	MOS	60			03-APR-2006 8305.8 4018			
	REF: AMM 28-10-31-208	HRS/MSC AFL								
+ 28-10-31-209 (s)	PRESSURE TEST FUEL AND VENT LINE SHROUDS (POST SB-601-0262 OR A/C 5135 AND SUBS) - TAIL TANK FUEL SHROUD	PKG 34	MOS	60			03-APR-2006 8305.8 4018			
	REF: AMM 28-10-31-209	HRS/MSC AFL								
+ 28-10-31-211 (s)	VISUAL CHECK FUEL AND VENT LINE SHROUDS - OF THE VENT AND DISTRIBUTION SHROUD DRAINS FOR BLOCKAGE AND LEAKAGE	PKG 2	MOS	300			09-SEP-2008 8806.5 4265			
	REF: AMM 28-10-31-211	HRS/MSC AFL								
28-10-36-210 (s)	INSPECTION TAIL TANK VENT SYSTEM (POST SB-601-0262 OR A/C 5135 AND SUBS) - VENT LINE CHECK VALVE	PKG 3	MOS	600			20-MAR-2009 8873.5 4304			
	REF: AMM 28-10-36-210	HRS/MSC AFL								
+ 28-21-11-212	CHECK COLLECTOR TANK FLAPPER CHECK VALVES		MOS	9600			01-OCT-1992 0 0	9600	9645	652.2
	REF: AMM 28-21-11-212	HRS/MSC AFL								
+ 28-21-16-213 (s)	CHECK FIREWALL FUEL SHUTOFF VALVE - INTERNAL LEAKAGE	PKG 6	MOS	2400			31-OCT-2003 7003 3486			
	REF: AMM 28-21-16-213	HRS/MSC AFL								

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
28-21-26-214 (s)	VISUAL CHECK SCAVENGE FUEL EJECTOR - OF PUMP SCREEN PKG 34	MOS	60				PKG 05-APR-2006 8305.8 4018			
	REF: GENERIC NO REF	HRS/MSC AFL								
28-22-00-215 (s)	VISUAL CHECK TAIL TANK FUEL TRANSFER SYSTEM / PRESSURE REFUEL/DEFUEL SYSTEM (POST SB-601-0262 OR A/C 5135 AND SUBS) PKG 3	MOS	600				PKG 20-MAR-2009 8873.5 4304			
	REF: GENERIC NO REF	HRS/MSC AFL								
+ 28-22-00-216 (s)	FUNCTIONAL TEST TAIL TANK FUEL TRANSFER SYSTEM (POST SB-601-0262 OR A/C 5135 AND SUBS) - FUEL TRANSFER PKG 4	MOS	1200				PKG 07-JUN-2005 8180 3964			
	REF: AMM 28-22-00-216	HRS/MSC AFL								
28-22-05-217 (s)	REPLACE TAIL TANK FUEL TRANSFER LINE CHECK VALVE (POST SB-601-0262 OR A/C 5135 AND SUBS) PKG 10	MOS	4800				PKG 21-FEB-2001 4859 2516			
	REF: AMM 28-22-05-217	HRS/MSC AFL								
+ 28-22-11-218 (s)	PRESSURE CHECK ROTOR BURST DETECTION SYSTEM (POST SB-601-0262 OR A/C 5135 AND SUBS) - SHROUD PKG 2	MOS	300				PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 28-22-11-218	HRS/MSC AFL								
+ 28-22-11-219 (s)	FUNCTIONAL TEST ROTOR BURST DETECTION SYSTEM (POST SB-601-0262 OR A/C 5135 AND SUBS) PKG 3	MOS	600				PKG 20-MAR-2009 8873.5 4304			
	REF: AMM 28-22-11-219	HRS/MSC AFL								
+ 28-22-16-220 (s)	CHECK TAIL TANK SYSTEM LEVEL SWITCHES (POST SB-601-0262 OR A/C 5135 AND SUBS) - PERFORM WARNING SYSTEM CHECK BEFORE FUEL OPERATIONAL TEST PKG 2	MOS	300				PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 28-22-16-220	HRS/MSC AFL								
+ 28-22-21-221 (s)	CHECK TAIL TANK SHUTOFF VALVES (POST SB-601-0262 OR A/C 5135 AND SUBS) - SHUTOFF VALVES INTERNAL LEAKAGE PKG 10	MOS	4800				PKG 22-FEB-2001 4859 2516			
	REF: AMM 28-22-21-221	HRS/MSC AFL								

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 28-25-21-222	INTERNAL LEAK TEST APU RETURN LINE CHECK VALVE (A/C 5001 TO 5109)									
		MOS					21-FEB-2001			
		HRS/MSC	N/A				4859			
	REF: See Workcard	AFL					2516			
+ 28-30-11-223 (s)	FUNCTIONAL TEST FUEL JETTISON SYSTEM (POST SB-601-0262 OR A/C 5135 AND SUBS)									
	PKG 2	MOS					09-SEP-2008			
		HRS/MSC	300				8806.5			
	REF: AMM 28-30-11-223	AFL					4265			
282000-001	PRESSURE SWITCH:LEFT MAIN EJECTOR PRESSURE SWITCH									
	12543-3	MOS					01-OCT-1992			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 282011	AFL		TSN:0			0			
282000-002	PRESSURE SWITCH:RIGHT MAIN EJECTOR PRESSURE SWITCH									
	600-59180-3	MOS		TSN:0			24-JUN-1997			
	1354	HRS/MSC	O/C	TSN:0			2589			
	REF: AMM 282011	AFL		TSN:0			1299			
282000-003	PRESSURE SWITCH:LEFT ELECTRONIC BOOST PUMP PRESSURE SWITCH									
	12543-3	MOS					01-OCT-1992			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 282011	AFL					0			
282000-004	PRESSURE SWITCH:RIGHT ELECTRONIC BOOST PUMP PRESSURE SWITCH									
	12543-3	MOS					01-OCT-1992			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 282011	AFL					0			
282101-001	VALVE:NO. 1 FUEL MOTORIZED SHUTOFF VALVE									
	AV16B2082-3	MOS					13-JUL-2000			
	T59036	HRS/MSC	O/C				4407			
	REF: AMM 282101	AFL					2273			
282102-001	PUMP:NO. 1 FUEL TRANSFER EJECTOR PUMP									
	2780473-105	MOS					01-OCT-1992			
	712	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 28-21-21	AFL					0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
282102-002	PUMP:NO. 2 FUEL TRANSFER EJECTOR PUMP 2780473-105 713 REF: AMM 28-21-21	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282103-001	PUMP:NO. 1 FUEL SCAVENGER EJECTOR PUMP 2780472-103 0546 REF: AMM 282103	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282103-002	PUMP:NO. 2 FUEL SCAVENGER EJECTOR PUMP 2780472-103 0557 REF: AMM 282103	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282115-001	VALVE:LEFT FUEL SHUTOFF VALVE 601-62900-1 P13655 REF: AMM 272116	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282115-002	VALVE:RIGHT FUEL SHUTOFF VALVE 601-62900-2 N95955 REF: AMM 272116	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282116-001	VALVE:NO. 1 FUEL SHUTOFF VALVE 601-62900-1 P14754 REF: AMM 282116	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-APR-1993 19 12			
282116-002	VALVE:NO. 2 FUEL SHUTOFF VALVE 13TX0515A SN-UNKNOWN REF: AMM 282116	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282116-003	VALVE:NO. 3 FUEL SHUTOFF VALVE 601-62900-1 P14753 REF: AMM 282116	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-APR-1993 19 12			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
282121-001	PUMP:NO. 1 FUEL EJECTOR PUMP 2780602-105 SN-UNKNOWN REF: AMM 282121	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282121-002	PUMP:NO. 2 FUEL EJECTOR PUMP 2780602-105 SN-UNKNOWN REF: AMM 282121	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282200-002	SWITCH:NO.2 FLOAT - AUX TANK LOW LEVEL SWITCH 86-4086 0103 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-APR-1993 19 12			
282200-003	SWITCH:NO.1 FLOAT - TAIL TANK LOW LEVEL SWITCH 86-4086 0106 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-APR-1993 19 12			
282200-004	SWITCH:NO.2 FLOAT - TAIL TANK LOW LEVEL SWITCH 86-4086 0014 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-APR-1993 19 12			
282200-005	SWITCH:FLOAT - TAIL TANK FULL LEVEL SWITCH 88-5475 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-APR-1993 19 12			
282200-006	SWITCH:NO. 3 FLOAT - TAIL TANK LOW LEVEL SWITCH 86-4086 0175 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-APR-1993 19 12			
282311-001	CARTRIDGE:NO. 1 FUEL PUMP DC CARTRIDGE 600-62991-5 B723 REF: AMM 282311	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
282311-002	CARTRIDGE:NO. 2 FUEL PUMP DC CARTRIDGE 600-62991-5 B724 REF: AMM 282311	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282312-003	CANISTER:TAIL TANK FUEL PUMP DC CANISTER 600-62991-5 B-470 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				09-SEP-1999 3833 1981			
282501-001	VALVE:3-WAY APU FUEL VALVE AV23B1149-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282711-001	VALVE:NO. 1 FUEL VENT - FLOAT VALVE 2780491-121 0912 REF: AMM 282711	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282711-002	VALVE:NO. 2 FUEL VENT - FLOAT VALVE 2780491-121 0894 REF: AMM 282711	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282711-003	VALVE:AUX FUEL VENT VALVE 2780491-121 0895 REF: AMM 282711	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282716-001	VALVE:NO. 1 SHUTOFF VALVE 2760129-101 0883S REF: AMM 282716	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282716-002	VALVE:NO. 2 SHUTOFF VALVE 2760129-101 0887S REF: AMM 282716	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
282716-003	VALVE:AUX SHUTOFF VALVE 2760129-101 0882S REF: AMM 282716	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282726-001	VALVE:NO. 1 TRANSFER FLOAT VALVE 2810007-101 559 REF: AMM 282726	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282726-002	VALVE:NO. 2 TRANSFER FLOAT VALVE 2810007-101 573 REF: AMM 282726	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282726-003	VALVE:AUX FLOAT VALVE 2760131-103 0621 REF: AMM 282726	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282727-001	VALVE:NO. 1 MAIN TANK FLOAT LEVEL CONTROL VALVE 2840000-102 593A REF: AMM 28-27-26	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
282727-002	VALVE:NO. 2 MAIN TANK FLOAT LEVEL CONTROL VALVE 2840000-102 604A REF: AMM 28-27-26	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
284000-001	TRANSMITTER:LEFT NO.1 FUEL QUANTITY TRANSMITTER 391002-332 086C REF: AMM 284000	MOS HRS/MSC AFL	O/C				16-DEC-1993 469 241			
284000-002	TRANSMITTER:RIGHT NO. 1 FUEL QUANTITY TRANSMITTER 391002-332 SN-UNKNOWN REF: AMM 284000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
284001-001	TRANSMITTER:LEFT NO.2 FUEL QUANTITY TRANSMITTER 391002-333 SN-UNKNOWN REF: AMM 284000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
284001-002	TRANSMITTER:RIGHT NO. 2 FUEL QUANTITY TRANSMITTER 391002-333 SN-UNKNOWN REF: AMM 284000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
284003-001	TRANSMITTER:LEFT NO.3 FUEL QUANTITY TRANSMITTER 391002-334 386F REF: AMM 284000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-1993 469 241			
284003-002	TRANSMITTER:RIGHT NO. 3 FUEL QUANTITY TRANSMITTER 391002-334 249F REF: AMM 284000	MOS HRS/MSC AFL	O/C				16-DEC-1993 469 241			
284004-001	TRANSMITTER:LEFT NO.4 FUEL QUANTITY TRANSMITTER 391002-418 SN-UNKNOWN REF: AMM 284000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
284004-002	TRANSMITTER:RIGHT NO. 4 FUEL QUANTITY TRANSMITTER 391002-418 SN-UNKNOWN REF: AMM 284000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
284005-001	TRANSMITTER:LEFT NO.5 FUEL QUANTITY TRANSMITTER 391002-419 SN-UNKNOWN REF: AMM 284000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
284005-002	TRANSMITTER:RIGHT NO. 5 FUEL QUANTITY TRANSMITTER 391002-419 SN-UNKNOWN REF: AMM 284000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
284006-001	TRANSMITTER:LEFT NO.6 FUEL QUANTITY TRANSMITTER 391002-420 SN-UNKNOWN REF: AMM 284000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
284006-002	TRANSMITTER:RIGHT NO.6 FUEL QUANTITY TRANSMITTER 391002-420 SN-UNKNOWN REF: AMM 284000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
284008-001	TRANSMITTER:NO. 1 AUX FUEL QUANTITY TRANSMITTER 391002-421 SN-UNKNOWN REF: AMM 284000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
284008-002	TRANSMITTER:NO. 2 AUX FUEL QUANTITY TRANSMITTER 391002-422 SN-UNKNOWN REF: AMM 284000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
284009-001	TRANSMITTER:FUEL QUANTITY TRANSMITTER 391002-438 009 REF: AMM 284000	MOS HRS/MSC AFL	O/C				28-AUG-1999 3812 1968			
284010-001	TRANSMITTER:NO. 1 FUEL QUANTITY TRANSMITTER 391057-297 SN-UNKNOWN REF: AMM 284000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
284010-002	TRANSMITTER:NO. 2 FUEL QUANTITY TRANSMITTER 391057-297 SN-UNKNOWN REF: AMM 284000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
284013-001	CONDITIONER:SIGNAL CONDITIONER 473382 404F REF: AMM 284013	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
284014-001	INDICATOR:FUEL QUANTITY INDICATOR 601-50921-1 523 REF: AMM 284014	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0				01-APR-1993 19 12		
284015-001	PROBE:AFT FUEL TANK (TAIL) PROBE 391002-446 089 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0				01-APR-1993 19 12		
285016	VALVE:TAIL TANK FUEL DUMP VALVE AV16B2178 N94558 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0				01-APR-1993 19 12		
285071	SHUTOFF VALVE:TAIL TANK AFT REFUEL/DEFUEL SHUTOFF VALVE 601-62900-1 P14755 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0				01-APR-1993 19 12		
285081	SHUTOFF VALVE:TAIL TANK FUEL TRANSFER SHUTOFF VALVE 601-62900-1 P14769 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0				01-APR-1993 19 12		
285126	CONDITIONER:TAIL TANK FUEL QUANTITY CONDITIONER 473382-01 140 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0				01-APR-1993 19 12		
285146	SWITCH:TAIL TANK NO.1 EMPTY LEVEL SWITCH 601-62157-1 1189 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		07/13/2001		13-JUL-2000 4407 2273		
285156	SWITCH:TAIL TANK NO.3 EMPTY LEVEL SWITCH 601-62157-1 1150 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		11/15/2001		15-NOV-2000 4682 2423		

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
288011	SWITCH:RIGHT SCAVENGE EJECTOR SWITCH 601R62292-7 144 REF:	MOS HRS/MSC AFL	O/C				05-APR-2002 5673 2899			
289051	LINE:FUEL XFER ROTORBURST LINE 601-62118-23 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			26-OCT-1994 901 448			
289511	CANISTER:FUEL PUMP T/TANK CANISTER RR54615A B651 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-APR-1993 19 12			
289516	TANK:FUEL TAIL CONE TANK 601-21001-1001/1 0078 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-APR-1993 19 12			
289521	SWITCH:ROTORBURST T/TANK SWITCH 601-62118-21 0877 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-APR-1993 19 12			
289526	VALVE:RAM AIR CK T/TANK VALVE 7F2R-200000 087 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-APR-1993 19 12			
289531	VALVE:FLOW SENSOR T/TANK VALVE 601-62910-3 032 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-APR-1993 19 12			
289536	PUMP:BACKUP T/TANK PUMP 3B7-4 8AG182 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-APR-1993 19 12			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
28R001	PANEL:REFUEL CONTROL PANEL 444-2252-105 NSN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
28R006	RELAY BOX:REFUEL SYSTEM RELAY BOX 444-2253-103 020 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
T28T01	DEFUEL , DRAINING AND PURGE REF:	MOS HRS/MSC AFL	O/C							
T28T02	FUEL SYSTEM QUANTITY CHECK REF:	MOS HRS/MSC AFL	O/C							
CHAPTER 29 HYDRAULIC POWER										
29-00-00-201 (s)	CHECK HYDRAULIC POWER - FILTER DIFFERENTIAL PRESSURE INDICATORS ON THE FOLLOWING: (7) CASE DRAIN FILTERS - NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEMS (6 LOCATIONS). (8) PRESSURE AND RETURN MANIFOLD FILTERS - NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEMS (6 LOCATIONS). PKG 2 REF: AMM 29-00-00-201	MOS HRS/MSC AFL	300				09-SEP-2008 8806.5 4265			
+ 29-00-00-202 (s)	INTERNAL LEAKAGE CHECK HYDRAULIC POWER PKG 3 REF: AMM 29-00-00-202	MOS HRS/MSC AFL	600				20-MAR-2009 8873.5 4304			
+ 29-00-00-301 (s)	CHECK HYDRAULIC FLUID ACIDITY PKG 32 REF: AMM 29-00-00-301	MOS HRS/MSC AFL	24				28-MAY-2009 8928.6 4336			
+ 29-10-00-204 (s)	FUNCTIONAL TEST MAIN SYSTEMS - OF RESERVOIR - MOUNTED RETURN LINE CHECK VALVE PKG 4 REF: AMM 29-10-00-204	MOS HRS/MSC AFL	1200				09-JUN-2005 8180 3964			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 29-10-00-205 (s)	BENCH CHECK MAIN SYSTEMS - REMOVE NO. 1 AND NO. 2 SYSTEM HYDRAULIC RESERVOIR IN-LINE CHECK VALVES FOR BENCH CHECK OR INSTALL NEW VALVES PKG 10 REF: See Workcard	MOS HRS/MSC AFL	4800				01-MAR-2001 4859 2516			
+ 29-10-00-206 (s)	BENCH CHECK MAIN SYSTEMS - REMOVE NO. 3 SYSTEM HYDRAULIC RESERVOIR IN-LINE CHECK VALVE FOR BENCH CHECK OR INSTALL NEW VALVE PKG 10 REF: See Workcard	MOS HRS/MSC AFL	4800				01-MAR-2001 4859 2516			
+ 29-11-31-208 (s)	CHECK CASE DRAIN FILTER - FILTER ELEMENT IN NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEMS (6 LOCATIONS) PKG 4 REF: AMM 29-11-31-208	MOS HRS/MSC AFL	1200				09-JUN-2005 8180 3964			
+ 29-11-36-209 (s)	CHECK PRESSURE MANIFOLD - FILTER ELEMENT IN NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEMS (3 LOCATIONS) PKG 4 REF: AMM 29-11-36-209	MOS HRS/MSC AFL	1200				07-JUN-2005 8180 3964			
+ 29-11-41-210 (s)	CHECK RETURN MANIFOLD - FILTER ELEMENT IN NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEMS (3 LOCATIONS) PKG 4 REF: AMM 29-11-41-210	MOS HRS/MSC AFL	1200				09-JUN-2005 8180 3964			
29-11-51-211 (s)	VISUAL CHECK HEAT EXCHANGER, PAYING PARTICULAR ATTENTION TO SECURITY OF ATTACHMENT PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	600				20-MAR-2009 8873.5 4304			
+ 29-13-00-212 (s)	VISUAL CHECK NO. 3 MAIN SYSTEM - PUMP INSTALLATION AREAS FOR CONTAMINATION BY HYDRAULIC FLUID PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	600				20-MAR-2009 8873.5 4304			
291000-001	MOTOR:NO. 1 HYDRAULIC PUMP MOTOR 9008D15-2 XB529 REF: AMM 291000	MOS HRS/MSC AFL	O/C				15-FEB-2005 7924 3845			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
291000-002	MOTOR:NO. 2 HYDRAULIC PUMP MOTOR 9008D15-2 WM2000 REF: AMM 291000	MOS HRS/MSC AFL	O/C				12-MAR-2004 7316 3614			
291000-003	MOTOR:LEFT NO. 3 HYDRAULIC PUMP MOTOR 62613 SN-UNKNOWN REF: AMM 291000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
291000-004	MOTOR:RIGHT NO. 3 HYDRAULIC PUMP MOTOR 63108-06 255779 REF: AMM 291000	MOS HRS/MSC AFL	O/C				09-MAR-2001 4859 2516			
291004-001	PUMP:NO. 1 HYDRAULIC PUMP 63108-04 270139 REF: AMM 29-11-16	MOS HRS/MSC AFL	O/C				12-MAR-2004 7316 3614			
291004-002	PUMP:NO. 2 HYDRAULIC PUMP 63108-04 270079 REF: AMM 29-11-16	MOS HRS/MSC AFL	O/C	TSO:3 TSO:277 TSO:108			12-MAR-2004 7316 3614			
291004-003	PUMP:LEFT NO. 3 HYDRAULIC PUMP 63108-03 SN-UNKNOWN REF: AMM 29-11-16	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
291004-004	PUMP:RIGHT NO. 3 HYDRAULIC PUMP 63108-06 251635 REF: AMM 29-11-16	MOS HRS/MSC AFL	O/C				11-APR-2001 4901 2526			
291105-001	GAUGE:NO. 1 AIR PRESSURE INDICATOR GAUGE 600-75125-3 3060528 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-SEP-2004 7621 3730			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
291105-002	GAUGE:NO. 2 AIR PRESSURE INDICATOR GAUGE 600-75125-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
291105-003	GAUGE:NO. 3 AIR PRESSURE INDICATOR GAUGE 600-75125-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
291111-001	PUMP:NO. 1 HYDRAULIC PUMP 601-75100-5 MX-536640A REF: AMM 291111	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			12-NOV-2002 6179 3137			
291111-002	PUMP:NO. 2 HYDRAULIC PUMP 601-75100-5 MX387936A REF: AMM 291111	MOS HRS/MSC AFL	O/C				03-JUN-2003 6624 3318			
291121-001	VALVE:NO. 1 HYDRAULIC SHUTOFF VALVE AV16B2069B2 N91207 REF: AMM 291121	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
291121-002	VALVE:NO. 2 MOTORIZED SHUTOFF VALVE AV16B2069B2 N91208 REF: AMM 291121	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
291126-001	RESERVOIR ASSEMBLY:NO. 1 HYDRAULIC RESERVOIR ASSEMBLY 600-75112-9 313A REF: AMM 291126	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
291126-002	RESERVOIR ASSEMBLY:NO. 2 HYDRAULIC RESERVOIR ASSEMBLY 600-75112-11 301A REF: AMM 291126	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
291146-001	ACCUMULATOR:NO. 1 HYDRAULIC SYSTEM ACCUMULATOR 2770571-103 EFS-0906A REF: AMM 291146	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			15-SEP-2004 7614 3726			
291146-002	ACCUMULATOR:NO. 2 HYDRAULIC SYSTEM ACCUMULATOR 2770571-103 1183A REF: AMM 291146	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
291151-001	EXCHANGER:NO. 1/NO. 2 HEAT HYDRAULIC FLUID EXCHANGER 600-75122-7 3G950073 REF: AMM 291151	MOS HRS/MSC AFL	O/C				26-FEB-2001 4859 2516			
291166	RESERVOIR:NO. 3 HYDRAULIC SYSTEM HYDRAULIC RESERVOIR 600-75111-5 192A REF:	MOS HRS/MSC AFL	O/C				02-MAR-2001 4859 2516			
291291	FILTER:NO. 3 RIGHT HYDRAULIC SYSTEM ACOUSTIC FILTER 206001-003 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				01-OCT-1992 0 0			
291300-001	VALVE:NO. 1 RELIEF VALVE 600-75111-7 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
291300-002	VALVE:NO. 2 RELIEF VALVE 600-75111-7 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
291300-003	VALVE:NO. 3 RELIEF VALVE 600-75111-7 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
291311-003	FILTER:NO. 3 ACOUSTIC FILTER 206001-003 SN-UNKNOWN REF: AMM 291311	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
291326-001	ACCUMULATOR:NO. 3 HYDRAULIC SYSTEM ACCUMULATOR 2770571-105 0246A REF: AMM 291326	MOS HRS/MSC AFL	O/C	TSN:1640 TSN:655			25-JUN-1996 1934 971			
293100-001	INDICATOR:NO. 1 HYDRAULIC PRESSURE INDICATOR 600-50932-3 92040882 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
293100-002	INDICATOR:NO. 2 HYDRAULIC PRESSURE INDICATOR 600-50932-3 92040881 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
293100-003	INDICATOR:NO. 3 HYDRAULIC PRESSURE INDICATOR 600-50932-3 92040880 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
293101-001	TRANSDUCER:NO. 1 PRESSURE SYSTEM TRANSDUCER 600-59101-1 4053-1-131 REF: AMM 293101	MOS HRS/MSC AFL	O/C	TSN:808 TSN:401			02-SEP-1994 808 401			
293101-002	TRANSDUCER:NO. 2 PRESSURE TRANSDUCER 600-59101-1 4123-7-116 REF: AMM 293101	MOS HRS/MSC AFL	O/C	TSN:808 TSN:401			02-SEP-1994 808 401			
293101-003	TRANSDUCER:NO. 3 PRESSURE SYSTEM TRANSDUCER 600-59101-1 4138-2-103 REF: AMM 293101	MOS HRS/MSC AFL	O/C	TSN:808 TSN:401			02-SEP-1994 808 401			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
293300-001	INDICATOR:NO. 1 HYDRAULIC QUANTITY INDICATOR 600-50931-3 92040861 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
293300-002	INDICATOR:NO. 2 HYDRAULIC QUANTITY INDICATOR 600-50931-3 92070888 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
293300-003	INDICATOR:NO. 3 HYDRAULIC QUANTITY INDICATOR 600-50931-3 92040868 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
299003	---SW,PRESS EDP SYS NO2 600-59134-1 1334 REF:	MOS HRS/MSC AFL	N/R				04-MAY-2001 4941 2543			
299031	SWITCH:LOW PRESSURE #3 SWITCH 600-59134-1 3318 REF:	MOS HRS/MSC AFL	O/C				08-JAN-2002 5454 2794			
29R001	OPERATIONAL TEST NO. 1 & NO. 2 HYDAULIC SYSTEM FAN REF:	MOS HRS/MSC AFL	300				09-SEP-2008 8806.5 4265	9106.5		158.7
29R021	MANIFOLD ASSY:#1 HYD PRES MANIFOLD ASSY 600-75138-9 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
29R023	MANIFOLD ASSY:#2 HYD PRES MANIFOLD ASSY 600-75138-9 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
29R025	MANIFOLD ASSY:#3 HYD PRES MANIFOLD ASSY 600-75138-9 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
29R041	--:IND ASSY,#1 HYD FLUID LVL 9416-5 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
29R043	--:IND ASSY,#2 HYD FLUID LVL 9416-5 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
29R044	--:IND ASSY, #3 HYD FLUID 9416-5 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			
29R051	--:CK VLV,#1A HYD PRESS ACA358-1D71 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
29R053	--:CK VLV,#1B HYD PRESS ACA358-1D71 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
29R055	--:CK VLV,#2A HYD PRESS ACA358-1D71 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
29R057	--:CK VLV,#2B HYD PRESS ACA358-1D71 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
29R059	--:CK VLV,#3A HYD PRESS ACA358-1D71 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
29R061	--:CK VLV,#3B HYD PRESS ACA358-1D71 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
T29T01	HYDRAULIC SYSTEM MAINTENANCE PRACTICES REF:	MOS HRS/MSC AFL	O/C							
T29T02	OPERATIONAL TEST - MAIN SYSTEMS REF:	MOS HRS/MSC AFL	O/C							
CHAPTER 30 ICE AND RAIN PROTECTION										
+ 30-11-00-201 (s)	CONDITION CHECK WING ANTI-ICING - CHECK VALVE PKG 6 REF: AMM 30-11-00-201	MOS HRS/MSC AFL	2400				PKG 28-OCT-2003 7003 3486			
+ 30-11-00-202	FUNCTIONAL TEST WING ANTI-ICING REF: AMM 30-11-00-202	MOS HRS/MSC AFL	9600				01-OCT-1992 0 0	9600	9645	652.2
30-11-06-204 (s)	VISUAL CHECK WING ANTI-ICING DUCTING - OF DUCTS, BRACKETS, CLAMPS AND ASSOCIATED WIRING, UNDERFLOOR AND IN WING LEADING EDGE PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG 03-APR-2006 8305.8 4018			
30-11-06-211 (s)	DETAILED INSPECTION WING ANTI-ICE COUPLING (A/C 5001 TO 5153, PRE SB-601-0433) - OF THE WING ANTI-ICE EXPANSION COUPLING BEARINGS PKG 3 REF: AMM 30-11-06-211	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 30-13-00-205	FUNCTIONAL TEST ANTI-ICING BLEED AIR LEAK DETECTION THERMAL SWITCHES	MOS	120	TSI:0	1		21-FEB-2001 4859 2516	21-MAR-2011	20-MAY-2011	195 d
	REF: AMM 30-13-00-205	HRS/MSC AFL								
30-20-21-206 (s)	VISUAL CHECK NOSE COWL ANTI-ICE / THRUST REVERSER DUCTING	MOS	300				PKG 09-SEP-2008 8806.5 4265			
	PKG 2	HRS/MSC AFL								
	REF: GENERIC NO REF									
30-40-00-213	FUNCTIONAL TEST WINDSHIELD RAIN REPELLANT LAYER	MOS	N/A				01-OCT-1992 0 0			
	REF: AMM 30-40-00-213	HRS/MSC AFL								
+ 30-41-00-209 (s)	FUNCTIONAL TEST ELECTRICAL ANTI-ICING - OF HEATING ELEMENT - OF SENSORS	MOS	1200				PKG 07-JUN-2005 8180 3964			
	PKG 4	HRS/MSC AFL								
	REF: AMM 30-41-00-209									
+ 30-41-16-210 (s)	TEST VARISTOR SUPPRESSOR - NOMINAL VARISTOR VOLTAGE TEST - DC STANDBY CURRENT TEST	MOS	1200				PKG 10-JUN-2005 8180 3964			
	PKG 4	HRS/MSC AFL								
	REF: SMM 30-40-01									
301000-001	CONTROLLER:ANTI-ICE CONTROLLER	MOS	O/C	TSN:0			01-OCT-1992 0 0			
	624382-2	HRS/MSC AFL								
	071C316									
	REF: AMM 301000									
301011-001	VALVE:NO. 1 MODULATING/SHUTOFF VALVE	MOS	O/C	TSN:0			01-OCT-1992 0 0			
	3214442-4	HRS/MSC AFL								
	479									
	REF: AMM 301011									
301011-002	VALVE:NO. 2 MODULATING/SHUTOFF VALVE	MOS	O/C	TSN:0			01-OCT-1992 0 0			
	3214442-4	HRS/MSC AFL								
	581									
	REF: AMM 301011									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
302001-001	VALVE:NO. 1 OVER PRESSURE RELIEF VALVE 228-56480-109 SN-UNKNOWN REF: AMM 302001	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-DEC-1993 468 240			
302001-002	VALVE:NO. 2 OVER PRESSURE RELIEF VALVE 228-56480-103 SN-UNKNOWN REF: AMM 302001	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
302011-001	VALVE:NO. 1 COWL ANTI-ICE VALVE 734027B 0658 REF: AMM 302011	MOS HRS/MSC AFL	O/C				11-MAR-1994 581 284			
302011-002	VALVE:NO. 2 COWL ANTI-ICE VALVE 734027B 0538 REF: AMM 302011	MOS HRS/MSC AFL	O/C				10-FEB-1994 555 272			
302016-001	SWITCH:NO. 1 COWL ANTI-ICE PRESSURE SWITCH 12681 SN-UNKNOWN REF: AMM 302016	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
302016-002	SWITCH:NO. 2 COWL ANTI-ICE PRESSURE SWITCH 12681 SN-UNKNOWN REF: AMM 302016	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
303000-001	PANEL:ADS HEATER CONTROL PANEL 600-50950-9 SN-UNKNOWN REF: AMM 303000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
304101-001	CONTROLLER:NO. 1 WINDSHIELD TEMPERATURE CONTROLLER 600-59100-9 680A REF: AMM 304101	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING	
304101-002	CONTROLLER:NO. 2 WINDSHIELD TEMPERATURE CONTROLLER 600-59100-9 673A REF: AMM 304101	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0				
304102-001	CONTROLLER:NO. 1 SIDE WINDOW TEMPERATURE CONTROLLER 600-59100-13 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0				
304102-002	CONTROLLER:NO. 2 SIDE WINDOW TEMPERATURE CONTROLLER 600-59100-13 SN-UNKNOWN REF: CMM CMM 32-40-94	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0				
308000-001	DETECTOR:NO. 1 ICE DETECTOR 871BN3-2 3031 REF: AMM 308000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0				
308000-002	DETECTOR:NO. 2 ICE DETECTOR 871BN3-2 2257 REF: AMM 308000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0				
30R001	ELEMENT:L 14 STG BLD OVHT ELEMENT 35602-4-310 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0				
30R006	ELEMENT:R 14 STG BLD OVHT ELEMENT 35602-4-310 NONE REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0		05/20/2006	20-MAY-2005 8162 3955				
CHAPTER 31 INDICATING/RECORDING SYSTEMS											
+ 31-51-00-201 (s)	OPERATIONAL TEST AURAL WARNING SYSTEM - FIRE DETECTION WARNING (BELL) - AND FUNCTIONAL TEST (1) LANDING GEAR WARNING (HORN) (2) TAKE-OFF CONFIGURATION (TOC) WARNING (INTERMITTENT HORN)						PKG				
	PKG 3	MOS					20-MAR-2009				
	REF: AMM 31-51-00-201	HRS/MSC AFL	600				8873.5 4304				

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 31-51-00-202 (s)	FUNCTIONAL TEST AURAL WARNING SYSTEM PKG 32 REF: AMM 31-51-00-202	MOS HRS/MSC AFL	24				PKG 28-MAY-2009 8928.6 4336			
315100-001	UNIT:AURAL WARNING UNIT 529-6 0322 REF: AMM 315100	MOS HRS/MSC AFL	O/C				02-NOV-2001 5318 2232			
315101-001	PANEL:AURAL WARNING TEST PANEL 530-5 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
315300-001	BOX:CIRCUIT BREAKER BOX 70-0197-3 0367 REF: AMM 315300	MOS HRS/MSC AFL	O/C				03-JUN-1993 117 66			
315301-001	PANEL:10-CHANNEL MASTER WARNING CAUTION PANEL 843346-5 357 REF: AMM 31-53-00	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
315302-001	PANEL:08-CHANNEL MASTER WARNING CAUTION PANEL 843347-3 347 REF: AMM 31-53-00	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
315303-001	MODULE ASSEMBLY:NO. 1 DIMMING MODULE ASSEMBLY 846199-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
315303-002	MODULE ASSEMBLY:NO. 2 DIMMING MODULE ASSEMBLY 846199-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
319001	RECORDER:FLIGHT DATA RECORDER S603-1000-00 00329 REF:	MOS HRS/MSC AFL	N/R	TSR:0 TSR:0			05-APR-2006 8305.8 4018			
319006	ACCELEROMETER:FDR ACCELEROMETER 17A471-02 00169 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
319019	BATTERY:FDR ULD BATTERY DK120 DP2480 REF:	MOS HRS/MSC AFL	O/C				14-APR-2004 7386 3636			
319021	BATTERY:REPLACE FDR ULD BATTERY REF:	MOS HRS/MSC AFL	DUE				19-JUL-2010 8947.8 4353	01-MAR-2016 M		2002 d
319025	ENCODER:FDR TRIP/DATE ENCODER 17A156250 04130 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
T31T01	TEST AURAL WARNING SYSTEM REF:	MOS HRS/MSC AFL	O/C							
CHAPTER 32 LANDING GEAR										
32-00-00-245	RESTORATION EXTENSION AND RETRACTION - MAIN LANDING GEAR SELECTOR VALVE (PART NO. 61750-1) REF: GENERIC NO REF	DAYS HRS/MSC AFL	15000				01-OCT-1992 0 0	15000	15060	10647
+ 32-05-11-201 (s)	FUNCTIONAL TEST WEIGHT-ON-WHEELS PKG 3 REF: AMM 32-05-11-201	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
32-10-00-210 (s)	VISUAL CHECK MAIN GEAR AND DOORS/MAIN LANDING GEAR UPLOCK /EMERGENCY EXTENSION PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: NDT VC-32-10-01									
+ 32-10-00-237	DETAILED INSPECTION MAIN LANDING GEAR ASSEMBLY PKG 34	MOS HRS/MSC AFL	60				18-AUG-2006 8378.1 4055	18-AUG-2011	17-OCT-2011	345 d
	REF: AMM 32-10-00-237									
+ 32-10-00-238	RESTORATION MAIN LANDING GEAR ASSEMBLY	MOS HRS/MSC AFL	120				22-MAR-2001 4859 2516	22-MAR-2011	21-MAY-2011	196 d
	REF: AMM 32-10-00-238									
32-10-00-241 (s)	LUBRICATE MAIN LANDING GEAR PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 32-10-00-241									
+ 32-10-36-204 (s)	CHECK MAIN GEAR TRAILING ARM - TRANSVERSE SHEAR BOLT PKG 30	MOS HRS/MSC AFL	12				PKG 19-JUL-2010 8947.8 4353			
	REF: AMM 32-10-36-204									
32-20-00-205 (s)	VISUAL CHECK NOSE GEAR AND DOORS PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: NDT VC-32-20-01									
+ 32-20-00-239	DETAILED INSPECTION NOSE LANDING GEAR ASSEMBLY PKG 34	MOS HRS/MSC AFL	60				18-AUG-2006 8378.1 4055	18-AUG-2011	17-OCT-2011	345 d
	REF: AMM 32-20-00-239									
+ 32-20-00-240	RESTORATION NOSE LANDING GEAR ASSEMBLY	MOS HRS/MSC AFL	120				22-MAR-2001 4859 2516	22-MAR-2011	21-MAY-2011	196 d
	REF: AMM 32-20-00-240									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
32-20-00-242 (s)	LUBRICATE NOSE LANDING GEAR PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 32-20-00-242									
+ 32-30-00-207 (s)	FUNCTIONAL TEST LANDING GEAR RETRACTION SYSTEM - LANDING GEAR EXTENSION SYSTEM PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: AMM 32-30-00-207									
+ 32-30-00-208 (s)	CHECK EXTENSION AND RETRACTION - LANDING GEAR CONTROL UNIT - CHECK FOR ZERO OUTPUT TO SELECTOR VALVES PKG 4	MOS HRS/MSC AFL	1200				PKG 06-JUN-2005 8180 3964			
	REF: AMM 32-30-00-208									
+ 32-30-00-209 (s)	FUNCTIONAL TEST EXTENSION AND RETRACTION - PRIORITY VALVES PKG 6	MOS HRS/MSC AFL	2400				PKG 07-NOV-2003 7003 3486			
	REF: AMM 32-30-00-209									
32-30-26-206 (s)	VISUAL CHECK NOSE GEAR DRAG BRACE PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: GENERIC NO REF									
32-30-51-211 (s)	VISUAL CHECK NOSE LANDING GEAR UPLOCK PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: GENERIC NO REF									
+ 32-35-00-212 (s)	FUNCTIONAL TEST EMERGENCY EXTENSION PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: AMM 32-35-00-212									
32-35-00-243 (s)	VISUAL CHECK EMERGENCY EXTENSION PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: GENERIC NO REF									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 32-35-00-244 (s)	VISUAL CHECK EMERGENCY EXTENSION PKG 34	MOS HRS/MSC AFL	60				PKG 03-APR-2006 8305.8 4018			
	REF: GENERIC NO REF									
32-43-11-220	CHECK MAIN WHEEL BRAKE CHANNEL REF: AMM 32-43-11-220	MOS HRS/MSC AFL	W/C				13-SEP-2007 8590 4155			
+ 32-43-16-222 (s)	CHECK ACCUMULATOR CHARGE PRESSURE (BRAKE ACCUMULATORS ONLY) PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: AMM 32-43-16-222									
32-43-16-223 (s)	VISUAL CHECK NO. 2 AND NO. 3 SYSTEM BRAKE ACCUMULATORS PKG 34	MOS HRS/MSC AFL	60				PKG 05-APR-2006 8305.8 4018			
	REF: GENERIC NO REF									
32-43-21-216 (s)	VISUAL CHECK DUAL BRAKE CONTROL VALVE ASSEMBLY - VISIBLE PORTIONS OF BRAKE PLUNGERS, ALL LINKAGES AND PUSH-PULL CABLES FORWARD OF PRESSURE BULKHEAD (FS 202.75) PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: GENERIC NO REF									
+ 32-43-21-221 (s)	CHECK DUAL BRAKE CONTROL VALVE ASSEMBLY - BRAKE PRESSURE DECAY PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: AMM 32-43-21-221									
32-45-11-217 (s)	VISUAL CHECK PARKING BRAKE CONTROL CABLE ASSEMBLY / PILOTS AND CO-PILOTS PUSH PULL BRAKE CABLES - OF INPUT MECHANISM TO BRAKE CONTROL VALVE AFT OF PRESSURE BULKHEAD FS 202.75 PKG 3	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
	REF: GENERIC NO REF									
+ 32-45-31-224 (s)	FUNCTIONAL TEST PARKING BRAKE SHUT-OFF VALVE PKG 6	MOS HRS/MSC AFL	2400				PKG 07-NOV-2003 7003 3486			
	REF: AMM 32-45-31-224									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 32-47-00-225 (s)	OPERATIONAL TEST ANTI-SKID SYSTEM PKG 3 REF: AMM 32-47-00-225	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
+ 32-50-00-226 (s)	FUNCTIONAL TEST NOSEWHEEL STEERING SELECTOR & ARMING VALVES PKG 2 REF: AMM 32-50-00-226	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
+ 32-50-00-236 (s)	FUNCTIONAL TEST NOSEWHEEL STEERING - OF ELECTRONIC CONTROL MODULE (PART NO. 601-86100-9/-13, VENDOR PART NO. 7040-11/-13/-15) PKG 3 REF: AMM 32-50-00-236	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
32-70-00-203 (s)	VISUAL CHECK GRAVEL RUNWAY PROTECTION (POST SB-601-0112) PKG 2 REF: GENERIC NO REF	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
321011-001	PIN:NO. 1 MLG SHOCK STRUT LOWER PIN 6232-1 SN-UNKNOWN REF: AMM 321011	MOS HRS/MSC AFL	50000	TSN:0 TSN:0			01-OCT-1992 0 0	50000	45647	LIFE LIMIT
321011-002	PIN:NO. 2 MLG SHOCK STRUT LOWER PIN 6232-1 SN-UNKNOWN REF: AMM 321011	MOS HRS/MSC AFL	50000	TSN:0 TSN:0			01-OCT-1992 0 0	50000	45647	LIFE LIMIT
321012-001	PIN:NO. 1 MLG SHOCK STRUT UPPER PIN 6232-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	50341	TSN:0 TSN:0			01-OCT-1992 0 0	50341	45988	LIFE LIMIT
321012-002	PIN:NO. 2 MLG SHOCK STRUT UPPER PIN 6232-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	50341	TSN:0 TSN:0			01-OCT-1992 0 0	50341	45988	LIFE LIMIT

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
321013-001	CYLINDER:NO. 1 MLG SHOCK STRUT CYLINDER 6216-1 SN-UNKNOWN REF: AMM 32-10-11	MOS HRS/MSC AFL	50000	TSN:0 TSN:0			01-OCT-1992 0 0	50000	45647	LIFE LIMIT
321013-002	CYLINDER:NO. 2 MLG SHOCK STRUT CYLINDER 6216-1 SN-UNKNOWN REF: AMM 32-10-11	MOS HRS/MSC AFL	50000	TSN:0 TSN:0			01-OCT-1992 0 0	50000	45647	LIFE LIMIT
321040-001	AXLE:NO. 1 MLG AXLE 6433-1 DCL546 REF: AMM 321040	MOS HRS/MSC AFL	50000	TSN:6785.33 TSN:3483			18-AUG-2006 8248 4053	50570	46217	LIFE LIMIT
321040-002	AXLE:NO. 2 MLG AXLE 6433-1 DCL294 REF: AMM 321040	MOS HRS/MSC AFL	50000	TSN:4274.5 TSN:2148			18-AUG-2006 8248 4053	51905	47552	LIFE LIMIT
321700-001	PISTON:NO. 1 MLG SHOCK STRUT PISTON 6226-3 SN-UNKNOWN REF: AMM 32-10-11	MOS HRS/MSC AFL	50000	TSN:0 TSN:0			01-OCT-1992 0 0	50000	45647	LIFE LIMIT
321700-002	PISTON:NO. 2 MLG SHOCK STRUT PISTON 6226-3 SN-UNKNOWN REF: AMM 32-10-11	MOS HRS/MSC AFL	50000	TSN:0 TSN:0			01-OCT-1992 0 0	50000	45647	LIFE LIMIT
321701-001	ARM:NO. 1 MLG TRAILING ARM 6416-1 SN-UNKNOWN REF: AMM 321701	MOS HRS/MSC AFL	50000	TSN:0 TSN:0			01-OCT-1992 0 0	50000	45647	LIFE LIMIT
321701-002	ARM:NO. 2 MLG TRAILING ARM 6416-1 SN-UNKNOWN REF: AMM 321701	MOS HRS/MSC AFL	50000	TSN:0 TSN:0			01-OCT-1992 0 0	50000	45647	LIFE LIMIT

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
321744-001	FITTING:NO. 1 MLG FITTING 6316-7 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	46126	TSN:0 TSN:0			01-OCT-1992 0 0	46126	41773	LIFE LIMIT
321744-002	FITTING:NO. 2 MLG FITTING 6316-8 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	46126	TSN:0 TSN:0			01-OCT-1992 0 0	46126	41773	LIFE LIMIT
321754-001	PIN:NO. 1 MLG PINTLE PIN 6324-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	47734	TSN:0 TSN:0			01-OCT-1992 0 0	47734	43381	LIFE LIMIT
321754-002	PIN:NO. 2 MLG PINTLE PIN 6324-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	47734	TSN:0 TSN:0			01-OCT-1992 0 0	47734	43381	LIFE LIMIT
321756-001	PIN:NO. 1 MLG PIVOT PIN 6329-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	50000	TSN:0 TSN:0			01-OCT-1992 0 0	50000	45647	LIFE LIMIT
321756-002	PIN:NO. 2 MLG PIVOT PIN 6329-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	50000	TSN:0 TSN:0			01-OCT-1992 0 0	50000	45647	LIFE LIMIT
321758-001	STUD:NO. 1 MLG DOOR STUD 6349-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	50000	TSN:0 TSN:0			01-OCT-1992 0 0	50000	45647	LIFE LIMIT
321758-002	STUD:NO. 2 MLG DOOR STUD 6349-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	50000	TSN:0 TSN:0			01-OCT-1992 0 0	50000	45647	LIFE LIMIT

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
321759-001	PIN:NO. 1 MLG SIDE STAY PIN 6318-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	43611	TSN:0 TSN:0			01-OCT-1992 0 0	43611	39258	LIFE LIMIT
321759-002	PIN:NO. 2 MLG SIDE STAY PIN 6318-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	43611	TSN:0 TSN:0			01-OCT-1992 0 0	43611	39258	LIFE LIMIT
322012-001	MAIN FITTING:NLG MAIN FITTING 200811310 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	14100	TSN:0			0	14100	9747	LIFE LIMIT
322013-001	FITTING:NLG AXLE FITTING 200811218 DCL516 REF: GENERIC NO REF	MOS HRS/MSC AFL	19480	TSN:3883.5 TSN:1899			18-AUG-2006 8248 4053	21634	17281	LIFE LIMIT
322017-001	ACTUATOR:NLG DOORS ACTUATOR 600-75136-5 HAI 0772 REF: AMM 322017	MOS HRS/MSC AFL	O/C				24-APR-2003 6546 3288			
322104-001	PIVOT PIN:NO. 1 NLG (TRUNION) PIVOT PIN 200811601 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	19480	TSN:0			0	19480	15127	LIFE LIMIT
322105-001	SHOCK STRUT:NLG SLIDING TUBE SHOCK STRUT 200811707 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	19480	TSN:0			0	19480	15127	LIFE LIMIT
322106-001	LINK:NLG FORGING DRAG BRACE UPPER LINK 200814312 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	19480	TSN:0			0	19480	15127	LIFE LIMIT

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
322107-001	LINK:NLG DRAG BRACE UPPER LINK 7202-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	19480	TSN:0			0	19480		LIFE LIMIT 15127
322113-001	LINK:NLG DRAG BRACE, LOWER LINK 200814311 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	19480	TSN:0			0	19480		LIFE LIMIT 15127
322115-001	PIN:NLG ATTACHMENT PIN 200811721 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	19480	TSN:0			0	19480		LIFE LIMIT 15127
322116-001	PIVOT PIN:NO. 1 NLG DRAG BRACE, UPPER PIVOT PIN 200814601 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	19480	TSN:0			0	19480		LIFE LIMIT 15127
322117-001	HINGE PIN:NLG DRAG BRACE HINGE PIN 200814624 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	19480	TSN:0			0	19480		LIFE LIMIT 15127
322118-001	PIN:NLG SLIDING TUBE TO END FITTING PIN 200811602 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	19480	TSN:0			0	19480		LIFE LIMIT 15127
323001-001	VALVE:MLG SELECTOR VALVE 61750 318 REF: AMM 323001	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
323002-001	UPLOCK:NOSE LANDING GEAR UPLOCK 600-85002-9 DCL293-95 REF: AMM 323002	MOS HRS/MSC AFL	52065	TSN:0 TSN:0 TSN:0		10/22/2001	22-OCT-2000 4628 2397	54462		LIFE LIMIT 50109

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
323005-001	UPLOCK:NO. 1 MLG UPLOCK 600-85001-33 DCL423-92 REF: AMM 32-30-46	MOS HRS/MSC AFL	61008	TSN:0 TSN:0			01-OCT-1992 0 0	61008		LIFE LIMIT 56655
323005-002	UPLOCK:NO. 2 MLG UPLOCK 600-85001-33 DCL421-92 REF: AMM 32-30-46	MOS HRS/MSC AFL	61008	TSN:0 TSN:0			01-OCT-1992 0 0	61008		LIFE LIMIT 56655
323006-001	ACTUATOR:NLG RETRACTION ACTUATOR 104471003 SN-UNKNOWN REF: AMM 32-30-16	MOS HRS/MSC AFL	O/C	TSN:0			0			
323008-001	VALVE:NOSE LANDING GEAR SELECTOR VALVE 55540-5 1097 REF: AMM 323008	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
323012-001	CYLINDER:NO. 1 MLG SIDE STAY CYLINDER 104467734 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	50000	TSN:19 TSN:12			17-MAY-1993 80 48	50036		LIFE LIMIT 45683
323012-002	CYLINDER:NO. 2 MLG SIDE STAY CYLINDER 104467734 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	50000	TSN:0 TSN:0			01-OCT-1992 0 0	50000		LIFE LIMIT 45647
323013-001	ROD:NO. 1 MLG SIDE STAY PISTON ROD 104467816 SN-UNKNOWN REF: AMM 323013	MOS HRS/MSC AFL	50000	TSN:19 TSN:12			17-MAY-1993 80 48	50036		LIFE LIMIT 45683
323013-002	ROD:NO. 2 MLG SIDE STAY PISTON ROD 104467816 SN-UNKNOWN REF: AMM 323013	MOS HRS/MSC AFL	50000	TSN:0 TSN:0			01-OCT-1992 0 0	50000		LIFE LIMIT 45647

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
323015-001	BOLT:NO. 1 MLG SIDE STAY EYE BOLT 104467705 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	63536	TSN:0 TSN:0			01-OCT-1992 0 0	63536		LIFE LIMIT 59183
323015-002	BOLT:NO. 2 MLG SIDE STAY EYE BOLT 104467705 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	63536	TSN:0 TSN:0			01-OCT-1992 0 0	63536		LIFE LIMIT 59183
323017-001	CONTROL:LANDING GEAR UNIT CONTROL 600-50969-9 466 REF: AMM 323017	MOS HRS/MSC AFL	O/C				03-JUN-1993 117 66			
323020-001	SELECTOR VALVE:NLG NOSE LANDING GEAR DOORS SELECTOR VALVE 601R75146-1 0313 REF: AMM 323020	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-APR-1996 1791 892			
323021-001	ACTUATOR:NO. 1 MLG DOWNLOCK ASSIST ACTUATOR 600-85001-87 DCL549-92 REF: AMM 323021	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
323021-002	ACTUATOR:NO. 2 MLG DOWNLOCK ASSIST ACTUATOR 600-85001-87 DCL558-92 REF: AMM 323021	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
323304-001	PIN:NLG RETRACTION ACTUATOR, LOWER PIN 200811773 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			0			
324111-001	WHEEL ASSEMBLY:NO. 1 MLG WHEEL ASSEMBLY 5009029-1 OCT90-0269 REF: AMM 324111	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			05-APR-2006 8305.8 4018			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 324111-001A	WHEEL ASSEMBLY:NON DESTRUCTIVE TEST NO. 1 MLG WHEEL ASSEMBLY WHEEL AND BOLTS (32-41-11-231)	MOS HRS/MSC AFL	400				13-SEP-2007 8590 4155	4555	4595	202
	REF: See Workcard									
+ 324111-001B	WHEEL ASSEMBLY:CHECK NO. 1 MLG WHEEL ASSEMBLY (32-41-11-232)	MOS HRS/MSC AFL	1600				06-MAY-2005 8119 3935	5535	5595	1182
	REF: SMM 32-40-94									
324111-002	WHEEL ASSEMBLY:NO. 2 MLG WHEEL ASSEMBLY 5009029-1 JAN83-20 REF: AMM 324111	MOS HRS/MSC AFL	O/C				20-MAR-2009 8873.5 4304			
+ 324111-002A	WHEEL ASSEMBLY:NON DESTRUCTIVE TEST NO. 2 MLG WHEEL ASSEMBLY WHEEL AND BOLTS (32-41-11-231)	MOS HRS/MSC AFL	400				20-MAR-2009 8873.5 4304	4704		351
	REF: See Workcard									
+ 324111-002B	WHEEL ASSEMBLY:CHECK NO. 2 MLG WHEEL ASSEMBLY (32-41-11-232)	MOS HRS/MSC AFL	1600				20-MAR-2009 8873.5 4304	5904		1551
	REF: SMM 32-40-94									
324111-003	WHEEL ASSEMBLY:NO. 3 MLG WHEEL ASSEMBLY 5009029-1 FEB85-399 REF: AMM 324111	MOS HRS/MSC AFL	O/C				05-APR-2006 8305.8 4018			
				TSR:0 TSR:0						
+ 324111-003A	WHEEL ASSEMBLY:NON DESTRUCTIVE TEST NO. 3 MLG WHEEL ASSEMBLY WHEEL AND BOLTS (32-41-11-231)	MOS HRS/MSC AFL	400				13-SEP-2007 8590 4155	4555	4595	202
	REF: See Workcard									
+ 324111-003B	WHEEL ASSEMBLY:CHECK NO. 3 MLG WHEEL ASSEMBLY (32-41-11-232)	MOS HRS/MSC AFL	1600				05-APR-2006 8305.8 4018	5618	5678	1265
	REF: SMM 32-40-94									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
324111-004	WHEEL ASSEMBLY:NO. 4 MLG WHEEL ASSEMBLY 5009029-1 JAN83-32 REF: AMM 324111	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			05-APR-2006 8305.8 4018			
+ 324111-004A	WHEEL ASSEMBLY:NON DESTRUCTIVE TEST NO. 4 MLG WHEEL ASSEMBLY WHEEL AND BOLTS (32-41-11-231) REF: See Workcard	MOS HRS/MSC AFL	400				13-SEP-2007 8590 4155	4555	4595	202
+ 324111-004B	WHEEL ASSEMBLY:CHECK NO. 4 MLG WHEEL ASSEMBLY (32-41-11-232) REF: SMM 32-40-94	MOS HRS/MSC AFL	1600				30-MAR-2005 8015 3883	5483	5543	1130
324116-001	WHEEL ASSEMBLY:LEFT NLG WHEEL ASSEMBLY 600-85003-7 SEP89-0442 REF: AMM 324116	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			20-MAY-2005 8162 3955			
+ 324116-001A	WHEEL ASSEMBLY:NON DESTRUCTIVE TEST LEFT NLG WHEEL ASSEMBLY 32-41-16-234 REF: See Workcard	MOS HRS/MSC AFL	400				28-MAY-2009 8928.6 4336	4736		383
+ 324116-001B	WHEEL ASSEMBLY:CHECK LEFT NLG WHEEL ASSEMBLY 32-41-16-235 REF: SMM 32-46-12	MOS HRS/MSC AFL	1600				20-MAY-2005 8162 3955	5555	5615	1202
324116-002	WHEEL ASSEMBLY:RIGHT NLG WHEEL ASSEMBLY 600-85003-7 OCT86-1651 REF: AMM 324116	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			20-MAY-2005 8162 3955			
+ 324116-002A	WHEEL ASSEMBLY:NON DESTRUCTIVE TEST RIGHT NLG WHEEL ASSEMBLY 32-41-16-234 REF: See Workcard	MOS HRS/MSC AFL	400				28-MAY-2009 8928.6 4336	4736		383

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 324116-002B	WHEEL ASSEMBLY:CHECK RIGHT NLG WHEEL ASSEMBLY 32-41-16-235									
		MOS					20-MAY-2005			
		HRS/MSC					8162			
	REF: SMM 32-46-12	AFL	1600				3955	5555	5615	1202
324117-001	TIRE:NO. 1 MLG WHEEL TUBELESS HIGH PRESS TIRE									
	256K43-3	MOS		TSN:0			20-MAR-2009			
	81477026	HRS/MSC	O/C	TSN:0			8873.5			
	REF: AMM 324117	AFL		TSN:0			4304			
324117-002	TIRE:NO. 2 MLG WHEEL TUBELESS HIGH PRESS TIRE									
	256K43-3	MOS		TSN:0			20-MAR-2009			
	81527012	HRS/MSC	O/C	TSN:0			8873.5			
	REF: AMM 324117	AFL		TSN:0			4304			
324117-003	TIRE:NO. 3 MLG WHEEL TUBELESS HIGH PRESS TIRE									
	256K43-3	MOS		TSN:0			13-SEP-2007			
	6165704	HRS/MSC	O/C	TSN:0			8590			
	REF: AMM 324117	AFL		TSN:0			4155			
324117-004	TIRE:NO. 4 MLG WHEEL TUBELESS HIGH PRESS TIRE									
	256K43-3	MOS		TSN:0			13-SEP-2007			
	61647047	HRS/MSC	O/C	TSN:0			8590			
	REF: AMM 324117	AFL		TSN:0			4155			
324118-001	TIRE:LEFT NLG TIRE									
	184F23-2	MOS		TSN:0			27-APR-2007			
	60631119	HRS/MSC	O/C	TSN:0			8539			
	REF: AMM 324118	AFL		TSN:0			4126			
324118-002	TIRE:RIGHT NLG TIRE									
	184F23-2	MOS		TSN:0			27-APR-2007			
	60631140	HRS/MSC	O/C	TSN:0			8539			
	REF: AMM 324118	AFL		TSN:0			4126			
324301-001	INDICATOR:BRAKE PRESSURE INDICATOR									
	600-50940-3	MOS		TSN:0			29-SEP-1994			
	91120294	HRS/MSC	O/C	TSN:0			864			
	REF: GENERIC NO REF	AFL		TSN:0			425			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
324302-001	ACCUMULATOR: BRAKE ACCUMULATOR 600-75125-1 SN-UNKNOWN REF: AMM 324302	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
324302-001	ACCUMULATOR: OUTBOARD (NO.2 SYS) BRAKE ACCUMULATOR 2770571-103 1190A REF:	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
324302-002	ACCUMULATOR: BRAKE ACCUMULATOR 600-75125-1 1419 REF: AMM 324302	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-DEC-1993 469 242			
324302-002	ACCUMULATOR: INBOARD (NO.3 SYS) BRAKE ACCUMULATOR 2770571-103 1189A REF:	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
324304-001	FUSE: NO. 1 BRAKE HYDRAULIC FUSE 6190 SN-UNKNOWN REF: AMM 324304	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
324304-002	FUSE: NO. 2 BRAKE HYDRAULIC FUSE 6190 SN-UNKNOWN REF: AMM 324304	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
324304-003	FUSE: NO. 3 BRAKE HYDRAULIC FUSE 6190 SN-UNKNOWN REF: AMM 324304	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
324304-004	FUSE: NO. 4 BRAKE HYDRAULIC FUSE 6190 SN-UNKNOWN REF: AMM 324304	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
324311-001	BRAKE:NO. 1 MLG BRAKE 600-85123-91 AUG83-683 REF: AMM 324311	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			18-JAN-2006			
324311-002	BRAKE:NO. 2 MLG BRAKE 600-85123-91 MAR83-635 REF: AMM 324311	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			18-JAN-2006			
324311-003	BRAKE:NO. 3 MLG BRAKE 600-85123-91 MAR82-321 REF: AMM 324311	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			18-JAN-2006			
324311-004	BRAKE:NO. 4 MLG BRAKE 600-85123-91 JUN94-0613 REF: AMM 324311	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			18-JAN-2006			
324321-001	VALVE:UPPER BRAKE CONTROL VALVE 600-75115-9 1547A REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			
324321-002	VALVE:LOWER BRAKE CONTROL VALVE 600-75115-9 1578A REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			
324500-001	VALVE:PARKING BRAKE SOV VALVE 15886-1 056 REF: AMM 324500	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			29-NOV-1993 445 225			
324700-001	CONTROL:ANTI-SKID CONTROL 600-87000-103 JUN92-0203 REF: AMM 324700	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
324701-001	VALVE:INBOARD BRAKE ANTI-SKID VALVE 600-87000-9 JUL92-589 REF: AMM 324701	MOS HRS/MSC AFL	O/C	TSN:24 TSN:15			08-APR-1993 24 15			
324701-002	VALVE:OUTBOARD BRAKE ANTI-SKID VALVE 600-87000-9 MAR93-616 REF: AMM 324701	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			08-APR-1993 24 15			
324711-001	SENSOR:NO. 1 WHEEL SPEED - ANTI-SKID SYSTEM SENSOR 6006568 APR97-0164 REF: AMM 324711	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-JUN-2004 7737 3772			
324711-002	SENSOR:NO. 2 WHEEL SPEED - ANTI-SKID SYSTEM SENSOR 6006568 FEB96-0051 REF: AMM 324711	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-JUN-1997 2547 1284			
324711-003	SENSOR:NO. 3 WHEEL SPEED - ANTI-SKID SYSTEM SENSOR 600-87000-5 FEB93-3309 REF: AMM 324711	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-1996 1804 899			
324711-004	SENSOR:NO. 4 WHEEL SPEED - ANTI-SKID SYSTEM SENSOR 6006568 NOV97-0225 REF: AMM 324711	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		02/04/1999	04-FEB-1998 2967 1482			
325000-001	VALVE:NLG STEERING SELECTOR - (FS193.00) VALVE 600-85002-11 DRG21-91 REF: AMM 325000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
325000-002	VALVE:NLG STEERING SELECTOR - ARMING (FS177.00) VALVE 600-85002-11 DRG28-91 REF: AMM 325000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
325005-001	CONTROL:NLG STEERING POTENTIOMETER CONTROL 601-86100-17 86136-802 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
325008-001	HANDWHEEL:NOSEWHEEL STEERING ASSY HANDWHEEL 601-86100-19 DCL298-92 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
325009-001	CONTROL:NOSEWHEEL STEERING MANIFOLD CONTROL 601-86100-15 SN-UNKNOWN REF: AMM 32-50-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
325013-001	COMPENSATOR:ELECTRONIC STEER-BY-WIRE ECU COMPENSATOR 600-85002-13 DCL214-91 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
325014-001	CONTROL:ELECTRONIC STEER BY WIRE ECU CONTROL 601-86100-13 92-340 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
329051	ACTUATOR:LEFT MAIN LANDING GEAR SIDE STAY ACTUATOR 600-85001-85 DCL235/92 REF:	MOS HRS/MSC AFL		TSN:4210.5 TSN:2846			18-AUG-2006 8248 4053		44818	40465
329056	ACTUATOR:RIGHT MAIN LANDING GEAR SIDE STAY/RETRACTION ACTUATOR 600-85001-85 DCL181/84/05R REF:	MOS HRS/MSC AFL	O/C	TSN:6132.9 TSN:4211			18-AUG-2006 8248 4053			
329326	VALVE:NLG PRIORITY VALVE 4622 131 REF:	MOS HRS/MSC AFL	N/R				22-FEB-2001 4859 2516			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
329401	HARNESS:L MLG #1 WOW HARNESS 601-57788-65 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			18-AUG-2006 8248 4053			
329403	HARNESS:R MLG #1 WOW HARNESS 601-57788-3 735 REF:	MOS HRS/MSC AFL	N/R				20-MAR-2001 4859 2516			
329405	HARNESS:L MLG #2 WOW HARNESS 601-57788-69 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			18-AUG-2006 8248 4053			
329407	HARNESS:R MLG #2 WOW HARNESS 601-57788-7 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			18-AUG-2006 8248 4053			
329409	HARNESS:L MLG #1 DOWNLOCK HARNESS 601-57788-21 271 REF:	MOS HRS/MSC AFL	N/R				29-MAR-2001 4865 2518			
329411	HARNESS:R MLG #1 DOWNLOCK HARNESS 601-57788-21 139 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			31-OCT-1995 1512 743			
329413	HARNESS:L MLG #2 DOWNLOCK HARNESS PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
329415	HARNESS:R MLG #2 DOWNLOCK HARNESS PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
329417	HARNES:L MLG UPLOCK HARNES PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
329419	HARNES:R MLG UPLOCK HARNES PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
329421	HARNES:NLG #1 DOWNLOCK HARNES PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
329423	HARNES:NLG #2 DOWNLOCK HARNES 601-57788-27 519 REF:	MOS HRS/MSC AFL	N/R				21-MAR-2001 4859.2 2516			
329425	HARNES:NLG WOW/OLEO HARNES 601-57788-9 468 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			23-FEB-1996 1728 855			
329427	HARNES:NLG UPLOCK HARNES PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
329429	HARNES:L NLG DOOR CNTRL HARNES PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
329431	HARNES:R NLG DOOR CNTRL HARNES PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
329433	HARNES:NLG STEERING HARNES PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
329701	CABLE ASSY:PKNG BRAKE CTL CABLE ASSY 600-88005-9 534 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0		05/05/1994	05-MAY-1993 59 32			
32R001	SWITCH:L MLG UPLOCK PROX SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
32R006	SWITCH:R MLG UPLOCK PROX SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
32R011	SWITCH:NLG UPLOCK PROX SWITCH 8-405-34 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
32R016	--:XDUCER,OB BRK,HYD SYS #2 600-59174-7 4138-2-316 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			09-APR-1999 3625 1861			
32R018	--:XDUCER,IB BRK,HYD SYS #3 600-59101-1 4135-2-254 REF:	MOS HRS/MSC AFL	N/R				02-SEP-1994 808 401			
32R021	--:SWTCH,L NLG DR UPLCK PROX 8-405-34 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
32R026	--:SWTCH,R NLG DR UPLCK PROX 8-405-34 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
32R051	VALVE:NWS ELECTRO SERVO VALVE 7026-3 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
32R101	--:PROX SW,L OUTB MLG WOW 8-405-34 35614 REF:	MOS HRS/MSC AFL	N/R				22-JUL-2003 6742 3377			
32R103	--:PROX SW,L INBD MLG WOW 8-405-34 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
32R105	--:PROX SW,R INBD MLG WOW 8-405-34 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
32R107	--:PROX SW,R OUTB MLG WOW 8-405-34 35607 REF:	MOS HRS/MSC AFL	N/R				22-JUL-2003 6742 3377			
32R109	--:PROX SW,L MLG #1 DOWNLOCK 8-405-34 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
32R111	--:PROX SW,L MLG #2 DOWNLOCK 8-405-34 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
32R113	--:PROX SW,R MLG #1 DOWNLOCK 8-405-34 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			31-OCT-1995 1512 743			
32R115	--:PROX SW,R MLG #2 DOWNLOCK 8-405-34 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
32R201	INSP LDG GEAR LT BULB REF:	MOS HRS/MSC AFL	O/C				20-JAN-1999 3489 1796			
32R205	WHEEL ASSEMBLY:SPARE WHEEL ASSEMBLY 600-85123-15 MAR92-0489 REF:	MOS HRS/MSC AFL	N/R				15-AUG-2005 8215.3 3975			
32R206	TIRE:SPARE TIRE 256K43-3 61637043 REF:	MOS HRS/MSC AFL	N/R				13-SEP-2007 8590 4155			
32R207	ROTATE SPARE WHEEL ASSEMBLY REF:	MOS HRS/MSC AFL	6				20-MAR-2009 8873.5 4304	20-SEP-2009		OVD
32R210	STRUT SERVICE REF:	MOS HRS/MSC AFL	N/R				04-JAN-1995 1017 508			
C32-10-801 (s)	CPCP CHECK MAIN LANDING GEAR. PKG 2 REF: GENERIC NO REF	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
C32-20-801 (s)	CPCP CHECK NOSE LANDING GEAR. PKG 2 REF: GENERIC NO REF	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
T32T01	JACKING AIRCRAFT REF:	MOS HRS/MSC AFL	O/C							
T32T02	BLEED BRAKE SYSTEM REF:	MOS HRS/MSC AFL	O/C							
T32T03	CHECK SHOCK STRUTS REF:	MOS HRS/MSC AFL	O/C							
T32T04	FUNCTIONAL TEST OF STEERING SYSTEM REF:	MOS HRS/MSC AFL	O/C							
T32T05	CHECK NOSE AND MAIN WHEEL REF:	MOS HRS/MSC AFL	O/C							
CHAPTER 33 LIGHTS										
33-40-00-201 (s)	OPERATIONAL TEST (1) RECOGNITION/TAXI AND LANDING LIGHTS (2) NAVIGATION LIGHTS (3) WING ICE INSPECTION LIGHTS (4) ANTI-COLLISION LIGHTS PKG 2 REF: AMM 33-40-00-201	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
+ 33-50-00-202 (s)	VISUAL CHECK/OPERATIONAL TEST EMERGENCY LIGHTING PKG 2 REF: AMM 33-50-00-202	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 33-50-00-203 (s)	INSPECT EMERGENCY LIGHTING POWER SUPPLIES PER CHECK SECTION AND CARRY OUT CAPACITY CHECK PER REPAIR SECTION OF CMM/PSP 608/608A 33-50-42, OR INSTALL NEW POWER SUPPLIES.						PKG			
	PKG 30	MOS	12					19-JUL-2010		
		HRS/MSC						8947.8		
	REF: SMM 33-50-42	AFL						4353		
331031	DIMMER:CENTER PEDESTAL INCANDESCENT DIMMER									
	2-459-06	MOS						01-OCT-1992		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF:	AFL						0		
331036	DIMMER:LEFT COCKPIT FLOOR DIMMER									
	600-51519-1	MOS						01-OCT-1992		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF:	AFL						0		
331041	DIMMER:RIGHT COCKPIT FLOOR DIMMER									
	600-51519-1	MOS						01-OCT-1992		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF:	AFL						0		
331046	DIMMER:LEFT SIDE CONSOLE DIMMER									
	2-459-06	MOS						01-OCT-1992		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF:	AFL						0		
331051	DIMMER:RIGHT SIDE CONSOLE DIMMER									
	2-459-06	MOS						01-OCT-1992		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF:	AFL						0		
331100-001	ASSEMBLY:NO. 1 DIMMER CONTROL ASSEMBLY									
	70-0180-3	MOS						01-OCT-1992		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF: AMM 331100	AFL						0		
331100-002	ASSEMBLY:NO. 2 DIMMER CONTROL ASSEMBLY									
	70-0180-3	MOS						01-OCT-1992		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF: AMM 331100	AFL						0		

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
334026-003	ASSEMBLY:TAIL ANTI-COLLISION/POS LIGHT ASSEMBLY 30-1192-7 BDL022 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				05-OCT-1999 3877 2013			
334027-001	ASSEMBLY:NO. 1 WING STROBE ASSEMBLY 30-1467-1 12296 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-SEP-2007 8590 4155			
334027-002	ASSEMBLY:NO. 2 WING STROBE ASSEMBLY 30-1467-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
334404-001	POWER SUPPLY:LEFT STROBE POWER SUPPLY 60-2799-3 SN-UNKNOWN REF: AMM 334404	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
334404-002	POWER SUPPLY:RIGHT STROBE POWER SUPPLY 60-2799-3 SN-UNKNOWN REF: AMM 334404	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
334407-001	POWER SUPPLY:TAIL STROBE POWER SUPPLY 60-2799-3 5881 REF: AMM 334407	MOS HRS/MSC AFL	O/C				05-APR-1993 19 12			
335001	POWER SUPPLY:CABIN DOOR EMERGENCY LIGHTING POWER SUPPLY 60-1321-1 18597 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-SEP-2007 8590 4155			
335003	POWER SUPPLY:OVERWING EMERGENCY LIGHTING POWER SUPPLY 60-1321-1 21024 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-SEP-2007 8590 4155			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
339001	POWER SUPPLY:LEFT NO.1 UPWASH PROTECTED POWER SUPPLY AL-5112 4254 REF:	MOS HRS/MSC AFL	O/C				25-JUL-2006 8363.2 4048			
339014	POWER SUPPLY:PILOT CABIN FLOURESCENT POWER SUPPLY 55-0532-6 726 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			24-APR-2002 5739 2927			
339015	POWER SUPPLY:COPILOT CABIN FLOURESCENT POWER SUPPLY 55-0532-6 726 REF:	MOS HRS/MSC AFL	O/C				24-APR-2002 5739 2927			
339021	POWER SUPPLY:NO. 1 CABIN EMERGENCY LIGHT POWER SUPPLY 60-1321- 1 12138 REF:	MOS HRS/MSC AFL	O/C				02-APR-1999 3617 1854			
339023	POWER SUPPLY:NO. 2 CABIN EMERGENCY LIGHT POWER SUPPLY 60-1321-1 9576 REF:	MOS HRS/MSC AFL	O/C				02-APR-1999 3617 1854			
339025	POWER SUPPLY:CABIN NO. 3 EMERGENCY LIGHT POWER SUPPLY 60-1321-1 19078 REF:	MOS HRS/MSC AFL	O/C				05-AUG-1997 2993 1369			
339031	POWER SUPPLY:BENCH CHECK NO. 1 CABIN EMERGENCY LIGHT POWER SUPPLY REF:	MOS HRS/MSC AFL	24				20-MAR-2009 8873.5 4304	20-MAR-2011		194 d
339033	POWER SUPPLY:BENCH CHECK NO. 2 CABIN EMERGENCY LIGHT POWER SUPPLY REF:	MOS HRS/MSC AFL	24				20-MAR-2009 8873.5 4304	20-MAR-2011		194 d

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
339101	LIGHT:UPPER STROBE LIGHT 30-1136-1 3137 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
339103	LIGHT:LOWER STROBE LIGHT 30-1136-1 2773 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
339105	POWER SUPPLY:UPPER STROBE POWER SUPPLY 60-2667-1 2736 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
339107	POWER SUPPLY:LOWER STROBE POWER SUPPLY 60-2667-1 2639 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
339109	LIGHT ASSEMBLY:NAVIGATION LIGHT ASSEMBLY 604-56000-1 (S2371-201) NONE REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		06/25/2005	25-JUN-2004 7576 3705			
339111	TRANSFORMER:L LOGO LIGHT TRANSFORMER 310-18132-01 545 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
339113	TRANSFORMER:R LOGO LIGHT TRANSFORMER 310-18132-01 597 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
339209	CHECK LUMINOUSITY OF BETA EXIT LIGHTS REF:	MOS HRS/MSC AFL	24				20-MAR-2009 8873.5 4304	20-MAR-2011		194 d

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
339211	OPERATIONAL CHECK CABIN LIGHTING REF:	MOS HRS/MSC AFL	300				09-SEP-2008 8806.5 4265	9106.5		158.7
339216	OPERATIONAL CHECK CABIN EMERGENCY LIGHTING REF:	MOS HRS/MSC AFL	300				09-SEP-2008 8806.5 4265	9106.5		158.7
339221	CONTROL:PULSE LIGHT CONTROL 600-50491-1 B00306 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R001	INVERTER:GALLEY NIGHT WORK LIGHT INVERTER 18-944-2 01004 REF:	MOS HRS/MSC AFL	N/R				24-FEB-1999 3565 1827			
33R006	INVERTER:GALLEY EFFECT LT INVERTER 18-944-2 774 REF:	MOS HRS/MSC AFL	N/R			12/26/2002	26-DEC-2001 5429 2786			
33R011	INVERTER:GALLEY WORK LTS INVERTER 18-944-2 71 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R051	INVERTER:LAV MIRROR LTS INVERTER 18-1030-2 5101 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R061	POWER SUPPLY:NO. 1 LAV MIRROR LIGHTS POWER SUPPLY TR-992-10 4125 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
33R066	POWER SUPPLY:NO. 2 LAV MIRROR LIGHTS POWER SUPPLY TR-992-10 4126 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R071	POWER SUPPLY:LAVATORY DOWNWASH LIGHTS POWER SUPPLY 18-992-10 4127 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R076	POWER SUPPLY:LAVATORY UPWASH LIGHTTS POWER SUPPLY TR-992-10 4128 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R091	INVERTER:L DOWNWASH LTS INVERTER 18-1030-2 5098 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R096	INVERTER:R DOWNWASH LTS INVERTER 18-1030-2 5099 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R101	--:SUP,L #1 DOWNWASH LTS PWR TR-992-10 3765 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R106	--:SUP,R #1 DOWNWASH LTS PWR TR-992-10 4117 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R111	--:SUP,L #2 DOWNWASH LTS PWR TR-992-10 3767 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
33R116	--:SUP,R #2 DOWNWASH LTS PWR TR-992-10 4119 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R121	--:SUP,L #3 DOWNWASH LTS PWR TR-992-10 3769 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R126	--:SUP,R #3 DOWNWASH LTS PWR TR-992-10 4121 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R131	--:SUP,L #4 DOWNWASH LTS PWR TR-992-10 3399 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R136	--:SUP,R #4 DOWNWASH LTS PWR TR-992-10 4124 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R151	INVERTER:L UPWASH LIGHTS INVERTER 18-1030-2 5097 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R156	INVERTER:R UPWASH LIGHTS INVERTER 18-1030-2 5100 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R161	POWER SUPPLY:LEFT NO. 1 UPWASH LIGHT POWER SUPPLY TR-992-10 3513 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
33R166	POWER SUPPLY:RIGHT NO. 1 UPWASH LIGHTS POWER SUPPLY TR-992-10 4118 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R171	--:SUP,L #2 UPWASH LTS POWER TR-992-10 3766 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R176	--:SUP,R #2 UPWASH LTS POWER TR-992-10 4120 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R181	--:SUP,L #3 UPWASH LTS POWER TR-992-10 3768 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R186	--:SUP,R #3 UPWASH LTS POWER TR-992-10 4122 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R191	--:SUP,L #4 UPWASH LTS POWER TR-992-10 3770 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R196	--:SUP,R #4 UPWASH LTS POWER TR-992-10 4123 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
33R201	CONTROLLER:UPWASH LIGHTS CONTROLLER MSM282B 300713A REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
33R206	--:PWR SPLY, CTR INST FLRSNT 55-0521-4 386 REF:	MOS HRS/MSC AFL	N/R				12-MAR-1996 1742 861			
T33T01	OPERATIONAL TEST PANEL INTEGRAL LIGHTING REF:	MOS HRS/MSC AFL	O/C							
CHAPTER 34		NAVIGATION								
34-11-00-201 (s)	VISUAL CHECK PITOT STATIC SYSTEM AND TEMPERATURE SENSING SYSTEM PKG 2 REF: GENERIC NO REF	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
+ 34-11-00-202 (s)	CHECK PITOT STATIC SYSTEM AND TEMPERATURE SENSING SYSTEM - PITOT STATIC SYSTEM MOISTURE AND CONTAMINATION CHECK PKG 30 REF: AMM 34-11-00-202	MOS HRS/MSC AFL	12				PKG 19-JUL-2010 8947.8 4353			
+ 34-11-00-203 (s)	TEST PITOT STATIC SYSTEM AND TEMPERATURE SENSING SYSTEM - PRESSURE LEAK TESTS PKG 32 REF: AMM 34-11-00-203	MOS HRS/MSC AFL	24				PKG 28-MAY-2009 8928.6 4336			
34-11-11-211 (s)	CLEAN PITOT STATIC HEADS - CLEAN PITOT DRAIN HOLES PKG 2 REF: AMM 34-11-11-211	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
+ 34-27-00-208	SWING CHECK STANDBY MAGNETIC COMPASS PKG 30 REF: AMM 34-27-00-208	MOS HRS/MSC AFL	12				19-JUL-2010 8947.8 4353	19-JUL-2011		315 d
340RNP	RENEW RNP-10 AUTHORIZATION # REF:	MOS HRS/MSC AFL	24				20-MAR-2009 8873.5 4304	20-MAR-2011		194 d

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
341000-001	INDICATOR:NO. 1 MACH AIRSPEED INDICATOR 7002860-912 90121388 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				03-NOV-2004 7737 3772			
341000-002	INDICATOR:NO. 2 MACH AIRSPEED INDICATOR 7002860-912 9102426 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				26-SEP-2003 6921 3457			
341001-001	INDICATOR:NO. 1 TCAS/VERTICAL SPEED INDICATOR 066-50001-2802 3118 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			19-NOV-1992 18 10			
341010-001	ALTIMETER:NO. 1 ALTIMETER 4016341-904 86044040 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:3331.8 TSO:1475			19-JUL-2010 8947.8 4353			
+ 341010-001A	ALTIMETER:CALIBRATION CHECK NO. 1 ALTIMETER (34-11-00-205) REF: See Workcard	MOS HRS/MSC AFL	24		-99		13-JUL-2010	05-APR-2012		576 d
341010-001B	ALTIMETER:RECERTIFY NO. 1 ALTIMETER PER FAR 91.411 REF: GENERIC NO REF	MOS HRS/MSC AFL	24		-86		19-JUL-2010 8947.8 4353	24-APR-2012		595 d
341010-002	ALTIMETER:NO. 2 ALTIMETER 4016341-904 88014950 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-JUL-2010 8947.8 4353			
+ 341010-002A	ALTIMETER:CALIBRATION CHECK NO. 2 ALTIMETER (34-11-00-205) REF: See Workcard	MOS HRS/MSC AFL	24		-99		13-JUL-2010	05-APR-2012		576 d

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
341010-002B	ALTIMETER:RECERTIFY NO. 2 ALTIMETER PER FAR 91.411 REF: GENERIC NO REF	MOS HRS/MSC AFL	24		-86		19-JUL-2010 8947.8 4353	24-APR-2012		595 d
341010-003	ALTIMETER:STANDBY ALTIMETER 8047-20 8866B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:55 TSR:720 TSR:372			19-JUL-2010 8947.8 4353			
+ 341010-003A	ALTIMETER:CALIBRATION CHECK STANDBY ALTIMETER (34-11-00-205) REF: See Workcard	MOS HRS/MSC AFL	24		-99		13-JUL-2010	05-APR-2012		576 d
341010-003B	ALTIMETER:CALIBRATE STANDBY ALTIMETER PER FAR 91.411 REF: GENERIC NO REF	MOS HRS/MSC AFL	24		-86		19-JUL-2010 8947.8 4353	24-APR-2012		595 d
341046	INDICATOR:RIGHT VERTICAL SPEED INDICATOR 066-01171-2804 23389 REF:	MOS HRS/MSC AFL	O/C				26-SEP-2003 6921 3457			
341100-001	PROBE:NO. 1 PITOT STATIC PROBE 856KV9 139403 REF: AMM 341100	MOS HRS/MSC AFL	9600	TSN:0 TSN:0 TSN:0			05-APR-1993 19 12	9619		LIFE LIMIT 671.2
341100-002	PROBE:NO. 2 PITOT STATIC PROBE 856KV10 202114 REF: AMM 341100	MOS HRS/MSC AFL	9600	TSN:5096 TSN:2625			31-JUL-2001 5096 2625	9600		LIFE LIMIT 652.2
341101-001	PORT:LEFT STATIC PRESSURE PORT ST300-3HA SN-UNKNOWN REF: AMM 341101	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
341101-002	PORT:RIGHT STATIC PRESSURE PORT ST300-3HA 7552 REF: AMM 341101	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		07/30/1998	30-JUL-1997 2626 1321			
341121-001	SENSOR:TOTAL TEMPERATURE SENSOR 102AH2AG A28341 REF: AMM 341121	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		10/27/2001	27-APR-2001 4937 2539			
341201-001	INDICATOR:STANDBY AIRSPEED INDICATOR 8059-2B 6949 REF: AMM 341201	MOS HRS/MSC AFL	O/C				19-JUL-2010 8947.8 4353			
+ 341201-001A	INDICATOR:CALIBRATION CHECK STANDBY AIRSPEED INDICATOR (34-11-00-206) REF: GENERIC NO REF	MOS HRS/MSC AFL	24		-99		13-JUL-2010	05-APR-2012		576 d
341300-001	COMPUTER:NO. 1 AIR DATA COMPUTER 7000700-974 92075437 REF: AMM 341300	MOS HRS/MSC AFL	O/C	TSO:51 TSO:642 TSO:335			19-JUL-2010 8947.8 4353			
+ 341300-001A	COMPUTER:FUNCTIONAL TEST NO. 1 AIR DATA COMPUTER (34-13-00-101) REF: AMM 34-13-00-101	MOS HRS/MSC AFL	24		-99		13-JUL-2010	05-APR-2012		576 d
+ 341300-001B	COMPUTER:RECERTIFY NO. 1 AIR DATA COMPUTER PER FAR 91.411 REF: GENERIC NO REF	MOS HRS/MSC AFL	24		-99		13-JUL-2010	05-APR-2012		576 d
341300-002	COMPUTER:NO. 2 AIR DATA COMPUTER 7000700-974 92075106 REF: AMM 341300	MOS HRS/MSC AFL	O/C	TSO:51 TSO:642 TSO:335			19-JUL-2010 8947.8 4353			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 341300-002A	COMPUTER:FUNCTIONAL TEST NO. 2 AIR DATA COMPUTER (34-13-00-101)	MOS HRS/MSC AFL	24		-99		13-JUL-2010	05-APR-2012		576 d
	REF: AMM 34-13-00-101									
+ 341300-002B	COMPUTER:RECERTIFY NO. 2 AIR DATA COMPUTER PER FAR 91.411	MOS HRS/MSC AFL	24		-99		13-JUL-2010	05-APR-2012		576 d
	REF: GENERIC NO REF									
342000-001	SYMBOL GENERATOR:NO. 1 (SG-815) SYMBOL GENERATOR	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
	7011674-515 92030806 REF: AMM 34-22-00									
342000-002	SYMBOL GENERATOR:NO. 2 (SG-815) SYMBOL GENERATOR	MOS HRS/MSC AFL	O/C				23-JUN-2006 8355 4043			
	7011674-525 92070861 REF: GENERIC NO REF									
342000-003	SYMBOL GENERATOR:MFD (MG-815) SYMBOL GENERATOR	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
	7011675-515 92040495 REF: AMM 34-22-00									
342001-001	DISPLAY:PILOT EFIS - EADI DISPLAY	MOS HRS/MSC AFL	O/C				29-JUN-1994 727 357			
	7003110-901 92056589 REF: AMM 34-22-00									
342001-002	DISPLAY:PILOT EFIS - EHSI DISPLAY	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			15-JUL-2002 5825 3013			
	7003110-901 89053492 REF: AMM 34-22-00									
342001-003	DISPLAY:CENTER EFIS - MULTI FUNCTION DISPLAY	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
	7003110-901 92056602 REF: AMM 34-22-00									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
342001-004	DISPLAY:COPILOT EFIS - EADI DISPLAY 7003110-901 98010971 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			13-JAN-2004 7121 3540			
342001-005	DISPLAY:COPILOT EFIS - EHSI DISPLAY 7003110-901 92046576 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
342003-001	CONTROLLER:EFIS MFD CONTROLLER 7007062-921 92031095 REF: AMM 34-22-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
342200-001	CONTROLLER:INSTRUMENT REMOTE CONTROLLER 7011345-902 92070555 REF: AMM 342200	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
342200-002	CONTROLLER:NO.2 INSTRUMENT REMOTE CONTROLLER 7011345-912 92040552 REF: AMM 34-22-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
342300-001	INERTIAL REFERENCE UNIT:NO. 1 INERTIAL REFERENCE UNIT HG1075AE04 2082 REF: AMM 342300	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			15-APR-1993 34 20			
342300-002	INERTIAL REFERENCE UNIT:NO. 2 INERTIAL REFERENCE UNIT HG1075AE04 SN-UNKNOWN REF: AMM 342300	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			30-MAR-2006 8312.1 4020			
342300-003	INERTIAL REFERENCE UNIT:NO. 3 INERTIAL REFERENCE UNIT HG1075AE04 93052334 REF: AMM 342300	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-2007 8459			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
342301-001	BLOWER:NO. 1 AC (LIRS) BLOWER 26012761-101 172 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		05/26/1998	26-AUG-1997 2677 1354			
342301-002	BLOWER:NO. 2 AC (LIRS) BLOWER 10089782-101 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
342301-003	BLOWER:NO. 3 AC (LIRS) BLOWER 10089782-101 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			03-APR-1993 19 12			
342302-001	DISPLAY:NO.1 IRS DISPLAY CG1230AC11 062 REF: AMM 34-23-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
342311-001	CHARGER:NO. 1 I.R.S BATTERY CHARGER 100-0202-01 1252 REF: AMM 342311	MOS HRS/MSC AFL	O/C				05-MAR-2001 4859 2516			
+ 342311-001A	CHARGER:CAPACITY CHECK NO. 1 I.R.S BATTERY CHARGER 34-23-11-209 (PRE SB-601-0478) REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A		-28		09-SEP-2008 8806.5 4265			
342311-001B	CHARGER:CAPACITY CHECK NO. 1 I.R.S BATTERY CHARGER 34-23-11-213 (POST SB-601-0478) PKG 30 REF: GENERIC NO REF	MOS HRS/MSC AFL	12				19-JUL-2010 8947.8 4353	19-JUL-2011		315 d
342311-002	CHARGER:NO. 2 I.R.S BATTERY CHARGER 100-0202-01 1028 REF: AMM 342311	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			18-AUG-2006 8248 4053			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 342311-002A	CHARGER:CAPACITY CHECK NO. 2 I.R.S BATTERY CHARGER 34-23-11-209 (PRE SB-601-0478)	MOS			-28		09-SEP-2008			
	REF: GENERIC NO REF	HRS/MSC AFL	N/A				8806.5 4265			
342311-002B	CHARGER:CAPACITY CHECK NO. 2 I.R.S BATTERY CHARGER 34-23-11-213 (POST SB-601-0478)	MOS	12				19-JUL-2010	19-JUL-2011		315 d
	PKG 30	HRS/MSC AFL					8947.8 4353			
	REF: GENERIC NO REF									
342311-003	CHARGER:NO. 3 I.R.S BATTERY CHARGER	MOS					05-MAR-2001			
	100-0202-01	HRS/MSC AFL	O/C				4859 2516			
	REF: AMM 342311									
+ 342311-003A	CHARGER:CAPACITY CHECK NO. 3 I.R.S BATTERY CHARGER 34-23-11-209 (PRE SB-601-0478)	MOS			-28		09-SEP-2008			
	REF: GENERIC NO REF	HRS/MSC AFL	N/A				8806.5 4265			
342311-003B	CHARGER:CAPACITY CHECK NO. 3 I.R.S BATTERY CHARGER 34-23-11-213 (POST SB-601-0478)	MOS	12				19-JUL-2010	19-JUL-2011		315 d
	PKG 30	HRS/MSC AFL					8947.8 4353			
	REF: GENERIC NO REF									
342400-001	INDICATOR:STANDBY HORIZON INDICATOR	MOS				01/09/2003	09-JUL-2001			
	501-1197-05	HRS/MSC AFL	O/C				5064 2605			
	REF: AMM 342400									
342500	INTERFACE UNIT:NO. 1 AVIONICS INTERFACE UNIT	MOS					10-SEP-2004			
	724986-802	HRS/MSC AFL	O/C	TSN:0			7608 3724			
	MSM2993			TSN:0						
	REF:			TSN:0						
342501	INTERFACE UNIT:NO. 2 AVIONICS INTERFACE UNIT	MOS					10-SEP-2004			
	724986-802	HRS/MSC AFL	O/C	TSN:0			7608 3724			
	MSM2998			TSN:0						
	REF:			TSN:0						

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
342700-001	COMPASS:STANDBY COMPASS PAI-700 23796A REF: AMM 342700	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-AUG-1999 3788 1957			
344030-001	MODE SELECTOR:NO. 1 IRU MODE SELECTOR CG1042AB03 1247 REF: AMM 34-23-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
344030-002	MODE SELECTOR:NO. 2 IRU MODE SELECTOR CG1042AB03 1080 REF: AMM 34-23-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
344030-003	MODE SELECTOR:NO. 3 IRU MODE SELECTOR CG1042AB03 98042310 REF: AMM 34-23-00	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			11-NOV-2003 7003 3486			
344101-001	CONTROL:NO. 1 WEATHER RADAR CONTROL 7008471-803 92061552 REF: AMM 344100	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
344110-001	TRANSCEIVER:WEATHER RADAR TRANSCEIVER 7012640-901 91120885 REF: AMM 344100	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			04-APR-2006 8305.8 4018			
344200-001	TRANSCEIVER:RADIO ALTITUDE TRANSCEIVER 7001840-922 89103200 REF: AMM 344200	MOS HRS/MSC AFL	O/C				09-OCT-2003 6956 3470			
344201-001	ANTENNA:NO. 1 RADIO ALTIMETER ANTENNA S67-2002 SN-UNKNOWN REF: AMM 344201	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
344201-002	ANTENNA:NO. 2 RADIO ALTIMETER ANTENNA S67-2002 SN-UNKNOWN REF: AMM 344201	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
345100-001	RECEIVER:NO. 1 VHF NAVIGATION RECEIVER 622-6137-201 9951 REF: AMM 345100	MOS HRS/MSC AFL	O/C			09/15/1998	15-SEP-1997 2693 1364			
345100-002	RECEIVER:NO. 2 VHF NAVIGATION RECEIVER 622-6137-201 12945 REF: AMM 345100	MOS HRS/MSC AFL	O/C			09/29/1998	29-SEP-1997 2746 1382			
345101-001	CONTROL:NO. 1 VHF NAVIGATION CONTROL 622-6521-013 13551 REF: AMM 34-51-00	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
345101-002	CONTROL:NO. 2 VHF NAVIGATION CONTROL 622-6521-013 14014 REF: AMM 34-51-00	MOS HRS/MSC AFL	O/C			12/13/2000	13-DEC-1999 4007 2082			
345102-001	COUPLER:VOR/LOC PHASING COUPLER DMN4-17-4 SN-UNKNOWN REF: AMM 345102	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
345103-001	ANTENNA:NO. 1 VOR/ILS ANTENNA DMN4-17-1A SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
345103-002	ANTENNA:NO. 2 VOR/ILS ANTENNA DMN4-17-1A SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
345111-001	ANTENNA:AFT MARKER BEACON ANTENNA S35-1000-2 SN-UNKNOWN REF: AMM 345111	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
345112-001	ANTENNA:GLIDESLOPE ANTENNA S41422-2 SN-UNKNOWN REF: AMM 34-51-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
345201-001	ANTENNA:ADF (ANT-462B) ANTENNA 622-7384-001 966 REF: AMM 345201	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			28-AUG-1996 2015 1018			
345203-001	CONTROL:NO. 1 ADF CONTROL 622-6522-005 6220 REF: AMM 34-52-00	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			14-OCT-2002 6077 3102			
345203-002	CONTROL:NO. 2 ADF CONTROL 622-6522-005 8757 REF: AMM 34-52-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
345205-001	RECEIVER:NO. 1 ADF RECEIVER 622-7382-101 1417 REF: AMM 34-52-00	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
345205-002	RECEIVER:NO. 2 ADF RECEIVER 622-7382-101 1370 REF: AMM 34-52-00	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			03-JUN-1993 117 66			
345300-001	TRANSCEIVER:NO. 1 DME TRANSCEIVER 622-6263-001 10941 REF: AMM 345300	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
345300-002	TRANSCEIVER:NO. 2 DME TRANSCEIVER 622-6263-001 3048 REF: AMM 345300	MOS HRS/MSC AFL	O/C			11/22/1999	22-NOV-1998 3397 1748			
345302-001	ANTENNA:NO.1 DME ANTENNA S65-5366-7L 29154 REF: AMM 345302	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
345302-002	ANTENNA:NO.2 DME ANTENNA S65-5366-7L 33824 REF: AMM 345302	MOS HRS/MSC AFL	O/C				02-MAY-2000 4258 2202			
345400-001	TRANSPONDER:NO. 1 MODE-S TRANSPONDER 066-01143-2101 U1377 REF: AMM 345400	MOS HRS/MSC AFL	O/C	TSO:68 TSO:1160.8 TSO:564			19-JUL-2010 8947.8 4353			
+ 345400-001A	TRANSPONDER:FUNCTIONAL TEST NO. 1 MODE-S TRANSPONDER (34-54-00-210) REF: GENERIC NO REF	MOS HRS/MSC AFL	24		-99		13-JUL-2010	05-APR-2012		576 d
345400-001B	TRANSPONDER:RECERTIFY NO. 1 MODE-S TRANSPONDER PER FAR 91.413 REF: GENERIC NO REF	MOS HRS/MSC AFL	24		-86		19-JUL-2010 8947.8 4353	24-APR-2012		595 d
345400-002	TRANSPONDER:NO. 2 MODE-S TRANSPONDER 066-01143-2101 U1379 REF: AMM 345400	MOS HRS/MSC AFL	O/C	TSO:68 TSO:1160.8 TSO:564			19-JUL-2010 8947.8 4353			
+ 345400-002A	TRANSPONDER:FUNCTIONAL TEST NO. 2 MODE-S TRANSPONDER (34-54-00-210) REF: GENERIC NO REF	MOS HRS/MSC AFL	24		-99		13-JUL-2010	05-APR-2012		576 d

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
345400-002B	TRANSPONDER:RECERTIFY NO. 2 MODE-S TRANSPONDER PER FAR 91.413 REF: GENERIC NO REF	MOS HRS/MSC AFL	24		-86		19-JUL-2010 8947.8 4353	24-APR-2012		595 d
345401-001	CONTROLLER:ATC CONTROLLER 071-01618-0121 386 REF: AMM 34-54-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-NOV-2004 7787 3789			
345403-001	ANTENNA:NO.1 ATC (TRANSPONDER) ANTENNA S65-5366-7L 26930 REF: AMM 345403	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
345403-002	ANTENNA:NO.2 ATC (TRANSPONDER) ANTENNA S65-5366-7L 26938 REF: AMM 345403	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
346000-001	CLOCK:NO. 1 DIGITAL CLOCK 811BLB 27060 REF: AMM 346000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
346000-001A (s)	CLOCK:REMOVE NO. 1 DIGITAL CLOCK BATTERIES AND INSTALL NEW (34-62-00-303) PKG 32 REF: GENERIC NO REF	MOS HRS/MSC AFL	24				PKG 28-MAY-2009 8928.6 4336			
346000-002	CLOCK:NO. 2 DIGITAL CLOCK 811BLB 27061 REF: AMM 346000	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
346000-002A (s)	CLOCK:REMOVE NO. 2 DIGITAL CLOCK BATTERIES AND INSTALL NEW (34-62-00-303) PKG 32 REF: GENERIC NO REF	MOS HRS/MSC AFL	24				PKG 28-MAY-2009 8928.6 4336			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
346100-001	COMPUTER:NO. 1 NAVIGATION COMPUTER 7018879-03014 96040938 REF: AMM 346100	MOS HRS/MSC AFL	O/C				18-OCT-2002 6098 3111			
346100-002	COMPUTER:NO. 2 NAVIGATION COMPUTER 7018879-03014 96040942 REF: AMM 346100	MOS HRS/MSC AFL	O/C				18-OCT-2002 6098 3111			
346105-001	CONTROL UNIT:NO. 1 DISPLAY (FMS) CONTROL UNIT 7007549-901 92101245 REF: AMM 34-61-00	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-SEP-2007 8590 4155			
346105-002	CONTROL UNIT:NO. 2 DISPLAY (FMS) CONTROL UNIT 7007549-901 98072927 REF: AMM 34-61-00	MOS HRS/MSC AFL	O/C				05-NOV-1999 3945 2047			
346111-001	CONTROL:NO. 1 EFIS DISPLAY CONTROL 7005819-707 92042145 REF: AMM 34-22-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
346111-002	CONTROL:NO. 2 EFIS DISPLAY CONTROL 7005819-707 92042146 REF: AMM 34-22-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
349001	CHECK MINIMUM NAVIGATIONAL PERFORMANCE SPECIFICATIONS REF:	MOS HRS/MSC AFL	24				20-MAR-2009 8873.5 4304	20-MAR-2011		194 d
349003	LOADER:FMS DATA LOADER 7004607-901 92070756 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
349161	IND:#1 DUAL BEARING DISTN IND 622-3702-014 569 REF:	MOS HRS/MSC AFL	N/R	TSR:0 TSR:0			29-MAY-2006 8344.8 4037			
349166	IND:#2 DUAL BEARING DISTN IND 622-3702-014 1069 REF:	MOS HRS/MSC AFL	N/R	TSO:0 TSO:0 TSO:0			07-NOV-2003 7003 3486			
349171	--:CONV,#1 DUAL BEARING DIST 500-2011-00 133 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
349176	--:CONV,#2 DUAL BEARING DIST 500-2301 132 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
349201	COMPUTER:GPWS COMPUTER 965-0676-006 1595 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
349206	SPEAKER:#1 GPWS SPEAKER 4C5Z8 (QUAM) SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
349237	PROBE:GPWS AOA PROBE 861CAL501FC4 00842 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			08-APR-1993 24 15			
349269	MODULE:NO.1 CONGIGURATION MODULE 7014940-903 96031126 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		08/28/1997	28-AUG-1996 2015 1018			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
349270	MODULE:NO.2 CONFIGURATION MODULE 7014940-903 96031225 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		08/28/1997	28-AUG-1996 2015 1018			
349291	ANTENNA:#1 GPS ANTENNA S67-1575-20 3467 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		08/28/1997	28-AUG-1996 2015 1018			
349293	ANTENNA:#2 GPS ANTENNA S67-1575-20 3470 REF:	MOS HRS/MSC AFL	N/R			08/28/1997	28-AUG-1996 2015 1018			
349295	SENSOR:#1 GPS SENSOR HG2021GD02 96081752 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0		08/28/1997	28-AUG-1996 2015 1018			
349297	SENSOR:#2 GPS SENSOR HG2021GD02 96081753 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0		08/28/1997	28-AUG-1996 2015 1018			
349351	PROCESSOR:TCAS PROCESSOR 066-50000-2320 5585 REF:	MOS HRS/MSC AFL	N/R				23-JUN-2000 4370 2259			
349357	SPEAKER:#1 TCAS SPEAKER 4C30T SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			13-APR-1993 31 19			
349359	SPEAKER:#2 TCAS SPEAKER 4C30T SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			13-APR-1993 31 19			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
349369	ANTENNA:UPPER TCAS ANTENNA 071-50001-8102 11078 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			27-JUN-1994 721 355			
349370	ANTENNA:LOWER TCAS ANTENNA 071-50001-8102 12261 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			09-SEP-1994 812 405			
349375	--:ANT,L UPPER MODE-S XPDR S65-5366-7L 29819 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			19-NOV-1992 18 10			
349377	--:ANT,R UPPER MODE-S XPDR S65-5366-7L 29821 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			19-NOV-1992 18 10			
349399	FAN:TCAS RACK FAN 8124 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			19-NOV-1992 18 10			
349969	REPLACE NO. 1 FMS BATTERY REF:	MOS HRS/MSC AFL	24				09-SEP-2008 8806.5 4265	09-SEP-2010		2 d
349971	REPLACE NO. 2 FMS BATTERY REF:	MOS HRS/MSC AFL	24				09-SEP-2008 8806.5 4265	09-SEP-2010		2 d
T34T01	ADJUSTMENT/TEST WEATHER RADAR SYSTEM REF:	MOS HRS/MSC AFL	O/C							

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
T34T02	OPERATIONAL TEST ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) AND EFIS POWER FILTER BOX	MOS								
	REF:	HRS/MSC AFL	O/C							
T34T03	OPERATIONAL TEST IRS ALIGNMENT	MOS								
	REF:	HRS/MSC AFL	O/C							
CHAPTER 35 OXYGEN										
+ 35-10-00-201 (s)	FUNCTIONAL TEST CREW OXYGEN SYSTEM						PKG			
	PKG 3	MOS					20-MAR-2009			
	REF: AMM 35-10-00-201	HRS/MSC AFL	600				8873.5 4304			
351000-001	MASK ASSEMBLY:NO. 1 OXYGEN REGULATOR MASK ASSEMBLY									
	MC10-13-03	MOS		TSO:0			01-OCT-2004			
	16679	HRS/MSC	O/C	TSO:0			7647			
	REF: GENERIC NO REF	AFL		TSO:0			3743			
+ 351000-001A	MASK ASSEMBLY:RESTORATION NO. 1 OXYGEN REGULATOR MASK ASSEMBLY (35-10-00-205)									
		MOS	72				01-OCT-2004	01-OCT-2010		24 d
	REF: GENERIC NO REF	HRS/MSC AFL					7647 3743			
351000-002	MASK ASSEMBLY:NO. 2 OXYGEN REGULATOR MASK ASSEMBLY									
	MC10-13-03	MOS		TSO:0			02-NOV-2004			
	16931	HRS/MSC	O/C	TSO:0			7737			
	REF: GENERIC NO REF	AFL		TSO:0			3772			
+ 351000-002A	MASK ASSEMBLY:RESTORATION NO. 2 OXYGEN REGULATOR MASK ASSEMBLY (35-10-00-205)									
		MOS	72				02-NOV-2004	02-NOV-2010		56 d
	REF: GENERIC NO REF	HRS/MSC AFL					7737 3772			
351001-001	VALVE:OXYGEN FILL VALVE									
	170080	MOS					01-OCT-1992			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: GENERIC NO REF	AFL					0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
351013-001	CYLINDER:CREW OXYGEN CYLINDER 802895-02 AE-68483 REF: GENERIC NO REF	MOS HRS/MSC AFL	288	TSN:0 TSN:0 TSN:0			19-JUL-2010 8947.8 4353	19-JUL-2034		LIFE LIMIT 8716 d
+ 351013-001A	CYLINDER:HYDROSTATIC/FUNCTIONAL CHECK CREW OXYGEN CYLINDER PRESSURE REGULATOR (35-10-11-203) REF: GENERIC NO REF	MOS HRS/MSC AFL	36				19-JUL-2010	19-JUL-2013		MRB 1046 d
351016-001	GAUGE:OXYGEN PRESSURE GAUGE 171007 SN-UNKNOWN REF: AMM 351016	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
351016-002	GAUGE:OXYGEN PRESSURE GAUGE 600-44100-3 0090 REF: AMM 35-10-16	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			10-FEB-2003 6397 3228			
359001	BOX:COPILOT / FLIGHT CREW OXYGEN MASK STOWAGE BOX MXP135-2 15380 REF:	MOS HRS/MSC AFL	O/C				21-JAN-2003 6333 3209			
359021	OXYGEN CYLINDER:CREW PORTABLE OXYGEN CYLINDER 5500-CIV-FY-30BN 182949 REF:	MOS HRS/MSC AFL	O/C	TSN:25			01-APR-1993 19 12			
359026	OXYGEN CYLINDER:CABIN PORTABLE OXYGEN CYLINDER 5500-CIV-FY30BN 138607 REF:	MOS HRS/MSC AFL	O/C	TSN:15			01-APR-1993 19 12			
359031	OXYGEN CYLINDER:HYDROSTATIC TEST CREW PORTABLE OXYGEN CYLINDER REF:	MOS HRS/MSC AFL	60				28-MAR-2006	28-MAR-2011		MANDATORY 202 d

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
359036	OXYGEN CYLINDER:HYDROSTATIC TEST CABIN PORTABLE OXYGEN CYLINDER REF:	MOS HRS/MSC AFL	60				24-APR-2008 8728 4226	24-APR-2013		MANDATORY 960 d
359071	CHECK PASSENGER OXYGEN CONTROL PANEL MOUNT REF:	MOS HRS/MSC AFL	300				09-SEP-2008 8806.5 4265	9106.5		158.7
359076	CHECK CABIN OXYGEN CYLINDER MOUNT REF:	MOS HRS/MSC AFL	300				09-SEP-2008 8806.5 4265	9106.5		158.7
359093	CHECK OXYGEN CYLINDER MOUNTING STRUCTURE REF:	MOS HRS/MSC AFL	1000				06-JUN-2005 8180 3964	4964		611
359101	OXYGEN CYLINDER:NO. 1 CABIN OXYGEN CYLINDER 895-01015 282-13310 REF:	MOS HRS/MSC AFL	180	TSN:5			10-MAR-2004 7315.6 3614	10-OCT-2018		LIFE LIMIT 2955 d
359106	OXYGEN CYLINDER:NO. 2 CABIN OXYGEN CYLINDER 895-01015 282-12562 REF:	MOS HRS/MSC AFL	180	TSN:13			10-MAR-2004 7315.6 3614	10-FEB-2018		LIFE LIMIT 2713 d
359121	OXYGEN CYLINDER:HYDROSTATIC TEST NO. 1 CABIN OXYGEN CYLINDER REF:	MOS HRS/MSC AFL	36				19-JUL-2010 8947.8 4353	19-JUL-2013		MANDATORY 1046 d
359126	OXYGEN CYLINDER:HYDROSTATIC TEST NO. 2 CABIN OXYGEN CYLINDER REF:	MOS HRS/MSC AFL	36				19-JUL-2010 8947.8 4353	19-JUL-2013		MANDATORY 1046 d

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
359138	OXYGEN CYLINDER:FUNCTION TEST NO. 1 CABIN OXYGEN CYLINDER REGULATOR	MOS	36				19-JUL-2010 8947.8 4353	19-JUL-2013		1046 d
	REF:	HRS/MSC AFL								
359143	OXYGEN CYLINDER:FUNCTION TEST NO. 2 CABIN OXYGEN CYLINDER REGULATOR	MOS	36				19-JUL-2010 8947.8 4353	19-JUL-2013		1046 d
	REF:	HRS/MSC AFL								
359151	OXYGEN MASK:FLIGHT ENGINEER OXYGEN MASK MC10-13-103	MOS					20-FEB-2005 7940			
	2531 REF:	HRS/MSC AFL	N/R				3851			
359156	OXYGEN MASK:RESTORE FLIGHT ENGINEER OXYGEN MASK	MOS	72				20-FEB-2005 7940 3851	20-FEB-2011		166 d
	REF:	HRS/MSC AFL								
359159	OPERATIONAL TEST FLIGHT ENGINEER'S OXYGEN SYSTEM	MOS					09-SEP-2008 8806.5 4265	9406.5		458.7
	REF:	HRS/MSC AFL	600							
359201	CONTROL PANEL:PASSENGER OXYGEN CONTROL PANEL 900-002-132	MOS					08-APR-1993 24			
	167 REF:	HRS/MSC AFL	N/R	TSN:0 TSN:0			15			
359203	CONTROL PANEL:OXYGEN WARNING CONTROL PANEL 310-0766	MOS					08-APR-1993 24			
	NSN REF:	HRS/MSC AFL	N/R	TSN:0 TSN:0			15			
359218	PRESSURE SWITCH:PASSENGER OXYGEN TEST PRESSURE SWITCH P24027	MOS					08-APR-1993 24			
	SN-UNKNOWN REF:	HRS/MSC AFL	N/R	TSN:0 TSN:0			15			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
359221	CONDITION CHECK / FLOW CHECK PASSENGER OXYGEN MASK	MOS					09-SEP-2008			
	REF:	HRS/MSC	600				8806.5		9406.5	458.7
		AFL					4265			
35R001	SONALERT:CABIN OXYGEN WARNING SONALERT	MOS					08-APR-1993			
	SC628	HRS/MSC	N/R	TSN:0			24			
	REF:	AFL		TSN:0			15			
35R011	VALVE:COCKPIT OXYGEN ON/OFF VALVE	MOS					08-APR-1993			
	CRU-18A	HRS/MSC	N/R	TSN:0			24			
	11261	AFL		TSN:0			15			
	REF:									
35R016	PRESSURE SWITCH:COCKPIT OXYGEN PRESSURE SWITCH	MOS					08-APR-1993			
	P24027	HRS/MSC	N/R	TSN:0			24			
	0020	AFL		TSN:0			15			
	REF:									
35R021	PRESENTATION UNIT:COCKPIT OXYGEN PRESENTATION UNIT	MOS					08-APR-1993			
	833-610	HRS/MSC	N/R	TSN:0			24			
	2570	AFL		TSN:0			15			
	REF:									
35R026	MANIFOLD:COCKPIT DUAL O2 MANIFOLD	MOS					08-APR-1993			
	833-613-2	HRS/MSC	N/R	TSN:0			24			
	SN-UNKNOWN	AFL		TSN:0			15			
	REF:									
35R051	MASK:COCKPIT O2 MASK	MOS					08-APR-1993			
	289-601-228	HRS/MSC	N/R	TSN:0			24			
	NSN	AFL		TSN:0			15			
	REF:									
35R096	PRESENTATION UNIT:CAB O2 PRESENTATION UNIT	MOS					08-APR-1993			
	833-610	HRS/MSC	N/R				24			
	2571	AFL					15			
	REF:									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
35R101	MANIFOLD:#1 CABIN DUAL O2 MANIFOLD 833-613-2 @FS 401 REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R106	MANIFOLD:#2 CABIN DUAL O2 MANIFOLD 833-613-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R111	MANIFOLD:#3 CABIN DUAL O2 MANIFOLD 833-613-2 @FS 450 REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R116	MANIFOLD:#4 CABIN DUAL O2 MANIFOLD 833-613-2 @FS 475 REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R121	MANIFOLD:#5 CABIN DUAL O2 MANIFOLD 833-613-2 @FS 497 REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R126	MANIFOLD:#6 CABIN DUAL O2 MANIFOLD 833-613-2 @FS 504 REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R131	MANIFOLD:#7 CABIN DUAL O2 MANIFOLD 833-613-2 @FS 566 REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R151	MASK:#1 CABIN O2 MASK 289-601-224 @FS 401 REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
35R156	MASK:#2 CABIN O2 MASK 289-601-224 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R161	MASK:#3 CABIN O2 MASK 289-601-224 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R166	MASK:#4 CABIN O2 MASK 289-601-224 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R171	MASK:#5 CABIN O2 MASK 289-601-224 @FS 450 REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R176	MASK:#6 CABIN O2 MASK 289-601-224 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R181	MASK:#7 CABIN O2 MASK 289-601-224 @FS 475 REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R186	MASK:#8 CABIN O2 MASK 289-601-224 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R191	MASK:#9 CABIN O2 MASK 289-601-224 @FS 497 REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
35R196	MASK:#10 CABIN O2 MASK 289-601-224 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R201	MASK:#11 CABIN O2 MASK 289-601-224 @FS 504 REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R206	MASK:#12 CABIN O2 MASK 289-601-224 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
35R211	MASK:#13 CABIN O2 MASK 289-601-224 @FS 566 REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
T35T01	OPERATIONAL CHECK OXYGEN SYSTEMS REF:	MOS HRS/MSC AFL	O/C							
CHAPTER 36		PNEUMATIC								
36-10-00-201 (s)	VISUAL CHECK BLEED AIR DISTRIBUTION - DUCTING PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
361001-001	VALVE:NO. 1 CHECK VALVE 3202232-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
361001-002	VALVE:NO. 2 CHECK VALVE 3202232-1 2782 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-OCT-2003 7003			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
361011-001	SHUTOFF VALVE:NO. 1 10TH STAGE PRESSURE REGULATING SHUTOFF VALVE 3213876-2 1099 REF: AMM 361011	MOS HRS/MSC AFL	O/C				05-MAR-2002 5600 2870			
361011-002	SHUTOFF VALVE:NO. 2 10TH STAGE PRESSURE REGULATING SHUTOFF VALVE 3213876-2 1413 REF: AMM 361011	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
361016-001	SHUTOFF VALVE:NO. 1 BLEED AIR -14TH STAGE SHUTOFF VALVE 3289590-2 547 REF: AMM 361016	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
361016-002	SHUTOFF VALVE:NO. 2 BLEED AIR-14TH STAGE SHUTOFF VALVE 3289590-2 546 REF: AMM 361016	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
361016-004	VALVE:10TH STAGE ISOLATION VALVE 979998-1 331 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-DEC-1994 1010 502			
361016-005	VALVE:NO. 1 ENGINE 10TH STAGE PRESSURE REGULATING SHUTOFF VALVE 979998-1 753 REF:	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
361016-006	VALVE:NO. 2 ENGINE 10TH STAGE PRESSURE REGULATING SHUTOFF VALVE 979998-1 556 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-MAR-2002 5627 2883			
361021-001	VALVE:NO. 1 BLEED AIR CHECK VALVE 62490-7B 802 REF: AMM 361021	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
361021-002	VALVE:NO. 2 BLEED AIR CHECK VALVE 62490-7B 187 REF: AMM 361021	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			12-MAR-1998 2992 1506			
362100-001	INDICATOR:BLEED AIR PRESSURE INDICATOR 600-50933-3 92080318 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
362111-001	TRANSDUCER:NO. 1 PRESSURE 10TH STAGE TRANSDUCER 600-59174-9 3752-7-312 REF: AMM 362111	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-JAN-1994 507 256			
362111-002	TRANSDUCER:NO. 2 PRESSURE 10TH STAGE TRANSDUCER 600-59174-9 3241-2-32 REF: AMM 362111	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-MAY-1993 80 48			
362311-001	CONTROLLER:NO. 1 ENGINE BLEED AIR CONTROLLER 35008-32 A647 REF: AMM 362311	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
362311-002	CONTROLLER:NO. 2 ENGINE BLEED AIR CONTROLLER 35008-32 A656 REF: AMM 362311	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
369061	VALVE:APU BLEED AIR CHECK VALVE 3202832-1-1 1126 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-AUG-2001 5131 2644			
36R001	ELEMENT:LEFT SENSOR 10TH STAGE A A51WK ELEMENT 35607-2-310 NSN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			09-JUN-1995 1266 613			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
36R002	ELEMENT:LEFT SENSOR 10TH STAGE B A50WK ELEMENT 35607-2-310 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			09-JUN-1995 1266 613			
36R003	ELEMENT:RIGHT SENSOR 10TH STAGE A 49K ELEMENT 35563-2-310 NSN REF:	MOS HRS/MSC AFL	O/C	TSN:0			24-APR-2002			
36R004	ELEMENT:RIGHT SENSOR 10TH STAGE "B" A 56WK ELEMENT 35563-2-310 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-JUN-2002 5826 2976			
49-52-11-213	VALVE:APU BLEED AIR CHECK VALVE 3202896-1 1090 REF:	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0			06-MAR-2003 6432 3242 4019			
CHAPTER 38		WATER/WASTE								
389002	FILTER:WATER SYSTEM FILTER 82773 (NORDSKOG) SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R				08-APR-1993 24 15			
389003	FILTER:REPLACE WATER SYSTEM FILTER REF:	MOS HRS/MSC AFL	6				19-JUL-2010 8947.8 4353	19-JAN-2011		134 d
389033	REGULATOR:WATER SYSTEM AIR PRESSURE REGULATOR R06-A SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
389035	CHECK CONDITION / SECURITY WATER SUPPLY SYSTEM MOUNTING REF:	MOS HRS/MSC AFL	300				09-SEP-2008 8806.5 4265	9106.5		158.7

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
389081	MAST:#1 DRAIN MAST 115677-2W 904 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
389091	CHECK CONDITION / SECURITY #1 DRAIN MAST MOUNTING REF:	MOS HRS/MSC AFL	300				09-SEP-2008 8806.5 4265	9106.5		158.7
389121	TANK:#1 WATER SYSTEM TANK RA27311-39419 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
389126	TANK:#2 WATER SYSTEM TANK RA27311-39419 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
389201	HEATER:#1 GALLEY WATER HEATER 444-0007-103 NSN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
389221	HEATER:#1 LAVATORY WATER HEATER 444-0007-103 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
38R001	MAST:WASTE SYSTEM DRAIN MAST 115677-102 382 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			04-FEB-1999 3533 1813			
38R020	--:DRAIN VLVS,SINK&ICE DRWR SS63TF8 @FS 310 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
38R021	VALVE:GALLEY PURGE VALVE SS62TF4 @FS 310 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
38R025	--:PURGE VALVE, LAV. SS62TF4 @FS 574 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
38R026	VALVE:LAV. CHECK VALVE 6133F4Y @FS 574 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
CHAPTER 49 AIRBORNE AUXILIARY POWER										
49-30-10-208 (s)	REPLACE APU FUEL SUPPLY FILTER - INSTALL NEW ELEMENT PKG 3 REF: AMM 49-30-10-208	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
+ 49-40-00-210	CHECK APU STARTING AND IGNITION (A/C 5001 TO 5134 PRE SB-601-0418) - BATTERY REQUIREMENTS REF: SMM 24-30-03	MOS HRS/MSC AFL	N/A				14-MAR-2005 7984 3870			
491176	BATTERY:APU AUXILIARY BATTERY 171BS101-1 721R REF:	MOS HRS/MSC AFL	N/A				14-AUG-2000 4495 2315			
493001	PUMP:APU FUEL BOOSTER PUMP 600-62991-5 B673 REF:	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
493016	VALVE:2 WAY APU FUEL VALVE AV16E1295 N85661 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
496101-001	ECU:APU ELECTRIC CONTROL UNIT ECU 2117406-6 40-1414 REF: AMM 496101	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
497000-001	INDICATOR:APU FAULT INDICATOR 601-53004-5 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
497100-001	INDICATOR:APU EGT INDICATOR 124-491-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
497101-001	INDICATOR:APU RPM INDICATOR 124-492-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
497103-001	PANEL:APU CONTROL PANEL 600-51158-823 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
499111	METER:APU HOUR METER K19773/5-002 NSN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			08-APR-1993 24 15			
499215	--:NEG G CHCK VALVE, APU 2790441-103 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				05-OCT-2000 4603 2379			
49APU1 49.APU1	APU:APU 3800050-5-1 P-413 REF: AMM 49APU1	MOS HRS/MSC AFL	E/C	TSN:4169			20-AUG-2003 6824.1 3412			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
49R001	CAP:APU COMBUSTION CHMBR CAP 3615086-1 NSN REF:	MOS HRS/MSC AFL APS	N/R	TSN:0 TSN:0 TSN:0			31-JUL-2001 3222 4140			
49R011	SEAL:APU CARBON SEAL PN SN-UNKNOWN REF:	MOS HRS/MSC AFL APS	N/R	TSN:0			01-OCT-1992 0			
49R016	SEAL:APU COMPRESSOR SEAL PN SN-UNKNOWN REF:	MOS HRS/MSC AFL APS	N/R	TSN:0			01-OCT-1992 0			
49R021	HOUSING:APU COMP INLET HOUSING PN SN-UNKNOWN REF:	MOS HRS/MSC AFL APS	N/R	TSN:0			01-OCT-1992 0			
49R026	DEFLECTOR:APU TURB WHEEL DEFLECTOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL APS	N/R	TSN:0			01-OCT-1992 0			
49R031	WHEEL:APU TURBINE WHEEL PN SN-UNKNOWN REF:	MOS HRS/MSC AFL APS	N/R	TSN:0			01-OCT-1992 0			
49R036	NOZZLE:APU TURBINE NOZZLE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL APS	N/R	TSN:0			01-OCT-1992 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
49R041	BEARING:APU SUNGEAR BEARING PN SN-UNKNOWN REF:	MOS HRS/MSC AFL APS	N/R	TSN:0			01-OCT-1992 0			
49R046	LEAD:APU IGNITION LEAD PN SN-UNKNOWN REF:	MOS HRS/MSC AFL APS	N/R	TSN:0			01-OCT-1992 0			
49R051	--:NEG. G CK. VLV., APU 2790441-103 NSN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			17-MAY-1993 80 48			
APU Model : GTCP36-100(E) (3A/3R,600/011) Serial # P-413 Part # 3800050-5-1										
+ 49-10-00-201 (s)	APU - INSPECT APU POWER PLANT-REMOVE & INSPECT COMBUSTION CHAMBER & FUEL NOZZLE ASSEMBLY PKG 1 REF: MM 49-10-00-201	MOS HRS/MSC APUS	400	+40/-40			PKG 04-JUN-2008 5745 7579			
49-10-00-205	APU - HOT SECTION INSPECTION AND VISUAL CHECK OF COMPRESSOR ROTOR - PRE HONEYWELL SB COMBINATION REF: MM 49-10-00-205	MOS HRS/MSC APUS	N/A				20-AUG-2003 4169 6082			
49-10-00-206	APU - HOT SECTION INSPECTION AND VISUAL CHECK OF COMPRESSOR ROTOR - POST HONEYWELL SB COMBINATION REF: MM 49-10-00-206	MOS HRS/MSC APUS	2100	+40/-40			20-AUG-2003 4169 6082	6269	6309	253
+ 49-10-00-207 (s)	APU - VISUAL CHECK APU POWER PLANT - REMOVE, CLEAN, AND REINSTALL COMBUSTOR/PLENUM DRAIN ORIFICE FITTINGS PKG 1 REF: MM 49-10-00-207	MOS HRS/MSC APUS	400	+40/-40			PKG 04-JUN-2008 5745 7579			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 49-10-10-202 (s)	APU - VISUAL CHECK APU ENCLOSURE PKG 1 REF:	MOS HRS/MSC APUS	400	+40/-40			PKG 04-JUN-2008 5745 7579			
+ 49-10-60-220 (s)	APU - VISUAL CHECK APU AIR INTAKE AND SUPPLY / APU EXHAUST DUCT. PAYING PARTICULAR ATTENTION TO ADJACENT SKIN AND ASSOCIATED DUCTING. PKG 1 REF:	MOS HRS/MSC APUS	400	+40/-40			PKG 04-JUN-2008 5745 7579			
49-31-02-209 (s)	APU - INSPECT APU FUEL CONTROL UNIT FUEL FILTER - REMOVE, INSPECT AND INSTALL NEW ELEMENT PKG 1 REF: MM 49-31-02-209	MOS HRS/MSC APUS	400	+40/-40			PKG 04-JUN-2008 5745 7579			
49-42-01-211	APU - INSPECT APU STARTER MOTOR. (PART NUMBER 519892-3, -4, AND -5) - REMOVE, INSPECT AND REINSTALL REF: MM 49-42-01-211	MOS HRS/MSC APUS	N/A				20-AUG-2003 4169 6082			
49-42-01-219	APU - INSPECT APU STARTER MOTOR. (PART NUMBER 519892-6) - REMOVE, INSPECT AND REINSTALL REF: MM 49-42-01-211	MOS HRS/MSC APUS	2100	+40/-40			20-AUG-2003 4169 6082	6269	6309	253
49-43-02-212 (s)	APU - VISUAL CHECK APU IGNITER PLUG - REMOVE, CLEAN, AND REINSTALL PKG 1 REF: MM 49-43-02-212	MOS HRS/MSC APUS	400				PKG 04-JUN-2008 5745			
49-90-00-215 (s)	APU - INSPECT APU ENGINE OIL SYSTEM/AUXILIARY POWER UNIT - DRAIN APU OIL TANK / FILL EMPTY APU OIL TANK PKG 1 REF: MM 49-90-00-215	MOS HRS/MSC APUS	400				PKG 04-JUN-2008 5745 7579			
+ 49-90-01-216	APU - VISUAL CHECK APU MAGNETIC DRAIN PLUG - REMOVE MAGNETIC ELEMENT FROM DRAIN PLUG AND REINSTALL PKG 1 REF: MM 49-90-01-216	MOS HRS/MSC APUS	12 400		-52		19-JUL-2010 6016	28-MAY-2011 6416		263 d 400

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
49-90-02-217 (s)	APU - INSPECT APU ENGINE OIL SYSTEM OIL FILTER - REMOVE, INSPECT AND INSTALL NEW ELEMENT PKG 1 REF: MM 49-90-02-217	MOS HRS/MSC APUS	400				PKG 04-JUN-2008 5745 7579			
+ 491000-001	ROTOR:APU - TURBINE ROTOR 3615880-1 980134502370 REF:	MOS HRS/MSC APUS	10000	TSN:0			25-AUG-1998 2046 2608	12046	6030	LIFE LIMIT
+ 491010-001	ROTOR:APU - COMPRESSOR ROTOR 3822014 SN-UNKNOWN REF: MM 49-10-00-206	MOS HRS/MSC APUS	10000	TSO:2046TSN:0			25-AUG-1998 2046 2608	12046	6030	
493010	CONTROL:APU - FUEL CONTROL 3882600-5-1 A-1782 REF:	MOS HRS/MSC APUS	O/C	TSN:0			25-AUG-1998 2046 2608			
493020-001	NOZZLE:APU - FUEL NOZZLE 3830061-5 3794 REF: MM 49-10-00-201	MOS HRS/MSC APUS	O/C	TSN:0			25-AUG-1998 2046 2608			
493025	ORIFICE:APU - PLENUM DRAIN ORIFICE 3606721-1 SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0			25-AUG-1998 2046 2608			
493030	ORIFICE:APU - COMBUSTOR DRAIN ORIFICE 3606721-1 SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0			25-AUG-1998 2046 2608			
493040	VALVE:APU - FUEL SHUTOFF SOLENOID VALVE 692545-1 SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0			25-AUG-1998 2046 2608			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
494000-001	IGNITER PLUG:APU - IGNITER PLUG 3888366-1 N/A REF: MM 49-43-02-212	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			06-JUN-2005 4929 7030			
494010-001	STARTER:APU - MOTOR APU STARTER 519892-6-2 125-2710C REF: MM 49-42-01-211	MOS HRS/MSC APUS	O/C	TSO:0 TSO:0 TSO:0			20-AUG-2003 4169 6082			
494034-001	IGNITION:APU - UNIT APU IGNITION 3888000-2 050218058555 REF: MM 494034-001	MOS HRS/MSC APUS	O/C				01-AUG-2005			
495010-001	VALVE:APU - APU PNEU SURGE VALVE 978668-3-1 3149 REF: MM 495010-001	MOS HRS/MSC APUS	O/C	TSN:0			25-AUG-1998 2046 2608			
495014-001	VALVE:APU - PNEUMATIC SHUTOFF VALVE 109776-4-2 581 REF: MM 495014-001	MOS HRS/MSC APUS	O/C	TSN:0			25-AUG-1998 2046 2608			
497010	TRANSDUCER:APU - MOTION PICK UP TRANSDUCER 3876000-1 SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0			25-AUG-1998 2046 2608			
497020	THERMOCOUPLE:APU - IMMERSION THERMOCOUPLE 3876003-1 SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0			25-AUG-1998 2046 2608			
497030	HOURLMETER:APU - HOURLMETER 3888033-4 SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0			25-AUG-1998 2046 2608			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
499010	PUMP:APU - OIL PUMP 38880000-2 SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0			25-AUG-1998 2046 2608			
499050	VALVE:APU - OIL PRESSURE REGULATING VALVE 3880021-16 SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0			25-AUG-1998 2046 2608			
499060	SWITCH:APU - HIGH OIL TEMPERATURE SWITCH 3888030-1 SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0			25-AUG-1998 2046 2608			
499070	SWITCH:APU - LOW OIL PRESSURE SWITCH 3876001-8 1964 REF:	MOS HRS/MSC APUS	O/C	TSN:0			25-AUG-1998 2046 2608			
49R006	CHAMBER:APU - APU COMBUSTION CHAMBER 3830077-9 61013-73608R REF:	MOS HRS/MSC APUS	N/R				24-APR-2002 3607			
CHAPTER 52 DOORS										
52-00-00-201 (s)	VISUAL CHECK PASSENGER/CREW ENTRANCE DOOR SEAL PKG 2 REF: AMM 52-00-00-201	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
+ 52-10-00-101	NDT CHECK PASSENGER DOOR HINGE REF: NDT ET-52-10-01	MOS HRS/MSC AFL	2400				09-JUN-2005 8180 3964	10580		1632.2
52-10-00-202 (s)	VISUAL CHECK PASSENGER/CREW ENTRANCE DOOR THAT WATER DRAINS ARE CLEAR PKG 2 REF: GENERIC NO REF	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 52-12-00-203 (s)	VISUAL CHECK DOWNWARD OPENING PASSENGER/CREW ENTRANCE DOOR - OF HINGE, PAYING PARTICULAR ATTENTION TO CRACKING AND CORROSION OF THE LUGS (WITHOUT DISASSEMBLY OF HINGE).						PKG			
	PKG 3	MOS					20-MAR-2009			
	REF: GENERIC NO REF	HRS/MSC	600				8873.5			
		AFL					4304			
+ 52-12-00-204	VISUAL CHECK DOWNWARD OPENING PASSENGER/CREW ENTRANCE DOOR (POWER ASSIST SYSTEM)									
		MOS					05-OCT-2007			
	REF: GENERIC NO REF	HRS/MSC					8612			
		AFL	600		-36		4166	4730	4790	377
52-12-00-205 (s)	LUBRICATE DOWNWARD OPENING DOOR (PRE SB-601-0451) - INTERNALLY LUBRICATE PASSENGER/CREW ENTRANCE DOOR						PKG			
	PKG 4	MOS					08-JUN-2005			
	REF: AMM 52-12-00-205	HRS/MSC	1200				8180			
		AFL					3964			
52-12-00-206 (s)	VISUAL CHECK DOWNWARD OPENING PASSENGER/CREW ENTRANCE DOOR						PKG			
	PKG 4	MOS					15-AUG-2005			
	REF: GENERIC NO REF	HRS/MSC	1200				8215.3			
		AFL					3975			
+ 52-12-00-207 (s)	FUNCTIONAL TEST DOWNWARD OPENING PASSENGER/CREW ENTRANCE DOOR MECHANISM						PKG			
	PKG 4	MOS					02-AUG-2005			
	REF: AMM 52-12-00-207	HRS/MSC	1200				8215.3			
		AFL					3975			
+ 52-12-00-218 (s)	SERVICING DOWNWARD OPENING PASSENGER/CREW ENTRANCE DOOR - VISUAL CHECK (EXTERNAL) - EXTERNALLY LUBRICATE PASSENGER/CREW ENTRANCE DOOR						PKG			
	PKG 2	MOS					09-SEP-2008			
	REF: AMM 52-12-00-218	HRS/MSC	300				8806.5			
		AFL					4265			
+ 52-12-00-219 (s)	FUNCTIONAL TEST DOWNWARD OPENING PASSENGER/CREW ENTRANCE DOOR CAM LATCH MECHANISM						PKG			
	PKG 2	MOS					09-SEP-2008			
	REF: AMM 52-12-00-219	HRS/MSC	300				8806.5			
		AFL					4265			
52-12-00-220 (s)	LUBRICATE DOWNWARD OPENING DOOR (POST SB-601-0451) - INTERNALLY LUBRICATE PASSENGER/CREW ENTRANCE DOOR									
		MOS					08-JUN-2005			
	REF: AMM 52-12-00-220	HRS/MSC	N/A				8180			
		AFL					3964			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
52-20-00-105	VISUAL CHECK OVERWING EMERGENCY EXIT - ATTACHMENT FITTINGS	MOS HRS/MSC AFL	10200				01-OCT-1992	10200	1252.2	
	REF: NDT VC-52-20-01									
+ 52-20-00-208 (s)	OPERATIONAL TEST OVERWING EMERGENCY EXIT	MOS HRS/MSC AFL	24				PKG 28-MAY-2009 8928.6 4336			
	PKG 32									
	REF: AMM 52-20-00-208									
+ 52-20-00-209 (s)	CHECK OVERWING EVERGENCY EXIT LIGHT CHECK	MOS HRS/MSC AFL	24				PKG 28-MAY-2009 8928.6 4336			
	PKG 32									
	REF: AMM 52-20-00-209									
52-20-00-210 (s)	VISUAL CHECK OVERWING EMERGENCY EXIT - OF ALL STRUCTURE, PAYING PARTICULAR ATTENTION TO THE STOPS, FITTINGS, ATTACHMENTS AND TO THE DOOR SEAL.	MOS HRS/MSC AFL	60				PKG 05-APR-2006 8305.8 4018			
	PKG 34									
	REF: GENERIC NO REF									
+ 52-20-00-221 (s)	LUBRICATE THE OVERWING EMERGENCY EXIT DOOR	MOS HRS/MSC AFL	24				PKG 28-MAY-2009 8928.6 4336			
	PKG 32									
	REF: AMM 12-20-00 15,16,23									
52-30-00-211 (s)	VISUAL CHECK BAGGAGE COMPARTMENT DOOR - OF ALL STRUCTURE, PAYING PARTICULAR ATTENTION TO THE DOOR ALIGNMENT CROTCH FITTINGS, SURROUNDING STRUCTURE AND THE DOOR SEAL.	MOS HRS/MSC AFL	60				PKG 05-APR-2006 8305.8 4018			
	PKG 34									
	REF: GENERIC NO REF									
+ 52-70-00-212 (s)	FUNCTIONAL TEST DOOR WARNING - BAGGAGE DOOR SWITCHES - PASSENGER/CREW ENTRANCE DOOR SWITCHES	MOS HRS/MSC AFL	1200				PKG 07-JUN-2005 8180 3964			
	PKG 4									
	REF: AMM 52-70-00-212									
+ 52-70-00-217 (s)	OPERATIONAL TEST DOOR WARNING - PASSENGER/CREW ENTRANCE DOOR SWITCHES	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	PKG 2									
	REF: AMM 52-70-00-217									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 52-80-00-102	VISUAL CHECK MAIN LANDING GEAR DOORS HINGES (A/C 5001 TO 5006 ONLY)	MOS						01-OCT-1992		
	REF: NDT VC-52-10-03	HRS/MSC AFL	N/A					0		0
520011	MECHANISM:BAGGAGE DOOR LATCH MECHANISM 600-35025-1 SN-UNKNOWN	MOS						01-OCT-1992		
	REF:	HRS/MSC AFL	O/C	TSN:0				0		0
521002-001	SPRING:FORWARD GAS SPRING 601R31911-13 MS001094	MOS						11-OCT-2004		
	REF: GENERIC NO REF	HRS/MSC AFL	O/C					7664		3752
521002-002	SPRING:AFT GAS SPRING 601R31911-13 MS001106	MOS						11-OCT-2004		
	REF: GENERIC NO REF	HRS/MSC AFL	O/C					7664		3752
529081	MOTOR:BAGG DR SPRING FWD MOTOR ML3844-11A 12387	MOS						05-OCT-2007		
	REF:	HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0						
529083	MOTOR:BAGGAGE DOOR AFT MOTOR ML3844-12A 12552	MOS						05-OCT-2007		
	REF:	HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0						
529101	PROXIMITY SWITCH:FORWARD BAGGAGE DOOR PROXIMITY SWITCH 8-405-04 22553A	MOS						30-OCT-2003		
	REF:	HRS/MSC AFL	N/R					7003		0
529111	--:SW, LAVATORY SERVICE DOOR V3L-111-D8 NSN	MOS						16-MAR-1995		
	REF:	HRS/MSC AFL	N/R	TSN:0 TSN:0				1131		559

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
52R001	ACTUATOR:MAIN ENT. DOOR ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
52R002	--:MCROSWT, HYD 3A SVC DOOR 1HM11 NSN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			05-APR-1994 622 299			
52R003	--:MCROSWT, HYD 3B SVC DOOR 1HM11 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			05-APR-1994 622 299			
52R021	--:PRX SW,DR OUT HNDL S107MB 8-405-04 B55055 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			21-DEC-2004 7818 3803			
52R026	--:PROX SW,MAIN DR FWD 8-405-04 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
C52-00-801 (s)	CPCP CHECK OVERWING EMERGENCY EXIT DOOR, EXTERNAL PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C52-00-802 (s)	CPCP CHECK BAGGAGE COMPARTMENT DOOR STRUCTURE PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C52-00-803 (s)	CPCP CHECK PASSENGER/CREW ENTRANCE DOOR STRUCTURE (EXTERNAL) PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	48				19-MAR-2007 8468 4101			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
C52-00-804 (s)	CPCP CHECK MAIN LANDING GEAR DOORS PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C52-00-805 (s)	CPCP CHECK PASSENGER/CREW ENTRANCE DOOR STRUCTURE (INTERNAL) PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C52-00-806 (s)	CPCP CHECK OVERWING EMERGENCY EXIT DOOR (INTERNAL) PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
CHAPTER 53 FUSELAGE										
53-00-00-201 (s)	VISUAL CHECK FUSELAGE - EXTERNAL PKG 2 REF: GENERIC NO REF	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
53-00-00-202 (s)	VISUAL CHECK FUSELAGE - OF THE EXTERNAL SKIN PKG 4 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200				PKG 02-AUG-2005 8215.3 3975			
53-00-00-203 (s)	VISUAL CHECK FUSELAGE - EXTERNAL - ALONG RIVET LINES, PAYING PARTICULAR ATTENTION FOR SIGNS OF CORROSION INDICATED BY PULLED RIVETS, DISCOLORED OR BLISTERED PAINT AND/OR BULGING SKINS. PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG 05-APR-2006 8305.8 4018			
+ 53-00-00-204	VISUAL CHECK FUSELAGE STRUCTURE (INTERNAL) - FS 169.00 TO FS 202.75 REF: NDT VC-53-10-57	MOS HRS/MSC AFL	240				01-OCT-1992 0 0	01-OCT-2012	30-NOV-2012	755 d
+ 53-00-00-231	VISUAL CHECK FUSELAGE STRUCTURE (INTERNAL) - FS 202.75 TO FS 621.0, BELOW FLOOR REF: NDT VC-53-10-59	MOS HRS/MSC AFL	60		-4		05-OCT-2007 8612 4166	01-OCT-2012	30-NOV-2012	755 d

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 53-00-00-232	VISUAL CHECK FUSELAGE STRUCTURE (INTERNAL) - FS 202.75 TO FS 621.0, ABOVE FLOOR	MOS HRS/MSC AFL	240				01-OCT-1992 0 0	01-OCT-2012	30-NOV-2012	755 d
	REF: NDT VC-53-10-58									
+ 53-00-00-233	VISUAL CHECK FUSELAGE STRUCTURE (INTERNAL) - FS 621.0 TO FS 755.0	MOS HRS/MSC AFL	60		-4		05-OCT-2007 8612 4166	01-OCT-2012	30-NOV-2012	755 d
	REF: NDT VC-53-10-60									
+ 53-10-00-102	VISUAL CHECK WINDSHIELD UPPER SILL - FS 234.0, BL 2.5	MOS HRS/MSC AFL	1200				06-JUN-2005 8180 3964	9380	9380	AIRWORTHINESS 432.2
	PKG 4									
	REF: NDT VC-53-10-14									
+ 53-10-00-103	VISUAL CHECK UNDERFLOOR PRESSURE BULKHEAD - FS 409.0	MOS HRS/MSC AFL	15000				28-JUN-2004 7576 3705	22576	22576	13628.2
	REF: GENERIC NO REF									
+ 53-10-00-104	NON DESTRUCTIVE TEST KEEL LONGERON	MOS HRS/MSC AFL	1200				10-JUN-2005 8180 3964	9380	9380	AIRWORTHINESS 432.2
	PKG 4									
	REF: NDT ET-53-10-05									
+ 53-10-00-105	VISUAL CHECK FLOOR BEAM ATTACHMENT TO PRESSURE BULKHEAD - FS 621.0	MOS HRS/MSC AFL	12600					12600 M		3652.2
	REF: NDT VC-53-10-30									
+ 53-10-00-106	VISUAL CHECK WINDSHIELD LOWER SILL - FS 209.0	MOS HRS/MSC AFL	1800				09-JUN-2005 8180 3964	9980	9980	AIRWORTHINESS 1032.2
	REF: NDT VC-53-10-11									
+ 53-10-00-107	VISUAL CHECK REAR PRESSURE BULKHEAD WEB - FEED-THROUGH HOLES AND CUTOUTS FS 621.0	MOS HRS/MSC AFL	2400				30-OCT-2003 7003 3486	9403	9403	AIRWORTHINESS 455.2
	REF: NDT VC-53-10-31									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 53-10-00-108	VISUAL CHECK WINDSHIELD LOWER SILL - FS 235.0, FS 249.0 AND FS 264.0	MOS					09-SEP-2008			AIRWORTHINESS
	REF: NDT VC-53-10-12	HRS/MSC AFL	2400				8806.5 4265	11206.5	11206.5	2258.7
+ 53-10-00-109	VISUAL CHECK FORWARD FUSELAGE FRAME - FS 220.0, WL 103.9	MOS					31-OCT-2003			AIRWORTHINESS
	REF: NDT VC-53-10-15	HRS/MSC AFL	2400				7003 3486	9403	9403	455.2
+ 53-10-00-110	VISUAL CHECK INTEGRAL ATTACHMENT FRAME - FS 513.0, BL 16.0	MOS								AIRWORTHINESS
	REF: NDT VC-53-10-28	HRS/MSC AFL	15000					15000 M		6052.2
+ 53-10-00-111	NON DESTRUCTIVE TEST AND VISUAL CHECK OVERWING EMERGENCY EXIT AND SURROUND STRUCTURE	MOS								AIRWORTHINESS
	REF: NDT ET-53-10-04	HRS/MSC AFL	15000					15000 M		6052.2
+ 53-10-00-113	VISUAL CHECK REAR PRESSURE BULKHEAD WEB - UNDER THE VERTICAL STIFFENERS	MOS					08-MAR-2003			AIRWORTHINESS
	REF: NDT VC-53-10-32	HRS/MSC AFL	4200				6432 3242	10632	10632	1684.2
+ 53-10-00-114	VISUAL CHECK REAR PRESSURE BULKHEAD, FLOOR BEAMS, FUSELAGE SKIN PANELS AND ASSOCIATED STRUCTURE AT FS 621.0	MOS								AIRWORTHINESS
	REF: NDT VC-53-10-37	HRS/MSC AFL	15000					15000 M		6052.2
+ 53-10-00-116	VISUAL CHECK FORWARD PRESSURE BULKHEAD VERTICAL STIFFENER - FS 202.75, BL 22.0	MOS					22-FEB-2001			AIRWORTHINESS
	REF: NDT VC-53-10-01	HRS/MSC AFL	4800	TSI:59			4859 2516	9600	9600	652.2
+ 53-10-00-117	NON DESTRUCTIVE CHECK FUSELAGE FRAME DRAG ANGLE - FS 755.0, BL 5.28	MOS					29-JUN-2004			AIRWORTHINESS
	REF: NDT ET-53-30-10	HRS/MSC AFL	4800				7576 3705	12376	12376	3428.2

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 53-10-00-118	VISUAL CHECK LONGITUDINAL FLOOR BEAMS - FS 513.0, BL 18.0	MOS								AIRWORTHINESS
	REF: NDT VC-53-10-27	HRS/MSC AFL	12000					12000 M		3052.2
+ 53-10-00-120	VISUAL CHECK STIFFENING VERTICAL ANGLES ON FORWARD FACE OF ENGINE SUPPORT BEAM - FS 625.3 - FOR CRACKS AND DISTORTION	MOS								AIRWORTHINESS
	REF: NDT VC-53-10-39	HRS/MSC AFL	15000					15000 M		6052.2
+ 53-10-00-122	VISUAL CHECK TRANSVERSE BEAM - AFT PRESSURE BULKHEAD - FS 621.0	MOS					15-JUN-2002			AIRWORTHINESS
	REF: NDT VC-53-10-29	HRS/MSC AFL	6000				5874 2988	11874	11874	2926.2
+ 53-10-00-123	VISUAL CHECK FORWARD PRESSURE BULKHEAD WEB - FS 202.75	MOS					07-MAR-2003			AIRWORTHINESS
	REF: NDT VC-53-10-02	HRS/MSC AFL	6000				6432 3242	12432	12432	3484.2
+ 53-10-00-124	VISUAL CHECK LONGITUDINAL FLOOR BEAMS - FS 484.0	MOS								AIRWORTHINESS
	REF: NDT VC-53-10-24	HRS/MSC AFL	15000					15000 M		6052.2
+ 53-10-00-125	VISUAL CHECK INTERCOSTALS AND CLIPS - FS 621.0 TO FS 625.3	MOS								AIRWORTHINESS
	REF: NDT VC-53-10-33	HRS/MSC AFL	9600					9600 M		652.2
+ 53-10-00-126	VISUAL CHECK PRESSURE BULKHEAD STIFFENER - FS 621.0	MOS								AIRWORTHINESS
	REF: NDT VC-53-10-35	HRS/MSC AFL	9000					9000 M		52.2
+ 53-10-00-127	NON DESTRUCTIVE TEST AND VISUAL CHECK SIDE PANEL END POST - FS 280.0	MOS								AIRWORTHINESS
	REF: NDT ET-53-10-01	HRS/MSC AFL	9600					9600 M		652.2

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
53-10-00-128	VISUAL CHECK OVERWING FLOOR INTERCOSTAL - FS 421.0, 427.0, 439.0, 449.85, 461.5, 469.58, 476.72, 484.0	MOS					01-OCT-1992			AIRWORTHINESS
	REF: NDT VC-53-10-21	HRS/MSC AFL	9600				0 0	9600	9600	652.2
53-10-00-129	VISUAL CHECK CLEAT - FRAME TO LONGERON - FS 439.0, 461.0, 484.0, 499.0, 529.0, 544.0	MOS					01-OCT-1992			AIRWORTHINESS
	REF: NDT VC-53-10-22	HRS/MSC AFL	9600				0 0	9600	9600	652.2
+ 53-10-00-130	VISUAL CHECK FLOOR STRUCTURE AND UNDERFLOOR LONGERONS - FS 513.0, BL 45.0	MOS								AIRWORTHINESS
	REF: NDT VC-53-10-26	HRS/MSC AFL	15000					15000 M		6052.2
+ 53-10-00-131	VISUAL CHECK KEEL LONGERON LINKS AND BOLTS	MOS								AIRWORTHINESS
	REF: NDT VC-53-10-25	HRS/MSC AFL	14400					14400 M		5452.2
53-10-00-133	VISUAL CHECK PASSENGER DOOR AND SURROUNDING STURCTURE	MOS					01-OCT-1992			AIRWORTHINESS
	REF: NDT VC-53-10-18	HRS/MSC AFL	15000				0 0	15000	15000	6052.2
53-10-00-134	VISUAL CHECK PRESSURE FLOOR - WING TIE BEAM - FS 460.0	MOS					01-OCT-1992			AIRWORTHINESS
	REF: NDT VC-53-10-23	HRS/MSC AFL	15000				0 0	15000	15000	6052.2
53-10-00-135	VISUAL CHECK FUSELAGE FRAME CAP ANGLE - FS 755.0	MOS					01-OCT-1992			AIRWORTHINESS
	REF: NDT VC-53-10-42	HRS/MSC AFL	15000				0 0	15000	15000	6052.2
53-10-00-136	VISUAL CHECK FUSELAGE FRAME AT FS755.0 - VERTICAL STABILIZER FRONT SPAR ATTACHMENT	MOS					01-OCT-1992			AIRWORTHINESS
	REF: NDT VC-53-10-44	HRS/MSC AFL	15000				0 0	15000	15000	6052.2

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
53-10-00-137	VISUAL CHECK FORWARD PRESSURE BULKHEAD VERTICAL MEMBER NEAR BL 22.0, WL 79.5 - WL 93.0	MOS					01-OCT-1992			AIRWORTHINESS
	REF: NDT VC-53-10-04	HRS/MSC AFL	15000				0 0	15000	15000	6052.2
53-10-00-138	VISUAL CHECK FUSELAGE FRAME FS 235.0 UPPER CAP ANGLE AT BL 8.0.	MOS					01-OCT-1992			AIRWORTHINESS
	REF: NDT VC-53-10-16	HRS/MSC AFL	15000				0 0	15000	15000	6052.2
53-10-00-139	VISUAL CHECK PILOT FLOOR CONNECTION CLIPS AT BL 13.0.	MOS					01-OCT-1992			AIRWORTHINESS
	REF: NDT VC-53-10-05	HRS/MSC AFL	15000				0 0	15000	15000	6052.2
53-10-00-140	VISUAL CHECK FORWARD PRESSURE BULKHEAD WEB AT WL 79.5 TO 91.7	MOS					01-OCT-1992			AIRWORTHINESS
	REF: NDT VC-53-10-03	HRS/MSC AFL	15000				0 0	15000	15000	6052.2
53-10-00-141	VISUAL CHECK NLG BEAM WEB BELOW DRAG BEAM - FS 210.0 TO FS 215.0.	MOS					01-OCT-1992			AIRWORTHINESS
	REF: NDT VC-53-10-06	HRS/MSC AFL	15000				0 0	15000		6052.2
53-10-00-142	VISUAL CHECK NLG DRAG STRUT AT FS 213.0.	MOS					01-OCT-1992			AIRWORTHINESS
	REF: NDT VC-53-10-08	HRS/MSC AFL	15000				0 0	15000		6052.2
53-10-00-143	VISUAL CHECK NLG BEAM VERTICAL STIFFENER CLIP - FS 215.0.	MOS					01-OCT-1992			AIRWORTHINESS
	REF: NDT VC-53-10-09	HRS/MSC AFL	15000				0 0	15000		6052.2
53-10-00-144	VISUAL CHECK NLG BEAM UPPER CAP - FS 210.0.	MOS					01-OCT-1992			AIRWORTHINESS
	REF: NDT VC-53-10-07	HRS/MSC AFL	15000				0 0	15000		6052.2

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
53-10-00-145	VISUAL CHECK NLG BEAM LOWER CAP AT FS 224.0. REF: NDT VC-53-10-10	MOS HRS/MSC AFL	15000				01-OCT-1992 0 0	15000	6052.2	
53-10-00-146	VISUAL CHECK OVERWING EMERGENCY EXIT - SURROUND STRUCTURE. REF: NDT VC-53-10-19	MOS HRS/MSC AFL	15000				01-OCT-1992 0 0	15000	6052.2	
53-10-00-147	VISUAL CHECK PASSENGER DOOR FRAMES - FS 310.0 AND FS 349.0. REF: NDT VC-53-10-17	MOS HRS/MSC AFL	15000				01-OCT-1992 0 0	15000	6052.2	
53-10-00-148	VISUAL CHECK FRAME ASSEMBLY PRESSURE BULKHEAD - VERTICAL STIFFENER - FS 621.0. REF: NDT VC-53-10-36	MOS HRS/MSC AFL	15000				01-OCT-1992 0 0	15000	6052.2	
53-10-00-149	VISUAL CHECK REAR PRESSURE BULKHEAD - FS 621.0 - FRAME CAP. REF: NDT VC-53-10-34	MOS HRS/MSC AFL	15000				01-OCT-1992 0 0	15000	6052.2	
53-10-00-150	VISUAL CHECK REAR PRESSURE BULKHEAD VERTICAL STIFFENER. REF: NDT VC-53-10-38	MOS HRS/MSC AFL	15000				01-OCT-1992 0 0	15000	6052.2	
+ 53-10-00-151	NON DESTRUCTIVE CHECK OUTER FLANGE CAP SPLICE ANGLE - FS 625.3. REF: NDT ET-53-10-07	MOS HRS/MSC AFL	15000					15000 M	6052.2	
+ 53-10-00-152	VISUAL CHECK FRAME SPLICE - FS 672.2, STRINGER 6. REF: NDT VC-53-10-41	MOS HRS/MSC AFL	15000					15000 M	6052.2	

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 53-10-00-153	VISUAL CHECK FUSELAGE FRAME FS 755.0 WEB BL 5.5 WL 125.0 TO WL 131.0	MOS								
	REF: NDT VC-53-10-43	HRS/MSC AFL	15000						15000 M	6052.2
53-10-00-154	VISUAL CHECK STRINGER #8 (L/R), 17 (L/R) AND 24 (L/R) BETWEEN FRAMES 55.62% AND 67.5% OF THE VERTICAL STABILIZER CHORD (A/C 5001 TO 5134 POST SB 601-0262 AND A/C 5135 TO 5194)	MOS					01-OCT-1992			
	REF: NDT VC-53-10-45	HRS/MSC AFL	15000				0		15000	6052.2
53-10-00-178	NON DESTRUCTIVE TEST AND VISUAL CHECK FUSELAGE TO FRAME ATTACHMENT - FS 424.0, WL 73.0	MOS					01-OCT-1992			
	REF: NDT ET-53-10-09	HRS/MSC AFL	15000				0		15000	6052.2
+ 53-10-00-190	ACCOMPLISH MACHINED STRAP - FS409.0, LBL6.0 TO RBL6.0 (POST 601-0503)	MOS								
	REF: GENERIC NO REF	HRS/MSC AFL	15000				0		15000	6052.2
+ 53-10-00-191	ACCOMPLISH FUSELAGE FRAME CAP - FS409.0, LBL18.0 AND RBL18.0 (POST SB 601-0503)	MOS								
	REF: GENERIC NO REF	HRS/MSC AFL	15000				0		15000	6052.2
53-10-00-205 (s)	VISUAL CHECK MAIN FRAME (PRSSURE BULKHEAD FS202.75) OF THE BULKHEAD WEB AND DOUBLERS AROUND THE FEED THROUGH HOLES, PAYING PARTICULAR ATTENTION FOR CRACKS AND CORROSION.						PKG			
	PKG 34	MOS	60				05-APR-2006			
	REF: GENERIC NO REF	HRS/MSC AFL					8305.8 4018			
53-10-00-206 (s)	VISUAL CHECK MAIN FRAME - FS 625.3 & ENGINE SUPPORT BEAM ATTACHMENT						PKG			
	PKG 34	MOS	60				05-APR-2006			
	REF: GENERIC NO REF	HRS/MSC AFL					8305.8 4018			
53-10-00-207 (s)	VISUAL CHECK MAIN FRAME (KEEL LONGERONS) OF THE FOLLOWING ITEMS						PKG			
	PKG 34	MOS	60				05-APR-2006			
	REF: GENERIC NO REF	HRS/MSC AFL					8305.8 4018			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
53-10-00-208 (s)	VISUAL CHECK MAIN FRAME - FS 755.0, PAYING PARTICULAR ATTENTION TO THE MACHINED ATTACHMENT FITTINGS FOR THE VERTICAL STABILIZER FRONT SPAR AND ADJACENT WEB PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG 05-APR-2006 8305.8 4018			
53-10-00-209 (s)	VISUAL CHECK MAIN FRAME - FLOOR BEAM END FITTINGS AT FS621.0 PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG 05-APR-2006 8305.8 4018			
53-10-00-210 (s)	VISUAL CHECK MAIN FRAME - PASSENGER DOOR SURROUND STRUCTURE PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG 05-APR-2006 8305.8 4018			
53-10-00-211 (s)	VISUAL CHECK MAIN FRAME - OVERWING EMERGENCY EXIT SURROUND STRUCTURE PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG 05-APR-2006 8305.8 4018			
53-10-00-212 (s)	VISUAL CHECK MAIN FRAME - BAGGAGE DOOR SURROUND STRUCTURE PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG 05-APR-2006 8305.8 4018			
53-10-00-213 (s)	VISUAL CHECK MAIN FRAME - EQUIPMENT BAY DOOR SURROUND STRUCTURE PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG 05-APR-2006 8305.8 4018			
53-10-00-214 (s)	VISUAL CHECK MAIN FRAME - FUSELAGE FLOOR BEAM SPLICES PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG 05-APR-2006 8305.8 4018			
53-10-00-215 (s)	VISUAL CHECK MAIN FRAME - FRAME ASSY FS 424.0, PAYING PARTICULAR ATTENTION TO THE INTEGRAL WING ATTACHMENT LUG AND THE UNDERFLOOR LONGERON ATTACHMENT POINTS PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG 05-APR-2006 8305.8 4018			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
53-10-00-216 (s)	VISUAL CHECK MAIN FRAME - FRAME ASSY FS 473.15, PAYING PARTICULAR ATTENTION TO THE INTEGRAL WING ATTACHMENT LUG AND THE UNDERFLOOR LONGERON ATTACHMENT POINTS.						PKG			
	PKG 34	MOS	60				05-APR-2006			
	REF: GENERIC NO REF	HRS/MSC					8305.8			
		AFL					4018			
53-10-00-217 (s)	VISUAL CHECK MAIN FRAME - FRAME ASSY FS 513.0						PKG			
	PKG 34	MOS	60				05-APR-2006			
	REF: GENERIC NO REF	HRS/MSC					8305.8			
		AFL					4018			
53-10-00-218 (s)	VISUAL CHECK MAIN FRAME - INTERNAL (FRAME ASSY FS 640.0)						PKG			
	PKG 34	MOS	60				05-APR-2006			
	REF: GENERIC NO REF	HRS/MSC					8305.8			
		AFL					4018			
53-10-00-219 (s)	VISUAL CHECK MAIN FRAME - INTERNAL (FRAME ASSY FS 654.5)						PKG			
	PKG 34	MOS	60				05-APR-2006			
	REF: GENERIC NO REF	HRS/MSC					8305.8			
		AFL					4018			
53-10-00-220 (s)	VISUAL CHECK MAIN FRAME - INTERNAL (FS 672.2 & FS 682.2)						PKG			
	PKG 34	MOS	60				05-APR-2006			
	REF: GENERIC NO REF	HRS/MSC					8305.8			
		AFL					4018			
53-10-11-228	INSPECT FLOOR STRUCTURE - UNDER TOILET & GALLEY (WITHOUT REMOVAL)									
	PKG 30	MOS	12				19-JUL-2010	19-JUL-2011		315 d
	REF: GENERIC NO REF	HRS/MSC					8947.8			
		AFL					4353			
53-10-11-230 (s)	DETAILED INSPECTION FLOOR STRUCTURE (PRE OR POST SB 601-0372) - OF ALL UNDER FLOOR STRUCTURE (INCLUDING BEAMS), PAYING PARTICULAR ATTENTION FOR CORROSIVE SPILLAGE.						PKG			
	PKG 34	MOS	60				05-APR-2006			
	REF: GENERIC NO REF	HRS/MSC					8305.8			
		AFL					4018			
53-20-00-155	VISUAL CHECK PILOT'S FLOOR WEB ADJACENT TO PRESSURE BULKHEAD - FS 203.0, BL 16.0									
		MOS					01-OCT-1992			
	REF: NDT VC-53-20-01	HRS/MSC	15000				0	15000		6052.2
		AFL					0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 53-30-00-156	NDT CHECK CABIN WINDOW CUTOUTS	MOS					09-SEP-2008			
	REF: NDT ET-53-30-01	HRS/MSC AFL	600		-26.5		8806.5 4265		9380	432.2
+ 53-30-00-158	VISUAL CHECK LIGHT FUSELAGE FRAMES, FS220.00 TO FS605.00	MOS					22-FEB-2001			
	REF: NDT VC-53-30-10	HRS/MSC AFL	15000				4859 2516		15000	6052.2
+ 53-30-00-160	VISUAL CHECK FUSELAGE SKIN PANEL - FS 625.3, STRINGER 0.0	MOS								
	REF: NDT VC-53-30-12	HRS/MSC AFL	15000						15000 M	6052.2
+ 53-30-00-162	VISUAL CHECK STRINGER SPLICE - FS 513.0, STRINGER 13	MOS					10-SEP-2004			
	REF: NDT VC-53-30-09	HRS/MSC AFL	6000				7608.8 3724		13608.8	4661
+ 53-30-00-164	VISUAL CHECK CABIN WINDOW SURROUND STRUCTRES FS 364.0 TO FS 529.0, STRINGERS 10 TO 13	MOS								
	REF: NDT VC-53-30-04	HRS/MSC AFL	15000						15000 M	6052.2
+ 53-30-00-166	VISUAL CHECK FUSELAGE SKIN PANEL - FS 559.0, STRINGER 0.0	MOS								
	REF: NDT VC-53-30-11	HRS/MSC AFL	15000						15000 M	6052.2
+ 53-30-00-167	VISUAL CHECK FUSELAGE SKIN AT NLG CUTOUT - FS 235.0	MOS								
	REF: NDT VC-53-30-02	HRS/MSC AFL	9600						9600 M	652.2
+ 53-30-00-169	NDT CHECK WING TO FUSELAGE ATTACHMENT FRAME - FS 513.0	MOS								
	REF: NDT ET-53-30-02	HRS/MSC AFL	15000						15000 M	6052.2

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
53-30-00-171	VISUAL CHECK STRINGER SPLICE AT FS 473.0, STRINGER 3	MOS					01-OCT-1992			
	REF: NDT VC-53-30-08	HRS/MSC AFL	15000				0	15000		6052.2
53-30-00-172	VISUAL CHECK SKIN SPLICE AT STRINGER 0 - FS 439.0	MOS					01-OCT-1992			
	REF: NDT VC-53-30-06	HRS/MSC AFL	15000				0	15000		6052.2
53-30-00-173	VISUAL CHECK SKIN SPLICE - FS 424.0 TO FS 439.0, STRINGER 8	MOS					01-OCT-1992			
	REF: NDT VC-53-30-05	HRS/MSC AFL	15000				0	15000		6052.2
53-30-00-174	VISUAL CHECK STRINGER SPLICE - STRINGER 1 L&R FS 718.0	MOS					01-OCT-1992			
	REF: NDT VC-53-30-14	HRS/MSC AFL	15000				0	15000		6052.2
53-30-00-175	VISUAL CHECK FUSELAGE STRINGER SPLICE AT STRINGER 0, FORWARD OF FS 718.0	MOS					01-OCT-1992			
	REF: NDT VC-53-30-14	HRS/MSC AFL	15000				0	15000		6052.2
+ 53-30-00-176	NDT CHECK BAGGAGE DOOR AND SURROUND STRUCTURE	MOS								
	REF: NDT ET-53-30-12	HRS/MSC AFL	15000					15000 M		6052.2
53-30-00-177	NON DESTRUCTIVE TEST AND VISUAL CHECK PRESSURE SKIN/FLOOR ANGLE AT WL 73.0 BETWEEN FS 409.0 AND FS 559.0	MOS					01-OCT-1992			
	REF: NDT ET-53-30-04	HRS/MSC AFL	15000				0	15000		6052.2
53-30-00-179	VISUAL CHECK FUSELAGE FRAME REF VS 55.625%, STRINGER 5	MOS								
	REF: NDT VC-53-30-15	HRS/MSC AFL	15000					15000 M		6052.2

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 53-30-00-180	NON DESTRUCTIVE TEST DRAG ANGLE AT FRAME 67.5% OF THE VERTICAL STABILIZER CHORD (A/C 5001 TO 5134 POST SB 601-0262 AND A/C 5135 TO 5194)	MOS								
	REF: NDT ET-53-30-07	HRS/MSC AFL	15000					15000 M		6052.2
53-30-00-181	VISUAL CHECK EXTERNAL SKIN AND DRAG ANGLES BETWEEN FRAMES 55.62% AND 67.5% OF VERTICAL STABILIZER CHORD (A/C 5001 TO 5134 POST SB 601-0262 AND A/C 5135 TO 5194)	MOS					01-OCT-1992			
	REF: NDT VC-53-30-20	HRS/MSC AFL	15000				0	15000		6052.2
+ 53-30-00-188	VISUAL CHECK STRUCTURES ADJACENT TO OVERBOARD LAVATORY SERVICES (INTERNAL)	MOS					08-MAR-2003			
	REF: NDT VC-53-30-01	HRS/MSC AFL	3600				6432	10032		1084.2
53-30-00-189	VISUAL CHECK STRUCTURES ADJACENT TO OVERBOARD LAVATORY SERVICES (EXTERNAL)	MOS					02-AUG-2005			
	REF: NDT VC-53-30-01	HRS/MSC AFL	A/R				8215.3			3975
+ 53-30-00-221 (s)	NDT CHECK CABIN WINDOW CUTOUTS	MOS					PKG			
	PKG 34	HRS/MSC AFL	N/A				03-APR-2006			
	REF: NDT ET-53-30-08						8305.8			4018
53-30-00-222 (s)	VISUAL CHECK PLATES/SKINS - SIDE SKIN PANEL FS 409.0, WL 73.5, PAYING PARTICULAR ATTENTION TO THE EXTERNAL CORNER AREA AT THE WING CUTOUT.	MOS					PKG			
	PKG 34	HRS/MSC AFL	60				05-APR-2006			
	REF: GENERIC NO REF						8305.8			4018
+ 53-30-00-224	NDT CHECK LOWER FUSELAGE SKINS EXTERNAL	MOS								
	REF: NDT ET-53-30-06	HRS/MSC AFL	96		-173		20-MAR-2009	28-SEP-2016		2213 d
							8873.5			
							4304			
53-30-00-403A	NDT AND VISUAL CHECK REPAIR - FUSELAGE SKIN FS 235.0, BL 6.0 - ZONE 114, 122	MOS								05-10-25 AIRWORTHINESS
	REF:	HRS/MSC AFL	6600				15-NOV-2003			
							7003	13603		4655.2
							3486			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
53-30-00-403B	NDT AND VISUAL CHECK REPAIR - FUSELAGE SKIN FS 235.0, BL 6.0 - ZONE 115, 121	MOS							05-10-25 AIRWORTHINESS	
	REF:	HRS/MSC AFL	15000					15000		6052.2
53-30-00-416	INSPECTION FUSELAGE SKIN FS243.50, STRINGER 26	MOS							05-10-25 AIRWORTHINESS	
	REF:	HRS/MSC AFL	13097					13097		4149.2
+ 53-40-00-183	VISUAL CHECK INTEGRAL FRAME ATTACHMENT LUGS - FS 424.0 BL 45	MOS								
	REF: NDT VC-53-40-01	HRS/MSC AFL	15000					15000		6052.2
+ 53-40-00-184	NON DESTRUCTIVE TEST AND VISUAL CHECK TAIL TANK ATTACHMENT BOLTS (A/C 5001 TO 5134 POST SB 601-0262 OR A/C 5135 TO 5194)	MOS								
	REF: NDT MT-53-40-01	HRS/MSC AFL	9600					9600 M		652.2
53-40-00-185	VISUAL CHECK INTEGRAL FRAME ATTACHMENT LUGS - FS 473 BL 45.0	MOS					01-OCT-1992			
	REF: NDT VC-53-40-03	HRS/MSC AFL	15000				0	15000		6052.2
53-40-00-186	VISUAL CHECK INTEGRAL FRAME ATTACHMENT LUGS - FS 513.0, BL 45.0 AND BL 13.5	MOS					01-OCT-1992			
	REF: NDT VC-53-40-04	HRS/MSC AFL	15000				0	15000		6052.2
+ 53-40-00-192	NON DESTRUCTIVE TEST INTEGRAL FRAME ATTACHMENT BOLTS - FS 424.0 BL 45.0	MOS								
	REF: NDT UT-53-40-01	HRS/MSC AFL	15000					15000 M		6052.2
+ 53-40-00-193	NON DESTRUCTIVE TEST INTEGRAL FRAME ATTACHMENT BOLTS - FS 473.0 BL 45.0	MOS								
	REF: NDT UT-53-40-02	HRS/MSC AFL	15000				0	15000		6052.2

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 53-40-00-194	NON DESTRUCTIVE TEST INTEGRAL FRAME ATTACHMENT BOLTS - FS 513.0, BL 45.0 AND BL 13.5	MOS HRS/MSC AFL	15000				0		15000	6052.2
	REF: NDT UT-53-40-03									
53-40-00-195	VISUAL CHECK OVERWING EMERGENCY EXIT - SURROUND STRUCTURE AND ATTACHMENT FITTINGS	MOS HRS/MSC AFL	10200				01-OCT-1992		10200	1252.2
	REF: NDT VC-53-40-05									
53-40-00-225 (s)	VISUAL CHECK ATTACHMENT FITTINGS - NOSE GEAR TRUNNION ASSEMBLY	MOS HRS/MSC AFL	12				PKG 19-JUL-2010 8947.8 4353			
	PKG 30									
	REF: AMM 53-40-00-225									
53-50-00-226	VISUAL CHECK TAIL CONE - OF INTERIOR SURFACES, FRAMES, ACCESS DOOR, DOOR SURROUNDING STRUCTURE AND FASTENERS.	MOS HRS/MSC AFL	9600				01-OCT-1992 0 0		9600 9645	652.2
	REF: GENERIC NO REF									
53-50-11-227 (s)	VISUAL CHECK NOSE RADOME - OF INTERIOR SURFACE & ATTACHMENT, PAYING PARTICULAR ATTENTION TO INTERIOR SURFACE AND ATTACHMENTS.	MOS HRS/MSC AFL	60				PKG 05-APR-2006 8305.8 4018			
	PKG 34									
	REF: AMM 53-50-11-227									
C53-00-801 (s)	CPCP CHECK FUSELAGE UPPER EXTERNAL SKIN, FS169.00 TO FS621.00, ABOVE WL73.5	MOS HRS/MSC AFL	60				PKG			
	PKG 34									
	REF: GENERIC NO REF									
C53-00-802 (s)	CPCP CHECK FUSELAGE LOWER EXTERNAL SKIN, FS169.00 TO FS621.00	MOS HRS/MSC AFL	60				PKG			
	PKG 34									
	REF: GENERIC NO REF									
C53-00-803	CPCP CHECK FUSELAGE STRUCTURE (INTERNAL), FS169.00 TO FS202.75	MOS HRS/MSC AFL	240				01-OCT-1992	01-OCT-2012	30-NOV-2012	755 d
	REF: GENERIC NO REF									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
C53-00-804 (s)	CPCP CHECK KEEL LONGERONS AND SURROUND STRUCTURE PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C53-00-805 (s)	CPCP CHECK FUSELAGE FRAME ATTACHMENT AT FS755.00 AND SKIN AT FS710.00 FO FS718.00, STRINGERS 1L TO 1R PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C53-00-806 (s)	CPCP CHECK PASSENGER DOOR SURROUND STRUCTURE PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C53-00-807 (s)	CPCP CHECK OVERWING EMERGENCY EXIT DOOR STRUCTURE PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C53-00-808 (s)	CPCP CHECK BAGGAGE DOOR SURROUND STRUCTURE PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C53-00-809 (s)	CPCP CHECK MAIN FRAME. (EQUIPMENT BAY DOOR SURROUND STRUCTURE) PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C53-00-810 (s)	CPCP CHECK WING TO FUSELAGE INTEGRAL ATTACHMENT AT FS424.00 BL45.00 PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C53-00-811 (s)	CPCP CHECK WING TO FUSELAGE INTEGRAL ATTACHMENT AT FS473.15 BL45.00 PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
C53-00-812 (s)	CPCP CHECK WING TO FUSELAGE INTEGRAL ATTACHMENT AT FS513.00 BL13.00 AND BL45.00 PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C53-00-813 (s)	CPCP CHECK CABIN WINDOW CUTOUTS AND SURROUND STRUCTURE FS364.00 TO FS529.00 (FS364.00 TO FS559.00 POST SB 601 -0006) PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C53-00-814 (s)	CPCP CHECK FUSELAGE EXTERNAL SKIN PANELS, FS621.00 TO VS67.5% PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	48				PKG 19-MAR-2007 8468 4101			
C53-00-815 (s)	CPCP CHECK NOSE LANDING GEAR WHEEL WELL STRUCTURE PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	48				PKG 19-MAR-2007 8468 4101			
C53-00-816 (s)	CPCP CHECK TAIL CONE ASSEMBLY (A/C 5001 TO 5134 PRE SB 601-0262) PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C53-00-817 (s)	CPCP CHECK NOSE RADOME PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C53-00-818 (s)	CPCP CHECK FLOOR STRUCTURE, FS589.00 TO FS621.00 PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C53-00-819	CPCP CHECK FUSELAGE STRUCTURE (INTERNAL), FS202.75 TO FS621.0 BELOW FLOOR REF: GENERIC NO REF	MOS HRS/MSC AFL	60		-4		05-OCT-2007 8612 4166	01-OCT-2012	30-NOV-2012	755 d

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
C53-00-820	CPCP CHECK FUSELAGE STRUCTURE (INTERNAL), FS202.75 TO FS621 ABOVE FLOOR	MOS HRS/MSC AFL	240				01-OCT-1992	01-OCT-2012	30-NOV-2012	755 d
	REF: GENERIC NO REF									
C53-00-821	CPCP CHECK FUSELAGE STRUCTURE (INTERNAL), FS621.00 TO VS67.5%	MOS HRS/MSC AFL	60		-4		05-OCT-2007 8612 4166	01-OCT-2012	30-NOV-2012	755 d
	REF: GENERIC NO REF									
C53-00-822 (s)	CPCP CHECK FLOOR STRUCTURE, FS 169.00 TO FS280.00	MOS HRS/MSC AFL	60				PKG			
	PKG 34									
	REF: GENERIC NO REF									
C53-00-823 (s)	CPCP CHECK FLOOR STRUCTURE, FS280.00 TO FS424.00	MOS HRS/MSC AFL	60				PKG			
	PKG 34									
	REF: GENERIC NO REF									
C53-00-824 (s)	CPCP CHECK FLOOR STRUCTURE, FS424.00 TO FS589.00	MOS HRS/MSC AFL	60				PKG			
	PKG 34									
	REF: GENERIC NO REF									
C53-00-825 (s)	CPCP CHECK STRUCTURE ADJACENT TO OVERBOARD LAVATORY SERVICES (EXTERNAL)	MOS HRS/MSC AFL	60				PKG			
	PKG 34									
	REF: GENERIC NO REF									
C53-00-826 (s)	CPCP CHECK FUSELAGE FRAME FS409.00, AFT FACE, EXTERNAL	MOS HRS/MSC AFL	60				PKG			
	PKG 34									
	REF: GENERIC NO REF									
C53-00-827 (s)	CPCP CHECK TAIL CONE (POST SB 601-0262 AND A/C 5135 TO 5194)	MOS HRS/MSC AFL	60				PKG			
	PKG 34									
	REF: GENERIC NO REF									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
T53T01	REMOVAL/INSTALLATION MAIN WHEEL BIN									
	REF:	MOS	O/C							
		HRS/MSC								
		AFL								
CHAPTER 54 NACELLES/PYLONS										
54-00-00-201 (s)	VISUAL CHECK NACELLES/PYLONS VISUAL CHECK - EXTERNAL						PKG			
	PKG 2	MOS					09-SEP-2008			
	REF: GENERIC NO REF	HRS/MSC	300				8806.5			
		AFL					4265			
54-00-00-202 (s)	VISUAL CHECK NACELLES/PYLONS - ENGINE SUPPRT STRUCTURE						PKG			
	PKG 34	MOS	60				05-APR-2006			
	REF: GENERIC NO REF	HRS/MSC					8305.8			
		AFL					4018			
54-10-00-101	VISUAL CHECK ENGINE SUPPORTING BEAM UPPER CAP - FS 625.3 BL 38.0									
	REF: NDT VC-54-10-01	MOS							15000 M	6052.2
		HRS/MSC	15000							
		AFL								
+ 54-10-00-102	NON DESTRUCTIVE TEST PYLON SPAR/FUSELAGE FRAME ATTACHMENT - FS 672.2									
	REF: NDT ET-54-10-04	MOS							15000 M	6052.2
		HRS/MSC	15000							
		AFL								
+ 54-10-00-103	NON DESTRUCTIVE TEST PYLON SPAR UPPER CAP - FS 625.3									
	REF: NDT ET-54-10-01	MOS							15000 M	6052.2
		HRS/MSC	15000							
		AFL								
54-10-00-104	VISUAL CHECK PYLON CANTED RIB - UPPER SPLICE AT FS 672.2									
	REF: NDT VC-54-10-02	MOS					01-OCT-1992		15000	6052.2
		HRS/MSC	15000				0			
		AFL					0			
54-30-00-105	VISUAL CHECK PYLON UPPER SKIN - FS 682.0									
	REF: NDT VC-54-30-01	MOS							15000 M	6052.2
		HRS/MSC	15000							
		AFL								

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
549027	--:NOSE INLET COWL 228-50020-63 149R REF:	MOS HRS/MSC AFL	O/C				23-JUN-1999 3693 1908			
C54-00-801 (s)	CPCP CHECK NACELLES/PYLONS, EXTERNAL. PKG 32 REF: GENERIC NO REF	MOS HRS/MSC AFL	24				PKG 28-MAY-2009 8928.6 4336			
C54-00-802 (s)	CPCP CHECK NACELLES/PYLONS, INTERNAL (PYLON STRUCTURE). PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
CHAPTER 55 STABILIZERS										
55-00-00-101	VISUAL CHECK PITCH TRIM ACTUATOR REF: NDT VC-55-00-01	MOS HRS/MSC AFL	10000				01-OCT-1992 0 0	10000		1052.2
55-00-00-201 (s)	VISUAL CHECK STABILIZERS - EXTERNAL PKG 2 REF: GENERIC NO REF	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
+ 55-10-00-102	VISUAL CHECK HORIZONTAL STABILIZER REAR SPAR CENTERLINE SPLICE REF: NDT VC-55-10-05	MOS HRS/MSC AFL	15000					15000 M		6052.2
+ 55-10-00-103	NON DESTRUCTIVE CHECK HORIZONTAL STABILIZER REAR SPAR UPPER CAP AT RIB 1, BL6.0 REF: NDT ET-55-10-01	MOS HRS/MSC AFL	4200				18-JUN-2002 5849 2988	10049		1101.2
+ 55-10-00-104	VISUAL CHECK HORIZONTAL STABILIZER REAR SPAR UPPER CAP AND SPLICE REF: NDT VC-55-10-04	MOS HRS/MSC AFL	15000					15000 M		6052.2

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 55-10-00-105	NON DESTRUCTIVE CHECK HORIZONTAL STABILIZER FRONT SPAR UPPER CAP SPLICE, BL6.0	MOS HRS/MSC AFL	15000						15000 M	6052.2
	REF: NDT ET-55-10-02									
55-10-00-106	VISUAL CHECK HORIZONTAL STABILIZER, UPPER STRINGER 1, BL6.0	MOS HRS/MSC AFL	15000						15000 M	6052.2
	REF: NDT VC-55-10-03									
55-10-00-107	VISUAL CHECK HORIZONTAL STABILIZER, CENTERLINE RIB	MOS HRS/MSC AFL	15000						15000 M	6052.2
	REF: NDT VC-55-10-02									
55-10-00-202 (s)	VISUAL CHECK HORIZONTAL STABILIZER OF THE FOLLOWING ITEMS						PKG			
	PKG 32	MOS HRS/MSC AFL	24				28-MAY-2009 8928.6 4336			
	REF: GENERIC NO REF									
55-10-00-203 (s)	VISUAL CHECK HORIZONTAL STABILIZER						PKG			
	PKG 34	MOS HRS/MSC AFL	60				05-APR-2006 8305.8 4018			
	REF: GENERIC NO REF									
55-10-00-204 (s)	VISUAL CHECK HORIZONTAL STABILIZER - INTERNAL						PKG			
	PKG 34	MOS HRS/MSC AFL	60				05-APR-2006 8305.8 4018			
	REF: GENERIC NO REF									
55-10-00-205	VISUAL CHECK HORIZONTAL STABILIZER OF INTERNAL STRUCTURE	MOS HRS/MSC AFL	120				27-MAR-2001 4859 2516	27-MAR-2011	26-MAY-2011	201 d
	REF: GENERIC NO REF									
+ 55-10-11-206 (s)	VISUAL CHECK HORIZONTAL STABILIZER (UPON REMOVAL OF THE INNER PIVOT PIN ONLY) OF THE INNER AND OUTER PIVOT PINS. REINSTALL INNER PIVOT PIN						PKG			
	PKG 32	MOS HRS/MSC AFL	24				28-MAY-2009 8928.6 4336			
	REF: See Workcard									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 55-20-00-108	NON DESTRUCTIVE CHECK ELEVATOR/HORIZONTAL STABILIZER PCU & SUPPORTING HINGES	MOS HRS/MSC AFL	7200				03-NOV-2003 7003 3486		14203	5255.2
	REF: NDT ET-55-20-01									
55-20-00-109	VISUAL CHECK ELEVATOR, SKIN AND FRONT SPAR	MOS HRS/MSC AFL	15000						15000 M	6052.2
	REF: NDT VC-55-20-01									
55-20-00-207 (s)	VISUAL CHECK ELEVATORS AND RUDDER - EXTERNAL PKG 2	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
	REF: GENERIC NO REF									
55-30-00-110	VISUAL CHECK VERTICAL STABILIZER - MID SPAR CAP AT RIB 1	MOS HRS/MSC AFL	3000						15000 M	6052.2
	REF: NDT VC-55-30-04									
55-30-00-111	VISUAL CHECK VERTICAL STABILIZER - FRONT SPAR	MOS HRS/MSC AFL	15000				01-OCT-1992 0 0		15000	6052.2
	REF: NDT VC-55-30-01									
55-30-00-112	VISUAL CHECK VERTICAL STABILIZER - FRONT SPAR CAP FS755.0, WS137.5	MOS HRS/MSC AFL	15000				01-OCT-1992 0 0		15000	6052.2
	REF: NDT VC-55-30-02									
55-30-00-113	VISUAL CHECK VERTICAL STABILIZER - STRINGER SPLICE	MOS HRS/MSC AFL	15000						15000 M	6052.2
	REF: NDT VC-55-30-03									
55-30-00-114	VISUAL CHECK VERTICAL STABILIZER - STRINGER SPLICE - VS 31.875% AT RIB 2 AND VS 55.625% AT RIB 3	MOS HRS/MSC AFL	15000						15000 M	6052.2
	REF: NDT VC-55-30-06									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
55-30-00-115	VISUAL CHECK VERTICAL STABILIZER - ACCESS HOLE SKIN CUT	MOS								
	REF: NDT VC-55-30-05	HRS/MSC AFL	15000					15000 M		6052.2
55-30-00-116	NON DESTRUCTIVE CHECK VERTICAL STABILIZER - REAR SPAR	MOS								
	REF: NDT ET-55-30-03	HRS/MSC AFL	15000					15000 M		6052.2
55-30-00-117	NON DESTRUCTIVE TEST VERTICAL STABILIZER - FRONT SPAR CAP AT RIB 1	MOS								
	REF: NDT ET-55-30-01	HRS/MSC AFL	15000					15000 M		6052.2
55-30-00-118	VISUAL CHECK VERTICAL STABILIZER - REAR SPAR WEB AT RIB 7	MOS								
	REF: NDT VC-55-30-07	HRS/MSC AFL	15000					15000 M		6052.2
55-30-00-119	NON DESTRUCTIVE TEST VERTICAL STABILIZER - FRONT SPAR CAP SPLICE STRAP	MOS								
	REF: NDT ET-55-30-02	HRS/MSC AFL	15000					15000 M		6052.2
55-30-00-209 (s)	VISUAL CHECK VERTICAL STABILIZER - CANTED TOP RIB FOR CRACKS AND CORROSION						PKG			
	PKG 32	MOS	24				28-MAY-2009			
	REF: GENERIC NO REF	HRS/MSC AFL					8928.6 4336			
55-30-00-210 (s)	VISUAL CHECK VERTICAL STABILIZER OF THE FOLLOWING ITEMS						PKG			
	PKG 34	MOS	60				05-APR-2006			
	REF: GENERIC NO REF	HRS/MSC AFL					8305.8 4018			
+ 55-40-00-120	NON DESTRUCTIVE CHECK RUDDER/VERTICAL STABILIZER SUPPORT AND PCU HINGE FITTINGS	MOS								
	REF: NDT ET-55-40-01	HRS/MSC AFL	7800				29-JUN-2004 7576 3705	15376		6428.2

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
55-40-00-121	VISUAL CHECK RUDDER, SKIN AND FRONT SPAR REF: NDT VC-55-40-01	MOS HRS/MSC AFL	15000					15000 M		6052.2
55-50-00-122	NON DESTRUCTIVE TEST VERTICAL STABILIZER PITCH TRIM ACTUATOR PIVOT LUGS REF: NDT ET-55-50-02	MOS HRS/MSC AFL	15000					15000 M		6052.2
55-50-00-123	NON DESTRUCTIVE TEST VERTICAL STABILIZER/HORIZONTAL STABILIZER PIVOT FITTING REF: NDT UT-55-50-01	MOS HRS/MSC AFL	15000					15000 M		6052.2
+ 55-50-00-124	VISUAL CHECK HORIZONTAL STABILIZER PIVOT FITTING LUG REF: NDT VC-55-50-02	MOS HRS/MSC AFL	15000					15000 M		6052.2
55-50-00-125	VISUAL CHECK HORIZONTAL STABILIZER BATHTUB FITTINGS REF: NDT VC-55-50-01	MOS HRS/MSC AFL	15000					15000 M		6052.2
+ 55-50-00-126	VISUAL CHECK RUDDER HINGE BOLTS REF: NDT VC-55-50-03	MOS HRS/MSC AFL	9600					9600 M		652.2
+ 55-50-00-127	VISUAL CHECK ELEVATOR HINGE BOLTS REF: NDT VC-55-50-04	MOS HRS/MSC AFL	9600					9600 M		652.2
55-50-00-211 (s)	VISUAL CHECK ATTACHMENT FITTINGS OF THE HORIZONTAL STABILIZER PIVOT FITTINGS PKG 32 REF: GENERIC NO REF	MOS HRS/MSC AFL	24				PKG 28-MAY-2009 8928.6 4336			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
55-50-00-212 (s)	VISUAL CHECK ATTACHMENT FITTINGS OF THE VERTICAL STABILIZER PIVOT FITTINGS PKG 32	MOS	24				PKG 28-MAY-2009 8928.6 4336			
	REF: GENERIC NO REF	HRS/MSC AFL								
55-50-00-213 (s)	VISUAL CHECK ATTACHMENT FITTINGS OF THE HORIZONTAL STABILIZER PITCH TRIM ACTUATOR PKG 32	MOS	24				PKG 28-MAY-2009 8928.6 4336			
	REF: GENERIC NO REF	HRS/MSC AFL								
55-50-00-214 (s)	VISUAL CHECK ATTACHMENT FITTINGS OF THE VERTICAL STABILIZER TO RUDDER CENTER HINGE FITTING PKG 33	MOS	36				PKG 19-JUL-2010 8947.8 4353			
	REF: GENERIC NO REF	HRS/MSC AFL								
55-50-00-215 (s)	VISUAL CHECK ATTACHMENT FITTINGS OF THE RUDDER ACTUATOR/HINGE FITTING PKG 33	MOS	36				PKG 19-JUL-2010 8947.8 4353			
	REF: GENERIC NO REF	HRS/MSC AFL								
55-50-00-216 (s)	VISUAL CHECK ATTACHMENT FITTINGS OF THE RUDDER ATTACHMENT FITTINGS PKG 33	MOS	36				PKG 19-JUL-2010 8947.8 4353			
	REF: GENERIC NO REF	HRS/MSC AFL								
55-50-00-217 (s)	VISUAL CHECK ATTACHMENT FITTINGS OF THE HORIZONTAL STABILIZER HINGE FITTING AT BL 15.25 PKG 33	MOS	36				PKG 19-JUL-2010 8947.8 4353			
	REF: GENERIC NO REF	HRS/MSC AFL								
55-50-00-218 (s)	VISUAL CHECK ATTACHMENT FITTINGS - PCU FITTINGS, HORIZONTAL STABILIZER, PAYING PARTICULAR ATTENTION TO THE LUGS OF THE ELEVATOR PCU. PKG 33	MOS	36				PKG 19-JUL-2010 8947.8 4353			
	REF: GENERIC NO REF	HRS/MSC AFL								
55-50-00-219 (s)	VISUAL CHECK ATTACHMENT FITTINGS - PCU & ELEVATOR, PAYING PARTICULAR ATTENTION TO THE INTEGRITY OF FASTENERS, FITTING LUGS AND THE ADJACENT SPAR WEB. PKG 33	MOS	36				PKG 19-JUL-2010 8947.8 4353			
	REF: GENERIC NO REF	HRS/MSC AFL								

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 55-50-00-220 (s)	NDT CHECK STABILIZERS STRUCTURE - VERTICAL STABILIZER TO RUDDER HINGE BOLTS FOR CRACKS. PKG 10	MOS HRS/MSC AFL	4800				PKG 27-FEB-2001 4859 2516			
	REF: NDT PT-55-50-02									
+ 55-50-00-221 (s)	NDT CHECK STABILIZERS STRUCTURE - HORIZONTAL STABILIZER TO ELEVATOR HINGE BOLTS FOR CRACKS. PKG 10	MOS HRS/MSC AFL	4800				PKG 01-MAR-2001 4859 2516			
	REF: NDT PT-55-50-01									
551000-001	STABILIZER ASSEMBLY:HORIZONTAL STABILIZER ASSEMBLY 600-23025-1017 5021	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
	REF: AMM 551011									
552000-001	ELEVATOR ASSEMBLY:LEFT ELEVATOR ASSEMBLY PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSI:0			01-OCT-1992 0 0			
	REF: AMM 27-33-00									
552000-002	ELEVATOR ASSEMBLY:RIGHT ELEVATOR ASSEMBLY PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSI:0			01-OCT-1992 0 0			
	REF: AMM 27-33-00									
554000-001	RUDDER ASSEMBLY:RUDDER ASSEMBLY 600-22000-1003 5121	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
	REF: GENERIC NO REF									
C55-00-801 (s)	CPCP CHECK VERTICAL STABILIZER EXTERNAL SURFACES PKG 40	MOS HRS/MSC AFL	48				PKG 19-MAR-2007 8468 4101			
	REF: GENERIC NO REF									
C55-00-802 (s)	CPCP CHECK VERTICAL STABILIZER FRONT SPAR PKG 34	MOS HRS/MSC AFL	60				PKG			
	REF: GENERIC NO REF									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
C55-00-803 (s)	CPCP CHECK VERTICAL STABILIZER INTERNAL STRUCTURE PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C55-00-804 (s)	CPCP CHECK VERTICAL STABILIZER, PITCH TRIM ACTUATOR ATTACHMENT STRUCTURE PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	48				PKG 19-MAR-2007 8468 4101			
C55-00-805 (s)	CPCP CHECK VERTICAL STABILIZER REAR SPAR STRUCTURE PKG 33 REF: GENERIC NO REF	MOS HRS/MSC AFL	36				PKG 19-JUL-2010 8947.8 4353			
C55-00-806 (s)	CPCP CHECK HORIZONTAL STABILIZER FRONT SPAR PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	48				PKG 19-MAR-2007 8468 4101			
C55-00-807 (s)	CPCP CHECK HORIZONTAL STABILIZER REAR SPAR PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C55-00-808 (s)	CPCP CHECK HORIZONTAL STABILIZER INTERNAL STRUCTURE PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C55-00-809 (s)	CPCP CHECK HORIZONTAL AND VERTICAL STABILIZER PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	48				PKG 19-MAR-2007 8468 4101			
C55-00-810 (s)	CPCP CHECK HORIZONTAL STABILIZER, PITCH TRIM ACTUATOR ATTACHMENT STRUCTURE PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	48				PKG 19-MAR-2007 8468 4101			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
C55-00-811 (s)	CPCP CHECK HORIZONTAL STABILIZER, EXTERNAL SURFACES PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	48				PKG 19-MAR-2007 8468 4101			
C55-00-812 (s)	CPCP CHECK RUDDER EXTERNAL SKIN, STRUCTURE AND ATTACHMENTS PKG 33 REF: GENERIC NO REF	MOS HRS/MSC AFL	36				PKG 19-JUL-2010 8947.8 4353			
C55-00-813 (s)	CPCP CHECK ELEVATOR EXTERNAL SKIN, STRUCTURE AND ATTACHMENTS PKG 33 REF: GENERIC NO REF	MOS HRS/MSC AFL	36				PKG 19-JUL-2010 8947.8 4353			
CHAPTER 56 WINDOWS										
+ 56-10-00-101	VISUAL CHECK SIDE WINDOW GLAZINGS - PRISM CHECKS PKG 3 REF: NDT VC-56-10-01	MOS HRS/MSC AFL	600				20-MAR-2009 8873.5 4304	9473.5		525.7
+ 56-10-00-102	VISUAL CHECK WINDSHIELD AND SIDE WINDOW GLAZINGS - PRISM CHECKS PKG 4 REF: NDT VC-56-10-02	MOS HRS/MSC AFL	1200				02-AUG-2005 8215.3 3975	9415.3		467.5
+ 56-10-00-104	NON DESTRUCTIVE CHECK WINDSHIELD AND SIDE WINDOW 'T' PLATE FASTENERS REF: NDT PT-56-10-01	MOS HRS/MSC AFL	2400				04-NOV-2003 7003 3486	9403		455.2
+ 56-10-00-105	VISUAL CHECK WINDSHIELD AND SIDE WINDOW LOWER T-CAPS REF: NDT VC-56-10-03	MOS HRS/MSC AFL	2400				30-OCT-2003 7003 3486	9403		455.2
+ 56-10-00-106	NON DESTRUCTIVE TEST WINDSHIELD AND SIDEWINDOW GLAZING - ALL FASTENERS REF: NDT PT-56-10-02	MOS HRS/MSC AFL	9600				05-MAR-1997 2397 1190	11997		3049.2

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
56-10-00-201 (s)	VISUAL CHECK FLIGHT COMPARTMENT WINDOWS - INTERNAL AND EXTERNAL, PAYING PARTICULAR ATTENTION TO THE AERODYNAMIC SEAL. PKG 2 REF: AMM 56-10-00-201	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
561011-001	WINDSHIELD:NO. 1 COCKPIT WINDSHIELD 600-33030-25 10177 REF: AMM 561011	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-APR-2007 8539 4126			
561011-002	WINDSHIELD:NO. 2 COCKPIT WINDSHIELD 600-33030-26 9900 REF: AMM 561011	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-SEP-2007 8590 4155			
561016-001	WINDOW:NO. 1 SIDE WINDOW 600-33030-27 8217 REF: AMM 561016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			05-APR-2006 8305.8 4018			
561016-002	WINDOW:NO. 2 SIDE WINDOW 600-33030-22 7680 REF: AMM 561016	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			26-NOV-2002 6218			
562000-001	WINDOW:NO.1 CABIN WINDOW 601R31056-17 19096 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		11/04/2004	04-NOV-2003 7003 3486			
562000-003	WINDOW:NO. 3 CABIN WINDOW 601R31056-17 9464 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		10/29/1998	29-OCT-1997 2832 1418			
562000-004	WINDOW:NO.4 CABIN WINDOW 601R31056-17 9468 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		10/29/1998	29-OCT-1997 2832 1418			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
562000-005	WINDOW:NO.5 CABIN WINDOW 601R31056-17 19094 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		11/03/2004	03-NOV-2003 7003 3486			
562000-006	WINDOW:NO.6 CABIN WINDOW 601R31056-17 19095 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		10/31/2004	31-OCT-2003 7003 3486			
562000-007	WINDOW:NO.7 CABIN WINDOW 601R31056-17 7849 REF: AMM 562000	MOS HRS/MSC AFL	O/C				02-APR-1997 2415 1208			
562000-008	WINDOW:NO.8 CABIN WINDOW 600-31055-11 0397 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			01-APR-1993 19 12			
562000-009	WINDOW:NO.9 CABIN WINDOW 601R31056-17 9472 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		10/29/1998	29-OCT-1997 2832 1418			
562000-010	WINDOW:NO.10 CABIN WINDOW 600-31055-11 0488 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			01-APR-1993 19 12			
562000-011	WINDOW:NO.11 CABIN WINDOW 601R31056-17 9471 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		10/29/1998	29-OCT-1997 2832 1418			
562000-012	WINDOW:NO. 12 CABIN WINDOW 601R31056-17 19099 REF: AMM 562000	MOS HRS/MSC AFL	O/C			11/04/2004	04-NOV-2003 7003 3486			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
562000-013	WINDOW:CABIN - OVERWING EMERGENCY WINDOW 600-31055-11 0405 REF: AMM 562000	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			01-APR-1993 19 12			
56R001	POLISH, LH FWD WINDSHIELD REF:	MOS HRS/MSC AFL	N/R				19-MAY-1995 1226 595			
56R002	POLISH, RH FWD WINDSHIELD REF:	MOS HRS/MSC AFL	N/R				18-MAY-1995 1226 595			
T56T01	MAINTENANCE PRACTICES - WINDOW REF:	MOS HRS/MSC AFL	O/C							
CHAPTER 57 WINGS										
57-00-00-202 (s)	VISUAL CHECK WING STRUCTURE OF LEADING EDGE EXTERNAL SURFACE PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	2400				PKG 31-OCT-2003 7003 3486			
57-00-00-203 (s)	VISUAL CHECK WING STRUCTURE OF THE FOLLOWING AREAS: PKG 30 REF: GENERIC NO REF	MOS HRS/MSC AFL	12				PKG 19-JUL-2010 8947.8 4353			
57-00-00-204 (s)	VISUAL CHECK WING STRUCTURE - WING BOX OF THE FOLLOWING ITEMS PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG 05-APR-2006 8305.8 4018			
+ 57-10-00-101	NDT CHECK LOWER WING PLANK AND REAR SPAR - WS 45.0 AND WS 47.0 REF: NDT RT-57-10-01	MOS HRS/MSC AFL	15000					15000 M		6052.2

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
57-10-00-102	NDT CHECK LOWER WING PLANK - REAR SPAR WS 178.0 AND WS 189.0	MOS					01-OCT-1992			
	REF: NDT ET-57-10-02	HRS/MSC AFL	10200				0 0		10200	1252.2
57-10-00-103	NDT CHECK LOWER WING PLANK - REAR SPAR AT WS 166.0	MOS					01-OCT-1992			
	REF: NDT ET-57-10-01	HRS/MSC AFL	10200				0 0		10200	1252.2
+ 57-10-00-104	VISUAL CHECK FRONT SPAR WEB AT LOWER WING PLANK - WS 45.0	MOS								
	REF: NDT VC-57-10-08	HRS/MSC AFL	15000						15000 M	6052.2
+ 57-10-00-106	VISUAL CHECK FRONT SPAR SPLICE AT THE LOWER WING PLANK - WS 29.42	MOS								
	REF: NDT VC-57-10-09	HRS/MSC AFL	15000						15000 M	6052.2
+ 57-10-00-108	VISUAL CHECK LOWER WING PLANK AND REAR SPAR AT WS 148.0	MOS					13-JUN-2005			
	REF: NDT VC-57-30-18	HRS/MSC AFL	1800		-110		8180 3964		9870	922.2
57-10-00-109	VISUAL CHECK LOWER WING PLANK - REAR SPAR - WS 242.0	MOS					01-OCT-1992			
	REF: NDT VC-57-10-05	HRS/MSC AFL	15000				0 0		15000	6052.2
+ 57-10-00-110	VISUAL CHECK WING BOX - INTERNAL STRUCTURE	MOS								
	REF: NDT VC-57-10-01	HRS/MSC AFL	9600						9600 M	652.2
+ 57-10-00-111	NDT CHECK LOWER WING PLANK - REAR SPAR AT WS 260.0	MOS								
	REF: NDT ET-57-10-03	HRS/MSC AFL	15000						15000 M	6052.2

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
57-10-00-112	NDT CHECK LOWER WING PLANK - REAR SPAR AT WS 217.0 AND WS 222.0	MOS					01-OCT-1992			
	REF: NDT ET-57-10-04	HRS/MSC AFL	15000				0	15000		6052.2
57-10-00-113	NDT CHECK REAR SPAR/LOWER WING PLANK AT WS 219.0	MOS					01-OCT-1992			
	REF: NDT RT-57-10-02	HRS/MSC AFL	15000				0	15000		6052.2
57-10-00-114	VISUAL CHECK LOWER WING PLANK - WS 314.5, BUTT STRAP AND FRONT SPAR	MOS					01-OCT-1992			
	REF: NDT VC-57-10-07	HRS/MSC AFL	15000				0	15000		6052.2
57-10-00-115	VISUAL CHECK LOWER WING PLANK - WS 315.0, BUTT STRAP AND REAR SPAR	MOS					01-OCT-1992			
	REF: NDT VC-57-10-06	HRS/MSC AFL	15000				0	15000		6052.2
57-10-00-205 (s)	VISUAL CHECK MAIN FRAME - WING CENTRE SECTION INTERNAL STRUCTURE	MOS					PKG			
	PKG 34	HRS/MSC AFL	60				05-APR-2006			
	REF: GENERIC NO REF						8305.8			4018
57-10-00-206 (s)	VISUAL CHECK MAIN FRAME (FRONT SPAR SPLICE WS 29.42) - INTERNAL & EXTERNAL OF THE AREA AROUND THE FRONT SPAR SPLICE, PAYING PARTICULAR ATTENTION TO THE WEBS, CAPS, SPLICES, RIB AND FASTENER SURROUND AREA.	MOS					PKG			
	PKG 34	HRS/MSC AFL	60				05-APR-2006			
	REF: GENERIC NO REF						8305.8			4018
57-10-00-207 (s)	VISUAL CHECK MAIN FRAME (WING INBOARD BOX INTERNAL STRUCTURE - WS 45.0 TO WS 65.7 AND WS 85.5 TO WS 106.0)	MOS					PKG			
	PKG 34	HRS/MSC AFL	60				05-APR-2006			
	REF: GENERIC NO REF						8305.8			4018
57-10-00-208 (s)	VISUAL CHECK MAIN FRAME - (WING OUTBOARD BOX INTERNAL STRUCTURE. WS 148.0 TO WS 163.0 AND WS 199.0 TO WS 220.0)	MOS					PKG			
	PKG 34	HRS/MSC AFL	60				05-APR-2006			
	REF: GENERIC NO REF						8305.8			4018

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
57-10-00-209 (s)	VISUAL CHECK MAIN FRAME - REAR SPAR SPLICE AT WS 45.0 (INTERNAL AND EXTERNAL) OF THE AREA AROUND THE REAR SPAR SPLICE, PAYING PARTICULAR ATTENTION TO THE WEBS, CAPS, SPLICES, RIB AND FASTENER SURROUND AREA.						PKG			
	PKG 34	MOS	60				05-APR-2006			
		HRS/MSC					8305.8			
	REF: GENERIC NO REF	AFL					4018			
+ 57-20-00-116	VISUAL CHECK WING TIP - EXTERNAL SURFACE									
		MOS								
		HRS/MSC	9600						9600 M	652.2
	REF: NDT VC-57-20-01	AFL								
57-20-00-210 (s)	VISUAL CHECK AUXILIARY STRUCTURE - WINGLET INTERNAL & EXTERNAL, PAYING PARTICULAR ATTENTION TO FRONT/REAR SPARS AND ATTACHMENT TO THE WING.						PKG			
	PKG 34	MOS	60				05-APR-2006			
		HRS/MSC					8305.8			
	REF: GENERIC NO REF	AFL					4018			
57-20-00-211 (s)	VISUAL CHECK AUXILIARY STRUCTURE - WING TRAILING & LEADING EDGES INTERNAL STRUCTURE						PKG			
	PKG 34	MOS	60				05-APR-2006			
		HRS/MSC					8305.8			
	REF: GENERIC NO REF	AFL					4018			
+ 57-30-00-117	NDT CHECK LOWER CENTER WING PLANK - WS 65.0, STRINGER 14 AND 15									
		MOS					09-SEP-2008			
		HRS/MSC	600		-26.5		8806.5		9380	432.2
	REF: NDT ET-57-30-08	AFL					4265			
+ 57-30-00-118	NDT CHECK LOWER WING PLANK NEAR MAIN LANDING GEAR TRUNNION - WS 65.75									
		MOS					29-JUN-2004			
		HRS/MSC	1800				7576		9376	428.2
	REF: NDT ET-57-30-01	AFL					3705			
+ 57-30-00-119	NDT CHECK LOWER WING PLANK - AUXILIARY SPAR ACCES HOLE AT WS 85.0									
	PKG 4	MOS					09-JUN-2005			
		HRS/MSC	1200				8180		9380	432.2
	REF: NDT ET-57-30-02	AFL					3964			
+ 57-30-00-120	VISUAL CHECK LOWER WING PLANK - WS 88.0, BETWEEN STRINGERS 14 AND 15									
	PKG 4	MOS					09-JUN-2005			
		HRS/MSC	1200				8180		9380	432.2
	REF: NDT VC-57-30-13	AFL					3964			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 57-30-00-121	NDT CHECK LOWER CENTER WING PLANK AT WS 45.0 - STRINGERS 14 AND 15, CENTER AND FORWARD SPLICE PKG 4	MOS					09-JUN-2005 8180 3964		9380	432.2
	REF: NDT ET-57-30-06	HRS/MSC AFL	1200							
+ 57-30-00-122	NDT CHECK LOWER CENTER WING PLANK - WS 65.0, STRINGER 10	MOS					09-SEP-2008 8806.5 4265		9380	432.2
	REF: NDT ET-57-30-09	HRS/MSC AFL	600		-26.5					
+ 57-30-00-124	NDT CHECK LOWER CENTER WING PLANK - WS 45.0, STRINGER 10 PKG 4	MOS					09-JUN-2005 8180 3964		9380	432.2
	REF: NDT ET-57-30-10	HRS/MSC AFL	1200							
+ 57-30-00-125	NDT CHECK LOWER WING PLANKS - WS 45.0, STRINGERS 15 AND 16 PKG 4	MOS					09-JUN-2005 8180 3964		9380	432.2
	REF: NDT ET-57-30-11	HRS/MSC AFL	1200							
+ 57-30-00-126	VISUAL CHECK WING UPPER COVER	MOS								AIRWORTHINESS
	REF: NDT VC-57-30-28	HRS/MSC AFL	9600						9600 M	652.2
57-30-00-127	NDT CHECK LOWER WING PLANK - AFT EDGE - WS 163.0 TO 170.5	MOS					01-OCT-1992 0 0		10200	1252.2
	REF: NDT ET-57-30-12	HRS/MSC AFL	10200							
57-30-00-128	NDT CHECK LOWER WING PLANKS - WS 86.0, STRINGERS 14 TO 17	MOS					01-OCT-1992 0 0		10200	1252.2
	REF: NDT ET-57-30-14	HRS/MSC AFL	10200							
57-30-00-129	NDT CHECK LOWER WING PLANKS - WS 163.0, STRINGER 15	MOS					01-OCT-1992 0 0		15000	6052.2
	REF: NDT ET-57-30-15	HRS/MSC AFL	15000							

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
57-30-00-130	NDT CHECK LOWER WING PLANK - WS 148.0, STRINGER 19	MOS					01-OCT-1992			
	REF: NDT RT-57-30-01	HRS/MSC AFL	15000				0 0		15000	6052.2
57-30-00-131	VISUAL CHECK LOWER WING PLANK - WS 127.5, STRINGERS 9 AND 10	MOS					01-OCT-1992			
	REF: NDT VC-57-30-17	HRS/MSC AFL	15000				0 0		15000	6052.2
57-30-00-132	VISUAL CHECK LOWER WING PLANK - CENTERLINE SPLICE, STRINGERS 15 AND 16	MOS					01-OCT-1992			
	REF: NDT VC-57-30-04	HRS/MSC AFL	15000				0 0		15000	6052.2
57-30-00-133	VISUAL CHECK LOWER WING PLANK - WS 94.0, STRINGER 23	MOS								
	REF: NDT VC-57-30-14	HRS/MSC AFL	15000						15000 M	6052.2
57-30-00-134	VISUAL CHECK LOWER WING PLANK - WS 106.4, STRINGER 10	MOS					01-OCT-1992			
	REF: NDT VC-57-30-15	HRS/MSC AFL	15000				0 0		15000	6052.2
57-30-00-135	VISUAL CHECK LOWER WING PLANK - WS 106.4, STRINGERS 15 AND 16	MOS					01-OCT-1992			
	REF: NDT VC-57-30-16	HRS/MSC AFL	15000				0 0		15000	6052.2
57-30-00-136	VISUAL CHECK LOWER WING PLANK - WS 199.0, STRINGERS 6 AND 7	MOS					01-OCT-1992			
	REF: NDT VC-57-30-21	HRS/MSC AFL	15000				0 0		15000	6052.2
57-30-00-137	VISUAL CHECK LOWER WING PLANK - WS 199.0, STRINGER 17	MOS					01-OCT-1992			
	REF: NDT VC-57-30-22	HRS/MSC AFL	15000				0 0		15000	6052.2

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
57-30-00-138	VISUAL CHECK LOWER WING PLANK - WS 220.0 STRINGER 7	MOS					01-OCT-1992			
	REF: NDT VC-57-30-23	HRS/MSC AFL	15000				0 0		15000	6052.2
+ 57-30-00-139	NDT CHECK LOWER WING PLANK - WS148.0 STRINGER 8 & 9	MOS					29-JUN-2004			
	REF: NDT ET-57-30-05	HRS/MSC AFL	1800				7576 3705		9376	428.2
+ 57-30-00-140	NDT CHECK LOWER CENTER WING PLANK-WS148 STRINGER 15	MOS					29-JUN-2004			
	REF: NDT ET-57-30-03	HRS/MSC AFL	1800				7576 3705		9376	428.2
+ 57-30-00-141	NDT CHECK LOWER CENTER WING PANEL ACCESS HOLE, WS112.0 STRINGER 10	MOS					29-JUN-2004			
	REF: NDT ET-57-30-04	HRS/MSC AFL	1800				7576 3705		9376	428.2
+ 57-30-00-142	VISUAL CHECK FUEL TANK WATER DRAIN PORT - WS 48.0, STRINGER 17.	MOS					09-JUN-2005			
	REF: NDT VC-57-30-01	HRS/MSC AFL	1800				8180 3964		9980	1032.2
+ 57-30-00-143	NDT CHECK LOWER CENTER WING PLANK ACCESS HOLE, WS220.0 STRINGER 10	MOS					29-JUN-2004			
	REF: NDT ET-57-30-07	HRS/MSC AFL	1800				7576 3705		9376	428.2
+ 57-30-00-145	VISUAL CHECK LOWER WING PLANK-WS 45.0,STRINGER 8	MOS								
	REF: NDT VC-57-30-05	HRS/MSC AFL	15000						15000 M	6052.2
+ 57-30-00-150	NDT CHECK LOWER FORWARD WING PLANK, WS65.75 STRINGER 17	MOS								
	REF: NDT ET-57-30-13	HRS/MSC AFL	9600						9600	652.2

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 57-30-00-153	NDT CHECK LOWER AFT WING PLANK REAR SPAR BETWEEN WS 59.0 AND WS 65.75.	MOS HRS/MSC AFL	15000						15000 M	6052.2
	REF: NDT ET-57-30-16									
+ 57-30-00-155	VISUAL CHECK LOWER WING PLANK - WS 242.0 STRINGER 9	MOS HRS/MSC AFL	15000						15000 M	6052.2
	REF: NDT VC-57-30-26									
+ 57-30-00-156	VISUAL CHECK LOWER WING PLANK - WS 242.0 INBOARD/OUTBOARD AND WS 238.0 STRINGER 16	MOS HRS/MSC AFL	15000						15000 M	6052.2
	REF: NDT VC-57-30-24									
57-30-00-159	VISUAL CHECK LOWER WING PLANK - WS 264.0 STRINGER 6 & 7	MOS HRS/MSC AFL	15000				01-OCT-1992 0 0		15000	6052.2
	REF: NDT VC-57-30-27									
+ 57-30-00-160	VISUAL CHECK LOWER WING PLANK CENTERLINE BETWEEN SPLICE STRINGER 8 & 9	MOS HRS/MSC AFL	15000						15000 M	6052.2
	REF: NDT VC-57-30-03									
57-30-00-162	VISUAL CHECK LOWER WING PLANK - WS 242.0 STRINGER 7	MOS HRS/MSC AFL	15000				01-OCT-1992 0 0		15000	6052.2
	REF: NDT VC-57-30-25									
57-30-00-212 (s)	VISUAL CHECK PLATES/SKINS - UPPER WING BOX - EXTERNAL PKG 6	MOS HRS/MSC AFL	2400				PKG 31-OCT-2003 7003 3486			
	REF: GENERIC NO REF									
57-30-00-213 (s)	VISUAL CHECK PLATES/SKINS - WING BOX LOWER SKIN PKG 30	MOS HRS/MSC AFL	12				PKG 19-JUL-2010 8947.8 4353			
	REF: GENERIC NO REF									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
57-30-00-402	NDT AND VISUAL CHECK WING FUEL ACCESS HOLES;ACCESS 650 AB	MOS							05-10-25 AIRWORTHINESS	
	REF:	HRS/MSC AFL	9204					9204		256.2
+ 57-40-00-163	VISUAL CHECK INBOARD FLAP - FORWARD ATTACHMENT FITTINGS	MOS								
	REF: NDT VC-57-40-01	HRS/MSC AFL	15000					15000 M		10647
+ 57-40-00-164	NDT CHECK OUTBOARD FLAP ARM-FORWARD UPPER LUGS WS 220.0	MOS								
	REF: NDT ET-57-40-07	HRS/MSC AFL	15000					15000 M		10647
+ 57-40-00-165	NDT CHECK INBOARD FLAP - FLAP ARM LOWER LUGS	MOS								
	REF: NDT ET-57-40-04	HRS/MSC AFL	15000					15000 M		10647
+ 57-40-00-166	NDT CHECK OUTBOARD FLAP WING/HINGE BOX FORWARD FITTING	MOS								
	REF: NDT ET-57-40-08	HRS/MSC AFL	15000					15000 M		10647
+ 57-40-00-167	VISUAL CHECK OUTBOARD FLAP VANE SUPPORT FITTING - FLAP STATIONS 189.57, 235.84 AND 280.66.	MOS								
	REF: NDT VC-57-40-03	HRS/MSC AFL	15000					15000 M		10647
+ 57-40-00-170	NDT CHECK FLIGHT SPOILERS WING/HINGE ATTCHMENT POINTS	MOS								
	REF: NDT ET-57-40-01	HRS/MSC AFL	3000				09-SEP-2008 8806.5 4265	11806.5		2858.7
+ 57-40-00-171	NDT CHECK OUTBOARD FLAP-HINGE BOX LOWER FLANGE SUPPORT	MOS								
	REF: NDT ET-57-40-09	HRS/MSC AFL	15000					15000 M		10647

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 57-40-00-172	NDT CHECK INBOARD FLAP - FORWARD ATTACHMENT LUGS	MOS HRS/MSC AFL								
	REF: NDT ET-57-40-05		15000						15000 M	10647
+ 57-40-00-173	NDT CHECK INBOARD FLAP - HINGE SUPPORTS	MOS HRS/MSC AFL								
	REF: NDT ET-57-40-02		5200						5200 M	847
57-40-00-174	NDT CHECK OUTBOARD FLAP - HINGE BOX FWD ATTACHMENT LUGS	MOS HRS/MSC AFL						01-OCT-1992 0 0		
	REF: NDT ET-57-40-10		15000						15000	10647
+ 57-40-00-177	NDT CHECK INBOARD FLAP - WS 127.25 WING RIB BACKUP FITTING	MOS HRS/MSC AFL								
	REF: NDT ET-57-40-03		7000						7000 M	2647
+ 57-40-00-178	VISUAL CHECK WING TO FUSELAGE ATTACHMENT FITTING LUGS AT FS 424.0 BL 45.0	MOS HRS/MSC AFL								
	REF: NDT VC-57-40-07		12000						12000 M	3052.2
+ 57-40-00-179	NDT CHECK INBOARD FLAP - VANE CARRIAGES	MOS HRS/MSC AFL								
	REF: NDT ET-57-40-06		15000						15000 M	10647
57-40-00-182	VISUAL CHECK WING/FUSELAGE ATTACH FITTING LUGS - FS473.0 BL45.0, FS513.0 BL 45.0, FS513.0 BL13.5	MOS HRS/MSC AFL						01-OCT-1992 0 0		
	REF: NDT VC-57-40-02		15000						15000	6052.2
+ 57-40-00-188	VISUAL CHECK AILERON HINGE BOLTS	MOS HRS/MSC AFL								
	REF: NDT VC-57-40-05		9600						9600 M	652.2

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 57-40-00-197	NON DESTRUCTIVE TEST FLAP HINGE BOLT ATTACHMENTS	MOS HRS/MSC AFL								
	REF: NDT PT-57-40-01		15000					15000 M		10647
+ 57-40-00-198	VISUAL CHECK OF FLIGHT SPOILER HINGE BOLTS	MOS HRS/MSC AFL								
	REF: NDT VC-57-40-06		9600					9600 M		652.2
57-40-00-214 (s)	VISUAL CHECK ATTACHMENT FITTINGS MAIN GEAR SIDE BRACE (MLG ACTUATOR PICKUP)	MOS HRS/MSC AFL					PKG 31-OCT-2003 7003 3486			
	PKG 6		2400							
	REF: GENERIC NO REF									
+ 57-40-00-215 (s)	NDT CHECK WING STRUCTURE OF THE WING TO AILERON HINGE BOLTS FOR CRACKS.	MOS HRS/MSC AFL					PKG 27-FEB-2001 4859 2516			
	PKG 10		4800							
	REF: NDT PT-57-40-02									
+ 57-40-00-216 (s)	NDT CHECK WING TO FLAP HINGE BOLTS	MOS HRS/MSC AFL					PKG 27-FEB-2001 4859 2516			
	PKG 10		4800							
	REF: NDT PT-57-40-03									
57-40-00-217 (s)	VISUAL CHECK ATTACHMENT FITTINGS - VISUAL CHECK (MAIN GEAR TRUNNION), (AS EXTERNALLY VISIBLE) BY GAINING ACCESS THROUGH THE MLG BAY AND TRAILING EDGE STRUCTURE WITH THE FLAPS EXTENDED	MOS HRS/MSC AFL					PKG 05-APR-2006 8305.8 4018			
	PKG 34		60							
	REF: GENERIC NO REF									
57-40-00-218 (s)	VISUAL CHECK ATTACHMENT FITTINGS (WING TO FUSE ATTACH ASSEMBLY FS 424.0 FWD) ASSEMBLY AS VISIBLE	MOS HRS/MSC AFL					PKG 05-APR-2006 8305.8 4018			
	PKG 34		60							
	REF: GENERIC NO REF									
57-40-00-219 (s)	VISUAL CHECK ATTACHMENT FITTINGS (WING TO FUSE ATTACH FITTING FS 473.15, CENTER) ASSEMBLY AS VISIBLE	MOS HRS/MSC AFL					PKG 05-APR-2006 8305.8 4018			
	PKG 34		60							
	REF: GENERIC NO REF									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
57-40-00-220 (s)	VISUAL CHECK ATTACHMENT FITTINGS (HINGE/ACTUATOR AILERON) (UPON REMOVAL OF THE UPPER AND LOWER AILERON AERODYNAMIC SEALS)						PKG			
	PKG 34	MOS	60				05-APR-2006			
	REF: GENERIC NO REF	HRS/MSC					8305.8			
		AFL					4018			
57-40-00-221 (s)	VISUAL CHECK ATTACHMENT FITTINGS (FLAP HINGES) (UPON EXTENSION OF THE FLAPS) OF THE HINGE ARM ASSEMBLY						PKG			
	PKG 34	MOS	60				05-APR-2006			
	REF: GENERIC NO REF	HRS/MSC					8305.8			
		AFL					4018			
57-50-00-222 (s)	VISUAL CHECK FLIGHT CONTROL SURFACES (AILERONS, SPOILERS AND FLAPS) EXTERNAL SURFACES OF AILERONS, SPOILERS, INBOARD FLAPS AND OUTBOARD FLAPS						PKG			
	PKG 34	MOS	60				05-APR-2006			
	REF: GENERIC NO REF	HRS/MSC					8305.8			
		AFL					4018			
+ 57-51-00-185	VISUAL CHECK AILERONS									
		MOS					03-NOV-2003			
	REF: NDT VC-57-51-01	HRS/MSC	3600				7003	10603		1655.2
		AFL					3486			
+ 57-51-00-186	VISUAL CHECK AILERON - UPPER & LOWER SKIN AND FRONT SPAR									
		MOS								
	REF: NDT VC-57-51-02	HRS/MSC	15000					15000 M		6052.2
		AFL								
+ 57-53-00-154	NDT CHECK OUTBOARD FLAP VANE INTERMEDATE SUPPORT- FLAP STATIONS 209.39 AND 254.96.									
		MOS								
	REF: See Workcard	HRS/MSC	15000					15000 M		10647
		AFL								
+ 57-53-00-161	NDT CHECK OUTBOARD FLAP VANE SUPPORT STRUTS FLAP STA 171.94/296.00									
		MOS								
	REF: NDT ET-57-53-08	HRS/MSC	7800					9000 M		4647
		AFL								
57-53-00-175	NDT CHECK OUTBD FLAP VANE INTERMEDIATE SUPPORT FITTINGS - FLAP STATION 209.39 AND 254.96									
		MOS					01-OCT-1992			
	REF: NDT ET-57-53-04	HRS/MSC	15000				0	15000		10647
		AFL					0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 57-53-00-180	NON DESTRUCTIVE TEST OF OUTBOARD FLAP-VANE END RAMPS - FLAP STATIONS 171.94 AND 296.00	MOS HRS/MSC AFL	15000						15000 M	10647
	REF: See Workcard									
+ 57-53-00-181	NON DESTRUCTIVE TEST OUTBOARD FLAP - FORWARD LUGS	MOS HRS/MSC AFL	15000						15000 M	10647
	REF: NDT ET-57-53-05									
+ 57-53-00-189	VISUAL CHECK INBOARD FLAP - FRONT SPAR	MOS HRS/MSC AFL	11000				0		11000	6647
	REF: NDT VC-57-53-01									
+ 57-53-00-190	NDT CHECK INBOARD FLAP - VANE SUPPORT ATTACH BRACKETS	MOS HRS/MSC AFL	600				09-SEP-2008 8806.5 4265		4865	512
	REF: NDT ET-57-53-01									
+ 57-53-00-191	NDT CHECK OUTBOARD FLAP - VANE TANGS END SUPPORT - FLAP STATIONS 189.57, 235.84 AND 280.66	MOS HRS/MSC AFL	10000						10000 M	5647
	REF: NDT ET-57-53-02									
+ 57-53-00-193	NDT CHECK OUTBOARD FLAP - FRONT SPAR	MOS HRS/MSC AFL	10000						10000 M	5647
	REF: NDT ET-57-53-03									
57-53-00-224 (s)	VISUAL CHECK FLAPS (INBOARD FLAP VANE ASSEMBLY) (UPON REMOVAL OF THE LOWER ACCESS PANELS) OF EACH OF THE VANE ACTUATING ASSEMBLIES. REINSTALL LOWER ACCESS PANELS.	PKG 6 MOS HRS/MSC AFL	2400				31-OCT-2003 7003 3486			
	REF: GENERIC NO REF									
57-55-00-196	VISUAL CHECK FLIGHT SPOILER - UPPER & LOWER SKIN	MOS HRS/MSC AFL	15000				01-OCT-1992 0 0		15000	6052.2
	REF: NDT VC-57-55-01									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
572000-001	TORSION BAR:NO. 1 AILERON ANTI-FLT TORSION BAR 600-10057-5 SN-UNKNOWN REF: AMM 572000	MOS HRS/MSC AFL	10000	TSN:0 TSN:0			01-OCT-1992 0 0	10000	5647	LIFE LIMIT
572000-002	TORSION BAR:NO. 2 AILERON ANTI-FLT TORSION BAR 600-10057-6 SN-UNKNOWN REF: AMM 572000	MOS HRS/MSC AFL	10000	TSN:0 TSN:0			01-OCT-1992 0 0	10000	5647	LIFE LIMIT
575100-001	AILERON:NO. 1 AILERON 600-13000-1003 5121 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
575100-002	AILERON:NO. 2 AILERON 600-13000-1004 5121 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
575300-001	FLAP:LH INBOARD FLAP 600-14002-805 5121 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
575300-002	FLAP:RH INBOARD FLAP 600-14002-806 5121 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
575305-001	VANE ASSEMBLY:LEFT INBOARD FLAP VANE ASSEMBLY 600-14302-3 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
575305-002	VANE ASSEMBLY:RIGHT INBOARD FLAP VANE ASSEMBLY 600-14302-4 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
575306-001	FLAP ASSEMBLY:LEFT OUTBOARD FLAP ASSEMBLY 600-14500-805 5121 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
575306-002	FLAP ASSEMBLY:RIGHT OUTBOARD FLAP ASSEMBLY 600-14500-806 5121 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
+ 575317-001	BEAM ASSEMBLY:NO.1 FLAP VANE ACTUATOR BEAM ASSEMBLY 600-14250-27 5121LH-3 REF: GENERIC NO REF	DAYS HRS/MSC AFL	9600	TSN:0 TSN:0			01-OCT-1992 0 0	9600	5247	LIFE LIMIT
+ 575317-002	BEAM ASSEMBLY:NO.2 FLAP VANE ACTUATOR BEAM ASSEMBLY 600-14250-27 5121LH-2 REF: GENERIC NO REF	MOS HRS/MSC AFL	9600	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0	9600	5247	LIFE LIMIT
+ 575317-003	BEAM ASSEMBLY:NO. 3 FLAP VANE ACTUATOR BEAM ASSEMBLY 600-14250-27 5121LH-1 REF: GENERIC NO REF	MOS HRS/MSC AFL	9600	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0	9600	5247	LIFE LIMIT
+ 575317-004	BEAM ASSEMBLY:NO.4 FLAP VANE ACTUATOR BEAM ASSEMBLY 600-14250-27 5121RH-1 REF: GENERIC NO REF	MOS HRS/MSC AFL	9600	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0	9600	5247	LIFE LIMIT
+ 575317-005	BEAM ASSEMBLY:NO.5 FLAP VANE ACTUATOR BEAM ASSEMBLY 600-14250-27 5121RH-2 REF: GENERIC NO REF	MOS HRS/MSC AFL	9600	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0	9600	5247	LIFE LIMIT
+ 575317-006	BEAM ASSEMBLY:NO.6 FLAP VANE ACTUATOR BEAM ASSEMBLY 600-14250-27 5121RH-3 REF: GENERIC NO REF	MOS HRS/MSC AFL	9600	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0	9600	5247	LIFE LIMIT

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
575500-001	SPOILER:LEFT FLIGHT SPOILER 600-10602-61 REL297 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
575500-002	SPOILER:RIGHT FLIGHT SPOILER 600-10602-62 228 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
575700-001	SPOILER:NO. 1 GROUND SPOILER 600-10502-41 287 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			08-APR-1993 24 15			
575700-002	SPOILER:NO. 2 GROUND SPOILER 600-10502-42 276 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
57R001	LENS:L NAV LIGHT LENS 601-10391-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
57R006	LENS:R NAV LIGHT LENS 601-10391-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
C57-00-801 (s)	CPCP CHECK WING FRONT SPAR AND LEADING EDGE WS50.00 TO WS353.00 PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C57-00-802 (s)	CPCP CHECK WING LOWER EXTERNAL SURFACE, BL0.0 TO WS353.00 PKG 32 REF: GENERIC NO REF	MOS HRS/MSC AFL	24				PKG 28-MAY-2009 8928.6 4336			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
C57-00-803 (s)	CPCP CHECK WING UPPER SURFACE, BL0.0 TO BL50.00 PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C57-00-804 (s)	CPCP CHECK WING STRUCTURE BETWEEN THE FRONT SPAR AND REAR SPAR, BL0.0 TO BL45.00 PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C57-00-805 (s)	CPCP CHECK WING FRONT SPAR, BL0.00 TO WS50.00 PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C57-00-806 (s)	CPCP CHECK WING STRUCTURE BETWEEN THE FRONT SPAR AND REAR SPAR, WS45.00 TO WS353.00 (INTERNAL) PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C57-00-807 (s)	CPCP CHECK WING REAR SPAR, BL0.0 TO WS66.00 (EXTERNAL) PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C57-00-808 (s)	CPCP CHECK WINGTIP/WINGLET ASSEMBLY (INTERNAL/EXTERNAL) PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C57-00-809 (s)	CPCP CHECK WING REAR SPAR AND AUXILIARY SPAR, WS50.00 TO WS353.00 PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C57-00-810 (s)	CPCP CHECK MAIN LANDING GEAR ACTUATOR FITTING AT WING BOX FS513.00 BL13.50 PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	48				PKG 19-MAR-2007 8468 4101			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
C57-00-811 (s)	CPCP CHECK WING REAR SPAR AND AUXILIARY SPAR, WS66.00 TO WS148.00 PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C57-00-812 (s)	CPCP CHECK WING TO FUSELAGE ATTACHMENT FITTING, FS424.00 BL45.00 PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C57-00-813 (s)	CPCP CHECK WING TO FUSELAGE ATTACHMENT FITTING, FS473.15 BL45.00 PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C57-00-814 (s)	CPCP CHECK OUTBOARD FLAP (EXTERNAL) PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C57-00-815 (s)	CPCP CHECK INBOARD FLAP (EXTERNAL) PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C57-00-816 (s)	CPCP CHECK INBOARD FLAP VANE ACTUATING ASSEMBLIES PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C57-00-817 (s)	CPCP CHECK AILERON (EXTERNAL) PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C57-00-818 (s)	CPCP CHECK FLIGHT SPOILER (EXTERNAL) PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
C57-00-819 (s)	CPCP CHECK WING UPPER EXTERNAL SURFACE, WS50.00 TO WS353.00 PKG 34	MOS	60				PKG			
	REF: GENERIC NO REF	HRS/MSC AFL								
C57-00-820 (s)	CPCP CHECK WING TO FUSELAGE ATTACHMENT FITTING, WS513.00, BL45.00 PKG 34	MOS	60				PKG			
	REF: GENERIC NO REF	HRS/MSC AFL								
T57T01	RIGGING/ADJUSTMENT/TEST - FLAPS	MOS								
	REF:	HRS/MSC AFL	O/C							
CHAPTER 71 POWER PLANT										
+ 71-10-00-101	NDT CHECK NOSE COWL ACTUATOR SUPPORT FITTING - FORWARD ATTACHMENT LUGS PKG 4	MOS	1200				09-JUN-2005 8180 3964	9380		432.2
	REF: NDT ET-71-10-01	HRS/MSC AFL								
+ 71-10-00-102	NDT CHECK FORWARD NACELLE STRUCTURE AT THE ENGINE NACELLE JOINT	MOS	13800					13800 M		4852.2
	REF: NDT ET-71-10-02	HRS/MSC AFL								
71-10-11-209 (s)	VISUAL CHECK NOSE COWL ASSEMBLY PKG 2	MOS	300				09-SEP-2008 8806.5 4265			
	REF: AMM 71-10-11-209	HRS/MSC AFL								
71-10-16-201 (s)	VISUAL CHECK TRANSLATING COWL DOORS PAYING PARTICULAR ATTENTION TO THE TRAILING EDGE UPPER AND LOWER DOORS. PKG 2	MOS	300				09-SEP-2008 8806.5 4265			
	REF: GENERIC NO REF	HRS/MSC AFL								
+ 71-10-26-206	VISUAL CHECK CORE COWL FIXED SIDE PANEL, PYLON INSTALLATION AND CASTING INCLUDING OIL COOLER INSTALLATION.	MOS	3000				20-MAR-2009 8873.5 4304	11849		2901.2
	REF: GENERIC NO REF	HRS/MSC AFL			-24.5					

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
71-12-01-202 (s)	CHECK CORE COWL DOORS PKG 2 REF: AMM 71-12-01-202	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
71-12-01-210	DETAILED INSPECTION CORE COWL DOORS - HINGES REF: AMM 71-12-01-210	MOS HRS/MSC AFL	N/A				29-OCT-2003 7003 3486			
71-12-01-211	FUNCTIONAL TEST CORE COWL DOORS OF THE LATCHES REF: AMM 71-12-01-211	MOS HRS/MSC AFL	N/A				01-OCT-1992 0 0			
71-12-01-212	FUNCTIONAL TEST CORE COWL DOORS - BLOWOUT DOORS REF: AMM 71-12-01-212	MOS HRS/MSC AFL	N/A				01-OCT-1992 0 0			
71-13-00-220	DETAILED INSPECTION MAIN/PYLON TRACK SLIDER BLOCKS REF: AMM 78-30-41	MOS HRS/MSC AFL	N/A				01-OCT-1992 0 0			
71-16-00-213	GENERAL VISUAL INSPECTION FORWARD CORE COWL AND LINK HOUSING FOR CONDITION AND SECURITY OF INSTALLATION. REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				29-OCT-2003 7003 3486			
71-16-00-214	GENERAL VISUAL INSPECTION FORWARD CORE COWL ATTENUATING PANELS FOR LOOSE OR MISSING FASTENERS. REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				29-OCT-2003 7003 3486			
71-16-00-215	GENERAL VISUAL INSPECTION FORWARD CORE COWL OF BLOCKER DOOR LINKS FOR CONDITION AND SECURITY OF INSTALLATION. REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				29-OCT-2003 7003 3486			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 71-20-00-103	NDT CHECK AFT ENGINE MOUNT - THRUST FITTING									AIRWORTHINESS
		MOS								
		HRS/MSC	15000						15000 M	6052.2
	REF: NDT ET-71-20-01	AFL								
+ 71-20-00-104	NDT CHECK ENGINE MOUNT YOKE - LOWER LUG									AIRWORTHINESS
		MOS								
		HRS/MSC	15000						15000 M	6052.2
	REF: NDT ET-71-20-02	AFL								
71-20-00-105	NDT CHECK FWD ENGINE MOUNT UPPER LINK									
		MOS					01-OCT-1992			
		HRS/MSC	15000				0		15000	6052.2
	REF: NDT UT-71-20-01	AFL					0			
71-20-00-106	NDT CHECK FWD ENGINE MOUNT UPPER BOLTS									
		MOS					01-OCT-1992			
		HRS/MSC	15000				0		15000	6052.2
	REF: NDT PT-71-20-01	AFL					0			
71-30-00-221	GENERAL VISUAL INSPECTION ENGINE FIRE SEALS									
		MOS					01-OCT-1992			
		HRS/MSC	N/A				0			
	REF: AMM 71-30-00-221	AFL					0			
71-61-00-216	GENERAL VISUAL INSPECTION NOSE COWL ASSEMBLY FOR CONDITION AND SECURITY OF INSTALLATI									
		MOS					29-OCT-2003			
		HRS/MSC	N/A				7003			
	REF: GENERIC NO REF	AFL					3486			
71-61-00-218	GENERAL VISUAL INSPECTION NOSE COWL ASSEMBLY OF ACCESS PANELS FASTENERS, ANTI-ICING EQUIPMENT AND P.D.U. SUPPORT BRACKETS FOR CONDITION AND SECURITY OF INSTALLATION.									
		MOS					29-OCT-2003			
		HRS/MSC	N/A				7003			
	REF: GENERIC NO REF	AFL					3486			
712010-001	MOUNT:NO. 1 ENGINE FORWARD MOUNT									
	601-37001-1	MOS					01-OCT-1992			
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0			
	REF: GENERIC NO REF	AFL					0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
712010-002	MOUNT:NO. 2 ENGINE FORWARD MOUNT 601-37001-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
712014-001	MOUNT:NO. 1 ENGINE AFT MOUNT 601-37002-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
712014-002	MOUNT:NO. 2 ENGINE AFT MOUNT 601-37002-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
719301	EJECTOR:RIGHT ENGINE ECOLOGY DRAIN EJECTOR 25850-1 0404 REF:	MOS HRS/MSC AFL	N/R				26-DEC-2001 5429 2786			
719401	--:UNITS, L/H ENGINE BUILD 601-6001-9 187LH REF:	MOS HRS/MSC AFL	N/R				01-OCT-1992 0 0			
719406	--:UNITS, R/H ENGINE BUILD 601-6001-10 187RH REF:	MOS HRS/MSC AFL	N/R				01-OCT-1992 0 0			
71EN1	ENGINE:NO. 1 ENGINE 6063T01G04 350-499 REF: AMM 71EN1	MOS HRS/MSC AFL	E/C	TSN:5852			29-AUG-2002 5989.9 3059			
71EN2	ENGINE:NO. 2 ENGINE 6063T01G04 350-498 REF: AMM 71EN1	MOS HRS/MSC AFL	E/C	TSN:5852			29-AUG-2002 5989.9 3059			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
C71-00-801 (s)	CPCP CHECK FORWARD ENGINE MOUNT PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C71-00-802 (s)	CPCP CHECK AFT ENGINE MOUNT PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
C71-00-803 (s)	CPCP CHECK FORWARD NACELLE AND NOSE COWL ACTUATOR SUPPORT FITTING. PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				PKG			
T71T01	REMOVAL/INSTALLATION , MID POINT INSPECTION - ENGINE REF:	MOS HRS/MSC AFL	O/C							
T71T02	ENGINE STARTING/SHUTDOWN, DRY MOTORING CYCLE AND WET MOTORING CYCLE, TRANSIENT CHECK (AIRCRAFT 5001 TO 5134) REF:	MOS HRS/MSC AFL	O/C							
T71T03	O REF:	MOS HRS/MSC AFL	O/C							
T71T04	LEAK CHECK - FUEL AND OIL SYSTEM REF:	MOS HRS/MSC AFL	O/C							
T71T05	REMOVAL/INSTALLATION , MID POINT INSPECTION - ENGINE (A/C 5135 AND SUBS) REF:	MOS HRS/MSC AFL	O/C							

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
T71T06	MAINTENANCE PRACTICES - ENGINE - TRANSLATING COWL DOORS AND CORE COWL DOORS	MOS								
	REF:	HRS/MSC AFL	O/C							
T71T07	ENGINE STARTING/SHUTDOWN, DRY MOTORING CYCLE AND WET MOTORING CYCLE, TRANSIENT CHECK (A/C 5135 AND SUBS)	MOS								
	REF:	HRS/MSC AFL	O/C							
CHAPTER 72 ENGINE										
729003	--:BAFFLE, AIR HPT STATOR	MOS						16-MAR-1998		
	6047T86G04	HRS/MSC	O/C	TSN:0				2991		
	GGMTA072	AFL		TSN:0				1506		
	REF:									
72R002	--:FAN BLADE # 5, RIGHT ENG.	MOS						17-MAY-1995		
	6018T30P06	HRS/MSC	N/R	TSN:1226				1226		
	KGAR4194	AFL		TSN:595				595		
	REF:									
72R003	--:FAN BLADE # 7, RIGHT ENG.	MOS						17-MAY-1995		
	6018T30P06	HRS/MSC	N/R	TSN:1226				1226		
	KGAR4584	AFL		TSN:595				595		
	REF:									
72R004	--:FAN BLADE #19, RIGHT ENG.	MOS						17-MAY-1995		
	6018T30P06	HRS/MSC	N/R	TSN:1226				1226		
	KGAR3376	AFL		TSN:595				595		
	REF:									
72R005	--:FAN BLADE #21, RIGHT ENG.	MOS						17-MAY-1995		
	6018T30P06	HRS/MSC	N/R	TSN:1226				1226		
	KGAR4842	AFL		TSN:595				595		
	REF:									
72R011	BALANCE LEFT ENGINE	MOS						01-OCT-1992		
	REF:	HRS/MSC AFL	N/R					0 0		

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
72R016	BALANCE RIGHT ENGINE REF:	MOS HRS/MSC AFL	N/R				02-APR-1997 2415 1208			
72R021	ASSY:L ENG #1 CARBON SEAL ASSY 6047T63P03 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
72R026	ASSY:R ENG #1 CARBON SEAL ASSY 6047T63P03 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
72R031	SEAL:L ENG #7 CARBON SEAL PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
72R036	SEAL:R ENG #7 CARBON SEAL PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
ENGINE NO. 1 Model : CF-34 (CIMMS) Serial # 350-499 Part # 6063T01G04										
72-00-00-201 (s)	NO. 1 ENGINE - VISUAL CHECK GENERAL - ENGINE FAN STATOR (1) FLOWPATH ALUMINUM SKIN FOR DENTS AND CRACKS. (2) ABRADABLE RUB STRIP FOR RUBBING.(REF. G.E. MM SEI-580, SECTION 5-21-00) PKG 2 REF:	MOS HRS/MSC ENC	300				PKG 09-SEP-2008 8668.5			
72-00-00-203 (s)	NO. 1 ENGINE - VISUAL CHECK ENGINE - GENERAL - CARRY OUT A VISUAL CHECK OF THE FOLLOWING: (1) ENGINE MOUNTS. (2) FAN ROTOR. (3) FAN STATOR. (4) COMPRESSOR CASE. (5) FRONT FRAME, PAYING PARTICULAR ATTENTION AROUND AGB MOUNT PADS. (6) ACCESSORY GEARBOX. (FOR ALL 6 ITEMS, REFER TO GE MM SEI-580, SECTION 5-21-00) PKG 2 REF:	MOS HRS/MSC ENC	300				PKG 09-SEP-2008 8668.5			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
72-00-00-207 (s)	NO. 1 ENGINE - VISUAL CHECK GENERAL -ENGINE EXTERNAL LINES,PORTS,FLANGES,CLAMPS, BRACKETS,ELECTRICAL CONNECTORS,ENGINE SURFACE AND ACCESSORIES.(REF. G.E. MM SEI-580, SECTION 5-21-00)						PKG			
	PKG 2	MOS						09-SEP-2008		
	REF:	HRS/MSC	300					8668.5		
		ENC								
72-00-00-208 (s)	NO. 1 ENGINE - VISUAL CHECK GENERAL -ENGINE - HIGH PRESSURE TURBINE SECTION CASING, PAYING PARTICULAR ATTENTION FOR CRACKS,BULGES,HOT SPOTS AND SECURITY OF CENTRE BODY.(REF. G.E. MM SEI-580, SECTION 5-21-00)						PKG			
	PKG 2	MOS						09-SEP-2008		
	REF:	HRS/MSC	300					8668.5		
		ENC								
72-00-00-209 (s)	NO. 1 ENGINE - VISUAL CHECK GENERAL - ENGINE CARRY OUT A VISUAL CHECK OF THE FOLLOWING: (1) COMPRESSOR ASSEMBLY FOR MISSING LOCK TABS ON VISIBLE VARIABLE VANE OUTER SHANKNUTS.(REF. G.E. MM SEI-580, SECTION 5-21-00) (2) FAN ROTOR BLADE REMOVAL PORT, WATER DRAIN FOR BLOCKAGE.(REF. G.E. MM SEI-580, SECTION 5-21-00)						PKG			
	PKG 3	MOS						20-MAR-2009		
	REF:	HRS/MSC	600					8735.6		
		ENC								
+ 72-00-00-210 (s)	NO. 1 ENGINE - ENGINE (A) BORESCOPE INSPECTION OF COMBUSTION LINER. (B) VISUAL CHECK FOR CRACKS IN COMBUSTION CHAMBER FRAME. (C) BORESCOPE INSPECTION OF FUEL INJECTORS, PAYING PARTICULAR ATTENTION TO CENTERING IN SWIRLERS. (REF. G.E. MM SEI-580, SECTION 5-21-00) (D) BORESCOPE INSPECTION OF OUTER TRANSITION LINER - THIS INSPECTION (D) APPLIES TO ENGINES 350485 AND BELOW AS INSTRUCTED IN G.E. SB 72-32 THAT HAVE NOT BEEN MODIFIED TO SB 72-38.						PKG			
	PKG 4	MOS						07-JUN-2005		
	REF: See Workcard	HRS/MSC	1200					8043		
		ENC								
+ 72-00-00-211 (s)	NO. 1 ENGINE - BORESCOPE INSPECTION TURBINE SECTION, STAGE 1 NOZZLE AND HPT STAGE 1 BLADES (REF. G.E. MM SEI-580, SECTION 5-21-00)						PKG			
	PKG 4	MOS						07-JUN-2005		
	REF: See Workcard	HRS/MSC	1200					8043		
		ENC								
+ 72-00-00-212	NO. 1 ENGINE - BORESCOPE INSPECTION GENERAL - ENGINE - POWER TAKE-OFF (PTO) PART NUMBER 6037T72G01 OR 6037T72G06 FOR FORWARD MOVEMENT OF CARBON SLEEVE. (PRE G.E. SB(CF34)72-11) (REF. G.E. MM SEI-580, SECTION 5-21-00)									
		MOS						29-AUG-2002		
	REF: EMM 72-00-00	HRS/MSC	O/C					5852		
		ENC						3407		

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
72-00-00-213	NO. 1 ENGINE - MIDPOINT INSPECTION GENERAL - ENGINE (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS HRS/MSC ENC	3000	TSI:0			29-AUG-2002 5852 3407	(8852) 8989.9		42.1
	REF: EMM 05-21-00									
72-00-00-215	NO. 1 ENGINE - BORESCOPE COMPRESSOR AND VISUAL CHECK OF VISIBLE AREAS OF COMPRESSOR CASINGS, VISUAL CHECK OF VARIABLE VANES, PAYING ATTENTION FOR NICKS,DENTS,CRACKS AND EXCESSIVE MOVEMENT. (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS HRS/MSC ENC	3000	TSI:0			29-AUG-2002 5852 3407	(8852) 8989.9		42.1
	REF:									
72-00-00-217	NO. 1 ENGINE - DETAILED INSPECTION OF ENGINE ACCESSORY GEARBOX MOUNTS (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS HRS/MSC ENC	3000	TSI:0			29-AUG-2002 5852 3407	(8852) 8989.9		42.1
	REF:									
+ 72-00-00-218A	NO. 1 ENGINE - OVERHAUL ENGINE	MOS HRS/MSC ENC	6000				29-AUG-2002 5852 3407	(11852) 11989.9		3042.1
	REF:									
+ 72-00-00-218B	NO. 1 ENGINE - BOROSCOPE ENGINE (IF REQUIRED)	MOS HRS/MSC ENC	120 3000				29-AUG-2002 5852 3407	29-AUG-2012 (8852) 8989.9		722 d 42.1
	REF:									
+ 72-00-00-219 (s)	NO. 1 ENGINE - CHECK GENERAL -ENGINE - OIL SAMPLE (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS HRS/MSC ENC	600				PKG 20-MAR-2009 8735.6			
	REF: EMM 72-00-00									
72-00-00-221	NO. 1 ENGINE - VISUAL CHECK GENERAL- ENGINE - 6 O'CLOCK C-SUMP SCAVENGE TUBE AND GROOVE FOR INTERNAL COKING.(REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS HRS/MSC ENC	3000	TSI:0			29-AUG-2002 5852 3407	(8852) 8989.9		42.1
	REF:									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
72-00-00-222	NO. 1 ENGINE - VISUAL CHECK GENERAL - ENGINE - LPT STATOR ASSEMBLY P/N 6020T15G14 FOR TACK WELDING OF THE PIN AND CLIP ASSEMBLIES. REWORK AND RE-IDENTIFY IF REQUIRED.(REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS HRS/MSC ENC	3000	TSI:0			29-AUG-2002 5852 3407	(8852) 8989.9	8892	42.1
72-00-00-223	NO. 1 ENGINE - VISUAL CHECK GENERAL - ENGINE - HPT STAGE 1 AND STAGE 2 SHROUDS (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS HRS/MSC ENC	3000	TSI:0			29-AUG-2002 5852 3407	(8852) 8989.9		42.1
72-00-00-224	NO. 1 ENGINE - INSPECT/CHECK TURBINE THERMOCOUPLE HARNESS (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS HRS/MSC ENC	3000	TSI:0			29-AUG-2002 5852 3407	(8852) 8989.9		42.1
72-00-00-225	NO. 1 ENGINE - VISUAL CHECK TURBINE NOZZLES (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS HRS/MSC ENC	3000	TSI:0			29-AUG-2002 5852 3407	(8852) 8989.9		42.1
72-00-00-226	NO. 1 ENGINE - DETAILED VISUAL INSPECTION SWIRLERS AFTER REMOVAL OF THE INJECTORS (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS HRS/MSC ENC	3000	TSI:0			29-AUG-2002 5852 3407	(8852) 8989.9		42.1
72-00-00-227	NO. 1 ENGINE - VISUAL CHECK PRIMARY SWIRLERS, PAYING PARTICULAR ATTENTION FOR WEAR (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS HRS/MSC ENC	3000	TSI:0			29-AUG-2002 5852 3407	(8852) 8989.9		42.1
72-00-00-228	NO. 1 ENGINE - VISUAL CHECK STAGE 1 AND STAGE 2 NOZZLE ASSEMBLIES. (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS HRS/MSC ENC	3000	TSI:0			29-AUG-2002 5852 3407	(8852) 8989.9		42.1

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
72-00-00-229	NO. 1 ENGINE - VISUAL CHECK COMBUSTION LINER AFTER DISASSEMBLY (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS HRS/MSC ENC	3000	TSI:0			29-AUG-2002 5852 3407	(8852) 8989.9		42.1
72-00-00-230	NO. 1 ENGINE - CHECK COMBUSTION SECTION FUEL INJECTOR HEAT SHIELDS FOR LOOSENESS. (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS HRS/MSC ENC	3000	TSI:0			29-AUG-2002 5852 3407	(8852) 8989.9		42.1
72-00-00-231	NO. 1 ENGINE - VISUAL CHECK FAN DISK TO ENSURE BUSHINGS ARE NOT PROTRUDING. (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS HRS/MSC ENC	3000	TSI:0			29-AUG-2002 5852 3407	(8852) 8989.9		42.1
+ 72-00-00-301 (s)	NO. 1 ENGINE - COMPRESSOR WASH GENERAL - ENGINE	MOS HRS/MSC ENC	300				PKG 09-SEP-2008 8668.5			
+ 72-00-00-302 (s)	NO. 1 ENGINE - POWER ASSURANCE CHECK ENGINE - GENERAL (ENGINE MODEL CF34-1A/-3A/-3A2 ONLY)	MOS HRS/MSC ENC	300				PKG 09-SEP-2008 8668.5			
720110	NO. 1 ENGINE - REPLACE NO.5 BEARING CARBON SEAL PREFORMED PACKING	MOS HRS/MSC ENC	3000				29-AUG-2002 5852 3407	(8852) 8989.9		LIFE LIMIT 42.1
722150-001	DISC:NO. 1 ENGINE - FAN DISC 6078T57G02 GAT7556M	MOS HRS/MSC ENC	9000	TSN:0			23-AUG-2002 5852 3407	12407		LIFE LIMIT 8063
722151-001	SHAFT:NO. 1 ENGINE - FAN DRIVE SHAFT 6036T78P02 REA1780H	MOS HRS/MSC ENC	15000	TSN:5852 TSN:3407			23-AUG-2002 5852 3407	15000		LIFE LIMIT 10656

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
722152-001	SHAFT:NO. 1 ENGINE - FAN FORWARD SHAFT 6078T51P01 GAT1030M REF:	MOS HRS/MSC ENC	15000	TSN:5852 TSN:3407			23-AUG-2002 5852 3407	15000	10656	LIFE LIMIT
722210-001	SHAFT:NO. 1 ENGINE - COMPRESSOR ROTOR REAR SHAFT 6087T03P03 GWN05A40 REF:	MOS HRS/MSC ENC	23000	TSN:0 TSN:0			23-AUG-2002 5852 3407	26407	22063	LIFE LIMIT
723120-001	SENSOR:NO. 1 ENGINE - FAN SPEED SENSOR 4021T56P03 GDB41615 REF: EMM 74-00-00	MOS HRS/MSC ENC	O/C	TSO:0TSN:5803.7 TSO:0TSN:5350			23-AUG-2002 5852 3407			
723318-001	SHAFT:NO. 1 ENGINE - COMPRESSOR ROTOR FWD SHAFT 5037T01P03 GAT2261M REF:	MOS HRS/MSC ENC	11740	TSN:5852 TSN:3407			23-AUG-2002 5852 3407	11740	7396	LIFE LIMIT
723320-001	DISC:NO. 1 ENGINE - STAGE 1 COMPRESSOR ROTOR DISC 6087T00G02 GATH6A5N REF:	MOS HRS/MSC ENC	15000	TSN:0 TSN:0			23-AUG-2002 5852 3407	18407	14063	LIFE LIMIT
723322-001	DISC:NO. 1 ENGINE - STAGE 2 COMPRESSOR ROTOR DISC 6036T91P01 GAT2281M REF:	MOS HRS/MSC ENC	15000	TSN:5852 TSN:3407			23-AUG-2002 5852 3407	15000	10656	LIFE LIMIT
723326-001	SEAL:NO. 1 ENGINE - CDP SEAL 4019T38P01 PAML9610 REF:	MOS HRS/MSC ENC	14400	TSN:5852 TSN:3407			23-AUG-2002 5852 3407	14400	10056	LIFE LIMIT
723328-001	SPOOL:NO. 1 ENGINE - 3 - 8 STAGE COMPRESSOR ROTOR SPOOL 6078T56P04 GWN04FRK REF:	MOS HRS/MSC ENC	27000	TSN:0 TSN:0			23-AUG-2002 5852 3407	30407	26063	LIFE LIMIT

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
723330-001	SPOOL:NO. 1 ENGINE - 10 - 14 STAGE COMPRESSOR ROTOR SPOOL 5087T46P02 GATH906H REF:	MOS HRS/MSC ENC	17000	TSN:0 TSN:0			23-AUG-2002 5852 3407	20407		LIFE LIMIT 16063
723351-001	DISC:NO. 1 ENGINE - STAGE 9 COMPRESSOR ROTOR DISC 6087T01P03 HAAJ9853 REF:	MOS HRS/MSC ENC	20000	TSN:0 TSN:0			23-AUG-2002 5852 3407	23407		LIFE LIMIT 19063
724220-001	LINER:NO. 1 ENGINE - ENGINE COMBUSTION LINER 6063T15G01 GGMTW382 REF:	MOS HRS/MSC ENC	O/C	TSN:5221.1 TSN:3105			23-AUG-2002 5852 3407			
724611-001	DISC:NO. 1 ENGINE - STAGE 1 TURBINE DISC 6031T89P03 GAT7275G REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			23-AUG-2002 5852 3407	6000		LIFE LIMIT 1656
724612-001	DISC:NO. 1 ENGINE - STAGE 2 TURBINE DISC 6031T90P03 GAT4725M REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			23-AUG-2002 5852 3407	6000		LIFE LIMIT 1656
724620-001	SHAFT:NO. 1 ENGINE - HPT SHAFT 6017T00P05 GATH654M REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			23-AUG-2002 5852 3407	6000		LIFE LIMIT 1656
724628-001	SEAL:NO. 1 ENGINE - BALANCE PISTON ROTATING AIR SEAL 6078T90P01 GATH4M1E REF:	MOS HRS/MSC ENC	6000	TSN:0 TSN:0			23-AUG-2002 5852 3407	9407		LIFE LIMIT 5063
724628-002	SEAL:NO. 1 ENGINE - BALANCE PISTON STATIONARY AIR SEAL PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
724630-001	PLATE:NO. 1 ENGINE - STAGE 1 FRONT COOLING PLATE 4027T15P03 GAT7887D REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			23-AUG-2002 5852 3407	6000		LIFE LIMIT 1656
724632-001	PLATE:NO. 1 ENGINE - STAGE 1 COOLING AFT PLATE 5041T70P03 GAT8148L REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			23-AUG-2002 5852 3407	6000		LIFE LIMIT 1656
724636-001	COUPLING:NO. 1 ENGINE - TORQUE INNER COUPLING 5079T02P01 GATH80TF REF:	MOS HRS/MSC ENC	6000	TSN:0 TSN:0			23-AUG-2002 5852 3407	9407		LIFE LIMIT 5063
724638-001	COUPLING:NO. 1 ENGINE - TORQUE OUTER COUPLING 5041T67P02 GAT3696M REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			23-AUG-2002 5852 3407	6000		LIFE LIMIT 1656
724640-001	PLATE:NO. 1 ENGINE - STAGE 2 FWD COOLING PLATE 5042T29P02 GAT2258H REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			23-AUG-2002 5852 3407	6000		LIFE LIMIT 1656
724642-001	PLATE:NO. 1 ENGINE - STAGE 2 AFT COOLING PLATE 5023T97P03 GAT4057H REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			23-AUG-2002 5852 3407	6000		LIFE LIMIT 1656
725011-001	STUD:NO. 1 ENGINE - HPT STG 2 STUD PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	6000	TSN:0			29-AUG-2002 5852 3407	(11852) 11989.9	11852	LIFE LIMIT 3042.1
725120	NO. 1 ENGINE - REPLACE HIGH PRESSURE TURBINE STAGE 2 NOZZLE RETAINING RING SECTOR REF:	MOS HRS/MSC ENC	3000				29-AUG-2002 5852 3407	(8852) 8989.9		LIFE LIMIT 42.1

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
725220-001	THERMOCOUPLE:NO. 1 ENGINE - LEFT ASSEMBLY THERMOCOUPLE 6030T41P01 GDBB857F REF:	MOS HRS/MSC ENC	O/C	TSN:2860.5 TSO:0 TSO:0TSN:1690			23-AUG-2002 5852 3407			
725220-002	THERMOCOUPLE:NO. 1 ENGINE - RIGHT ASSEMBLY THERMOCOUPLE 6030T40P01 GDB09299 REF:	MOS HRS/MSC ENC	O/C	TSO:0TSN:5852 TSO:0TSN:3407			23-AUG-2002 5852 3407			
725236-001	BLADE:NO. 1 ENGINE - TURBINE STAGE 1 BLADE 6078T19P02 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:5852 TSN:3407			23-AUG-2002 5852 3407			
725314-001	SHAFT:NO. 1 ENGINE - LOW PRESSURE TURBINE REAR SHAFT 6030T72P02 GAT2170L REF:	MOS HRS/MSC ENC		TSN:5852 TSN:3407			23-AUG-2002 5852 3407	39000		34656
725323-001	DISC:NO. 1 ENGINE - STAGE 3 TURBINE DISC 5026T16P02 GAT7634L REF:	MOS HRS/MSC ENC		TSN:5852 TSN:3407			23-AUG-2002 5852 3407	6000		1656
725324-001	DISC:NO. 1 ENGINE - STAGE 4 TURBINE DISC 6078T02P01 GAT2192L REF:	MOS HRS/MSC ENC		TSN:5852 TSN:3407			23-AUG-2002 5852 3407	15000		10656
725325-001	DISC:NO. 1 ENGINE - STAGE 5 TURBINE DISC 5024T53P02 GAT1996D REF:	MOS HRS/MSC ENC		TSN:5852 TSN:3407			23-AUG-2002 5852 3407	6000		1656
725326-001	DISC:NO. 1 ENGINE - STAGE 6 TURBINE DISC 6078T89P01 GAT6277C REF:	MOS HRS/MSC ENC		TSN:5852 TSN:3407			23-AUG-2002 5852 3407	15000		10656

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
725330-001	SEAL:NO. 1 ENGINE - 3 - 4 STAGE TURBINE SEAL 5023T59P02 PAMM0589 REF:	MOS HRS/MSC ENC	29730	TSN:4336.4 TSN:5931			23-AUG-2002 5852 3407	27206		LIFE LIMIT 22862
725332-001	SEAL:NO. 1 ENGINE - 4 - 5 STAGE TURBINE SEAL 5023T67P01 PAML3424 REF:	MOS HRS/MSC ENC	29730	TSN:4336 TSN:5931			23-AUG-2002 5852 3407	27206		LIFE LIMIT 22862
725334-001	SEAL:NO. 1 ENGINE - 5 - 6 STAGE TURBINE SEAL 5023T64P02 PAMM0442 REF:	MOS HRS/MSC ENC	29730	TSN:4336.4 TSN:5935			23-AUG-2002 5852 3407	27202		LIFE LIMIT 22858
725338-001	CONE:NO. 1 ENGINE - TURBINE DRIVE CONE 5023T40P01 GAT1802M REF:	MOS HRS/MSC ENC	15000	TSN:5852 TSN:3407			23-AUG-2002 5852 3407	15000		LIFE LIMIT 10656
726210-001	GEARBOX:NO. 1 ENGINE - ACCESSORY GEARBOX 6014T81G25 WIA96833 REF: EMM 72-60-00	MOS HRS/MSC ENC	O/C	TSN:5852 TSN:3407			23-AUG-2002 5852 3407			
726410-001	DRIVE:NO. 1 ENGINE - POWER TAKE OFF ASSEMBLY DRIVE 6037T72G11 AGRA8229 REF:	MOS HRS/MSC ENC	O/C	TSO:0TSN:5852 TSN:3407 TSO:0			23-AUG-2002 5852 3407			
ENGINE NO. 2 Model : CF-34 (CIMMS) Serial # 350-498 Part # 6063T01G04										
72-00-00-201 (s)	NO. 2 ENGINE - VISUAL CHECK GENERAL - ENGINE FAN STATOR (1) FLOWPATH ALUMINUM SKIN FOR DENTS AND CRACKS. (2) ABRADABLE RUB STRIP FOR RUBBING.(REF. G.E. MM SEI-580, SECTION 5-21-00) PKG 2 REF:	MOS HRS/MSC ENC	300				09-SEP-2008 8632.5			PKG

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
72-00-00-203 (s)	NO. 2 ENGINE - VISUAL CHECK (1) ENGINE MOUNTS. (2) FAN ROTOR. (3) FAN STATOR. (4) COMPRESSOR CASE. (5) FRONT FRAME, PAYING PARTICULAR ATTENTION AROUND AGB MOUNT PADS. (6) ACCESSORY GEARBOX. (FOR ALL 6 ITEMS, REFER TO GE MM SEI-580, SECTION 5-21-00)	ENGINE - GENERAL					PKG			
	PKG 2	MOS					09-SEP-2008			
	REF:	HRS/MSC	300				8632.5			
		ENC								
72-00-00-207 (s)	NO. 2 ENGINE - VISUAL CHECK BRACKETS,ELECTRICAL CONNECTORS,ENGINE SURFACE AND ACCESSORIES.(REF. G.E. MM SEI-580, SECTION 5-21-00)	GENERAL -ENGINE EXTERNAL LINES,PORTS,FLANGES,CLAMPS,					PKG			
	PKG 2	MOS					09-SEP-2008			
	REF:	HRS/MSC	300				8632.5			
		ENC								
72-00-00-208 (s)	NO. 2 ENGINE - VISUAL CHECK PAYING PARTICULAR ATTENTION FOR CRACKS,BULGES,HOT SPOTS AND SECURITY OF CENTRE BODY.(REF. G.E. MM SEI-580, SECTION 5-21-00)	GENERAL -ENGINE - HIGH PRESSURE TURBINE SECTION CASING,					PKG			
	PKG 2	MOS					09-SEP-2008			
	REF:	HRS/MSC	300				8632.5			
		ENC								
72-00-00-209 (s)	NO. 2 ENGINE - VISUAL CHECK (1) COMPRESSOR ASSEMBLY FOR MISSING LOCK TABS ON VISIBLE VARIABLE VANE OUTER SHANKNUTS.(REF. G.E. MM SEI-580, SECTION 5-21-00) (2) FAN ROTOR BLADE REMOVAL PORT, WATER DRAIN FOR BLOCKAGE.(REF. G.E. MM SEI-580, SECTION 5-21-00)	GENERAL - ENGINE CARRY OUT A VISUAL CHECK OF THE FOLLOWING:					PKG			
	PKG 3	MOS					20-MAR-2009			
	REF:	HRS/MSC	600				8699.7			
		ENC								
+ 72-00-00-210 (s)	NO. 2 ENGINE - ENGINE (A) BORESCOPE INSPECTION OF COMBUSTION LINER. (B) VISUAL CHECK FOR CRACKS IN COMBUSTION CHAMBER FRAME. (C) BORESCOPE INSPECTION OF FUEL INJECTORS, PAYING PARTICULAR ATTENTION TO CENTERING IN SWIRLERS. (REF. G.E. MM SEI-580, SECTION 5-21-00) (D) BORESCOPE INSPECTION OF OUTER TRANSITION LINER - THIS INSPECTION (D) APPLIES TO ENGINES 350485 AND BELOW AS INSTRUCTED IN G.E. SB 72-32 THAT HAVE NOT BEEN MODIFIED TO SB 72-38.	(A) BORESCOPE INSPECTION OF COMBUSTION LINER.					PKG			
	PKG 4	MOS					04-AUG-2005			
	REF: See Workcard	HRS/MSC	1200				8042.8			
		ENC								

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 72-00-00-211 (s)	NO. 2 ENGINE - BORESCOPE INSPECTION TURBINE SECTION, STAGE 1 NOZZLE AND HPT STAGE 1 BLADES (REF. G.E. MM SEI-580, SECTION 5-21-00)						PKG			
	PKG 4	MOS					04-AUG-2005			
	REF: See Workcard	HRS/MSC	1200				8042.8			
		ENC								
+ 72-00-00-212	NO. 2 ENGINE - BORESCOPE INSPECTION GENERAL - ENGINE - POWER TAKE-OFF (PTO) PART NUMBER 6037T72G01 OR 6037T72G06 FOR FORWARD MOVEMENT OF CARBON SLEEVE. (PRE G.E. SB(CF34)72-11) (REF. G.E. MM SEI-580, SECTION 5-21-00)									
		MOS					23-AUG-2002			
	REF: EMM 72-00-00	HRS/MSC	O/C				5852			
		ENC								
72-00-00-213	NO. 2 ENGINE - MIDPOINT INSPECTION GENERAL - ENGINE (REF. G.E. MM SEI-580, SECTION 5-21-00)									
		MOS					04-AUG-2005			
	REF: EMM 05-21-00	HRS/MSC	3000				8042.8	(11042.8)		2268.8
		ENC						11216.6		
72-00-00-215	NO. 2 ENGINE - BORESCOPE COMPRESSOR AND VISUAL CHECK OF VISIBLE AREAS OF COMPRESSOR CASINGS, VISUAL CHECK OF VARIABLE VANES, PAYING ATTENTION FOR NICKS,DENTS,CRACKS AND EXCESSIVE MOVEMENT. (REF. G.E. MM SEI-580, SECTION 5-21-00)									
		MOS					04-AUG-2005			
	REF:	HRS/MSC	3000				8042.8	(11042.8)		2268.8
		ENC						11216.6		
72-00-00-217	NO. 2 ENGINE - DETAILED INSPECTION OF ENGINE ACCESSORY GEARBOX MOUNTS (REF. G.E. MM SEI-580, SECTION 5-21-00)									
		MOS					04-AUG-2005			
	REF:	HRS/MSC	3000				8042.8	(11042.8)		2268.8
		ENC						11216.6		
+ 72-00-00-218A	NO. 2 ENGINE - OVERHAUL ENGINE									OVERHAUL
		MOS					23-AUG-2002			
	REF:	HRS/MSC	6000				5852	(11852)	12025.8	3078
		ENC								
+ 72-00-00-218B	NO. 2 ENGINE - BOROSCOPE ENGINE (IF REQUIRED)									
		MOS	120				04-AUG-2005	04-AUG-2015		1792 d
	REF:	HRS/MSC	3000				8042.8	(11042.8)		2268.8
		ENC						11216.6		

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 72-00-00-219	NO. 2 ENGINE - CHECK GENERAL -ENGINE - OIL SAMPLE (REF. G.E. MM SEI-580, SECTION 5-21-00) PKG 3 REF: EMM 72-00-00	MOS HRS/MSC ENC	600				20-MAR-2009 8699.7	(9299.7) 9473.5		525.7
72-00-00-221	NO. 2 ENGINE - VISUAL CHECK GENERAL- ENGINE - 6 O'CLOCK C-SUMP SCAVENGE TUBE AND GROOVE FOR INTERNAL COKING.(REF. G.E. MM SEI-580, SECTION 5-21-00) REF:	MOS HRS/MSC ENC	3000				04-AUG-2005 8042.8	(11042.8) 11216.6		2268.8
72-00-00-222	NO. 2 ENGINE - VISUAL CHECK GENERAL - ENGINE - LPT STATOR ASSEMBLY P/N 6020T15G14 FOR TACK WELDING OF THE PIN AND CLIP ASSEMBLIES. REWORK AND RE-IDENTIFY IF REQUIRED.(REF. G.E. MM SEI-580, SECTION 5-21-00) REF:	MOS HRS/MSC ENC	3000				04-AUG-2005 8042.8	(11042.8) 11216.6	11082.8	2268.8
72-00-00-223	NO. 2 ENGINE - VISUAL CHECK GENERAL - ENGINE - HPT STAGE 1 AND STAGE 2 SHROUDS (REF. G.E. MM SEI-580, SECTION 5-21-00) REF:	MOS HRS/MSC ENC	3000				04-AUG-2005 8042.8	(11042.8) 11216.6		2268.8
72-00-00-224	NO. 2 ENGINE - INSPECT/CHECK TURBINE THERMOCOUPLE HARNESS (REF. G.E. MM SEI-580, SECTION 5-21-00) REF:	MOS HRS/MSC ENC	3000				04-AUG-2005 8042.8	(11042.8) 11216.6		2268.8
72-00-00-225	NO. 2 ENGINE - VISUAL CHECK TURBINE NOZZLES (REF. G.E. MM SEI-580, SECTION 5-21-00) REF:	MOS HRS/MSC ENC	3000				04-AUG-2005 8042.8	(11042.8) 11216.6		2268.8
72-00-00-226	NO. 2 ENGINE - DETAILED VISUAL INSPECTION SWIRLERS AFTER REMOVAL OF THE INJECTORS (REF. G.E. MM SEI-580, SECTION 5-21-00) REF:	MOS HRS/MSC ENC	3000				04-AUG-2005 8042.8	(11042.8) 11216.6		2268.8
72-00-00-227	NO. 2 ENGINE - VISUAL CHECK PRIMARY SWIRLERS, PAYING PARTICULAR ATTENTION FOR WEAR (REF. G.E. MM SEI-580, SECTION 5-21-00) REF:	MOS HRS/MSC ENC	3000				04-AUG-2005 8042.8	(11042.8) 11216.6		2268.8

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
72-00-00-228	NO. 2 ENGINE - VISUAL CHECK STAGE 1 AND STAGE 2 NOZZLE ASSEMBLIES. (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS					04-AUG-2005 8042.8	(11042.8) 11216.6		2268.8
	REF:	HRS/MSC ENC	3000							
72-00-00-229	NO. 2 ENGINE - VISUAL CHECK COMBUSTION LINER AFTER DISASSEMBLY (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS					04-AUG-2005 8042.8	(11042.8) 11216.6		2268.8
	REF:	HRS/MSC ENC	3000							
72-00-00-230	NO. 2 ENGINE - CHECK COMBUSTION SECTION FUEL INJECTOR HEAT SHIELDS FOR LOOSENESS. (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS					04-AUG-2005 8042.8	(11042.8) 11216.6		2268.8
	REF:	HRS/MSC ENC	3000							
72-00-00-231	NO. 2 ENGINE - VISUAL CHECK FAN DISK TO ENSURE BUSHINGS ARE NOT PROTRUDING. (REF. G.E. MM SEI-580, SECTION 5-21-00)	MOS					04-AUG-2005 8042.8	(11042.8) 11216.6		2268.8
	REF:	HRS/MSC ENC	3000							
+ 72-00-00-301 (s)	NO. 2 ENGINE - COMPRESSOR WASH GENERAL - ENGINE						PKG 09-SEP-2008 8632.5			
	PKG 2	MOS								
	REF: EMM 72-00-00	HRS/MSC ENC	300							
+ 72-00-00-302 (s)	NO. 2 ENGINE - POWER ASSURANCE CHECK ENGINE - GENERAL (ENGINE MODEL CF34-1A/-3A/-3A2 ONLY)						PKG 09-SEP-2008 8632.5			
	PKG 2	MOS								
	REF: EMM 72-00-00	HRS/MSC ENC	300							
720110	NO. 2 ENGINE - REPLACE NO.5 BEARING CARBON SEAL PREFORMED PACKING						04-AUG-2005 8042.8	(11042.8) 11216.6		LIFE LIMIT 2268.8
	REF:	MOS HRS/MSC ENC	3000							
722150-001	DISC:NO. 2 ENGINE - FAN DISC						28-AUG-2002 5852			LIFE LIMIT
	6078T57G03	MOS								
	GAT7551M	HRS/MSC			TSN:0					
	REF:	ENC	9000		TSN:0		3407	12407		7974

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
722151-001	SHAFT:NO. 2 ENGINE - FAN DRIVE SHAFT 6036T78P02 REA1795H REF:	MOS HRS/MSC ENC	15000	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	15000	10567	LIFE LIMIT
722152-001	SHAFT:NO. 2 ENGINE - FAN FORWARD SHAFT 6078T51P01 GAT1029M REF:	MOS HRS/MSC ENC	15000	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	15000	10567	LIFE LIMIT
722210-001	SHAFT:NO. 2 ENGINE - COMPRESSOR ROTOR REAR SHAFT 6087T03P03 GWN056J2 REF:	MOS HRS/MSC ENC	23000	TSN:0 TSN:0			28-AUG-2002 5852 3407	26407	21974	LIFE LIMIT
723120-001	SENSOR:NO. 2 ENGINE - FAN SPEED SENSOR 4021T56P03 GDB41589 REF: EMM 74-00-00	MOS HRS/MSC ENC	O/C	TSO:0TSN:5832.1 TSO:0TSN:5367			28-AUG-2002 5852 3407			
723318-001	SHAFT:NO. 2 ENGINE - COMPRESSOR ROTOR FWD SHAFT 5037T01P03 GAT2259M REF:	MOS HRS/MSC ENC	11740	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	11740	7307	LIFE LIMIT
723320-001	DISC:NO. 2 ENGINE - STAGE 1 COMPRESSOR ROTOR DISC 6087T00G02 GATH6GGL REF:	MOS HRS/MSC ENC	15000	TSN:0 TSN:0			28-AUG-2002 5852 3407	18407	13974	LIFE LIMIT
723322-001	DISC:NO. 2 ENGINE - STAGE 2 COMPRESSOR ROTOR DISC 6036T91P01 GAT2283M REF:	MOS HRS/MSC ENC	15000	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	15000	10567	LIFE LIMIT
723326-001	SEAL:NO. 2 ENGINE - CDP SEAL 4019T38P01 PAML9654 REF:	MOS HRS/MSC ENC	14400	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	14400	9967	LIFE LIMIT

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
723328-001	SPOOL:NO. 2 ENGINE - 3 - 8 STAGE COMPRESSOR ROTOR SPOOL 6078T56P04 GWN04FRP REF:	MOS HRS/MSC ENC	27000	TSN:0 TSN:0			28-AUG-2002 5852 3407	30407		LIFE LIMIT 25974
723330-001	SPOOL:NO. 2 ENGINE - 10 - 14 STAGE COMPRESSOR ROTOR SPOOL 5087T46P02 GWN041JW REF:	MOS HRS/MSC ENC	17000	TSN:0 TSN:0			28-AUG-2002 5852 3407	20407		LIFE LIMIT 15974
723351-001	DISC:NO. 2 ENGINE - STAGE 9 COMPRESSOR ROTOR DISC 6016T43P03 HAAK0087 REF:	MOS HRS/MSC ENC	6000	TSN:0 TSN:0			28-AUG-2002 5852 3407	9407		LIFE LIMIT 4974
724220-001	LINER:NO. 2 ENGINE - ENGINE COMBUSTION LINER 6063T15G01 GGMUE718 REF:	MOS HRS/MSC ENC	O/C	TSN:4626.3			28-AUG-2002 5852			
724611-001	DISC:NO. 2 ENGINE - STAGE 1 TURBINE DISC 6031T89P03 GAT7648L REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	6000		LIFE LIMIT 1567
724612-001	DISC:NO. 2 ENGINE - STAGE 2 TURBINE DISC 6031T90P03 GAT0800M REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	6000		LIFE LIMIT 1567
724620-001	SHAFT:NO. 2 ENGINE - HPT SHAFT 6017T00P05 GAT4657M REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	6000		LIFE LIMIT 1567
724628-001	SEAL:NO. 2 ENGINE - BALANCE PISTON ROTATING AIR SEAL 5025T33P06 GAT2234M REF:	MOS HRS/MSC ENC	7200	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	7200		LIFE LIMIT 2767

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
724628-002	SEAL:NO. 2 ENGINE - BALANCE PISTON STATIONARY AIR SEAL PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			
724630-001	PLATE:NO. 2 ENGINE - STAGE 1 FRONT COOLING PLATE 4027T15P03 GAT7877D REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	6000	1567	LIFE LIMIT
724632-001	PLATE:NO. 2 ENGINE - STAGE 1 COOLING AFT PLATE 5041T70P03 GAT0998J REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	6000	1567	LIFE LIMIT
724636-001	COUPLING:NO. 2 ENGINE - TORQUE INNER COUPLING 5041T66P02 GAT3842L REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	6000	1567	LIFE LIMIT
724638-001	COUPLING:NO. 2 ENGINE - TORQUE OUTER COUPLING 5041T67P02 GAT2921M REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	6000	1567	LIFE LIMIT
724640-001	PLATE:NO. 2 ENGINE - STAGE 2 FWD COOLING PLATE 5042T29P02 GAT4188H REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	6000	1567	LIFE LIMIT
724642-001	PLATE:NO. 2 ENGINE - STAGE 2 AFT COOLING PLATE 5023T97P03 GAT4093H REF:	MOS HRS/MSC ENC	6000	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	6000	1567	LIFE LIMIT
725011-001	STUD:NO. 2 ENGINE - HPT STG 2 STUD PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	6000	TSN:0			23-AUG-2002 5852 3407	(11852) 12025.8	11852	3078

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
725120	NO. 2 ENGINE - REPLACE HIGH PRESSURE TURBINE STAGE 2 NOZZLE RETAINING RING SECTOR									LIFE LIMIT
		MOS					04-AUG-2005			
		HRS/MSC	3000				8042.8	(11042.8)		2268.8
	REF:	ENC						11216.6		
725220-001	THERMOCOUPLE:NO. 2 ENGINE - LEFT ASSEMBLY THERMOCOUPLE									
	6030T41P01	MOS					28-AUG-2002			
	GDB09020	HRS/MSC	O/C	TSN:5852 TSO:0			5852			
	REF:	ENC		TSO:0TSN:3407			3407			
725220-002	THERMOCOUPLE:NO. 2 ENGINE - RIGHT ASSEMBLY THERMOCOUPLE									
	6030T40P01	MOS					28-AUG-2002			
	GDB09309	HRS/MSC	O/C	TSO:0TSN:5852			5852			
	REF:	ENC		TSN:3407 TSO:0			3407			
725236-001	BLADE:NO. 2 ENGINE - TURBINE STAGE 1 BLADE									
	6078T19P02	MOS					28-AUG-2002			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:5852 TSO:0			5852			
	REF:	ENC		TSN:3407 TSO:0			3407			
725314-001	SHAFT:NO. 2 ENGINE - LOW PRESSURE TURBINE REAR SHAFT									LIFE LIMIT
	6030T72P02	MOS					28-AUG-2002			
	GAT2168L	HRS/MSC		TSN:5852			5852			
	REF:	ENC	39000	TSN:3407			3407	39000		34567
725323-001	DISC:NO. 2 ENGINE - STAGE 3 TURBINE DISC									LIFE LIMIT
	5026T16P02	MOS					28-AUG-2002			
	GAT7645L	HRS/MSC		TSN:5852			5852			
	REF:	ENC	6000	TSN:3407			3407	6000		1567
725324-001	DISC:NO. 2 ENGINE - STAGE 4 TURBINE DISC									LIFE LIMIT
	6078T02P01	MOS					28-AUG-2002			
	GAT7462L	HRS/MSC		TSN:5852			5852			
	REF:	ENC	15000	TSN:3407			3407	15000		10567
725325-001	DISC:NO. 2 ENGINE - STAGE 5 TURBINE DISC									LIFE LIMIT
	5024T53P02	MOS					28-AUG-2002			
	GAT6419L	HRS/MSC		TSN:5852			5852			
	REF:	ENC	6000	TSN:3407			3407	6000		1567

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
725326-001	DISC:NO. 2 ENGINE - STAGE 6 TURBINE DISC 6078T89P01 GAT8003L REF:	MOS HRS/MSC ENC	15000	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	15000	10567	LIFE LIMIT
725330-001	SEAL:NO. 2 ENGINE - 3 - 4 STAGE TURBINE SEAL 5023T59P02 PAMM6021 REF:	MOS HRS/MSC ENC	29730	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	29730	25297	LIFE LIMIT
725332-001	SEAL:NO. 2 ENGINE - 4 - 5 STAGE TURBINE SEAL 5023T67P01 PAMM5770 REF:	MOS HRS/MSC ENC	29730	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	29730	25297	LIFE LIMIT
725334-001	SEAL:NO. 2 ENGINE - 5 - 6 STAGE TURBINE SEAL 5023T64P02 PAMM6294 REF:	MOS HRS/MSC ENC	29730	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	29730	25297	LIFE LIMIT
725338-001	CONE:NO. 2 ENGINE - TURBINE DRIVE CONE 5023T40P01 GAT0048K REF:	MOS HRS/MSC ENC	15000	TSN:5852 TSN:3407			28-AUG-2002 5852 3407	15000	10567	LIFE LIMIT
726210-001	GEARBOX:NO. 2 ENGINE - ACCESSORY GEARBOX 6014T81G20 WIA96832 REF: EMM 72-60-00	MOS HRS/MSC ENC	O/C	TSN:5852 TSO:0 TSO:0TSN:3407			28-AUG-2002 5852 3407			
726410-001	DRIVE:NO. 2 ENGINE - POWER TAKE OFF ASSEMBLY DRIVE 6037T72G11 AGRA8213 REF:	MOS HRS/MSC ENC	O/C	TSN:5852 TSO:0 TSO:0TSN:3407			28-AUG-2002 5852 3407			
729111	SEAL:NO. 2 ENGINE - NO. 3 CARBON SEAL 5022T04P03 STA0156L REF:	MOS HRS/MSC ENC	O/C				06-JAN-2001 4781.8 2469			

CHAPTER 73 ENGINE FUEL AND CONTROL

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
732000-001	AMPLIFIER:NO. 1 CONTROLLER AMPLIFIER 4074T27G03 ECDK1068 REF: AMM 732000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			
732000-002	AMPLIFIER:NO. 2 CONTROLLER AMPLIFIER 4074T27G03 ECDK1079 REF: AMM 732000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			
733011	INDICATOR:FUEL FLOW INDICATOR 601-50914-3 527 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
733100-001	FLOWMETER:NO. 1 FUEL FLOWMETER 9-127-58 6154 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
733100-002	FLOWMETER:NO. 2 FUEL FLOWMETER 9-127-58 6151 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
733300-001	BULB:NO. 1 TEMPERATURE BULB MS28034-3 SN-UNKNOWN REF: AMM 733311	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
733300-002	BULB:NO. 2 TEMPERATURE BULB MS28034-3 SN-UNKNOWN REF: AMM 733311	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
733301-001	INDICATOR:FUEL TEMPERATURE INDICATOR 600-50919-11 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
733500-001	SWITCH:NO. 1 LOW FUEL PRESSURE WARNING SWITCH 601-62904-1 0294 REF: AMM 733511	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-APR-1999 3631 1866			
733500-002	SWITCH:NO. 2 LOW FUEL PRESSURE WARNING SWITCH 601-62904-1 SN-UNKNOWN REF: AMM 733511	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
73R001	DISTRIBUTOR:FUEL L ENG DISTRIBUTOR 6021T93G05 APM1022N REF:	MOS HRS/MSC AFL	N/R	TSN:1505 TSN:1270		11/17/1995 1526	17-MAY-1995 1226 595			
73R002	DISTRIBUTOR:FUEL R ENG DISTRIBUTOR 6021T93G05 APM1027N REF:	MOS HRS/MSC AFL	N/R	TSN:1547 TSN:1251		11/17/1995 1526	17-MAY-1995 1226 595			
73R003	--:DISTR. BLOCK, FUEL L ENG. 5047T20G01 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			
73R004	--:DIST. BLOCK, FUEL R ENG. 5047T20G01 ELB0681L REF:	MOS HRS/MSC AFL	N/R			11/22/1995 1526	22-MAY-1995 1226 595			
73R005	FUEL INJECTORS, LEFT ENG. REF:	MOS HRS/MSC AFL	N/R				22-MAY-1995 1226 595			
73R006	FUEL INJECTORS, RIGHT ENG. REF:	MOS HRS/MSC AFL	N/R				22-MAY-1995 1226 595			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
73R007	HOSE:LH #2 FUEL INJECTOR HOSE 5085T32P01 NSN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			02-APR-1997 2415 1208			
73R008	HOSE:LH #3 FUEL INJECTOR HOSE 5085T32P02 NSN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			02-APR-1997 2415 1208			
73R009	HOSE:RH #3 FUEL INJECTOR HOSE 5085T32P02 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			02-APR-1997 2415 1208			

ENGINE NO. 1 Model : CF-34 (CIMMS) Serial # 350-499 Part # 6063T01G04

73-10-11-204	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE FUEL PUMP ASSEMBLY (REF. G.E. MM SEI-580, SECTION 5-21-00) REF:	MOS HRS/MSC ENC	3000	TSI:0			29-AUG-2002 5852 3407	(8852) 8989.9		42.1
73-10-16-208 (s)	NO. 1 ENGINE - INSPECT FUEL HEATER ASSEMBLY CHECK FOR EVIDENCE OF LEAKAGE FROM FUEL HEATER.(REF. G.E. MM SEI-580, SECTION 5-21-00) PKG 2 REF:	MOS HRS/MSC ENC	300				09-SEP-2008 8668.5			
73-10-21-202 (s)	NO. 1 ENGINE - FUEL FILTER ASSEMBLY CHECK BYPASS INDICATOR AND CARRY OUT A VISUAL CHECK OF MOUNTING BRACKET PKG 2 REF:	MOS HRS/MSC ENC	300				09-SEP-2008 8668.5			
73-10-21-203 (s)	NO. 1 ENGINE - INSPECT FUEL FILTER ASSEMBLY CHECK FUEL FILTER ELEMENT PKG 3 REF: EMM 73-00-00	MOS HRS/MSC ENC	600				20-MAR-2009 8735.6			
73-20-11-206	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF MAIN FUEL CONTROL ASSEMBLY - FUEL CONTROL UNIT (REF. G.E. MM SEI-580, SECTION 5-21-00) REF:	MOS HRS/MSC ENC	3000	TSI:0			29-AUG-2002 5852 3407	(8852) 8989.9		42.1

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
73-20-16-210 (s)	NO. 1 ENGINE - VISUAL CHECK SECTION 5-21-00)	N1 SPEED CONTROL AMPLIFIER CONTROL AMPLIFIER (REF. G.E. MM SEI-580,					PKG			
	PKG 2	MOS								
	REF:	HRS/MSC 300					09-SEP-2008			
		ENC					8668.5			
730006-001	SENSOR:NO. 1 ENGINE - COMPRESSOR INLET TEMPERATURE SENSOR									
	4071T72P01	MOS								
	WYG72681	HRS/MSC	O/C	TSO:0TSN:5852						
	REF: EMM 73-00-00	ENC		TSO:0TSN:3407			23-AUG-2002			
							5852			
							3407			
730010-001	HEATER:NO. 1 ENGINE - FUEL HEATER									
	5023T57P02	MOS								
	JADA7995	HRS/MSC	O/C	TSO:0TSN:5852						
	REF: EMM 73-00-00	ENC		TSO:0TSN:3407			23-AUG-2002			
							5852			
							3407			
731011-001	CONTROL:NO. 1 ENGINE - MFC - MAIN FUEL CONTROL									
	6091T07P03	MOS								
	WYG49739	HRS/MSC	O/C	TSN:6195.5 TSO:0						
	REF: EMM 73-00-00	ENC		TSN:3930 TSO:0			23-AUG-2002			
							5852			
							3407			
731014-001	PUMP:NO. 1 ENGINE - FUEL PUMP									
	6052T06P05	MOS								
	CGWE0073	HRS/MSC	O/C	TSO:0TSN:5681.4						
	REF: EMM 73-00-00	ENC		TSN:3991 TSO:0			23-AUG-2002			
							5852			
							3407			
ENGINE NO. 2 Model : CF-34 (CIMMS) Serial # 350-498 Part # 6063T01G04										
73-10-11-204	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE FUEL PUMP ASSEMBLY (REF. G.E. MM SEI-580, SECTION 5-21-00)									
		MOS								
	REF:	HRS/MSC 3000					04-AUG-2005			
		ENC					8042.8	(11042.8)		2268.8
								11216.6		
73-10-16-208 (s)	NO. 2 ENGINE - INSPECT FUEL HEATER ASSEMBLY CHECK FOR EVIDENCE OF LEAKAGE FROM FUEL HEATER.(REF. G.E. MM SEI-580, SECTION 5-21-00)						PKG			
	PKG 2	MOS								
	REF:	HRS/MSC 300					09-SEP-2008			
		ENC					8632.5			
73-10-21-202 (s)	NO. 2 ENGINE - FUEL FILTER ASSEMBLY CHECK BYPASS INDICATOR AND CARRY OUT A VISUAL CHECK OF MOUNTING BRACKET						PKG			
	PKG 2	MOS								
	REF:	HRS/MSC 300					09-SEP-2008			
		ENC					8632.5			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
73-10-21-203 (s)	NO. 2 ENGINE - INSPECT FUEL FILTER ASSEMBLY CHECK FUEL FILTER ELEMENT PKG 3 REF: EMM 73-00-00	MOS HRS/MSC ENC	600				PKG 20-MAR-2009 8699.7			
73-20-11-206	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF MAIN FUEL CONTROL ASSEMBLY - FUEL CONTROL UNIT (REF. G.E. MM SEI-580, SECTION 5-21-00) REF:	MOS HRS/MSC ENC	3000				04-AUG-2005 8042.8	(11042.8) 11216.6		2268.8
73-20-16-210 (s)	NO. 2 ENGINE - VISUAL CHECK N1 SPEED CONTROL AMPLIFIER CONTROL AMPLIFIER (REF. G.E. MM SEI-580, SECTION 5-21-00) PKG 2 REF:	MOS HRS/MSC ENC	300				PKG 09-SEP-2008 8632.5			
730006-001	SENSOR:NO. 2 ENGINE - COMPRESSOR INLET TEMPERATURE SENSOR 4071T72P01 WYG91845 REF: EMM 73-00-00	MOS HRS/MSC ENC	O/C	TSO:0TSN:5852 TSN:3407 TSO:0			28-AUG-2002 5852 3407			
730010-001	HEATER:NO. 2 ENGINE - FUEL HEATER 5023T57P02 JADA8205 REF: EMM 73-00-00	MOS HRS/MSC ENC	O/C	TSN:5852 TSO:0 TSN:3407 TSO:0			28-AUG-2002 5852 3407			
731011-001	CONTROL:NO. 2 ENGINE - MFC - MAIN FUEL CONTROL 6047T07P03 WYG59237 REF: EMM 73-00-00	MOS HRS/MSC ENC	O/C	TSO:0TSN:6173.7 TSO:0TSN:3980			28-AUG-2002 5852 3407			
731014-001	PUMP:NO. 2 ENGINE - FUEL PUMP 6052T06P05 CGWE0306 REF: EMM 73-00-00	MOS HRS/MSC ENC	O/C	TSN:5688.9 TSO:0 TSN:3980 TSO:0			28-AUG-2002 5852 3407			
CHAPTER 74 IGNITION										
74-00-00-204 (s)	OPERATIONAL TEST IGNITION SYSTEM PKG 3 REF: AMM 74-00-00-204	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
740001	TRANSMITTER:LEFT ENGINE FAN INLET TEMPERATURE TRANSMITTER 4033T65P03 EGNC5022 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			
740006	TRANSMITTER:RIGHT ENGINE FAN INLET TEMPERATURE TRANSMITTER 4033T65P03 EGNC5017 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			
741000-001	INVERTER:RUDDER STATIC IGNITION INVERTER ASH671-2 DM969 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			11-JAN-2005 7859 3818			
74R001	LEAD:L ENG 10 O'C IGNITOR LEAD 4096T96P04 UNN648AJ REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0		2226	17-MAY-1995 1226 595			
74R006	LEAD:R ENG 10 O'C IGNITOR LEAD 4096T96P04 UNN655AJ REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0		2226	17-MAY-1995 1226 595			
74R011	LEAD:L ENG 2 O'C IGNITOR LEAD 4096T96P03 UNN723AA REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0		2226	17-MAY-1995 1226 595			
74R016	LEAD:R ENG 2 O'C IGNITOR LEAD 4096T96P03 UNN752AA REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0		2226	17-MAY-1995 1226 595			

ENGINE NO. 1 Model : CF-34 (CIMMS) Serial # 350-499 Part # 6063T01G04

74-10-11-203 (s)	NO. 1 ENGINE - VISUAL CHECK IGNITION EXCITER (REF. G.E. MM SEI-580, SECTION 5-21-00)						PKG			
	PKG 2	MOS					09-SEP-2008			
	REF:	HRS/MSC ENC	300				8668.5			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
74-10-16-211 (s)	NO. 1 ENGINE - INSPECT PKG 4 REF: EMM 74-00-00	IGNITER PLUG (REF. G.E. MM SEI-580, SECTION 5-21-00)					PKG 07-JUN-2005 8043			
740020	EXCITER:NO. 1 ENGINE - UPPER IGNITION EXCITER 9238M66P08 UNNDA728 REF:	MOS HRS/MSC ENC	1200 O/C	TSI:0 TSN:4262.3 TSO:0 TSN:2729 TSO:0			23-AUG-2002 5852 3407			
741024-001	EXCITER:NO. 1 ENGINE - IGNITION EXCITER 5027T49P01 SN-UNKNOWN REF: EMM 74-00-00	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			
741024-002	EXCITER:NO. 1 ENGINE - IGNITION EXCITER 9238M66P08 UNNDA948 REF: EMM 74-00-00	MOS HRS/MSC ENC	O/C	TSO:0TSN:4626.3 TSN:2729 TSO:0			23-AUG-2002 5852 3407			
742000-001	IGNITER:NO. 1 ENGINE - IGNITER PLUG IGNITER 4096T38P10 UNJD9484 REF: EMM 74-00-00	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-AUG-2002 5852 3407			
742000-002	IGNITER:NO. 1 ENGINE - IGNITER PLUG IGNITER 4096T38P10 UNJD9503 REF: EMM 74-00-00	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-AUG-2002 5852 3407			
743014-001	SENSOR:NO. 1 ENGINE - FAN INLET TEMPERATURE SENSOR 4033T65P03 SN-UNKNOWN REF: EMM 74-00-00	MOS HRS/MSC ENC	O/C							
ENGINE NO. 2 Model : CF-34 (CIMMS) Serial # 350-498 Part # 6063T01G04										
74-10-11-203 (s)	NO. 2 ENGINE - VISUAL CHECK PKG 2 REF:	IGNITION EXCITER (REF. G.E. MM SEI-580, SECTION 5-21-00)					PKG 09-SEP-2008 8632.5			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
74-10-16-211 (s)	NO. 2 ENGINE - INSPECT PKG 4 REF: EMM 74-00-00	IGNITER PLUG (REF. G.E. MM SEI-580, SECTION 5-21-00) MOS HRS/MSC ENC	1200	TSI:0			PKG 07-JUN-2005 8043			
741024-001	EXCITER:NO. 2 ENGINE - IGNITION EXCITER 9238M66P08 UNNDB646 REF: EMM 74-00-00	MOS HRS/MSC ENC	O/C	TSN:4626.3 TSO:0 TSO:0TSN:2729			28-AUG-2002 5852 3407			
741024-002	EXCITER:NO. 2 ENGINE - IGNITION EXCITER 9238M66P08 UNNDB596 REF: EMM 74-00-00	MOS HRS/MSC ENC	O/C	TSN:4626.3 TSO:0 TSO:0TSN:2729			28-AUG-2002 5852 3407			
742000-001	IGNITER:NO. 2 ENGINE - IGNITER PLUG IGNITER 4096T38P10 UNJD9471 REF: EMM 74-00-00	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			28-AUG-2002 5852 3407			
742000-002	IGNITER:NO. 2 ENGINE - IGNITER PLUG IGNITER 4096T38P10 UNJD9478 REF: EMM 74-00-00	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			28-AUG-2002 5852 3407			
743014-001	SENSOR:NO. 2 ENGINE - FAN INLET TEMPERATURE SENSOR 4033T65P03 SN-UNKNOWN REF: EMM 74-00-00	MOS HRS/MSC ENC	O/C							
CHAPTER 75		AIR								
75R001	SEAL:CMB LNR INR AIR,L-EN SEAL 4922T81G01 NSN REF:	MOS HRS/MSC AFL	N/R	TSN:933		11/22/1995 1526	22-MAY-1995 1226 595			
75R002	SEAL:CMB LNR INR AIR,R-EN SEAL 4922T81G01 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:1505 TSN:1270		11/22/1995 1526	22-MAY-1995 1226 595			
ENGINE NO. 1 Model : CF-34 (CIMMS) Serial # 350-499 Part # 6063T01G04										

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
75-30-00-201 (s)	NO. 1 ENGINE - VISUAL CHECK VARIABLE GEOMETRY SYSTEM PAYING PARTICULAR ATTENTION TO ROD END BUSHINGS, ACTUATOR SHAFT BEARINGS, LEVER ARMS, FEEDBACK CABLE, ACTUATOR ATTACHMENT POINTS, TURNBUCKLES, ACTUATOR RING AND TORQUE SHAFT FORWARD BEARING FOR MIGRATION. LUBRICATE VG ROD END BEARINGS. (24 LOCATIONS) (REF. G.E. MM SEI-580, SECTION 5-21-00)						PKG			
	PKG 2	MOS						09-SEP-2008		
	REF:	HRS/MSC	300					8668.5		
		ENC								
750007-001	VALVE:NO. 1 ENGINE - B-SUMP VENT REGULATOR VALVE 5922T32G01	MOS						23-AUG-2002		
	SN-UNKNOWN	HRS/MSC	O/C	TSO:0				5852		
	REF: EMM 75-00-00	ENC		TSO:0				3407		
751003-001	ACTUATOR:NO. 1 ENGINE - VARIABLE GEOMETRY ACTUATOR 5050T37G02	MOS						23-AUG-2002		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				5852		
	REF:	ENC		TSN:0				3407		
751003-002	ACTUATOR:NO. 1 ENGINE - VARIABLE GEOMETRY ACTUATOR 5050T37G02	MOS						23-AUG-2002		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				5852		
	REF:	ENC		TSN:0				3407		
751020-001	VALVE:NO. 1 ENGINE - PRESSURE REGULATING VALVE 4020T35G04	MOS		TSN:0				01-OCT-1992		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF: EMM 75-00-00	ENC		TSN:0				0		
ENGINE NO. 2 Model : CF-34 (CIMMS) Serial # 350-498 Part # 6063T01G04										
75-30-00-201 (s)	NO. 2 ENGINE - VISUAL CHECK VARIABLE GEOMETRY SYSTEM PAYING PARTICULAR ATTENTION TO ROD END BUSHINGS, ACTUATOR SHAFT BEARINGS, LEVER ARMS, FEEDBACK CABLE, ACTUATOR ATTACHMENT POINTS, TURNBUCKLES, ACTUATOR RING AND TORQUE SHAFT FORWARD BEARING FOR MIGRATION. LUBRICATE VG ROD END BEARINGS. (24 LOCATIONS) (REF. G.E. MM SEI-580, SECTION 5-21-00)						PKG			
	PKG 2	MOS						09-SEP-2008		
	REF:	HRS/MSC	300					8632.5		
		ENC								
750007-001	VALVE:NO. 2 ENGINE - B-SUMP VENT REGULATOR VALVE 5922T32G01	MOS						28-AUG-2002		
	APM0467U	HRS/MSC	O/C					5852		
	REF: EMM 75-00-00	ENC						3407		

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
751003-001	ACTUATOR:NO. 2 ENGINE - VARIABLE GEOMETRY ACTUATOR 5050T37G02 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			28-AUG-2002 5852 3407			
751003-002	ACTUATOR:NO. 2 ENGINE - VARIABLE GEOMETRY ACTUATOR 5050T37G02 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C				28-AUG-2002 5852 3407			
751020-001	VALVE:NO. 2 ENGINE - PRESSURE REGULATING VALVE 4020T35G04 SN-UNKNOWN REF: EMM 75-00-00	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			
CHAPTER 76 ENGINE CONTROLS										
76-10-00-204	GENERAL VISUAL INSPECTION THROTTLE CONTROL - THROTTLE GEARBOX MOUNTING BRACKET - CONDITION AND SECURITY OF INSTALLATION REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				29-OCT-2003 7003 3486			
76-10-00-205	FUNCTIONAL TEST THROTTLE CONTROL - GEARBOX ASSEMBLY REF: AMM 76-10-00-205	MOS HRS/MSC AFL	N/A				01-OCT-1992 0 0			
761011-001	QUADRANT:ENGINE THROTTLE QUADRANT 600-90601-1035 186 REF: AMM 761011	MOS HRS/MSC AFL	O/C				23-JUN-1999 3693 1908			
761100-001	GEARBOX:NO. 1 THROTTLE CONTROL GEARBOX 2100140-007 663 REF: AMM 761021	MOS HRS/MSC AFL	O/C				30-MAR-1999 3617 1854			
761100-001A	FUNCTIONAL TEST OF THE ENGINE THROTTLE CONTROL GEARBOX ASSEMBLY , PART NO. 2100140-003 / -005 / -007 / -010. (76-10-00-101) REF: AMM 761000	MOS HRS/MSC AFL	1000				(EBT) 9470.67			522.87

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
761100-002	GEARBOX:NO. 2 THROTTLE CONTROL GEARBOX 2100140-XXX SN-UNKNOWN REF: AMM 761021	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			
761100-002A	FUNCTIONAL TEST OF THE ENGINE THROTTLE CONTROL GEARBOX ASSEMBLY , PART NO. 2100140-003 / -005 / -007/ -010 (76-10-00-101) REF: AMM 761000	MOS HRS/MSC AFL	1000				(EBT) 9470.67		522.87	CMR
769001	CABLE ASSEMBLY:NO. 1 ENGINE CONTROL CABLE ASSEMBLY 1603730-007 676 REF:	MOS HRS/MSC AFL	N/R	TSR:0 TSR:0 TSR:0			15-JUN-2005 8180 3964			
769006	CABLE ASSEMBLY:NO. 2 ENGINE CONTROL CABLE ASSEMBLY 1603730-005 705 REF:	MOS HRS/MSC AFL	N/R	TSO:0 TSO:0 TSO:0			25-APR-2003 6546 3288			
76R001	--:CONTROLEX,L THROTTLE PYLN PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
76R006	--:CONTROLEX,R THROTTLE PYLN PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			
CHAPTER 77 ENGINE INDICATING										
771000-001	INDICATOR:N1 FAN RPM INDICATOR 601-50911-3 708 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				10-FEB-1994 555 272			
771003-001	INDICATOR:DIGITAL BOARD N2 INDICATOR 418-098-120 1204 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-SEP-2007 8590 4155			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
771100-001	PANEL:ENGINE INSTRUMENT CONTROL PANEL 601-50920-1 SN-UNKNOWN REF: AMM 771100	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
772000-001	INDICATOR:ITT TURBINE INLET TEMPERATURE INDICATOR 601-50912-5 689 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
773000-001	INDICATOR:ENGINE VIBRATION INDICATOR 124-497-2 94040060 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			11/12/2002	12-NOV-2001 5337 2743			
773010-001	CONDITIONER:ENGINE VIBRATION SIGNAL CONDITIONER 601-50910-13 059242 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
773011-001	ACCELEROMETER:NO. 1 ENGINE VIBRATION ACCELEROMETER 600-59131-1 BB71 REF: AMM 773011	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
773011-002	ACCELEROMETER:NO. 2 ENGINE VIBRATION ACCELEROMETER 600-59131-1 BB73 REF: AMM 773011	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
77R001	CONVERTER:SIGNAL DATA CONVERTER 601-50917-3 684 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0			01-OCT-1992 0 0			

ENGINE NO. 1 Model : CF-34 (CIMMS) Serial # 350-499 Part # 6063T01G04

771014-001	AMPLIFIER:NO. 1 ENGINE - ENGINE APR CONTROL AMPLIFIER 4074T27G01 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C							
------------	---	-----------------------	-----	--	--	--	--	--	--	--

ENGINE NO. 2 Model : CF-34 (CIMMS) Serial # 350-498 Part # 6063T01G04

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
771014-001	AMPLIFIER:NO. 2 ENGINE - ENGINE APR CONTROL AMPLIFIER 4074T27G01 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C							
CHAPTER 78 EXHAUST										
78-10-00-211 (s)	VISUAL CHECK EXHAUST NOZZLE ASSEMBLY - REMOVE EXHAUST NOZZLE FAIRING AND CARRY OUT A VISUAL CHECK OF FAIRING, NOZZLE, STIFFENERS, ATTACHMENT LINKS AND BRACKETS. REINSTALL FAIRING. PKG 4 REF: AMM 78-10-00-211	MOS HRS/MSC AFL	1200				09-JUN-2005 8180 3964			
78-10-00-219	GENERAL VISUAL INSPECTION EXHAUST NOZZLE ASSEMBLY FOR CRACKS, HOT SPOTS OR DISTORTION REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				01-OCT-1992 0 0			
78-10-00-232	GENERAL VISUAL INSPECTION EXHAUST NOZZLE - FAIRING ACCESS PANELS - CONDITION AND SECURITY OF INSTALLATION REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				29-OCT-2003 7003 3486			
+ 78-30-00-101	NDT CHECK THRUST REVERSER - MAIN TRACK AFT LUGS REF: NDT ET-78-30-01	MOS HRS/MSC AFL	1800				29-JUN-2004 7576 3705	9376		428.2
+ 78-30-00-102	NDT CHECK THRUST REVERSER, MAIN UPPER & LOWER PYLON TRACKS REF: NDT ET-78-30-02	MOS HRS/MSC AFL	4800	TSI:59			28-FEB-2001 4859 2516	9600		652.2
+ 78-30-00-103	NDT CHECK THRUST REVERSER - MAIN TRACK ATTACHMENT FITTING REF: See Workcard	MOS HRS/MSC AFL	5400	TSI:59			28-FEB-2001 4859 2516	10200		1252.2
+ 78-30-00-104	NDT CHECK THRUST REVERSER - MAIN TRACKS LOWER FLANGE REF: NDT ET-78-30-03	MOS HRS/MSC AFL	6600				18-JUN-2002 5849 2988	12449		3501.2

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
+ 78-30-00-105	NDT CHECK THRUST REVERSER, SERVICE PYLON SUPPORT RAIL	MOS					03-NOV-2003			
	REF: NDT ET-78-30-04	HRS/MSC AFL	7200				7003 3486	14203		5255.2
+ 78-30-00-106	VISUAL CHECK SERVICE PYLON-UPPER/LOWER PYLO TRACK SUPPORT BED	MOS								
	REF: NDT VC-78-30-01	HRS/MSC AFL	15000					15000 M		6052.2
+ 78-30-00-202 (s)	FUNCTIONAL TEST THRUST REVERSER - AUTO STOW SYSTEM	MOS					PKG			
	PKG 4	HRS/MSC AFL	1200				16-JUN-2005 8180 3964			
	REF: AMM 78-30-00-202									
78-30-00-208 (s)	VISUAL CHECK THRUST REVERSER - WITH THRUST REVERSERS MANUALLY DEPLOYED, VISUAL CHECK OF BLOCKER DOORS, ACTUATORS, LINKS AND HINGES. WITH THRUST REVERSERS STOWED, CARRY OUT A VISUAL CHECK TO ENSURE THAT BLOCKER DOORS ARE CLOSED AND FAIRED.	MOS					PKG			
	PKG 2	HRS/MSC AFL	300				09-SEP-2008 8806.5 4265			
	REF: GENERIC NO REF									
78-30-00-212 (s)	GENERAL VISUAL CHECK THRUST REVERSER - TORQUE BOX, TORQUE BOX MOLDED SEAL, FITTINGS, INNER AND OUTER SKIN PANELS, RIB ASSEMBLIES, RING SEGMENTS AND ATTACHING CASCADES	MOS					PKG			
	PKG 6	HRS/MSC AFL	2400				29-OCT-2003 7003 3486			
	REF: GENERIC NO REF									
+ 78-30-00-215 (s)	FUNCTIONAL TEST THRUST REVERSER - WARNING CIRCUIT	MOS					PKG			
	PKG 6	HRS/MSC AFL	2400				27-OCT-2003 7003 3486			
	REF: AMM 78-30-00-215									
+ 78-30-00-216 (s)	FUNCTIONAL TEST THRUST REVERSER - UNLOCKED LIGHT	MOS					PKG			
	PKG 4	HRS/MSC AFL	1200				09-JUN-2005 8180 3964			
	REF: AMM 78-30-00-216									
78-30-00-218 (s)	LUBRICATION BALLSCREW ACTUATORS AND MOUNTS	MOS					PKG			
	PKG 3	HRS/MSC AFL	600				20-MAR-2009 8873.5 4304			
	REF: AMM 78-30-00-218									

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
78-30-00-220	GENERAL VISUAL INSPECTION	THRUST REVERSER - TORQUE BOX - CONDITION AND SECURITY OF INSTALLATION						29-OCT-2003		
		MOS					7003			
	REF: GENERIC NO REF	HRS/MSC	N/A				3486			
		AFL								
78-30-00-221	GENERAL VISUAL INSPECTION	THRUST REVERSER - CASCADES - CONDITION AND SECURITY OF INSTALLATION						29-OCT-2003		
		MOS					7003			
	REF: GENERIC NO REF	HRS/MSC	N/A				3486			
		AFL								
78-30-00-222	GENERAL VISUAL INSPECTION	THRUST REVERSER - BLOCKER DOORS AND ATTACHMENTS - WITH THRUST REVERSERS FULLY DEPLOYED AND STOWED FOR CONDITION AND SECURITY OF INSTALLATION.						29-OCT-2003		
		MOS					7003			
	REF: GENERIC NO REF	HRS/MSC	N/A				3486			
		AFL								
78-30-00-223	GENERAL VISUAL INSPECTION	THRUST REVERSER - MAIN TRACKS - AT FULLY STOWED AND FULLY DEPLOYED - CONDITION AND SECURITY OF INSTALLATION						29-OCT-2003		
		MOS					7003			
	REF: GENERIC NO REF	HRS/MSC	N/A				3486			
		AFL								
78-30-00-224	GENERAL VISUAL INSPECTION	THRUST REVERSER - PYLON TRACKS AND ATTACHING LUGS - CONDITION AND SECURITY OF INSTALLATION						29-OCT-2003		
		MOS					7003			
	REF: GENERIC NO REF	HRS/MSC	N/A				3486			
		AFL								
78-30-00-225	GENERAL VISUAL INSPECTION	THRUST REVERSER - TRANSLATING COWL DOORS - CONDITION AND SECURITY OF INSTALLATION						29-OCT-2003		
		MOS					7003			
	REF: GENERIC NO REF	HRS/MSC	N/A				3486			
		AFL								
78-30-00-226	GENERAL VISUAL INSPECTION	THRUST REVERSER - DIVERTER FAIRING - CONDITION AND SECURITY OF INSTALLATION						29-OCT-2003		
		MOS					7003			
	REF: GENERIC NO REF	HRS/MSC	N/A				3486			
		AFL								
78-30-00-228	LUBRICATION	BALLSCREW ACTUATORS AND MOUNTS						01-OCT-1992		
		MOS					0			
	REF: AMM 78-30-00-228	HRS/MSC	N/A				0			
		AFL					0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
78-30-00-233	GENERAL VISUAL INSPECTION OF INSTALLATION	BLOCKER DOOR HOUSING - ATTACHING HARDWARE - CONDITION AND SECURITY								
	REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				29-OCT-2003 7003 3486			
78-30-00-413	NDT AND VISUAL CHECK	THRUST REVERSER MAIN TRACK, UPPER RADIUS, AFT END;ACCESS 413 AB-AT								05-10-25 AIRWORTHINESS
	REF:	MOS HRS/MSC AFL	A/R							
78-30-11-209 (s)	VISUAL CHECK	CASCADES/PYLON TRACKS					PKG			
	PKG 3	MOS HRS/MSC AFL	600				20-MAR-2009 8873.5 4304			
	REF: AMM 78-30-11-209									
78-30-16-237	DETAILED INSPECTION	THRUST REVERSER (A/C 5135 TO 5150, 5160 TO 5162, 5164 TO 5166, 5168 TO 5173 AND 5178 PRE SB 601-1084) - 6 O'CLOCK SAM PANEL AND UNDERLYING BRACKETS								
	REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				01-OCT-1992 0 0			
78-30-26-204 (s)	SPECIAL DETAILED INSPECTION	BLOCKER DOORS - BLOCKER DOOR BUSHINGS					PKG			
	PKG 6	MOS HRS/MSC AFL	2400				29-OCT-2003 7003 3486			
	REF: AMM 78-30-26-204									
78-30-31-210 (s)	VISUAL CHECK	MAIN TRACKS AND ATTACHMENTS.					PKG			
	PKG 3	MOS HRS/MSC AFL	600				20-MAR-2009 8873.5 4304			
	REF: GENERIC NO REF									
78-30-41-201 (s)	DETAILED INSPECTION	MAIN AND PYLON TRACK SLIDER BLOCK					PKG			
	PKG 4	MOS HRS/MSC AFL	1200				09-JUN-2005 8180 3964			
	REF: AMM 78-30-41-201									
78-30-46-227	CHECK	THRUST REVERSER - RIGGING OF PNEUMATIC DRIVE FLEXSHAFT LOCK UNIT								
	REF: AMM 78-30-46-227	MOS HRS/MSC AFL	N/A				01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
78-30-51-217 (s)	SPECIAL DETAILED INSPECTION PKG 6 REF: AMM 78-30-51-217	FLEXSHAFTS MOS HRS/MSC AFL	2400				PKG 29-OCT-2003 7003 3486			
78-30-51-229	SPECIAL DETAILED INSPECTION REF: AMM 78-30-51-229	THRUST REVERSER - FLEXSHAFTS MOS HRS/MSC AFL	N/A				29-OCT-2003 7003 3486			
78-30-56-214 (s)	DETAILED INSPECTION PKG 6 REF: AMM 78-30-56-214	BALLSCREW ACTUATORS INSPECTION MOS HRS/MSC AFL	2400				PKG 29-OCT-2003 7003 3486			
78-30-56-234	DETAILED INSPECTION REF: AMM 78-30-56-234	NOSE COWL ASSEMBLY - BALLSCREW ACTUATOR SUPPORT FITTINGS MOS HRS/MSC AFL	N/A				29-OCT-2003 7003 3486			
+ 78-30-61-213 (s)	FUNCTIONAL TEST PKG 4 REF: AMM 78-30-61-213	AUTO-THROTTLE RETARDER CONTROL MOS HRS/MSC AFL	1200				PKG 14-JUN-2005 8180 3964			
78-30-61-230	FUNCTIONAL TEST REF: AMM 78-30-61-230	THRUST REVERSER - AUTO-THROTTLE RETARDER SYSTEM AND THROTTLE LOCKS MOS HRS/MSC AFL	N/A				01-OCT-1992 0 0			
78-30-61-231	DETAILED INSPECTION REF: AMM 78-30-61-231	THRUST REVERSER - AUTO-THROTTLE RETARDER AND THROTTLE LOCKS MOS HRS/MSC AFL	N/A				29-OCT-2003 7003 3486			
783000-001	PDU:NO. 1 THRUST REVERSER PDU 126758-6-2 539 REF: AMM 783000	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0		02/06/2003	06-AUG-2002 5945 3038			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
783000-002	PDU:NO. 2 THRUST REVERSER PDU 126758-6-2 438 REF: AMM 783000	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			16-FEB-2007 8453 4104			
783001-001	BALLSCREW:NO.1 ACTUATOR GEARBOX BALLSCREW 3272570-3 1913 REF: AMM 783001	MOS HRS/MSC AFL	16000	TSN:0 TSN:0			01-OCT-1992 0 0	16000	11647	LIFE LIMIT
783001-002	BALLSCREW:NO.2 ACTUATOR GEARBOX BALLSCREW 3272570-3 1927 REF: AMM 783001	MOS HRS/MSC AFL	16000	TSN:0 TSN:0			01-OCT-1992 0 0	16000	11647	LIFE LIMIT
783001-003	BALLSCREW:NO. 3 ACTUATOR GEARBOX BALLSCREW 3272570-3 1917 REF: AMM 783001	MOS HRS/MSC AFL	16000	TSN:0 TSN:0			01-OCT-1992 0 0	16000	11647	LIFE LIMIT
783001-004	BALLSCREW:NO.4 ACTUATOR GEARBOX BALLSCREW 3272570-3 1929 REF: AMM 783001	MOS HRS/MSC AFL	16000	TSN:0 TSN:0			01-OCT-1992 0 0	16000	11647	LIFE LIMIT
783001-005	BALLSCREW:NO.5 ACTUATOR GEARBOX BALLSCREW 3272570-3 1926 REF: AMM 783001	MOS HRS/MSC AFL	16000	TSN:0 TSN:0			01-OCT-1992 0 0	16000	11647	LIFE LIMIT
783001-006	BALLSCREW:NO.6 ACTUATOR GEARBOX BALLSCREW 3272570-3 1918 REF: AMM 783001	MOS HRS/MSC AFL	16000	TSN:0 TSN:0			01-OCT-1992 0 0	16000	11647	LIFE LIMIT
783001-007	BALLSCREW:NO.7 ACTUATOR GEARBOX BALLSCREW 3272570-3 1928 REF: AMM 783001	MOS HRS/MSC AFL	16000	TSN:0 TSN:0			01-OCT-1992 0 0	16000	11647	LIFE LIMIT

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
783001-008	BALLSCREW:NO.8 ACTUATOR GEARBOX BALLSCREW 3272570-3 1910 REF: AMM 783001	MOS HRS/MSC AFL	16000	TSN:0 TSN:0			01-OCT-1992 0 0		16000	LIFE LIMIT 11647
783004-001	SWITCH:NO. 1 STOW THRUST REVERSER SWITCH 4EN1-6 SN-UNKNOWN REF: AMM 78-30-66	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
783004-002	SWITCH:NO. 2 STOW THRUST REVERSER SWITCH 228-50741-105 5065 REF: AMM 78-30-66	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-2007 8459			
783040-001	ROD END:NO.1 THRUST REVERSER ROD END 3233445-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	6500	TSN:0 TSN:0			01-OCT-1992 0 0		6500	LIFE LIMIT 2147
783040-002	ROD END:NO.2 THRUST REVERSER ROD END 3233445-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	6500	TSN:0 TSN:0			01-OCT-1992 0 0		6500	LIFE LIMIT 2147
783040-003	ROD END:NO. 3 THRUST REVERSER ROD END 3233445-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	6500	TSN:0 TSN:0			01-OCT-1992 0 0		6500	LIFE LIMIT 2147
783040-004	ROD END:NO. 4 THRUST REVERSER ROD END 3233445-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	6500	TSN:0 TSN:0			01-OCT-1992 0 0		6500	LIFE LIMIT 2147
783040-005	ROD END:NO.5 THRUST REVERSER ROD END 3233445-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	6500	TSN:0 TSN:0			01-OCT-1992 0 0		6500	LIFE LIMIT 2147

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
783040-006	ROD END:NO.6 THRUST REVERSER ROD END 3233445-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	6500	TSN:0 TSN:0			01-OCT-1992 0 0	6500	2147	LIFE LIMIT
783040-007	ROD END:NO.7 THRUST REVERSER ROD END 3233445-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	6500	TSN:0 TSN:0			01-OCT-1992 0 0	6500	2147	LIFE LIMIT
783040-008	ROD END:NO.8 THRUST REVERSER ROD END 3233445-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	6500	TSN:0 TSN:0			01-OCT-1992 0 0	6500	2147	LIFE LIMIT
783046-001	TANG:2 O'CLOCK LEFT ANTI ROTATION TANG 3233586-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
783046-002	TANG:4 O'CLOCK LEFT ANTI ROTATION TANG 3233586-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
783046-003	TANG:8 O'CLOCK LEFT ANTI ROTATION TANG 3233586-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
783046-004	TANG:10 O'CLOCK LEFT ANTI ROTATION TANG 3233586-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
783046-005	TANG:2 O'CLOCK RIGHT ANTI ROTATION TANG 3233586-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
783046-006	TANG:4 O'CLOCK RIGHT ANTI ROTATION TANG 3233586-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
783046-007	TANG:8 O'CLOCK RIGHT ANTI ROTATION TANG 3233586-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
783046-008	TANG:10 O'CLOCK RIGHT ANTI ROTATION TANG 3233586-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
+ 783158	VISUAL CHECK LEFT THRUST REVERSER - MAIN TRACK ATTACHMENT FITTINGS REF:	MOS HRS/MSC AFL	5400	TSI:59			27-FEB-2001 4859 2516	10200		AIRWORTHINESS 1252.2
+ 783159	VISUAL CHECK RIGHT THRUST REVERSER - MAIN TRACK ATTACHMENT FITTINGS REF:	MOS HRS/MSC AFL	5400	TSI:59			27-FEB-2001 4859 2516	10200		AIRWORTHINESS 1252.2
789001	SWITCH:L T/REVERSE DEPLOY SWITCH 402EN61-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			23-MAY-1994 683 337			
789006	SWITCH:R T/REVERSE DEPLOY SWITCH 402EN61-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			16-JUN-1994 710 348			
789010	SWITCH:LEFT THRUST REVERSER THROTTLE LOCK OUT SWITCH 21EN9-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C							

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
789011	SWITCH:RIGHT THRUST REVERSER THROTTLE LOCK OUT SWITCH 21EN9-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C					12-FEB-2001 4830 2504		
789152	--:11 O'CLOCK BLOCKER DOOR 228-50232-101 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C					26-DEC-2001 5429 2786		
78R008	HOSE:LH #3 INJECTOR FUEL HOSE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R							
C78-00-801 (s)	CPCP CHECK THRUST REVERSER PKG 34 REF: GENERIC NO REF	MOS HRS/MSC AFL		60					PKG	
T78T01	SAFETY PRECAUTIONS - THRUST REVERSER REF:	MOS HRS/MSC AFL	O/C							
T78T02	RIG MICROSWITCH / DEPLOY MICROSWITCH / FUNCTIONAL CHECK THROTTLE LOCKOUT MICROSWITCH REF:	MOS HRS/MSC AFL	O/C							
T78T03	RIG AUTO THROTTLE RETARDER CONTROL REF:	MOS HRS/MSC AFL	O/C							
CHAPTER 79 OIL										
791000-001	VALVE:SELECTOR - OIL REPL SYSTEM VALVE 601-63902-1 40503230 REF: AMM 791000	MOS HRS/MSC AFL	O/C					28-MAR-1996 1761 872		

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
791001-001	CONTROL:ENGINE OIL LEVEL CONTROL 601-63903-9 400 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
791002-001	PROBE:NO. 1 OIL LEVEL PROBE 601-63903-15 191 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				18-MAY-2001 4977 2563			
791002-002	PROBE:NO. 2 OIL LEVEL PROBE 601-63903-7 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
791003-001	PUMP:LUBRICATING SYSTEM PUMP 601-63901-1 8AK-26 REF: AMM 791003	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			26-FEB-1996 1728 855			
791006-001	SENSOR:NO. 1 OIL FILTER BYPASS SENSOR 4060T64P01 54141 REF: AMM 791006	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-JUN-2005 8180 3964			
791006-002	SENSOR:NO. 2 OIL FILTER BYPASS SENSOR 4060T64P01 SN-UNKNOWN REF: AMM 791006	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-OCT-1992 0 0			
793000-001	TRANSDUCER:NO. 1 ENGINE OIL PRESSURE TRANSDUCER 601-50919-3 2988-17-153 REF: AMM 793000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-DEC-1997 2893 1450			
793000-002	TRANSDUCER:NO. 2 ENGINE OIL PRESSURE TRANSDUCER 601-50919-3 4461-3-261 REF: AMM 793000	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-JUN-1993 117 66			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
793001-001	SWITCH:NO. 1 ENGINE OIL PRESSURE SWITCH 1153P0012 SN-UNKNOWN REF: AMM 793001	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
793001-002	SWITCH:NO. 2 ENGINE OIL PRESSURE SWITCH 1153P0012 SN-UNKNOWN REF: AMM 793001	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-OCT-1992 0 0			
793002-001	BULB:NO. 1 TEMPERATURE BULB MS28034-3 SN-UNKNOWN REF: AMM 793002	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
793002-002	BULB:NO. 2 TEMPERATURE BULB MS28034-3 SN-UNKNOWN REF: AMM 793002	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
793003-001	INDICATOR:OIL TEMPERATURE INDICATOR 601-50916-3 660 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
793004-001	INDICATOR:OIL PRESSURE INDICATOR 601-50915-1 841 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
79R001	VALVE:CK OIL REPLENISH VALVE 2810044-101 0486 REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			12-APR-1995 1178 574			
T79T01	REPLENISH ENGINE OIL SYSTEM REF:	MOS HRS/MSC AFL	O/C							

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
T79T02	CHECK REQUIRED AFTER MAINTENANCE ON FAN SPEED PICKUP									
	REF:	MOS HRS/MSC AFL	O/C							
ENGINE NO. 1 Model : CF-34 (CIMMS) Serial # 350-499 Part # 6063T01G04										
79-20-21-203 (s)	NO. 1 ENGINE - INSPECT OIL FILTER ASSEMBLY & INSTALL NEW FILTER (REF. G.E. MM SEI-580, SECTION 5-21-00)						PKG			
	PKG 3	MOS						20-MAR-2009		
	REF: EMM 79-00-00	HRS/MSC ENC	600					8735.6		
79-20-21-301	NO. 1 ENGINE - INSPECT OIL FILTER ASSEMBLY - & INST NEW FILTER ELEMENT									
	REF: EMM 79-00-00	MOS HRS/MSC ENC	E/C							
79-20-26-208 (s)	NO. 1 ENGINE - VISUAL CHECK OIL/FUEL HEAT EXCHANGER ASSEMBLY PAYING PARTICULAR ATTENTION FOR CHAFING OF HOUSING FROM LOOP CLAMP ON C-SUMP AFT SCAVENGE HOSE (REF. G.E. MM SEI-580, SECTION 5-21-00)						PKG			
	PKG 4	MOS						02-AUG-2005		
	REF:	HRS/MSC ENC	1200	TSI:0				8078.3		
79-20-31-201 (s)	NO. 1 ENGINE - INSPECT CHIP DETECTOR CHECK CHIP DETECTOR (5/ENGINE)						PKG			
	PKG 1	MOS						19-JUL-2010		
	REF: See Workcard	HRS/MSC ENC	100					8809.9		
79-21-01-202	NO. 1 ENGINE - DETAILED INSPECTION C-SUMP SCAVENGE SCREENS (REF. G.E. MM SEI-580, SECTION 5-21-00)									
	REF: EMM 79-00-00	MOS HRS/MSC ENC	3000	TSI:0				29-AUG-2002		
								5852	(8852) 8989.9	42.1
								3407		
79-30-26-204 (s)	NO. 1 ENGINE - FUNCTIONAL TEST OIL FILTER IMPENDING BYPASS SENSOR						PKG			
	PKG 3	MOS						20-MAR-2009		
	REF:	HRS/MSC ENC	600					8735.6		
790010-001	COOLER:NO. 1 ENGINE - OIL COOLER									
	4048T39P01	MOS						23-AUG-2002		
	AE403547	HRS/MSC	O/C					5852		
	REF: EMM 79-00-00	ENC		TSN:9500 TSO:0				3407		
				TSN:9700 TSO:0						

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
791012-001	PUMP:NO. 1 ENGINE - LUBE & SCAVENGE PUMP 4022T27G22 NMAA0879 REF: EMM 79-00-00	MOS HRS/MSC ENC	O/C	TSN:4839.5 TSO:0 TSO:0			23-AUG-2002 5852 3407			
791014-001	PUMP:NO. 1 ENGINE - A-SUMP SCAVENGE PUMP 4018T11P02 LJA34034 REF: EMM 79-00-00	MOS HRS/MSC ENC	O/C	TSO:0TSN:5852 TSO:0TSN:3407			23-AUG-2002 5852 3407			
ENGINE NO. 2 Model : CF-34 (CIMMS) Serial # 350-498 Part # 6063T01G04										
79-20-21-203 (s)	NO. 2 ENGINE - INSPECT OIL FILTER ASSEMBLY & INSTALL NEW FILTER (REF. G.E. MM SEI-580, SECTION 5-21-00) PKG 3 REF: EMM 79-00-00	MOS HRS/MSC ENC	600				PKG 20-MAR-2009 8699.7			
79-20-21-301	NO. 2 ENGINE - INSPECT OIL FILTER ASSEMBLY - & INST NEW FILTER ELEMENT REF: EMM 79-00-00	MOS HRS/MSC ENC	E/C							
79-20-26-208 (s)	NO. 2 ENGINE - VISUAL CHECK OIL/FUEL HEAT EXCHANGER ASSEMBLY PAYING PARTICULAR ATTENTION FOR CHAFING OF HOUSING FROM LOOP CLAMP ON C-SUMP AFT SCAVENGE HOSE (REF. G.E. MM SEI-580, SECTION 5-21-00) PKG 4 REF:	MOS HRS/MSC ENC	1200	TSI:0			PKG 04-AUG-2005 8042.8			
79-20-31-201 (s)	NO. 2 ENGINE - INSPECT CHIP DETECTOR CHECK CHIP DETECTOR (5/ENGINE) PKG 1 REF: See Workcard	MOS HRS/MSC ENC	100				PKG 19-JUL-2010 8774			
79-21-01-202	NO. 2 ENGINE - DETAILED INSPECTION C-SUMP SCAVENGE SCREENS (REF. G.E. MM SEI-580, SECTION 5-21-00) REF: EMM 79-00-00	MOS HRS/MSC ENC	3000				04-AUG-2005 8042.8 (11042.8) 11216.6			2268.8
79-30-26-204 (s)	NO. 2 ENGINE - FUNCTIONAL TEST OIL FILTER IMPENDING BYPASS SENSOR PKG 3 REF:	MOS HRS/MSC ENC	600				PKG 20-MAR-2009 8699.7			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
790010-001	COOLER:NO. 2 ENGINE - OIL COOLER 4048T39P01 AEYA0128 REF: EMM 79-00-00	MOS HRS/MSC ENC	O/C	TSN:5852 TSO:0 TSN:3407 TSO:0			28-AUG-2002 5852 3407			
791012-001	PUMP:NO. 2 ENGINE - LUBE & SCAVENGE PUMP 4022T27G22 NMAA1160 REF: EMM 79-00-00	MOS HRS/MSC ENC	O/C	TSN:5852 TSO:0 TSN:3407 TSO:0			28-AUG-2002 5852 3407			
791014-001	PUMP:NO. 2 ENGINE - A-SUMP SCAVENGE PUMP 4018T11P02 LJA34039 REF: EMM 79-00-00	MOS HRS/MSC ENC	O/C	TSN:5852 TSO:0 TSN:3407 TSO:0			28-AUG-2002 5852 3407			
CHAPTER 80 STARTING										
+ 80-10-11-201 (s)	VISUAL CHECK AIR TURBINE STARTER/REPLENISH - OIL LEVEL CHECK PKG 2 REF: AMM 80-10-11-201	MOS HRS/MSC AFL	300				PKG 09-SEP-2008 8806.5 4265			
80-10-11-202 (s)	SERVICING AIR TURBINE STARTER AIR TURBINE STARTER OIL CHANGE PKG 3 REF: AMM 80-10-11-202	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
+ 80-10-11-203 (s)	DETAILED INSPECTION AIR TURBINE STARTER - DRAIN PLUG MAGNETIC CHIP-DETECTOR (P/N 3505188-9 AND SUBS) PKG 3 REF: AMM 80-10-11-203	MOS HRS/MSC AFL	600				PKG 20-MAR-2009 8873.5 4304			
801000-001	STARTER:NO. 1 ENGINE AIR STARTER 3505188-7-4 P-138C REF: AMM 801000	MOS HRS/MSC AFL	O/C	TSN:2557			01-JUL-1996 1945 980			
801000-002	STARTER:NO. 2 ENGINE AIR STARTER 3505188-7-2 3200 REF: AMM 801000	MOS HRS/MSC AFL	O/C				31-MAR-2000 4207 2174			

Status Report

CL-601-3A/3R (CIMMS) S/N 5121 (N328AM): 8947.8 HRS, 4353 AFL as of 19-Jul-2010

Owner/Operator: CESSNA FINANCE CORPORATION

Report Date: 07-SEP-2010

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENH) AFH	MAX LIMIT	TIME REMAINING
801016-001	VALVE:NO. 1 ENGINE AIR START VALVE 898930-7-2 812 REF: AMM 801016	MOS HRS/MSC AFL	O/C	TSN:0			01-OCT-1992 0 0			
801016-002	VALVE:NO. 2 ENGINE AIR START VALVE 898930-7-2 826 REF: AMM 801016	MOS HRS/MSC AFL	O/C				24-FEB-2000 4136 2140			